

ELITE AUTOMOTIVE PTE LTD

280 Woodlands Industrial Park E5, #01-17,
Harvest @ Woodlands Singapore 757322
Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SLA 7692J

Vehicle Model : HONDA STREAM

Chassis Number : JHMRN68408S204747

Estimated Repair Cost

S/N	Parts Description	Qty	List Price
1	BOOT LID ✓ DD	1	\$ 903.25 ✓
2	BOOT LID LOCK ✓ Jammed	1	\$ 150.00 ✓
3	BOOT LID "H" LOGO ✓ Nec	1	\$ 31.95 ✓
4	"STREAM" EMBLEM ✓ Nec	1	\$ 51.65 ✓
5	BOOT LID INNER TRIM COVER ? ✓ CRU	1	\$ 161.05 ✓
6	BOOT LID INNER TRIM COVER CLIPS ? ✓ Nec	15	\$ 75.00 30
7	BOOT LID WEATHERSTRIP ✓ CUT	1	\$ 151.65 ✓
8	BOOT LID SCREEN INNER SEAL unwritten ✓ Nec	1SET	\$ 130.30 100
9	BOOT LID ABSORBER LH & RH X SVC	2	\$ 313.40 X
10	BOOT LID CENTER GARNISH . . . ? ✓ CRU	1	\$ 162.85 ✓
11	BOOT LID HANDLE COVER ✓ CRU	1	\$ 35.10 ✓
12	TAIL LAMP LH & RH ✓ RH ✓ CRA	1/2	\$ 705.70 352.85
13	REAR BUMPER ✓ CRU	1	\$ 588.90 ✓
14	REAR BUMPER CLIPS ✓ Nec	10	\$ 50.00 30
15	REAR BUMPER RETAINER LH & RH ✓ BR. LH / BR	2/2	\$ 58.90 ✓
16	REAR BUMPER BRACKET LH & RH ? ✓ BT	2	\$ 30.50 ✓
17	END PANEL ✓ DD	1	\$ 306.75 ✓
18	END PANEL UPPER GARNISH ✓ CRU.	1	\$ 195.00 ✓
19	TOWING CAP X SVC	1	\$ 25.00 X
20	EXHAUST ? X SVC	1	\$ 514.25 X
21	EXHAUST MOUNTING ? X SVC	2	\$ 40.00 X
22	EXHAUST OUTER CHROME ? ✓ SCH	1	\$ 151.80 ✓
23	TOOL BOX ✓ CRU.	1	\$ 64.20 ✓
24	SPARE TYRE TANK X DD LH ✓ CRU.	1	\$ 1062.60 855.60
25	REAR FENDER INNER TRIM COVER LH & RH ✓ CRU.	1/2	\$ 594.10 297.05
26	REAR RHS FENDER X R	1	\$ 858.35 X
27	REVERSE CAMERA X SVC	1	\$ 850.00 X
28	REAR NUMBER PLATE LIGHT LH & RH ? . . . X SVC.	2	\$ 80.00 X 4,709.05

ELITE AUTOMOTIVE PTE LTD

280 Woodlands Industrial Park E5, #01-17,
Harvest @ Woodlands Singapore 757322
Tel: 6339 7378 Fax: 6339 7475

S/N	Special Nett Items:	Qty	
1	REAR NUMBER PLATE WITH HOLDER	X5VU C.	ISET \$ 60.00
2	REVERSE SENSORS	✓ short	ISET \$ 350.00 / 200
Special Nett Total		\$ 410.00	
Spare Part's Total Price		\$ 7083.80	M = 250

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

ELITE AUTOMOTIVE PTE LTD

280 Woodlands Industrial Park E5, #01-17,
Harvest @ Woodlands Singapore 757322
Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SLA 7692J

Vehicle Model : HONDA STREAM

Chassis Number : JHMNRN68408S204747

S/N	Labour Descriptions	Charges
1	LABOUR CHARGES TO REMOVE & INSTALL REAR END ATTACHMENTS & FITTINGS TO ENABLE REPAIRS; TO CUT & WELD WHERE NECESSARY; TO STRAIGHTEN & REPAIR BOOT FLOOR PANEL, TO REPLACE DAMAGED PARTS AS LISTED ABOVE.	\$ 1800.00 500 1200 1050 700
2	TO SPRAY PAINTING ON: BOOT LID (INNER, OUTER), REAR BUMPER, REAR END PANEL & BOOT FLOOR PANEL, REAR RHS FENDER.	\$ 1800.00 600 850
3	TO REMOVE & REPLACE REVERSE SENSOR & TEST FUNCTION.	\$ 100.00 30
4	TO REMOVE & TRANSFER BOOT LID SERVICEABLE COMPONENTS & TRIMMINGS TO NEW BOOT LID & TEST FUNCTION.	\$ 100.00 60
5	TO REMOVE & INSTALL BOOT COMPARTMENTS ATTACHMENTS, TRIMMINGS & FITTINGS TO ENABLE REPAIRS.	\$ 120.00 X / 60
6	TO CHECK ELECTRICAL WIRINGS & REAR LIGHTS FUNCTIONS.	\$ 100.00 30
7	TO RESET & REMOVE FAULT CODES AFTER ACCIDENT REPAIRS.	\$ 280.00 X
8	TO REMOVE & TRANSFER BOOT LID SCREEN TO NEW BOOT LID AND PERFORM WEST TEST.	\$ 150.00 / 20

Labour Total \$ 4450.00 2,150

Parts & Labour Total \$ 11533.80

P - \$ 3,767.24

N = 250

L = 2,150

6,167.24

- 20%

4,933.79

Sun Pm (Lk)

Tp without predrue