

A.S. REG. BY: Sun Pm

REF: INC

ASSIGNMENT

From:

Date

7/1/2020

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLA 7692J

at Workshop m/s

Elite Automotive

of 280 woodlands Ind. Park ES # 01-17

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Christy @ 8660 6722

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{Imp}

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLA 7692J

Yr Regn: 20/04 / 2008

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Stream 1.8L

C.C. 1799

Colour:

Silver.

A/C: Insured / Std / NI / NA

Sp. Reading

133860

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JHMRN684085204747

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 205/65 R15

R: 205/65 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake.

Front

Rear

R/Bal. 5 mm

R/Bal. 5 mm

L/Bal. 5 mm

L/Bal. 5 mm

D.O.A. 03/01/2020

D.O.I. 07/01/2020

Survey held at

Elite Auto.

4.45pm

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV = 50,000

PV = 31,612

NV = 18,388

Date/Time, File Pass to?



: Prel. Report

1) 14/05 Typist



: Final Report

Date/Time, File Return to?

2)

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech. Insp (\$)



: Weekend (\$)

Report Format:

TP

Lump Sum /

5000

Days Of Repair:

7

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

S + RS, \$

Photos

Other:

TOTAL