

22/03/2002

ASS. REC. BY:

REF:

CS/INC20000443/Bsc302

Special Instruction:

Surveyor: Mr hm

ASSIGNMENT (Office)

From (Person): Theresa Vimola

of

INC

Date/Time: 7/1/2020 @ 10:11am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJP 7003T

Insured:

PC1588J

at Workshop m/s

Team Autopro

Tel:

6258 1955

of

160 Sin Ming Drive # 01-14

Policy No:

Claim No:

MT/107 8683002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

6/1/2020

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:17am @ 7/1/2020

Person Contacted:

peach

Vehicle

☒ IN ☐ OUT

Date/Time

Action/Instruction

Isbnngly ✓

SJP 7003T-NBA / Lpc 20000332/Y

DOA: 6/01/2020

31/01/2020 Cof reviewed. To offer next value of rev -
 MV quoted reasonable.

ASS. REC. BY:

REF: INC

Shirley

ASSIGNMENT

From:

Date:

7/1/2020

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SJP 7003T

at Workshop m/s

Team Auto pro

of

160 Sin Ming Drive # 01-14

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

30,000/-

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

14

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

lup

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SJP 7003T

Yr Regn:

1/4/2009

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota RAV4 2.4 cc 2362

Colour:

White

A/C:

Insured / Std / NI / NA

Sp. Reading

108218

T/Radio:

Insured / Std / NI / NA

Eng/No:

2AZ 5836309

C/No:

ACA365022986

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / SRim / STD A/Rim or

Tyre Size:

F: 245/50/18

R: 245/50/18

BS / BUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

6/1/2020

D.O.I.

7/1/2020

Survey held at

Team Auto pro

0218PM

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

Team Auto pro

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Range 23,000/- - 24,000/-

Recommendation - Beyond economical repair. Date 15/1/2020

16,000/-

Finalised with KCA Team Auto pro

Lump Sum 24,500/- Team Auto 12/1/2020

Recommended Lump sum @

(P 34,520.28 Red 68% im)

16,000/- due to NV, with 14

MV 30,000/-

As check parts prices repair days

PV 13,961/-

Team Auto 12/1/2020

NV 16,039/-

5/1/2020

Date/Time, File Pass to?

14/02/20

1)

Typ. 4



Preli. Report



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

14

Resurvey No. of Trip:

4

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



W/End (\$)

Survey Fee:

250

Transportation:

S + RS - SI

Photos

Others

TOTAL

250

Report Format:

Lump Sum / L.B. / C

\$16K L/S

Nivitha (LKK Auto)

From: Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>
Sent: Tuesday, 7 January 2020 10:11 AM
To: Admin-D (LKKAuto); assignments; SUR
Cc: Thio Tse Kiat; Theresa Vimala D/O Balagangadharan
Subject: RE: TP CASES FARMED OUT TO LKK ON 7/1/2020

Hi Lkk,

Please include another 2 more vehicles to be surveyed today.

SN	OIC	Claim No.	Survey Date	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
9		MT/1078683-002	7/1/2020	SJP7003T	TEAM AUTOPRO PTE LTD	BLK 160 SIN MING DRIVE #01-14 SINGAPORE 575722	Eric Lee / 8269 9999				
10		MT/1078728-001	7/1/2020	SJX4367X	TEAM AUTOPRO PTE LTD	BLK 160 SIN MING DRIVE #01-14 SINGAPORE 575722	Eric Lee / 8269 9999				

Theresa Vimala
Senior Administrator
Operations, Motor & Personal Lines (PL)
T +65 6430 7898
www.income.com.sg

Theresa Vimala
Senior Administrator
Operations, Motor & Personal Lines (PL)
T +65 6430 7898
www.income.com.sg



in with
you

At Income, we are 'in with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at Income.com.sg/careers

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 993G

Vehicle Details

Vehicle No.: SJP7003T
Vehicle to be Exported: No
Intended Deregistration Date: 08 Jan 2020
Vehicle Make: TOYOTA
Vehicle Model: RAV4 2.4 A
Primary Colour: White
Manufacturing Year: 2008
Engine No.: 2AZ5836309
Chassis No.: ACA365022986
Maximum Power Output: 125.0 kW (167 bhp)
Open Market Value: \$29,038.00
Original Registration Date: 01 Apr 2009
First Registration Date: 01 Apr 2009
Transfer Count: 1
Actual ARF Paid: \$29,038.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 31 Mar 2024
COE Category: E - Open Category
COE Period(Years): 5
PQP Paid: \$16,509.00
COE Rebate Amount: \$13,961.00
Total Rebate Amount: \$13,961.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 08 Jan 2020

OK

COE left 4yr 2mths

Dep. 7,000/yr
583/mth

MV 30,000/2
PV 13,961/2
NV 16,039/2

TETIM
8/1/2020

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)
Sent: Thursday, 9 January 2020 4:55 pm
To: Chester Chong
Cc: Admin-D (LKKAuto)
Subject: RE: ERV of SJP7003T at TEAM AUTOPRO PTE. LTD.

Dear Chester,

We refer to your below email above matter.

Market Value - \$ 27,000.00 (Estimated)

Total rebate amount - \$ 13,961.00

Nett Value - \$ 13,039.00

"Wishing you a Happy and Prosperous Lunar New Year"



Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Chester Chong <Chester.Chong@income.com.sg>
Sent: Thursday, 9 January 2020 11:45 am
To: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Subject: ERV of SJP7003T at TEAM AUTOPRO PTE. LTD.

Dear Sir/Mdm,

We have farmed out the survey of the above mentioned vehicle to you. Could please advise me on the ERV of the vehicle and whether if the vehicle is economically reparable?

Thank you

Kind regards,
Chester Chong
Claims Executive
Operations, Motor and Personal Lines (PL)
T +65 6430 7919
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify. Find out more at income.com.sg/careers



Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

[f Connect with Facebook](#)


Find out how much your car is worth
Click here for a **FREE** valuation!

HOME

NEW CARS

USED CARS

COMMERCIAL VEH

RENTAL CARS

SELL CARS

MOTOR DIRECTORY

ARTICLES

Home > Used Cars > Toyota Rav4 Search Results

TOYOTA RAV4 SEARCH RESULTS (4 listings)

30 results/page

Sort By Recommended

Toyota Rav4 2.0A Premium



Transmission: Auto
Engine Cap : 1,987 cc
Reg Date : 13-Feb-2019
(9yrs 1mth COE left)

Mileage : 9,000 km
Paper Value : \$61,985
Depreciation : \$10,750 / year

\$117,800
AVAILABLE

Most Desirable Facelift! Rare Unit! High OMV And High Value Model! 1 Careful Owner! Full Agent Maintained Unit! Agent Warranty Till Feb 2022! Like New Showroom Condition! 100% Loan Approval! Loan 100%! Bank/In House Loa...

Posted On 07 January 2020

Tags: Toyota Rav4 Car, 2019 Toyota Rav4 Car, Rav4 Car, Used Toyota Car



SELLING
YOUR CAR OR COMMERCIAL VEHICLE?

POST YOUR FREE AD TODAY!



USED CAR SEARCH

Save This Search

toyota rav4

Category	Car Type
Transmission	Engine Capacity
Min Price	Max Price
Min Depreciation	Max Depreciation
From Reg Year	To Reg Year

VEHICLE TOOLS

COE Results Loan Calculator
Post an Ad Road Tax Calculator
Carpark Rates Car Insurance Quotes

SG carconsign

Selling Your Car?
Get up to **\$5000 More**
with our proven professional assistance since 1996

LEARN MORE

CARS WANTED



LIFESTYLE

Food & Beverage Health Care & Wellness
Home Needs IT Products & Services
Men's Fashion Men's Hobby
Personal Needs Transport Services

Toyota Rav4 2.0A Premium



Transmission: Auto
Engine Cap : 1,987 cc
Reg Date : 30-Jul-2018
(8yrs 6mths COE left)

Mileage : 15,000 km
Paper Value : \$63,225
Depreciation : \$10,780 / year

\$112,200
AVAILABLE

Most Desirable Facelift! Rare Unit! High OMV And High Value Model! 1 Careful Owner! Full Agent Maintained Unit! Agent Warranty Till July 2021! Like New Showroom Condition! 100% Loan Approval! Loan 100%! Bank/In House Loa...

Posted On 07 January 2020

Tags: Toyota Rav4 Car, 2018 Toyota Rav4 Car, Rav4 Car, Used Toyota Car



Toyota Rav4 2.0A Premium



Transmission: Auto
Engine Cap : 1,987 cc
Reg Date : 18-Apr-2019
(9yrs 3mths COE left)

Mileage : 10,000 km
Paper Value : \$56,522
Depreciation : \$10,470 / year

\$113,800
AVAILABLE

Immediate Transfer Of Ownership Upon Collection. 1 Owner, Serviced And Warranty By Agent, Road Tax Till Oct 2020, The SUV That Brings Top Class Spaciousness And Utility To Suit Your Active Lifestyle. Best Price In Town.

Posted On 02 January 2020

Tags: Toyota Rav4 Car, 2019 Toyota Rav4 Car, Rav4 Car, Used Toyota Car



Toyota Rav4 2.4A (COE till 08/2029)



Transmission: Auto
Engine Cap : 2,362 cc
Reg Date : 17-Aug-2009
(9yrs 7mths COE left)

Mileage : 138,800 km
Paper Value : \$38,382
Depreciation : \$6,950 / year

\$66,800
AVAILABLE

100% Loan Available. Bank And In House Loan Available! Accident Free, Low Mileage, Sunroof! Good For Family Usage, A Well Maintained SUV! Engine And Gearbox In Excellent Conditions! No Gimmicks! Trade In Welcome! Don't Mis...

Posted On 15 November 2019

Tags: Toyota Rav4 Car, 2009 Toyota Rav4 Car, Rav4 Car, Used Toyota Car



Sort By Recommended

Email: sm@idac.com.sg

Tel no: 6555 6888 Fax no: 6454 3279

Personal Particulars of Owner & Driver (Vehicle A)

Date of Accident: 6/1/2020 (dd/mm/yy) Time of Accident: 08 15 (24-HR-FORMAT)
Vehicle No.: SJP 7003 T Vehicle Make & Model: TOYOTA RAV4 2.4 A
Exact location of Accident: Mandai Road towards BKE
Policyholder's Name / IC No.: Seah Hwa Kim Calvin S1745993G
Driver's Name / IC No.: Seah Hwa Kim Calvin S1745993G (As Above) ☐
Driver's Contact No.: 9675 4307 Company Contact No: _____
Driver's Address: Blk 583 Pasir Ris St 53 #07-25 S(510583)
Insurance Company: Lonpac Email address (if any): _____

Relationship between Owner & Driver: Owner

or Others specify: _____

What do you wish to claim? (Please TICK one only)

☐ Own Insurance / ☒ Other Vehicle (The one you want to claim against) / ☐ Reporting (For Record Purpose)

Exact purpose for which the vehicle
Was being used at time of accident?

Occupation (nature of job) ☒ Indoor / ☐ Outdoor

☒ Private use / ☐ Work purpose

No. of Passengers (Including Driver): 01

Passenger Name : _____

Gender : _____

Passenger Name : _____

Gender : _____

Weather condition & Road conditions? (On the day of accident)

☒ Clear & Dry / ☐ Raining & Wet / ☐ After-Rain & Wet / ☐ Drizzling & Wet / Others: _____

Was there any video captured by your Car Camera? ☐ Yes / ☒ No

Any Injuries: ☐ Yes / ☒ No (If YES) Injured Person's Name: _____

Injuries Sustain: _____ Injured Person in Which Vehicle: _____

Police Report filed: ☐ Yes / ☒ No (If YES) Which Police Station: _____

The Other Party(s) Details:

1. Driver's Name / IC No: _____ Vehicle No: PC 1588 J (B)

Driver's Contact No: _____ Insurance Company (If any): _____

2. Driver's Name / IC No: _____ Vehicle No: SGK 6864 T (D)

Driver's Contact No: _____ Insurance Company (If any): _____

*Independent Witness (If Any): _____ Contact No: SLA 9226 J (c)

Preferred Workshop Name: _____ Contact No: _____

*If no proper documents are produced, IDAC should not file the report. Information will be discarded after one week.

SKETCH PLAN

Mandai Road towards BKE

(A) SJP 7003 T

(B) PC 1588 J

(C) SLA 9226 J

(D) SGK 6864 T

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date and time, I vehicle A was travelling straight on my rightful lane. Vehicle C in front of me stopped. I stopped too. Suddenly Vehicle B hit onto my stationary Vehicle rear portion. The impact is so strong it caused my vehicle to propel forward and hit onto Vehicle C rear portion. After I alighted, I realised I'm involved in a 4 car chain collision.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

SJE : _____
 Date of Survey : _____
 Date of ReSurvey: _____ After-Paint: _____
 Contacts : _____

Vehicle Nos : **SJP 7003 T**
 Model : **TOYOTA RAV 4**
 Year : _____
 Chassis No : _____

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____ Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$	
1	BONNET	1	\$ 1,682.30	\$ 1,682.30	DD ✓
2	BONNET LOCK	1	\$ 254.60	\$ -254.60	NDX
3	BONNET HINGE RH 1	2	\$ 51.00 105.60	\$ 51.00 211.20	BT ✓
4	BONNET INSULATOR PAD	1	\$ 189.20	\$ -189.20	NDX
5	FRONT SUPPORT PANEL	1	\$ 1,103.00	\$ 1,103.00	BT ✓
6	FRONT SUPPORT PANEL TOP GARNISH	1	\$ 286.50	\$ 286.50	BT ✓
7	FRONT BRACE PANEL	1	\$ 298.00	\$ 298.00	NSPX
8	FRONT BUMPER	1	\$ 1,463.20	\$ 1,463.20	BR ✓
9	FRONT BUMPER REINFORCEMENT	1	\$ 476.30	\$ 476.30	DD ✓
10	FRONT BUMPER REINFORCEMENT SPOONGE	1	\$ 286.30	\$ 128.70 286.30	BR ✓
11	FRONT BUMPER TOP BRACKET	1	\$ 297.60	\$ 230.00 297.60	BT ✓
12	FRONT BUMPER TOW CAP	2	\$ 40.60 206.80	\$ 81.20 413.60	MIS ✓
13	FRONT BUMPER GRILLE	1	\$ 456.20	\$ 358.00 456.20	BR ✓
14	FRONT BUMPER CENTRE GRILLE	1	\$ 286.20	\$ 108.95 286.20	BR ✓
15	FRONT BUMPER LOWER GRILLE	1	\$ 186.30	\$ 186.30	BR ✓
16	FRONT LICENSE PLATE	1	\$ 138.60	\$ 50.00 138.60	DIS ✓
17	FRONT CHROME GRILLE	1	\$ 339.40	\$ 250.60 339.40	BR ✓
18	FRONT LOGO	1	\$ 186.20	\$ 86.50 186.20	NECV
19	FRONT FOG LAMP	2	\$ 328.10 415.60	\$ 656.20 831.20	BR ✓
20	FRONT FOG LAMP GARNISH	2	\$ 132.00 189.20	\$ 264.00 378.40	BR ✓
21	FRONT FENDER RH 1	2	\$ 570.00 894.30	\$ 570.00 1,788.60	DD ✓
22	FRONT FENDER INNER COWLING RH 1	2	\$ 297.00 368.40	\$ 297.00 736.80	BT ✓
23	FRONT FENDER QUARTER GARNISH	2	\$ 187.60	\$ -375.20	NSPX
24	ENGINE LOWER CAVER	1	\$ 489.20	\$ 269.20 489.20	BR ✓
25	RADIATOR	1	\$ 836.40	\$ 836.40	BT ✓
26	A/C CONDENSER	1	\$ 985.70	\$ 985.70	BT / DD ✓
27	A/C CONDENSER HIGH PRESSURE PIPE	1	\$ 286.70	\$ 286.70	NDX
28	A/C CONDENSER LOW PRESSURE PIPE	1	\$ 256.30	\$ 256.30	NDX
29	FAN ASSY	1	\$ 723.60	\$ 675.00 723.60	BR ✓
30	HEADLAMP	2	\$ 1,893.40	\$ 3,786.80	BR ✓
31	HEADLAMP LOWER BRACKET	2	\$ 216.20	\$ 432.40	NSPX
32	FRONT SIDE MIRROR RH	1	\$ 846.80	\$ 846.80	MIS ✓
33	REAR BUMPER	1	\$ 1,786.40	\$ 1,502.40 1,786.40	DD ✓
34	REAR BUMPER TOP GARNISH	1	\$ 327.20	\$ 252.80 327.20	DL ✓
35	REAR BUMPER REINFORCEMENT	1	\$ 452.30	\$ 452.30	BT ✓

17,099.95

36	REAR BUMPER RETAINER	2	\$	176.50	\$ 129.00	353.00	} NEC
37	REAR BUMPER SIDE RETAINER	2	\$	182.30	\$ 232.00	364.60	
38	REAR BUMPER BRACKET	2	\$	125.00	\$ 224.00	250.00	BTV
39	REAR BUMPER REFLECTOR RH	1	\$	286.20	\$ 152.00	286.20	} BRV
40	REAR BUMPER REFLECTOR LH	1	\$	286.20	\$ 152.00	286.20	
41	REAR END PANEL	1	\$	1,052.60	\$	✓ 1,052.60	DDV
42	REAR END PANEL TOP GARNISH	1	\$	347.20	\$	347.20	NNX
43	SPARE TYRE PANEL	1	\$	985.40	\$ 640.00	985.40	DDV
44	SPARE TYRE PANEL TOP BOARD	1	\$	441.30	\$ 441.30	441.30	BTV
45	SPARE TYRE PANEL FASTENER	1	\$	106.80	\$	106.80	NSPX
46	TALIGATE	1	\$	1,964.50	\$ 1382.40	1,964.50	DDV
47	TAILGATE LOGO	1	\$	162.40	\$ 36.25	162.40	} NECV
48	TAILGATE EMBLEM 'RAV 4'	1	\$	89.00	\$ 36.25	89.00	
49	TAILGATE EMBLEM 'RALLI//ART'	1	\$	89.00	\$ 36.25	89.00	4515.00
50	TAILGATE NUMBER PLATE LAMP	2	\$	204.60	\$ 256.00	409.20	BRV
51	TAILGATE OUTER MOULDING	1	\$	386.20	\$	✓ 386.20	BRV
52	TAILGATE LOWER OUTER MOULDING	1	\$	573.60	\$	✓ 573.60	MISV
53	TAILGATE INNER TRIM	1	\$	473.10	\$ 389.65	473.10	BRV
54	TAILGATE WEATHER STRIP	1	\$	396.40	\$ 261.60	396.40	TNV
55	TAILGATE LOCK ASSY	1	\$	476.20	\$	✓ 476.20	JAMV
56	TAILGATE HINGE <i>lower</i>	1	\$	✓ 341.60	\$ 170.00	683.20	BTV
57	TAILGATE STRIKER	1	\$	62.00	\$	62.00	NDX
58	TAILGATE ANTENNA SENSOR	1	\$	358.60	\$	358.60	NDX
59	TAILGATE LOCK SENSOR	1	\$	138.00	\$	✓ 138.00	CUTV
60	TAILGATE OUTER HANDLE W/SENSOR	1	\$	523.40	\$ 186.50	523.40	CUTV
61	TAILGATE WINDSCREEN	1	\$	984.60	\$	984.60	NDX
62	TAILGATE WINDSCREEN MOILDING	1	\$	214.60	\$	✓ 214.60	NECV
63	TAILGATE WINDSCREEN WIPER ARM	1	\$	201.60	\$	201.60	} NDX
64	TAILGATE WINDSCREEN WIPER MOTOR	1	\$	489.20	\$	489.20	
65	TAILGATE WINDSCREEN WIPER GARNISH	1	\$	342.60	\$	342.60	
66	TAILLAMP	2	\$	984.60	\$ 810.00	1,969.20	BRV
67	TAILLAMP LOWER BRACKET	2	\$	82.60	\$	165.20	NSPX
68	TAIL LAMP BASE PANEL	2	\$	436.50	\$ 421.20	873.00	DDV
69	FUEL CAVER	1	\$	386.10	\$	386.10	NDX
70	REAR FENDER	2	\$	1,197.80	\$ 2395.60	2,395.60	DDV
71	REAR FENDER UPPER INNER TRIM	2	\$	476.50	\$	953.00	NSPX
72	REAR FENDER LOWER INNER TRIM	2	\$	756.10	\$ 1,197.80	1,512.20	BTV
73	REAR FENDER AIR VENTS <i>RH</i>	1	\$	138.40	\$ 110.20	276.80	BTV
74	REAR FENDER QUARTER GLASS MOULDING	2	\$	173.50	\$	✓ 347.00	NECV
75	REAR DOOR LOCK LH	1	\$	543.60	\$ 476.20	543.60	JAMV
76	EXHAUST PIPE	1	\$	869.80	\$ 730.07	869.80	BTV
77	EXHAUST PIPE MOUNTING	2	\$	120.00	\$	240.00	NDX
				Parts Sub Total :	\$ 31155.42	48,453.70	14055.42
				25% Discount	\$ 7788.86	12,113.43	17099.95
				PARTS TOTAL :	\$ 23366.57	36,340.28	31155.42

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$		
1	SUNDRIES	1	\$	80.00	\$ 80.00	NNX
2	BONNET INSULATOR CLIPS	1	\$	50.00	50.00	} NECV
3	BONNET SEALANT	1	\$	100.00	100.00	
4	RADIATOR COOLANT	1	\$	80.00	80.00	} NECV
5	A/C COMPRESSOR FLUID	1	\$	80.00	80.00	
6	FRONT NO PLATE WITH COVER	1	\$	80.00	80.00	BTV
7	FRONT SUPPORT PANEL SEALANT	1	\$	80.00	80.00	} NECV
8	FRONT SUPPORT PANEL TOP GARNISH CLIPS	1	\$	50.00	50.00	
9	FRONT BUMPER GRILLE CLIPS	1	\$	50.00	50.00	} NECV
10	FRONT BUMPER CENTRE GRILLE CLIPS	1	\$	50.00	50.00	
11	FRONT BUMPER LOWER GRILLE CLIPS	1	\$	50.00	50.00	} NECV
12	FRONT FENDER QUARTER GARNISH	1	\$	50.00	50.00	

14	FRONT FENDER INNER COWLING CLIPS LH	1	\$	50.00	\$30.00	50.00
15	ENGINE LOWER CAVEER	1	\$	50.00	\$30.00	50.00
16	REAR BUMPER REVERSE SENSOR	4	\$	200.00	\$200.00	800.00
17	REAR END PANEL TOP GARNISH CLIPS	1	\$	50.00	\$30.00	50.00
18	TAILGATE SEALANT	1	\$	80.00	\$40.00	80.00
19	TAILGATE OUTER MOULDING CLIPS	1	\$	50.00	\$30.00	50.00
20	TAILGATE LOWER OUTER MOULDING CLIPS	1	\$	50.00	\$30.00	50.00
21	TAILGATE INNER TRIM CLIPS	1	\$	50.00	\$30.00	50.00
22	TAILGATE WINDSCREEN SEAL	1	\$	60.00	\$40.00	60.00
23	TAILGATE WINDSCREEN SEALANT	1	\$	80.00	\$50.00	80.00
24	REAR NO PLATE WITH COVER	1	\$	80.00	\$50.00	80.00
25	REVERSE CAMERA	1	\$	380.00	\$300.00	380.00
26	TAILLAMP CLIPS	2	\$	50.00	\$60.00	100.00
27	TAILLAMP SEALANT	2	\$	100.00		200.00
28	TAILLAMP BASE PANEL SEALANT	2	\$	80.00	\$60.00	160.00
29	REAR FENDER INNER TRIM CLIPS	2	\$	50.00	\$30.00	100.00
30	REAR FENDER QUARTER GLASS SEALANT	2	\$	80.00	\$80.00	160.00
31	REAR END PANEL SEALANT	1	\$	100.00	\$40.00	100.00
32	SPARE TYRE PANEL SEALANT	1	\$	100.00	\$40.00	100.00
33	SPARE TYRE PANEL INSULATOR PAD	1	\$	280.00	\$180.00	280.00
34	REAR FENDER SEALANT	2	\$	80.00	\$60.00	160.00
35	WINDSCREEN PRIMER AND CLEANER	1	\$	80.00	\$	80.00

SPECIAL NETT TOTAL : \$2010.00 4,020.00

Nos.	LABOUR		\$S
1	R&R REAR WINDSCREEN		\$120.00 150.00
2	R&R TAILGATE COMPONENT		\$80.00 100.00
3	R&R REAR FENDER COMPONENT		\$ 200.00
4	R&R FRONT FENDER COMPONENT		\$ 200.00
5	R&R REAR FENDER QUARTER GLASS		\$ 150.00
6	R&R REAR DOOR COMPONENT		\$80.00 150.00
7	R&R FUEL FILLER HOSE		\$ 100.00
8	R&R SPARE TYRE PANEL COMPONENT		\$60.00 180.00
9	R&R REVERSE SENSOR WITH RESPRASY		\$60.00 200.00
10	R&R EXHAUST PIPE		\$ 180.00
11	R&R A/C CONDENSER		\$70.00 150.00
12	R&R RADIATOR		\$70.00 150.00
13	UPHOLSTERY		\$80.00 200.00
14	CHECK WIRING		\$80.00 150.00
15	PANEL BEAT FRONT PORTION		\$1000.00 1,800.00
16	PANEL BEAT REAR PORTION		\$1200.00 2,000.00
17	CONDUCT WATER LEAKAGE TEST		\$ 100.00
18	DIAGNOTIC & RESET FAULT CODE		\$80.00 200.00
19	RUST PROOFING		\$80.00 200.00
20	SPRAY PAINTING FRONT PORTION		\$1000.00 1,600.00
21	SPRAYING PAINTING REAR PORTION		\$1200.00 2,000.00
LABOUR TOTAL :			\$5260.00 10,160.00

Survey 7/1/2020
Tetim lin 1518hrs

Repair 9/1/2020
Tetim lin 1500hrs

Lump Sum repair

Repair days 14

PARTS TOTAL : \$23,366.57 36,340.28
SPECIAL NETT TOTAL : \$2010.00 4,020.00
LABOUR TOTAL : \$5,260.00 10,160.00

GRAND TOTAL : \$ 50,520.28

@20%

30636.57
6127.31
24509.57

45 24500
16/1

Tetim lin
15/11/2020



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC20000443/Bsd3e2

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 17-02-2020



ATTN : CHESTER CHONG

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PC 1588J	Veh. Inspected	SJP 7003T
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1078683-002	Excess (\$)	0.00
Assign From	THERESA VIMALA	Assign Date	07/01/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA RAV4 2.4	c.c	2362
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	ACA365022986	Colour	WHITE
Odometer	108218 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	POOR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/50 R18	DUNLOP	6 mm
L/H Front Tyre	245/50 R18	DUNLOP	6 mm
R/H Rear Tyre	245/50 R18	DUNLOP	6 mm
L/H Rear Tyre	245/50 R18	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	06/01/2020	Inspect Date / Time	07/01/2020 (03:18 PM)
Survey held at	TEAM AUTOPRO PTE LTD 160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	14 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJP 7003T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BONNET	DENTED	1,682.30	1,300.00
1	BONNET LOCK	NOT DAMAGED	254.60	-
2	BONNET HINGE @\$105.60	O/S BENT	211.20	51.00
1	BONNET INSULATOR PAD	NOT DAMAGED	189.20	-
1	FRONT SUPPORT PANEL	BENT	1,103.00	1,071.00
1	FRONT SUPPORT PANEL TOP GARNISH	BENT	286.50	286.50
1	FRONT BRACE PANEL	NO SUCH PARTS	298.00	-
1	FRONT BUMPER	BROKEN	1,463.20	1,077.10
1	FRONT BUMPER REINFORCEMENT	DENTED	476.30	476.30
1	FRONT BUMPER REINFORCEMENT SPONGE	BROKEN	286.30	128.70
1	FRONT BUMPER TOP BRACKET	BENT	297.60	230.00
2	FRONT BUMPER TOW CAP @\$206.80	MISSING	413.60	81.20
1	FRONT BUMPER GRILLE	BROKEN	456.20	358.00
1	FRONT BUMPER CENTRE GRILLE	BROKEN	286.20	108.95
1	FRONT BUMPER LOWER GRILLE	BROKEN	186.30	186.30
1	FRONT LICENSE PLATE	DISTORTED	138.60	50.00
1	FRONT CHROME GRILLE	BROKEN	339.40	250.60
1	FRONT LOGO	NECESSARY	186.20	86.50
2	FRONT FOG LAMP @\$415.60	BROKEN	831.20	656.20
2	FRONT FOG LAMP GARNISH @\$189.20	BROKEN	378.40	264.00
2	FRONT FENDER @\$894.30	O/S DENTED	1,788.60	570.00
2	FRONT FENDER INNER COWLING @\$368.40	O/S BENT	736.80	297.00
2	FRONT FENDER QUARTER GARNISH @\$187.60	NO SUCH PARTS	375.20	-
1	ENGINE LOWER CAVER	BROKEN	489.20	269.20
1	RADIATOR	BENT	836.40	836.40
1	A/C CONDENSER	BENT / DENTED	985.70	985.70
1	A/C CONDENSER HIGH PRESSURE PIPE	NOT DAMAGED	286.70	-
1	A/C CONDENSER LOW PRESSURE PIPE	NOT DAMAGED	256.30	-
1	FAN ASSY	BROKEN	723.60	675.00
2	HEADLAMP @\$1893.40	BROKEN	3,786.80	3,750.00
2	HEADLAMP LOWER BRACKET @\$216.20	NO SUCH PARTS	432.40	-

Report Ref No. CS/INC20000443/Bsd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT SIDE MIRROR RH	MISSING	846.80	846.80
1	REAR BUMPER	DENTED	1,786.40	1,502.40
1	REAR BUMPER TOP GARNISH	DISLODGE	327.20	252.80
1	REAR BUMPER REINFORCEMENT	BENT	452.30	452.30
2	REAR BUMPER RETAINER @\$176.50	NECESSARY	353.00	129.00
2	REAR BUMPER SIDE RETAINER @\$182.30	NECESSARY	364.60	232.00
2	REAR BUMPER BRACKET @\$125.00	BENT	250.00	224.00
1	REAR BUMPER REFLECTOR RH	BROKEN	286.20	152.00
1	REAR BUMPER REFLECTOR LH	BROKEN	286.20	152.00
1	REAR END PANEL	DENTED	1,052.60	1,052.60
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	347.20	-
1	SPARE TYRE PANEL	DENTED	985.40	640.00
1	SPARE TYRE PANEL TOP BOARD	BENT	441.30	441.30
1	SPARE TYRE PANEL FASTENER	NO SUCH PARTS	106.80	-
1	TAILGATE	DENTED	1,964.50	1,383.40
1	TAILGATE LOGO	NECESSARY	162.40	36.25
1	TAILGATE EMBLEM 'RAV 4'	NECESSARY	89.00	36.25
1	TAILGATE EMBLEM 'RALLI//ART'	NECESSARY	89.00	36.25
2	TAILGATE NUMBER PLATE LAMP @\$204.60	BROKEN	409.20	256.00
1	TAILGATE OUTER MOULDING	BROKEN	386.20	386.20
1	TAILGATE LOWER OUTER MOULDING	MISSING	573.60	573.60
1	TAILGATE INNER TRIM	BROKEN	473.10	389.65
1	TAILGATE WEATHER STRIP	TORN	396.40	261.60
1	TAILGATE LOCK ASSY	JAMMED	476.20	476.20
2	TAILGATE HINGE @\$341.60	LOWER BENT	683.20	170.00
1	TAILGATE STRIKER	NOT DAMAGED	62.00	-
1	TAILGATE ANTENNA SENSOR	NOT DAMAGED	358.60	-
1	TAILGATE LOCK SENSOR	CUT	138.00	138.00
1	TAILGATE OUTER HANDLE W/SENSOR	CUT	523.40	186.50
1	TAILGATE WINDSCREEN	NOT DAMAGED	984.60	-
1	TAILGATE WINDSCREEN MOULDING	NECESSARY	214.60	214.60
1	TAILGATE WINDSCREEN WIPER ARM	NOT DAMAGED	201.60	-
1	TAILGATE WINDSCREEN WIPER MOTOR	NOT DAMAGED	489.20	-

Report Ref No. CS/INC20000443/Bsd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TAILGATE WINDSCREEN WIPER GARNISH	NOT DAMAGED	342.60	-
2	TAILLAMP @\$984.60	BROKEN	1,969.20	810.00
2	TAILLAMP LOWER BRACKET @\$82.60	NO SUCH PARTS	165.20	-
2	TAIL LAMP BASE PANEL @\$436.50	DENTED	873.00	421.20
1	FUEL CAVER	NOT DAMAGED	386.10	-
2	REAR FENDER @\$1476.20	DENTED	2,952.40	2,395.60
2	REAR FENDER UPPER INNER TRIM @\$476.50	NO SUCH PARTS	953.00	-
2	REAR FENDER LOWER INNER TRIM @\$756.10	BENT	1,512.20	1,197.80
2	REAR FENDER AIR VENTS @\$138.40	O/S BENT	276.80	110.20
2	REAR FENDER QUARTER GLASS MOULDING @\$173.50	NECESSARY	347.00	347.00
1	REAR DOOR LOCK LH	JAMMED	543.60	476.20
1	EXHAUST PIPE	BENT	869.80	730.07
2	EXHAUST PIPE MOUNTING @\$120.00	NOT DAMAGED	240.00	-
	LESS 25% DISCOUNT		-12,113.43	-7,788.86
			36,340.27	23,366.56
	<u>SPECIAL NETT ITEMS</u>			
1	SUNDRIES (SN)	NOT NECESSARY	80.00	-
1	BONNET INSULATOR CLIPS (SN)	NECESSARY	50.00	30.00
1	BONNET SEALANT (SN)	NECESSARY	100.00	30.00
1	RADIATOR COOLANT (SN)	NECESSARY	80.00	40.00
1	A/C COMPRESSOR FLUID (SN)	NECESSARY	80.00	80.00
1	FRONT NO PLATE WITH COVER (SN)	BENT	80.00	50.00
1	FRONT SUPPORT PANEL SEALANT (SN)	NECESSARY	80.00	30.00
1	FRONT SUPPORT PANEL TOP GARNISH CLIPS (SN)	NECESSARY	50.00	30.00
1	FRONT BUMPER GRILLE CLIPS (SN)	NECESSARY	50.00	30.00
1	FRONT BUMPER CENTRE GRILLE CLIPS (SN)	NECESSARY	50.00	30.00
1	FRONT BUMPER LOWER GRILLE CLIPS (SN)	NECESSARY	50.00	30.00
1	FRONT FENDER QUARTER GARNISH (SN)	NOT NECESSARY	50.00	-
1	FRONT FENDER INNER COWLING CLIPS LH (SN)	NECESSARY	50.00	30.00
1	ENGINE LOWER CAVEER (SN)	NECESSARY	50.00	30.00
4	REAR BUMPER REVERSE SENSOR @\$200.00 (SN)	NECESSARY	800.00	200.00
1	REAR END PANEL TOP GARNISH CLIPS (SN)	NECESSARY	50.00	30.00
1	TAILGATE SEALANT (SN)	NECESSARY	80.00	40.00

Report Ref No. CS/INC20000443/Bsd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TAILGATE OUTER MOULDING CLIPS (SN)	NECESSARY	50.00	30.00
1	TAILGATE LOWER OUTER MOULDING CLIPS (SN)	NECESSARY	50.00	30.00
1	TAILGATE INNER TRIM CLIPS (SN)	NECESSARY	50.00	30.00
1	TAILGATE WINDSCREEN SEAL (SN)	NECESSARY	60.00	40.00
1	TAILGATE WINDSCREEN SEALANT (SN)	NECESSARY	80.00	50.00
1	REAR NO PLATE WITH COVER (SN)	NECESSARY	80.00	50.00
1	REVERSE CAMERA (SN)	NECESSARY	380.00	300.00
2	TAILLAMP CLIPS @\$50.00 (SN)	NECESSARY	100.00	60.00
2	TAILLAMP SEALANT @\$100.00 (SN)	NOT NECESSARY	200.00	-
2	TAILLAMP BASE PANEL SEALANT @\$80.00 (SN)	NECESSARY	160.00	60.00
2	REAR FENDER INNER TRIM CLIPS @\$50.00 (SN)	NECESSARY	100.00	30.00
2	REAR FENDER QUARTER GLASS SEALANT @\$80.00 (SN)	NECESSARY	160.00	80.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	100.00	40.00
1	SPARE TYRE PANEL SEALANT (SN)	NECESSARY	100.00	40.00
1	SPARE TYRE PANEL INSULATOR PAD (SN)	NECESSARY	280.00	180.00
2	REAR FENDER SEALANT @\$80.00 (SN)	NECESSARY	160.00	60.00
1	WINDSCREEN PRIMER AND CLEANER (SN)	NOT NECESSARY	80.00	-
			4,020.00	1,790.00
	LABOUR			
	R&R REAR WINDSCREEN.		150.00	120.00
	R&R TAILGATE COMPONENT.		100.00	80.00
	R&R REAR FENDER COMPONENT.	NOT NECESSARY	200.00	-
	R&R FRONT FENDER COMPONENT.	NOT NECESSARY	200.00	-
	R&R REAR FENDER QUARTER GLASS.	NOT NECESSARY	150.00	-
	R&R REAR DOOR COMPONENT.		150.00	80.00
	R&R FUEL FILLER HOSE.	NOT NECESSARY	100.00	-
	R&R SPARE TYRE PANEL COMPONENT.		180.00	60.00
	R&R REVERSE SENSOR WITH RESPRASY.		200.00	60.00
	R&R EXHAUST PIPE.	NOT NECESSARY	180.00	-
	R&R A/C CONDENSER.		150.00	70.00
	R&R RADIATOR.		150.00	70.00
	UPHOLSTERY.		200.00	80.00
	CHECK WIRING.		150.00	80.00

Report Ref No. CS/INC20000443/Bsd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PANEL BEAT FRONT PORTION.	NOT NECESSARY	1,800.00	1,000.00
	PANEL BEAT REAR PORTION.		2,000.00	1,200.00
	CONDUCT WATER LEAKAGE TEST.		100.00	-
	DIAGNOTIC & RESET FAULT CODE.		200.00	80.00
	RUST PROOFING.		200.00	80.00
	SPRAY PAINTING FRONT PORTION.		1,600.00	1,000.00
	SPRAYING PAINTING REAR PORTION.		2,000.00	1,200.00
			10,160.00	5,260.00
GRAND TOTAL			50,520.27	30,416.56
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				16,000.00

Report Ref No. CS/INC20000443/Bsd3e2

LIM TEOW GUAN

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.