

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

MR. TAY TZE KIAN, EUGENE

BLK 475C UPPER SERANGOON CRESCENT

#11-555

SINGAPORE 533475

Contact : 92712624

TP FWD
Xiao Tang

ESTIMATE

Repair Code : CLM14823

Date in : 06/01/2020

Vehicle Num. : SGM895H

Model : HONDA CROSSROAD 1.8LX A

Chassis/Eng# : RT11008502/R18A3011544

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
AIRCON CONDENSER Warpped	1	866.80	✓ 866.80
FRONT BONNET Dented	1	785.00	✓ 785.00
FRONT BONNET GUIDE RUBBER STOPPER L/R Not m	4	6.00	X 24.00
FRONT BONNET MECHANISM LOCK Not m	1	75.00	X 75.00
FRONT BONNET RUBBER SEAL L/R Not m	2	35.00	X 70.00
FRONT BUMPER Dented	1	1108.60	✓ 1,108.60
FRONT BUMPER FOGLAMP COVER L/R Not m	2	65.10	X 130.20
FRONT BUMPER REINFORCEMENT Not m	1	330.00	X 330.00
FRONT BUMPER SIDE GARNISH L/R Dented	2	283.50	✓ 567.00
FRONT BUMPER SIDE RETAINER L/R Not m	2	30.50	✓ 61.00
FRONT GRILLE Cracked	1	295.00	✓ 295.00
FRONT GRILLE 'LOGO' EMBLEM Not m	1	25.40	✓ 25.40
FRONT GRILLE GARNISH Not m	1	245.00	X 245.00
FRONT HEADLAMP L/R Cracked	2	910.00	✓ 1,820.00
FRONT HEADLAMP LOWER BRACKET L/R Cracked	2	60.00	✓ 120.00
FRONT SUPPORT PANEL Bunkled	1	634.00	✓ 634.00
FRONT SUPPORT PANEL TOP COVER Not m	1	96.50	X 96.50
RADIATOR ASSY (AUTO) Not m	1	1670.70	X 1,670.70

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

MR. TAY TZE KIAN, EUGENE
BLK 475C UPPER SERANGOON CRESCENT
#11-555
SINGAPORE 533475

Contact : 92712624

ESTIMATE

Repair Code : CLM14823

Date in : 06/01/2020

Vehicle Num. : SGM895H

Model : HONDA CROSSROAD 1.8LX A

Chassis/Eng# : RT11008502/R18A3011544

REAR BUMPER <i>Deformed.</i>	1	950.00	✓	950.00
REAR BUMPER BEAM <i>Bent</i>	1	80.00	✓	80.00
REAR BUMPER BRACKET L/R <i>New</i>	2	47.50	x	95.00
REAR BUMPER CORNER BRACKET L/R <i>New</i>	2	28.00	x	56.00
REAR BUMPER REFLECTOR L/R <i>Hit cracked</i>	2	55.90	55.90	111.80
REAR BUMPER SIDE GARNISH L/R <i>LH Deformed</i>	2	180.00	180	360.00
REAR BUMPER SIDE RETAINER L/R <i>New</i>	2	27.50	✓	55.00
REAR BUMPER TOW HOOK COVER <i>Misshy</i>	1	22.50	✓	22.50
REAR END PANEL <i>Dented.</i>	1	540.00	✓	540.00
REAR END PANEL INNER TOP GARNISH <i>Deformed</i>	1	250.00	✓	250.00
REAR EXHAUST ALUMINIUM HEAT SHIELD <i>Crumpled.</i>	1	105.00	✓	105.00
REAR EXHAUST GASKET <i>New</i>	1	31.60	✓	31.60
REAR EXHAUST RUBBER MOUNTING <i>New</i>	2	15.50	x	31.00
REAR EXHAUST SILENCER BOX <i>Bent</i>	1	990.00	✓	990.00
REAR LH FENDER INNER TRIM GARNISH <i>Deformed</i>	1	285.00	✓	285.00
REAR TAILGATE <i>Dented</i>	1	1247.00	✓	1,247.00
REAR TAILGATE 'CROSSROAD' EMBLEM	1	58.00	✓	58.00
REAR TAILGATE 'H' LOGO EMBLEM <i>New</i>	1	35.50	✓	35.50

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

MR. TAY TZE KIAN, EUGENE
BLK 475C UPPER SERANGOON CRESCENT
#11-555
SINGAPORE 533475

Contact : 92712624

ESTIMATE

Repair Code : CLM14823

Date in : 06/01/2020

Vehicle Num. : SGM895H

Model : HONDA CROSSROAD 1.8LX A

Chassis/Eng# : RT11008502/R18A3011544

REAR TAILGATE INNER PULL HANDLE GARNISH	Not nec	1	28.00	X	28.00
REAR TAILGATE INNER TRIM GARNISH	Not nec	1	285.00	X	285.00
REAR TAILGATE MECHANISM LOCK	Done	1	225.00	✓	225.00
REAR TAILGATE OUTER PROTECTOR GARNISH	Del'd	1	535.00	✓	535.00
REAR TAILGATE RUBBER GUIDE STOPPER L/R	Not nec	2	8.00	X	16.00
REAR TAILGATE WEATHER STRIP	ut	1	185.00	✓	185.00
REAR TAILGATE WINDSCREEN GLASS MOULDING	Not nec	1	80.00	✓	80.00
REAR TAILLAMP L/R	LH cracked	2	475.00	420	950.00

Subtotal before discount

16,531.60

Percentage discount 20%

3,306.32

Sub-total 1

13,225.28

FRONT BONNET INSULATOR MAT CLIPS - SET	Not nec	1	50.00	X	50.00
FRONT BUMPER CLIPS - SET	2 nec	1	50.00	30	50.00
FRONT GRILLE CLIPS - SET	2 nec	1	30.00	20	30.00
FRONT NUMBER PLATE	2 nec	1	25.00	X	25.00
FRONT NUMBER PLATE HOLDER	2 nec	1	50.00	X	50.00
FRONT SUPPORT PANEL TOP COVER CLIPS - SET	Not nec	1	50.00	X	50.00
RADIATOR COOLANT	Not nec	1	60.00	40	60.00

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

MR. TAY TZE KIAN, EUGENE
BLK 475C UPPER SERANGOON CRESCENT
#11-555
SINGAPORE 533475

Contact : 92712624

ESTIMATE

Repair Code : CLM14823

Date in : 06/01/2020

Vehicle Num. : SGM895H

Model : HONDA CROSSROAD 1.8LX A

Chassis/Eng# : RT11008502/R18A3011544

REAR BUMPER CLIPS - SET <i>Nu</i>	1	50.00	<i>20</i> 50.00
REAR BUMPER REVERSE SENSOR - SET <i>Dangd</i>	1	250.00	<i>200</i> 250.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET <i>nu</i>	1	30.00	<i>10</i> 30.00
REAR LH FENDER INNER TRIM GARNISH CLIPS - SET <i>Nu</i>	1	50.00	<i>30</i> 50.00
REAR NUMBER PLATE <i>cancel</i>	1	25.00	<i>✓</i> 25.00
REAR NUMBER PLATE HOLDER <i>cancel</i>	1	50.00	<i>30</i> 50.00
REAR TAILGATE INNER TRIM GARNISH CLIPS - SET <i>He m</i>	1	50.00	<i>505</i> 50.00
REAR TAILGATE OUTER PROTECTOR GARNISH CLIPS - SET <i>nu</i>	1	50.00	<i>80</i> 50.00
REAR TAILGATE WINDSCREEN GLASS SEALANT <i>Nu</i>	1	80.00	<i>60</i> 80.00
REAR TAILLAMP CLIPS L/R - SET <i>Nu</i>	2	20.00	<i>10</i> 40.00
Subtotal before discount			990.00
Percentage discount 0%			0.00
Sub-total 2			990.00
Parts-total			14,215.28

LABOUR

To remove, change air con parts, vacuums, refill air con gas.

To remove, reinstall electrical wiring harness, check lighting, resetting headlamp focussing and rewire for parking sensor.

To remove, reinstall tailgate windscreen

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

120 ~~150.00~~

✓ 100.00

120 ~~150.00~~

60 ~~120.00~~

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

MR. TAY TZE KIAN, EUGENE
BLK 475C UPPER SERANGOON CRESCENT
#11-555
SINGAPORE 533475

Contact : 92712624

ESTIMATE

Repair Code : CLM14823

Date in : 06/01/2020

Vehicle Num. : SGM895H

Model : HONDA CROSSROAD 1.8LX A

Chassis/Eng# : RT11008502/R18A3011544

To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.

To re-spray painting on the front bonnet, front support panel, front fender (L/R) and front bumper.

To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

To remove, reinstall tailgate mechanism and check for function

~~1,400.00~~ 800

~~1,200.00~~ 800

~~150.00~~ 80

~~1,600.00~~ 1800

~~120.00~~ 60

~~80.00~~ ✓

3820

Labour Total

5,070.00

Parts & Labour Total

19,285.28

*** This is a computer-generated document which requires no signature.***

page 5

total 14414.04

L/S: 11SK

10 Days.

11SK

10 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: