

TO: Khanching

1 pc	Front bumper clips	nll	\$	48.00
1 set	o/s door stickers	nll	\$	100.00
1 set	Front o/s fender inner shield clips	xnn	\$	28.00
1 pc	Front n/s tyre 195 65R15 Maxxis	1xnn	\$	200.00
	Towing Fee		\$	50.00
	Sundry		\$	50.00
	To check wiring on headlamp		\$	80.00
	To dismantle and replace front o/s undercarriage		\$	250.00

Acknowledged by repairer:
 Signature: _____
 Date: _____

PP: \$4294.64 /
 4 repairs

To check for front o/s wheel alignment

\$ 80.00 \$60

To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.

\$ 180.00 xmr

To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same.

\$ 1,450.00 \$600

To putty and spray painting on front bumper, front o/s fender, o/s mirror, front o/s door, rear o/s door, o/s rocker panel, o/s front pillar

\$ 1,400.00 \$540
~~\$600~~

To apply rustproofing on the repaired and replaced panels.

\$ 120.00 \$80
\$ 10,451.36

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)
THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.

Ran (4411)
07/01/2020 1715hrs
PavaSuren@alacanto.com
886227118
Best paint
photo
#P/D
4411

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

10-Feb-20

SUPPLEMENTARY ESTIMATE REPAIR BILL FOR HYUNDAI IONIQ REGN NO: SHB 8686 M

1 pc	Front o/s rim <i>scr</i>	\$	1,091.50
1 pc	Front o/s fender <i>DD</i>	\$	490.70
		\$	1,582.20
	Less 20%	\$	316.44
		\$	1,265.76

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

**THE ABOVE ESTIMATED COST OF REPAIR DO NOT
INCLUDE ANY UNFORESEEN DAMAGES.**