

INS. CASE OWNER: CHAN KUN HING

CC 4/A/G 2000 0457 / H65391

LKK:
IDAC:

Surveyor:

Hock Ann

DOI:

6/1/2020

Date / Time:

6/1/2020

Registered in Merimen:

7/1/2020

Pre-assign / CCU / FTE

Insured Vehicle No. : SKU 1639KClaim No. : B35A 437A05 06Name of Insured : Fulco Leasing Pte Ltd

Policy No. :

Insured Tel No. : _____ HP: _____

Make / Model :

Excess Sec II : SS

D.O.A. : 1/1/2020

Place of Accident :

Is driver the owner?

(YES / NO)

Nature of Accident :

If NO, Driver Name / Age :

Driver Tel No. :

(V/L YES / NO)OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability : % Final ? Yes / No

SLP/ISSITINSRS:
WSP: SKS motor
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/ Time	STAGE	DATE / PIC
	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	<u>23/01/2020 - VIC</u>
	Documentation Check List: Handler Typist	
	Notification ltr (if non-pickup)	☐
	After call ltr to OI:	☒
	Authorisation To Act:	☒
	Release Voucher:	☒
	Final Repair Bill:	☒
	Car Rental Invoice:	☒
	Towing Invoice:	☐
	LTA / GIA :	☒
	Medical Bill:	☐
	PIR:	☐
	Mandate/Reject Instruction:	☒
	LOD	☒
	Payment Breakdown Form:	☐
	Post-Repair Photos:	☐
	Others:	☐
PRELIMINARY ADVICE Date/Time: _____ Sent By: _____		
FINALIZATION Date/Time: _____ Confirm with: _____ Confirm by: _____		
Repair Cost: <u>L19</u> S\$ 7,700.00 (8 days) Reduction: <u>50</u> % Email ☐ Call ☐		
FINAL SETTLEMENT Date/Time: <u>24/02/2020</u> Confirm with: <u>LOBUS</u> Email ☒ Call ☐		
Final Liability: % <u>100</u> (Agreed / Assessed) BOLA S/N No. : <u>27</u>		
Repair Cost: <u>(w/600)</u> S\$ 8,239.00		
Loss of Rental (LOR): S\$ 1,980.00 (11 days) x \$180.00		
Loss of Use (LOU): S\$ — (\$ x days)		
Loss of Income (LOI): S\$ — (\$ x days)		
LOR only ☒ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]		
GIA/LTA Search S\$ 7.45		
Medical: S\$ —		
Disbursement: S\$ — (e.g. Tow/ Independent)		
Legal Cost S\$ —		
Total: S\$ 10,226.45 Global Sum S\$: —		
FINAL PAYMENT Date/Time: _____ Confirm with: _____ Email ☐ Call ☐		
Payee 1: S\$ 10,226.45 Name 1: <u>SKS MOTOR WORKS PTE LTD</u>		
Payee 2: (Strike if N.A.) S\$ — Name 2: —		
Payee 3: (Strike if N.A.) S\$ — Name 3: —		

COPY SENT
24/2/20201) Claim status: Normal / Reject / Private Settle
2) Report Format:
3) Survey fee: 4320.00

File No: H-ANW 1 AIG 614 / MW Emen ✓

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SLP 1551 T
at Workshop n/s: JRS motor
of: 8/1/2011 Subst 4 #03-95
Insured: _____
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Est. or Market Value: _____
IDAC Accident Report: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 8 days Res.: Yes or No
Turn Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLP 1551 T Yr Regn: 26/06/2011
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or

Make: Mercedes Benz S500 Lec 2917
Colour: Black A/C: Insured / Std / NI / NA
Sp. Reading: 227170k T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: WDD2211542A195305

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/40/22

R: 245/40/22

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: 5 mm sumitomo Rear: 5 mm sumitomo
L/Bal: 5 mm L/Bal: 5 mm
D.O.A: 11/1/20 D.O.I: 6/1/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>* SLP 1551 T</u>
	<u>L/B \$ 7,700.00</u>
	<u>(R/OB: \$ 7,840.50 / 50%)</u>
	<u>600 down</u>
	<u>Hu Bann</u>
	<u>MV - 80000</u>
	<u>PV - 38846</u>
	<u>NV - 41000</u>
	<u>1st R → 88119996</u>

Date/Time: File Pass to? ☐ : Prelim. Report

to ☐ : Final Report

Date/Time: File Return to?

to

Request Forbid:

Request Forbid:

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Insp (\$

☐ : Wheel align (\$

Survey Fee:

Transportation:

\$ - PS - \$

Pinch

Clamp

Pinch



JKS MOTOR WORKS PTE LTD

8 KAKI BUKIT AVENUE 4, #03-46, Premier @ Kaki Bukit, Singapore, 415875
Company Reg and GST No. : 201407714K
TEL: 67026828 FAX: 6702 6829
EMAIL: accidentclaims@jksmotorworks.com.sg

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To resurvey damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: JKSQUOTE121

Date: 3-Jan-20

Motor Claims Department

AIG Singapore

78, #07-16 Shenton Way, AIG Building, Singapore 079120

REF NO :

VEH NO : SKU1639K @ SIMON ROAD
ON 1 JANUARY 2020 @ 6:15 AM

QUOTE NO.

DATE :

VEHICLE NO : SLP1551T
MAKE/MODEL : MERCEDES BENZ S300L
CHASSIS : WDD2211542A145305
ENGINE NO : 27294630641938
REG. DATE : 26-Jun-07
CAPACITY :
MILEAGE :

ESTIMATE FOR : SLP1551T MERCEDES BENZ S300L

Description	Qty	UOM	Repairer's Estimate	Revised Amount (Less 10%)
SPARE PARTS				
1 REAR TAIL LAMPS ✓ 1/4 CR4 R/HX(SVC) 2	2	PCS	1,000.00 545	900.00
2 REAR TAIL LAMPS SIDE GARNISH X(SVC)	2	PCS	340.00 ✓	306.00
3 REAR END PANEL ✓ BT	1	PC	1,400.00 745	1,260.00
4 REAR END PANEL INNER GARNISH ✓ CR4	1	PC	100.00 ✓	90.00
5 REAR BUMPER ✓ cut	1	PC	1,500.00 1300	1,350.00
6 REAR BUMPER CLIP ✓ acc	1	SET	40.00 ✓	36.00
7 REAR BUMPER RETAINER LH & RH ✓ CR4	2	PCS	180.00 160 ✓	162.00
8 REAR BUMPER BRACKET LH & RH ✓ CR4 2	2	PCS	120.00 ✓	108.00
9 REAR BUMPER REINFORCEMENT ✓ BT	1	PC	800.00 650	720.00
10 REAR BUMPER TOW COVER X(SVC)	1	PC	85.00	76.50
11 REAR BUMPER PDC SENSORS ✓ short 4 pins	4	PCS	1,000.00 680	900.00
12 REAR BUMPER SENSOR WIRE HARNESS X(SVC)	1	SET	250.00	225.00
13 REAR BUMPER BRACKET SUPPORT LH & RH ✓ CR4 2	2	PCS	320.00 180	288.00
14 REAR BOOT ✓ BT	1	PC	2,600.00 2042	2,340.00
15 REAR BOOT CHROME X(SVC)	1	PC	150.00	135.00
16 REAR BOOT CENTER 'LOGO' ✓	1	PC	50.00 ✓	45.00
17 REAR BOOT EMBLEM 'S350' ✓ } acc	1	PC	45.00 ✓	40.50
18 REAR BOOT EMBLEM 'MERCEDES' ✓	1	PC	55.00 ✓	49.50
19 REAR BOOT EMBLEM '7G TRONIC' ✓	1	PC	50.00 ✓	45.00
20 REAR BOOT LOCK ✓ 1m	1	PC	380.00 280	342.00
21 REAR TRUNK SIDE TRIM BRACKET X(SVC)	6	PCS	180.00	162.00
22 REAR BOOT LID RUBBER ✓ CR4	1	PC	120.00 ✓	108.00
23 REAR BOOT HANDLE X(SVC)	1	PC	100.00	90.00
24 REAR BOOT HANDLE BUTTOM X(SVC)	1	PC	90.00	81.00

25	REAR BOOT HANDLE LOWER	X (suc)	1	PC	80.00	72.00
26	REAR SPARE TYRE BOARD / PANEL	✓ cut	1	PC	1,200.00 950	1,080.00
27	REAR SPARE TYRE COMPARTMENT SEALANT	X (suc)	1	PC	80.00	72.00
28	REAR SPARE TYRE UNDERCOVER	✓ 4RA	1	PC	450.00 350	405.00

NETT PRICE						
29	REVERSE CAMERA	X (suc)	1	SET	350.00	350.00
30	NUMBER PLATE WITH HOLDER	X (suc)	1	SET	50.00	50.00

LABOUR						
31	LABOUR CHARGE TO REPAIR & REBUILD INCLUDING CUT & WELD WHERE NECESSARY; REMOVE & REPACE REAR DAMAGE PARTS AS LISTED ABOVE	✓	1	SRV	1,400.00	1,400.00 1100
32	TO SPRAY PAINT ON REAR PORTION AFFECTED AREAS	✓	1	SRV	1,600.00	1,600.00 800
33	TO REMOVE AND INSTALL REAR COMPARTMENT ATTACHMENTS & FITTINGS TO ENABLE REPAIRS	X	1	SRV	250.00	250.00
34	TO CHECK ALL WIRINGS AND LIGHTS FUNCTION AND FOCUS	✓	1	SRV	100.00	100.00 30
35	TO INSTALL REAR SENSORS & REVERSE CAMERA	✓	1	SRV	160.00	160.00 40
36	TO APPLY ANTI RUST PROOFING ON AFFECTED AREAS	- photo	1	SRV	120.00	120.00 40
37	TO DIAGNOSE & ERASE FAULT CODES AFTER REPAIR	✓	1	SRV	120.00	120.00 100

L/s repair
with paint
respray after paint

8:00 Day 4:25pm
6/1/20
Hock ANN
85311883 / 67418434
Hock ANN@Hock Ann
need to check 7 (100)

Respray sub
H. ANN
6/1/20
12:00pm

	15,548.50
Paints	8382
Paints less	10%
	7543.80
Labour	2110
	9563.80
L/s less	22%
	7723.04
	↓
	\$ 7700



JKS MOTOR WORKS PTE LTD

8 KAKI BUKIT AVENUE 4, #03-46, Premier @ Kaki Bukit, Singapore, 415875

Company Reg and GST No. : 201407714K

TEL: 67026828 FAX: 6702 6829

EMAIL: accidentclaims@jksmotorworks.com.sg

Motor Claims Department

AIG Singapore

78, #07-16 Shenton Way, AIG Building, Singapore 079120

REF NO :

VEH NO : SKU1639K @ SIMON ROAD
ON 1 JANUARY 2020 @ 6:15 AM

QUOTE NO. : JKSQUOTE121

DATE : 3-Jan-20

VEHICLE NO : SLP1551T

MAKE/MODEL : MERCEDES BENZ S300L

CHASSIS : WDD2211542A145305

ENGINE NO : 27294630641938

REG. DATE : 26-Jun-07

CAPACITY :

MILEAGE :

ESTIMATE FOR : SLP1551T MERCEDES BENZ S300L

Description	Qty	UOM	Repairer's Estimate	Revised Amount (Less 10%)
SPARE PARTS				
1 REAR TAIL LAMPS ?	2	PCS	1,000.00	900.00
2 REAR TAIL LAMPS SIDE GARNISH ?	2	PCS	340.00	306.00
3 REAR END PANEL ?	1	PC	1,400.00	1,260.00
4 REAR END PANEL INNER GARNISH ✓ call	1	PC	0.00	0.00
5 REAR BUMPER ✓ cut	1	PC	1,500.00	1,350.00
6 REAR BUMPER CLIP ✓ all	1	SET	40.00	36.00
7 REAR BUMPER RETAINER LH & RH ✓ call	2	PCS	180.00	162.00
8 REAR BUMPER BRACKET LH & RH ?	2	PCS	120.00	108.00
9 REAR BUMPER REINFORCEMENT ?	1	PC	800.00	720.00
10 REAR BUMPER TOW COVER X (svc)	1	PC	85.00	76.50
11 REAR BUMPER PDC SENSORS ✓ short 47ps	4	PCS	1,000.00	900.00
12 REAR BUMPER SENSOR WIRE HARNESS X (svc)	1	SET	250.00	225.00
13 REAR BUMPER BRACKET SUPPORT LH & RH ?	2	PCS	320.00	288.00
14 REAR BOOT ✓ st	1	PC	2,600.00	2,340.00
15 REAR BOOT CHROME X (svc)	1	PC	150.00	135.00
16 REAR BOOT CENTER 'LOGO' ✓	1	PC	50.00	45.00
17 REAR BOOT EMBLEM 'S350' ✓ } all	1	PC	45.00	40.50
18 REAR BOOT EMBLEM 'MERCEDES' ✓	1	PC	55.00	49.50
19 REAR BOOT EMBLEM '7G TRONIC' ✓	1	PC	50.00	45.00
20 REAR BOOT LOCK ✓ JM	1	PC	380.00	342.00
21 REAR TRUNK SIDE TRIM BRACKET X (svc)	6	PCS	180.00	162.00
22 REAR BOOT LID RUBBER	1	PC	120.00	108.00
23 REAR BOOT HANDLE X (svc)	1	PC	100.00	90.00
24 REAR BOOT HANDLE BOTTOM X (svc)	1	PC	90.00	81.00

25	REAR BOOT HANDLE LOWER	X (suc)	1	PC	80.00	72.00
26	REAR SPARE TYRE BOARD / PANEL	X (R)	1	PC	1,200.00	1,080.00
27	REAR SPARE TYRE COMPARTMENT SEALANT	X (suc)	1	PC	80.00	72.00
28	REAR SPARE TYRE UNDERCOVER	X (suc)	1	PC	450.00	405.00

NETT PRICE

29	REVERSE CAMERA	X (suc)	1	SET	350.00	350.00
30	NUMBER PLATE WITH HOLDER	X (suc)	1	SET	50.00	50.00

LABOUR

31	LABOUR CHARGE TO REPAIR & REBUILD INCLUDING CUT & WELD WHERE NECESSARY; REMOVE & REPACE REAR DAMAGE PARTS AS LISTED ABOVE		1	SRV	1,400.00	1,400.00
32	TO SPRAY PAINT ON REAR PORTION AFFECTED AREAS		1	SRV	1,600.00	1,600.00
33	TO REMOVE AND INSTALL REAR COMPARTMENT ATTACHMENTS & FITTINGS TO ENABLE REPAIRS	X	1	SRV	250.00	250.00
34	TO CHECK ALL WIRINGS AND LIGHTS FUNCTION AND FOCUS	✓	1	SRV	100.00	100.00 30
35	TO INSTALL REAR SENSORS & REVERSE CAMERA	✓	1	SRV	160.00	160.00 40
36	TO APPLY ANTI RUST PROOFING ON AFFECTED AREAS	photo	1	SRV	120.00	120.00 30?
37	TO DIAGNOSE & ERASE FAULT CODES AFTER REPAIR	✓	1	SRV	120.00	120.00 60

15,548.50

L/s report
without production
Resurvey after paint

6/1/20 4.25pm
Hoch ANN
85311883 / 67418434
Hoch ANN@lklAuto.com
need to check 7 (mv)

LK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Hock Ann (LKK Auto)

From: Hock Ann (LKK Auto)
Sent: Thursday, 23 January, 2020 8:56 AM
To: JKS Admin
Cc: Vic (LKKAuto)
Subject: RE: FINALIZED SLP 1551T

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear ms leslie ,

Good day, o.k will be process base on finalized total amount COR \$ 7700 L/sump REPAIR and DOR 8 days close.

Noted : All finalized document > LOA ,LOD,DV,LTA need send direct to lkk claim dept person incharge handler vic (vicalpeh@lkkauto.com)

Thanks.

Best Regards,
Hock Ann | Assistant Automotive Assessor
LKK Auto Consultants
Phone: 6741 3061 | Email: HockAnn@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: JKS Admin [mailto:admin@jksmotorworks.com.sg]
Sent: Wednesday, 22 January, 2020 5:57 PM
To: Hock Ann (LKK Auto)
Cc: Vic (LKKAuto)
Subject: Re: FINALIZED SLP 1551T

Without Prejudice

Dear Hock Ann,

Thank you for your email.

We confirm to accept the your COR offer.

We will email the LOD for final offer.

Thanks.

Leslie

88119996

On Wed, Jan 22, 2020 at 4:32 PM Hock Ann (LKK Auto) <HockAnn@lkkauto.com> wrote:

'WITHOUT PREJUDICE'

SAVE AS TO COSTS

Dear leslie ,

Good day , Kindly attached refer SLP 1551T MERCEDES BENZ S300L finalized updated calculate adjustment on 22.1.2020

COR - \$ 7700

DOR – 8 DAYS

Please refer adjustment updated total L/SUMP amount \$ 7700 if agree total L/SUMP amount and repair days, will be to close case.

Please update soon asap.

Thanks.

Best Regards,

Hock Ann | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6741 3061 | Email: HockAnn@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Best Regards,

JKS Motor Works Pte Ltd
8811-9996

8 Kaki Bukit Ave 4
Premier @ Kaki Bukit
#03-45 Singapore 415875

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	513C
Vehicle Details	
Vehicle No.:	SLP1551T
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Jan 2020
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	S300L
Primary Colour:	Silver
Manufacturing Year:	2007
Engine No.:	27294630641938
Chassis No.:	WDD2211542A145305
Maximum Power Output:	170.0 kW (227 bhp)
Open Market Value:	\$81,510.00
Original Registration Date:	26 Jun 2007
First Registration Date:	26 Jun 2007
Transfer Count:	3
Actual ARF Paid:	\$89,661.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 May 2027
COE Category:	E - Open Category
COE Period(Years):	10
PQP Paid:	\$52,491.00
COE Rebate Amount:	\$38,846.00
Total Rebate Amount:	\$38,846.00

The information contained herein is correct as at 06 Jan 2020

OK

Best Car Repair Workshops in Singapore

Browse more than 3,000 car workshops in Singapore.

You can read customers' reviews & ratings on their services too.

Mercedes s300 Price Range Depreciation Year Reg Vehicle Type

Home » Used Cars » Auto Empire Pte Ltd » Mercedes-Benz S-Class S300L (COE till 11/2027)

Mercedes-Benz S-Class S300L (COE till 11/2027)

Overview Financial Insurance Accessories Similar Research Photos Map

Price	\$98,500	Reg Date	13-Nov-2007 (7yrs 10mths 6days COE left)
Depreciation	\$12,540 /yr	Manufactured	2007
Mileage	140,000 km (11.5k /yr)	Transmission	Auto
Road Tax	\$3,097 /yr	OMV	\$83,187
Dereg Value	\$39,406 as of today (change)	ARF	\$91,506
COE	\$50,168	Power	170.0 kW (227 bhp)
Engine Cap	2,997 cc	No. of Owners	1
Curb Weight	1,850 kg		
Type of Vehicle	Luxury Sedan		

Features

Powerful 3.0L V6 Engine Producing 227Bhp, 7G-Tronic Auto Transmission, Sunroof, Rear Aircon, Keyless Entry/Start, Suction Doors, Paddle Shifters. View specs of the Mercedes-Benz S-Class (2007-2013)

Accessories

Factory Fitted Audio System, Bluetooth, Reverse Camera, Auto Climate Aircon, Electric Roller Blind, Sunroof, Rain Sensors.

Description

New Road Tax.Sunroof Model.1 Owner, Low Mileage Done,Comes With Warranty And 1 Year Servicing Package, Beautiful Condition, Family Car Space, Great Value For Short Term Drive. 90% Loan Of The Car Price Available. Call Now For Viewing 24/7 For Viewing.

Category

COE Car

Status

Available

Resources



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



Car Valuation - Free

Find out the market value of your existing car for free. Get started



Shortlist

Compare

Add to

Report Error

More Actions

Seller Information

Auto Empire Pte Ltd

20 vehicles for sale. 21 sold in past 3 mths

61 Ubi Road 1 #02-29

Oxley Bizhub

Tel: 69700168

Search cars nearby

Bebe Leong

88769680

Elle

93590919

George

93837397

Nivitha (LKK Auto)

From: AIG SGP, Claims-Survey <AIGSGP_ClaimsSurvey@aig.com>
Sent: Monday, 6 January 2020 2:21 PM
To: Admin A; assignments
Cc: Fong, Andy-SY
Subject: Aigencypt Accident involving SLP1551T and your vehicle SKU1639K on 2 January 2020
Attachments: SLP1551T MERCEDES S300L.pdf

Hi LKK,

Kindly assist to survey.

Winnie Fan
AIG
Claims Service Associate
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

winnie-lw.fan@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

P. Leslie

T: 6.1.20 3.24p.m

V: 14

E. ✓

From: JKS Accident Claims <accidentclaims@jksmotorworks.com.sg>
Sent: Thursday, January 2, 2020 5:45 PM
To: AIG SGP, Claims-Survey <AIGSGP_ClaimsSurvey@aig.com>
Cc: Lee, Ming-Yao <MingYao.Lee@aig.com>
Subject: [EXTERNAL] Accident involving SLP1551T and your vehicle SKU1639K on 2 January 2020

This message is from an external sender; be cautious with links and attachments.

Without Prejudice

Dear Sir / Madam :

We have instructions from our client to seek repair cost and loss of car rental from you through Direct Settlement.

Attached is the GIA report for your consideration.

Please let us have your confirmation that you agree that the liability is clear and we may proceed with Direct Settlement.

The vehicle is already in the workshop at 8 Kaki Bukit Avenue 4, Premier @ Kaki Bukit 03-45 Singapore and ready for PRS.

Thank you.

Best Regards,

Leslie Enriquez
JKS Motor Works Pte Ltd
HP : 88119996

8 Kaki Bukit Avenue 4
Premier @ Kaki Bukit
#03-45, Singapore 415875

Disclaimer : Confidential Information may be contained in this message. If you received this message in error please notify our office at 67026828 and delete it immediately. You should not disclose its contents to anyone and shall not retain the message at all.

Vic (LKKAuto)

From: JKS Admin <admin@jksmotorworks.com.sg>
Sent: Thursday, 27 February, 2020 10:50 AM
To: Vic (LKKAuto)
Cc: Admin A
Subject: Re: LOD of SLP1551T DOA : 1 JANUARY 2020 - LKK REF CC4/AIG20000457/Hhs3
Attachments: SIGNED DV SLP1551T.pdf

Without Prejudice

Dear Vic,

Thank you for your email.

Please see attached signed DV for your reference and perusal.

Thanks & Regards

Leslie Enriquez
JKS Motor Works Pte Ltd
8811-9996

8 Kaki Bukit Ave 4
Premier @ Kaki Bukit
#03-45 Singapore 415875

On Thu, Feb 27, 2020 at 9:53 AM Vic (LKKAuto) <vicalpeh@lkkauto.com> wrote:

Without Prejudice

Dear Leslie,

We refer further to our below email.

Purely for an amicable settlement on a without prejudice basis and without admission of any liability to our Insured's part, we have our principal's mandate and we offer below amount to settle your client's claim:

Cost of Repair (w/gst)	\$ 8,239.00
Loss of Rental (\$180 x 11 days)	\$ 1,980.00
LTA Search Fee	\$ <u>7.45</u>

TOTAL

\$ 10,226.45

If agreeable, kindly chop and sign the attached DV and forward back a copy to us for payment processing.

The above amount is to be made payable to **JKS MOTOR WORKS PTE LTD.**

Thank you.

"Please note that our above offer and any settlement arising from the above offer are made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our Insured Driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LKK

Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

Print Received Message

This mail is associated with :

***SLP1551T (8361437405SG)**

[SKU1639K]

TP

LEO ZHINENG

Jan 1 2020 6:00AM

[FULCO LEASING PTE LTD]

Jks Motorworks (accident Claims) Pte Ltd

From AIG Asia Pacific Insurance Pte, Ltd. (Express) (AIG_SG_EXPRESS), sent on 24/02/2020 15:28 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$10226.45) - SLP1551T - Claim Handler: Chan, Kian-Meng

Approved:10226.45:Kindly settle at best



JKS MOTOR WORKS PTE LTD

8 KAKI BUKIT AVENUE 4, #03-45, Premier @ Kaki Bukit, Singapore, 415875

Company Reg & GST No. : 201407714K

TEL: 67026828 FAX: 6702 6829

EMAIL: admin@jksmotorworks.com.sg

SATISFACTORY VOUCHER

This is to certify that I am satisfied with the repair and replacement carrier out by JKS Motor Works Pte Ltd, with Postal code at 8 Kaki Bukit Avenue 4, #03-45, Premier @ Kaki Bukit Singapore 415875 to my car with license plate number SLP1551T,
Make and Model MERCEDES S300L Which is involved in the accident on
1 JANUARY 2020 - 6:15 AM at
SIMON ROAD.

I do hereby discharge the company from all further liabilities in respect to this accident.

✓ 
Full Name and Signature

NRIC: SXXXX53C

DATE: 15 JANUARY 2020
7pm

Enquire Vehicle Transfer Fee

Vehicle Details

Vehicle No.
SMG3231P

Make / Model
AUDI / A4 2.0T FSI MU S-LINE CVT ABS D/AB HID

Vehicle Type :
R10 - Private Hire (Self-Drive) Motor Car

Vehicle Attachment 1 :
No Attachment

Vehicle Scheme :
Normal

Chassis No. :
WAUZZZ8H68K016180

Propellant :
Petrol

Engine No. :
BWE048095

Motor No. :
-

Engine Capacity :
1984 cc

Power Rating :
-

Maximum Power Output :
147.0 kW (197 bhp)

Maximum Laden Weight :

2110 kg

Unladen Weight :

1630 kg

Year Of Manufacture :

2008

Original Registration Date :

15 Jan 2009

Lifespan Expiry Date :

-

COE Category :

B - Car (1601cc & above)

PQP Paid :

\$31,335.00

COE Expiry Date :

14 Jan 2029

Road Tax Expiry Date :

14 Jul 2020

PARF Eligibility Expiry Date :

-

Inspection Due Date :

14 Jan 2021

Intended Transfer Date :

05 Feb 2020

CO2 Emission :

-

CEV/VES Rebate Utilised Amount :

-

CO Emission :

-

HC Emission :

-

NOx Emission :

-

PM Emission :

Fees To Be Paid For Transfer

Transfer Fees	\$25.00
---------------	---------

Print

OK →

Save as PDF

Copy as Text

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Jan 2020 Edit Reg		06 Jan 2020 00:00 Edit Adj Rpt	\$57,700.00 Edit Estimates	\$57,700.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: FULCO LEASING PTE LTD , Co. Reg. No.: NA, Tel: +6599999999									
Main Claimant: LEO ZHINENG									
Vehicle Reg. No.: SLP1551T		Date of Loss: 01/01/2020 06:00 - :59 [150 Months and 6 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 8361437405SG		Policy/Cover Note No.: 0999993931 (Comprehensive)							
Vehicle Reg. No. (Insured): SKU1639K		Policy No. (Claimant):							
		Excess:							
Repairer: JKS Motor Works Pte Ltd (HQ) 8 KAKI BUKIT ROAD 4, #03-45, PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel: 67026828									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 16/01/2020]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG_EXPRESS (24/02/2020): Alert - Adj Mandate Approved (\$510226.45) - SLP1551T - Claim Handler: Chan, Kian...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLP1551T (8361437405SG)
[SKU1639K]
TP
LEO ZHINENG
Jan 1 2020 6:00AM
[FULCO LEASING PTE LTD]
JKS Motor Works Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page			☒		
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print		
1	(Draft)		Third Party Express Settlement – Payment Breakdown															Edit		
Photos/Images															3 per page			☒		
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print		
1	08/01/20 09:48		Chassis Number															Load JPG ☒		
2	08/01/20 09:48		Odometer Reading															Load JPG ☒		
3	08/01/20 09:49		General View															Load JPG ☒		
4	08/01/20 09:49		General View															Load JPG ☒		
5	08/01/20 09:49		General View															Load JPG ☒		
6	08/01/20 09:49		General View															Load JPG ☒		
7	08/01/20 09:49		General View															Load JPG ☒		
8	08/01/20 09:49		General View															Load JPG ☒		
9	08/01/20 09:49		General View															Load JPG ☒		
10	08/01/20 09:49		General View															Load JPG ☒		
11	08/01/20 09:49		General View															Load JPG ☒		
12	08/01/20 09:49		General View															Load JPG ☒		
13	08/01/20 09:49		General View															Load JPG ☒		
14	08/01/20 09:49		General View															Load JPG ☒		
15	08/01/20 09:49		General View															Load JPG ☒		
16	08/01/20 09:49		General View															Load JPG ☒		
17	08/01/20 09:49		General View															Load JPG ☒		
18	08/01/20 09:49		General View															Load JPG ☒		
19	08/01/20 09:49		General View															Load JPG ☒		
20	08/01/20 09:49		General View															Load JPG ☒		
21	08/01/20 09:49		General View															Load JPG ☒		
22	08/01/20 09:49		General View															Load JPG ☒		
23	08/01/20 09:49		General View															Load JPG ☒		
24	08/01/20 09:49		General View															Load JPG ☒		
25	08/01/20 09:49		General View															Load JPG ☒		
26	08/01/20 09:49		General View															Load JPG ☒		
27	08/01/20 09:49		General View															Load JPG ☒		
28	08/01/20 09:49		General View															Load JPG ☒		
29	08/01/20 09:49		General View															Load JPG ☒		
30	08/01/20 09:49		General View															Load JPG ☒		
31	08/01/20 09:49		General View															Load JPG ☒		
32	08/01/20 09:49		General View															Load JPG ☒		
33	08/01/20 09:49		General View															Load JPG ☒		
34	08/01/20 09:49		General View															Load JPG ☒		
35	08/01/20 09:49		General View															Load JPG ☒		
36	08/01/20 09:49		General View															Load JPG ☒		
37	08/01/20 09:49		General View															Load JPG ☒		
38	08/01/20 09:49		General View															Load JPG ☒		
39	08/01/20 09:49		General View															Load JPG ☒		
40	08/01/20 09:49		General View															Load JPG ☒		

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
					☒
41	08/01/20 09:49	General View		Load JPG	☒
42	08/01/20 09:49	General View		Load JPG	☒
43	08/01/20 09:49	General View		Load JPG	☒
44	08/01/20 09:49	General View		Load JPG	☒
45	08/01/20 09:49	General View		Load JPG	☒
46	08/01/20 09:49	General View		Load JPG	☒
47	08/01/20 09:49	General View		Load JPG	☒
48	08/01/20 09:49	General View		Load JPG	☒
49	08/01/20 09:49	General View		Load JPG	☒
50	08/01/20 09:49	General View		Load JPG	☒
51	08/01/20 09:49	General View		Load JPG	☒
52	08/01/20 09:49	General View		Load JPG	☒
53	08/01/20 09:49	General View		Load JPG	☒
54	08/01/20 09:49	General View		Load JPG	☒
55	08/01/20 09:49	General View		Load JPG	☒
56	09/01/20 11:20	Reinspection Photo		Load JPG	☒
57	09/01/20 11:20	Reinspection Photo		Load JPG	☒
58	09/01/20 11:20	Reinspection Photo		Load JPG	☒
59	09/01/20 11:20	Reinspection Photo		Load JPG	☒
60	09/01/20 11:20	Reinspection Photo		Load JPG	☒
61	09/01/20 11:20	Reinspection Photo		Load JPG	☒
62	09/01/20 11:20	Reinspection Photo		Load JPG	☒
63	09/01/20 11:20	Reinspection Photo		Load JPG	☒
64	09/01/20 11:20	Reinspection Photo		Load JPG	☒
65	09/01/20 11:20	Reinspection Photo		Load JPG	☒
66	09/01/20 11:20	Reinspection Photo		Load JPG	☒
67	09/01/20 11:20	Reinspection Photo		Load JPG	☒
68	09/01/20 11:20	Reinspection Photo		Load JPG	☒
69	09/01/20 11:20	Reinspection Photo		Load JPG	☒
70	09/01/20 11:20	Reinspection Photo		Load JPG	☒
71	09/01/20 11:20	Reinspection Photo		Load JPG	☒
72	09/01/20 11:20	Reinspection Photo		Load JPG	☒
73	09/01/20 11:20	Reinspection Photo		Load JPG	☒
74	09/01/20 11:20	Reinspection Photo		Load JPG	☒
75	09/01/20 11:20	Reinspection Photo		Load JPG	☒
76	09/01/20 11:20	Reinspection Photo		Load JPG	☒
77	09/01/20 11:20	Reinspection Photo		Load JPG	☒
78	09/01/20 11:20	Reinspection Photo		Load JPG	☒
79	09/01/20 11:20	Reinspection Photo		Load JPG	☒
80	09/01/20 11:20	Reinspection Photo		Load JPG	☒
81	09/01/20 11:20	Reinspection Photo		Load JPG	☒
82	09/01/20 11:20	Reinspection Photo		Load JPG	☒
83	09/01/20 11:20	Reinspection Photo		Load JPG	☒
84	09/01/20 11:20	Reinspection Photo		Load JPG	☒
85	09/01/20 11:20	Reinspection Photo		Load JPG	☒
86	09/01/20 11:21	Reinspection Photo		Load JPG	☒
87	09/01/20 11:21	Reinspection Photo		Load JPG	☒
88	09/01/20 11:21	Reinspection Photo		Load JPG	☒
89	09/01/20 11:21	Reinspection Photo		Load JPG	☒
90	09/01/20 11:21	Reinspection Photo		Load JPG	☒
91	09/01/20 11:21	Reinspection Photo		Load JPG	☒
92	09/01/20 11:21	Reinspection Photo		Load JPG	☒
93	09/01/20 11:21	Reinspection Photo		Load JPG	☒
94	09/01/20 11:21	Reinspection Photo		Load JPG	☒
95	09/01/20 11:21	Reinspection Photo		Load JPG	☒

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
96	09/01/20 11:21	Reinspection Photo		☒
97	09/01/20 11:21	Reinspection Photo		☒
98	09/01/20 11:21	Reinspection Photo		☒
99	09/01/20 11:21	Reinspection Photo		☒
100	09/01/20 11:21	Reinspection Photo		☒
101	09/01/20 11:21	Reinspection Photo		☒
102	09/01/20 11:21	Reinspection Photo		☒
103	09/01/20 11:21	Reinspection Photo		☒
104	09/01/20 11:21	Reinspection Photo		☒
105	09/01/20 11:21	Reinspection Photo		☒
106	09/01/20 11:21	Reinspection Photo		☒
107	09/01/20 11:21	Reinspection Photo		☒
108	09/01/20 11:21	Reinspection Photo		☒
109	09/01/20 11:21	Reinspection Photo		☒
110	09/01/20 11:21	Reinspection Photo		☒
111	09/01/20 11:21	Reinspection Photo		☒
112	09/01/20 11:21	Reinspection Photo		☒
113	09/01/20 11:21	Reinspection Photo		☒
114	09/01/20 11:21	Reinspection Photo		☒
115	09/01/20 11:21	Reinspection Photo		☒
116	09/01/20 11:21	Reinspection Photo		☒
117	09/01/20 11:21	Reinspection Photo		☒
118	09/01/20 11:21	Reinspection Photo		☒
119	09/01/20 11:21	Reinspection Photo		☒
120	09/01/20 11:21	Reinspection Photo		☒
121	17/01/20 09:33	After Repair Photo		☒
122	17/01/20 09:33	After Repair Photo		☒
123	17/01/20 09:33	After Repair Photo		☒
124	17/01/20 09:33	After Repair Photo		☒
125	17/01/20 09:33	After Repair Photo		☒
126	17/01/20 09:33	After Repair Photo		☒
127	17/01/20 09:33	After Repair Photo		☒
128	17/01/20 09:33	After Repair Photo		☒
129	17/01/20 09:33	After Repair Photo		☒
130	17/01/20 09:33	After Repair Photo		☒
131	17/01/20 09:33	After Repair Photo		☒
132	17/01/20 09:33	After Repair Photo		☒
133	17/01/20 09:33	After Repair Photo		☒
134	17/01/20 09:33	After Repair Photo		☒
135	17/01/20 09:33	After Repair Photo		☒
136	17/01/20 09:33	After Repair Photo		☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/01/20 17:56	TP GIA REPORT		
2	07/01/20 17:56	EMAIL FROM AIG DD06012020		
3	07/01/20 17:56	ACKNOWLEDGEMENT EMAIL TO AIG DD06012020		
4	16/01/20 11:48	TP ESTIMATE-MARKED		
5	23/01/20 10:23	EMAIL TO OI		
6	23/01/20 10:23	LETTER TO OI		
7	05/02/20 10:03	TP ESTIMATE - FINALIZED		
8	10/02/20 14:33	RENTAL RECEIPT		
9	10/02/20 14:33	LTA SEARCH		
10	10/02/20 14:33	LOD		
11	27/02/20 11:01	EMAIL FROM TP		
12	02/03/20 10:23	WORKSHOP INVOICE		
13	02/03/20 10:23	AUTHORISATION TO ACT FORM		
14	02/03/20 10:23	Release Voucher		
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	09/01/20 10:48	OI GIA REPORT		 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SKU1639K (Insd veh)	Model:	MERCEDES-BENZ S300L
	SLP1551T (TP veh)		3.0 (A)
Date of Accident:	01/01/2020		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	16,733.20
Final Repair Cost	:	\$	8,239.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	1,980.00 11 days
LTA / GIA Search Fee	:	\$	7.45
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	10,226.45

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For **Non GIA Registered Workshop**: Agreed Liability _____ 100 _____ (%)

B) For **GIA Registered Workshop**: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	JKS Motor Works Pte Ltd	:	\$ 10,226.45
2)		:	\$
3)		:	\$
4)		:	\$

JOANNE LEE KHANG MIN

02 Mar
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co Reg.No:199807198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20000457/HHS3Q2

Date: 02/03/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999993931
Claimant
Vehicle No : SLP1551T **Insured Vehicle No :** SKU1639K
Date of Loss: 01/01/2020 **Nature of Claim:** TP **Claim No:** 8361437405SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLP1551T**
 Make & Model: MERCEDES-BENZ S300L, 3.0 (A) Engine No: 27294630641938
 Reg. Date: 26/06/2007 (Man. Year: 2007) Chassis No: WDD2211542A145305
 Colour: Black/Silver Odometer: 227190 km
 Engine Capacity: 2997 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40Z R20 Rear Tyre Size: 245/40Z R20
 Front Left Side: Sumitomo 5 mm Rear Left Side: Sumitomo 5 mm
 Front Right Side: Sumitomo 5 mm Rear Right Side: Sumitomo 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,888.50	7,543.80	4,344.70	36.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,750.00	2,110.00	1,640.00	43.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,638.50	9,653.80	5,984.70	38.27
Approved Total (Overridden) (S\$)		7,700.00		
(S\$)	15,638.50	7,700.00	7,938.50	50.76
+ GST 7.00/7.00% (S\$)	1,094.70	539.00	555.70	50.76
Nett Amount (S\$)	16,733.20	8,239.00	8,494.20	50.76
+ Car Rental (11.0 x S\$180.00/day) (S\$)		1,980.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		10,226.45		

INSPECTION

Date of Assignment: 06/01/2020
 Date Inspected: 06/01/2020 Inspected At: JKS MOTOR WORKS PTE LTD
 8 KAKI BUKIT AVE 4 #03-45
 PREMIER @ KAKI BUKIT
 SINGAPORE 415875

Estimated Period of Repair: 8.0 days

Adjuster: LEE HOCK ANN**Manager:** VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAIL LAMPS	N/S Cracked / O/S Serviceable	1,000.00 FL	*545.00 FL
2	2		*REAR TAIL LAMPS SIDE GARNISH	Serviceable	340.00 FL	*- FL
3	1		*REAR END PANEL	Bent	1,400.00 FL	*745.00 FL
4	1		*REAR END PANEL INNER GARNISH	Crumpled	100.00 FL	*100.00 FL
5	1		*REAR BUMPER	Cut	1,500.00 FL	*1,300.00 FL
6	1		*SET REAR BUMPER CLIP	Necessary	40.00 FL	*40.00 FL
7	2		*REAR BUMPER RETAINER LH & RH	Crumpled	180.00 FL	*160.00 FL
8	2		*REAR BUMPER BRACKET LH & RH	Crumpled	120.00 FL	*120.00 FL
9	1		*REAR BUMPER REINFORCEMENT	Bent	800.00 FL	*650.00 FL
10	1		*REAR BUMPER TOW COVER	Serviceable	85.00 FL	*- FL
11	4		*REAR BUMPER PDC SENSORS	Shorted (3 PCS ONLY)	1,000.00 FL	*600.00 FL
12	1		*SET REAR BUMPER SENSOR WIRE HARNESS	Serviceable	250.00 FL	*- FL
13	2		*REAR BUMPER BRACKET SUPPORT CENTRE	Cracked (1PCS ONLY)	320.00 FL	*180.00 FL
14	1		*REAR BOOT	Bent	2,600.00 FL	*2,042.00 FL
15	1		*REAR BOOT CHROME	Serviceable	150.00 FL	*- FL
16	1		*REAR BOOT CENTER LOGO	Necessary	50.00 FL	*50.00 FL
17	1		*REAR BOOT EMBLEM S350	Necessary	45.00 FL	*45.00 FL
18	1		*REAR BOOT EMBLEM MERCEDES	Necessary	55.00 FL	*55.00 FL
19	1		*REAR BOOT EMBLEM 7G TRONIC	Necessary	50.00 FL	*50.00 FL
20	1		*REAR BOOT LOCK	Jammed	380.00 FL	*280.00 FL
21	6		*REAR TRUNK SIDE TRIM BRACKET	Serviceable	180.00 FL	*- FL
22	1		*REAR BOOT LID RUBBER	Crumpled	120.00 FL	*120.00 FL
23	1		*REAR BOOT HANDLE	Serviceable	100.00 FL	*- FL
24	1		*REAR BOOT HANDLE BUTTOM	Serviceable	90.00 FL	*- FL
25	1		*REAR BOOT HANDLE LOWER	Serviceable	80.00 FL	*- FL
26	1		*REAR SPARE TYRE BOARD /PANEL	Cut	1,200.00 FL	*950.00 FL
27	1		*REAR SPARE TYRE COMPARTMENT SEALANT	Serviceable	80.00 FL	*- FL
28	1		*REAR SPARE TYRE UNDERCOVER	Cracked	450.00 FL	*350.00 FL
29	1		*SET REVERSE CAMERA	Serviceable	350.00 FS	*- FS
30	1		*SET NUMBER PLATE WITH HOLDER	Serviceable	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,165.00	8,382.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,276.50	838.20
Total Parts (\$\$)	11,888.50	7,543.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGE TO REPAIR & REBUILD INCLUDING CUT & WELD WHERE NECESSARY ,REMOVE & REPLACE REAR DAMAGE PARTS AS LISTED ABOVE	New	1,400.00	1,100.00
2	TO SPRAY PAINT ON REAR PORTION AFFECTED AREAS	New	1,600.00	800.00
3	TO REMOVE AND INSTALL REAR COMPARTMENT ATTACHMENTS & FITTINGS TO ENABLE REPAIRS	New	250.00	0.00
4	TO CHECK ALL WIRINGS AND LIGHTS FUNCTION AND FOCUS	New	100.00	30.00
5	TO INSTALL REAR SENSORS & REVERSE CAMERA	New	160.00	40.00
6	TO APPLY ANTI RUST PROOFING ON AFFECTED AREAS	New	120.00	40.00
7	TO DIAGNOSE & ERASE FAULT CODES AFTER REPAIR	New	120.00	100.00
Gross Labour Cost (S\$)			3,750.00	2,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >