

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20000468/AES3Q2

Date: 20/10/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994039

Claimant
Vehicle No : SGN183Z **Insured Vehicle No :** SLZ8492G

Date of Loss: 03/01/2020 Nature of Claim: TP Claim No: 4582657651SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGN183Z		
Make & Model:	BMW 320I, 2.0 ABS D/AB 2WD 2DR GAS/D (A)	Engine No:	A5031693N46B20BD
Reg. Date:	22/03/2011 (Man. Year: 2010)	Chassis No:	WBAKD52090E492261
Colour:	Black	Odometer:	0 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	265/30 R19	Rear Tyre Size:	265/30 R19
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	0.00	0.00	0.00	
Approved Total (Overridden) (S\$)		10,820.00		
Nett Amount (S\$)	0.00	10,820.00	-10,820.00	
+ Loss of Use (14.0 x S\$100.00/day) (S\$)		1,400.00		
Nett Liability (S\$)		12,220.00		

INSPECTION

Date of Assignment: 06/01/2020

Date Inspected: 06/01/2020 Inspected At: Advance Automobile (HQ)
Singapore

Estimated Period of Repair: 0.0 days

Adjuster: ADRIAN LING

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

PLEASE BE INFORMED OWNER THAT THE VEHICLE NOT ECONOMICAL FOR REPAIR.

MARKET VALUE : \$38,000.00

LTA REIMBURSEMENT VALUE (RV) : \$27,180.00

NETT VALUE : \$10,820.00

IN VIEW OF THE ABOVE, THE VEHICLE IS UNECONOMICAL TO BE REPAIRED.

REPAIR DETAILS

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >