

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	09 Nov 2019		07 Jan 2020 18:22 Edit Adj Rpt	\$S\$1,722.00 Edit Estimates	\$S\$1,722.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents						
Show All									
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: KOH NAN YANG , ID: S6942029Z, Tel: +6582283712, Email: NICKJOY@SINGNET.COM.SG									
Vehicle Reg. No.: SDB2388K		Date of Loss:	03/11/2019 10:00 - :59 [31 Months and 13 Days From LTA Reg Date (Man Yr)]						
Claim Type: OD / 0647103536SG		Policy/Cover Note No.:	2100503499-02 (Comprehensive)						
		Excess:	\$S\$0.00						
Repairer: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Azlan, Syazairdina] syazairdina.azlan@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 16/01/2020]									
Driver/Custodian: KOH NAN YANG (49 / Male) , NRIC: S6942029Z, Tel: +6582283712 Email: NICKJOY@SINGNET.COM.SG									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (28/04/2020): Alert - Adj Mandate Approved (\$S\$1722.00) - SDB2388K - Claim Handler: Azlan, Syaz... - AIG_SG (31/03/2020): Alert - Adj Mandate Maintained - SDB2388K - Claim Handler: Azlan, Syazairdina - AIG_SG (20/03/2020): Alert - Adj Mandate Maintained - SDB2388K - Claim Handler: Azlan, Syazairdina - AIG_SG (13/01/2020): Alert - Adj Mandate Approved (\$S\$1722.00) - SDB2388K - Claim Handler: Azlan, Syaz... - AIG_SG (09/01/2020): SDB2388K / OD / 03/11/2019 / Coverage & Excess update									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SDB2388K (0647103536SG)**
OD
Nov 3 2019 10:55AM
[KOH NAN YANG]
Premium Automobiles Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

Upload Video

Upload Audio

View

View in Browser

Video															1 per page		
No	Finalized On		Premium Automobiles Pte Ltd (UBI)											Thumbnail	Print		
1	04/11/19 14:31		Video - Accident [Linked Accident Report Documents]											Load MP4			
Assessment Reports															1 per page		
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)											Thumbnail	Print		
1	08/01/20 10:31		Adjuster Immediate Advice											Load HTM			
Photos/Images															3 per page		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)											Thumbnail	Print			
1	08/01/20 10:33	General View											Load JPG				
2	08/01/20 10:33	General View											Load JPG				
3	08/01/20 10:33	General View											Load JPG				
4	08/01/20 10:33	General View											Load JPG				
5	08/01/20 10:33	General View											Load JPG				
6	08/01/20 10:33	General View											Load JPG				
Documentation															1 per page		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)											Thumbnail	Print			
1	08/01/20 10:35	GIA AND POLICE REPORT											Load PDF				
2	08/01/20 10:36	LTA											Load PDF				
3	08/01/20 10:36	SG CAR MART											Load PDF				
4	08/01/20 10:36	MARK ESTIMATE											Load PDF				
5	08/01/20 15:38	Certificate of Insurance											Load PDF				
6	08/01/20 15:39	Insured's Driving License											Load PDF				
7	19/03/20 11:16	FINAL MARKING											Load PDF				
8	30/03/20 17:45	Paint coating invoice before and after											Load PDF				
9	30/03/20 17:45	Paint coating invoice before and after											Load PDF				
10	24/06/20 10:14	WORKSHOP INVOICE											Load PDF				
11	24/06/20 10:14	DISCHARGE VOUCHER											Load PDF				

Linked Accident Report Documents

												View View in Browser									
Video												1 per page									
No	Finalized On	Premium Automobiles Pte Ltd (UBI)													Thumbnail		Print				
1	04/11/19 14:31	Video - Accident										i			Load MP4						
Assessment Reports												1 per page									
No	Finalized On	Premium Automobiles Pte Ltd (UBI)													Thumbnail		Print				
1	06/12/19 19:25	Accident Statement										i			Load HTM						
2	06/12/19 19:26	Accident Statement										i			Load HTM						
3	06/12/19 19:33	Accident Statement										i			Load HTM						
4	06/12/19 19:33	Accident Statement										i			Load HTM						
5	07/01/20 10:34	Addendum Sheet										i			Load JPG						
6	07/01/20 10:38	Accident Statement Addm. #1										i			Load HTM						
Photos/Images						3 per page															
No	Finalized On	Premium Automobiles Pte Ltd (UBI)							Thumbnail		Print										

Video				1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	04/11/19 14:29	Accident Photo		Load JPG	☒
2	04/11/19 14:29	Accident Photo		Load JPG	☒
3	04/11/19 14:29	Accident Photo		Load JPG	☒
4	04/11/19 14:29	Accident Photo		Load JPG	☒
5	04/11/19 14:29	Accident Photo		Load JPG	☒
6	04/11/19 14:29	Accident Photo		Load JPG	☒
7	04/11/19 14:29	Accident Photo		Load JPG	☒
8	04/11/19 14:29	Accident Photo		Load JPG	☒
9	04/11/19 14:29	Accident Photo		Load JPG	☒
10	04/11/19 14:29	Accident Photo		Load JPG	☒
11	04/11/19 14:31	Accident Photo		Load JPG	☒
12	04/11/19 14:33	Police Report		Load JPG	☒
13	04/11/19 14:33	Police Report		Load JPG	☒
14	04/11/19 14:33	Police Report		Load JPG	☒
Documentation				1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	04/11/19 14:33	Sketch Plan		Load JPG	☒
2	04/11/19 14:33	Sketch Plan #2		Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20000470/AVF3S2**Date:** 24/06/2020**REFERENCE**

Insured/Claimant:	KOH NAN YANG	Policy No:	2100503499-02	
Date of Loss:	03/11/2019	Nature of Claim:	OD	Claim No: 0647103536SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDB2388K	Engine No:	CYG017660
Make & Model:	AUDI A6, 1.8 TFSI S-tronic (A)	Chassis No:	WAUZZZ4G2HN061225
Reg. Date:	21/03/2017 (Man. Year: 2016)	Odometer:	58954 km
Colour:	Black		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	S\$126,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,081.00	0.00	4,081.00	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,425.00	1,722.00	1,703.00	49.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	7,506.00	1,722.00	5,784.00	77.06
+ GST 7.00/7.00% (\$\$)	525.42	120.54	404.88	77.06
Nett Amount (\$\$)	8,031.42	1,842.54	6,188.88	77.06

INSPECTION

Date of Assignment:	07/01/2020		
Date Inspected:	07/01/2020	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	2,787.00 FS	*- FS
2	14		*LOCKING CLIP	Not Necessary	51.00 FS	*- FS
3	1		*FRONT BUMPER FIXING PARTS	Not Necessary	491.00 FS	*- FS
4	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Not Necessary	452.00 FS	*- FS
5	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					4,081.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER ASSY. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	New	1,200.00	500.00
3	TO RESPRAY FRONT BUMPER.	New	1,000.00	550.00
4	TO REAPPLY PAINT COATING ON FRONT BUMPER. (BY OWNER)	New	553.00	-
5	TO CARRY OUT DIAGNOSTIC CHECKS.	New	192.00	192.00
Gross Labour Cost (\$\$)			3,425.00	1,722.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >