

parts 1596.60

parts 100%

less 1436.94

spec net 320

labor 850

2606.94



TAN LIM MOTOR PTE LTD

NTUC Insured's Veh No : EQ1221Z

Date of Accident : 31 December 2019

1 Defu Lane 6 Singapore 539365

Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Messrs Poon Yong Hup Industry Co Pte Ltd 1/sup 20%

Date : 03 January 2020

2085.55

Estimate To Repair GX2385S - NISSAN Cabstar

Chassis No : JN1SF4F23Z0851855

total 1/5 at \$2100#

S/No	Quantity	Description	Amount
		NETT ITEMS	
01	1 pc	tailgate lid R/H ✓ B+	\$ 1,500.00
02	1 pc	tailgate lid Nissan sticker X (src)	\$ 25.50
03	1 pc	rear cargo deck end panel X (R)	\$ 886.40
04	1 pc	n/s rear lamp R/H ✓ C.R.A	\$ 248.60
05	1 pc	n/s rear lamp panel L/H ✓ B+	\$ 35.00
		Less 10 %	\$ 2,695.50
			\$ 269.55
			\$ 2,425.95
		SPECIAL NETT ITEMS	
06	1 pc	tailgate lid 70 KM/H sticker X (src)	\$ 15.00
07	1 pc	rear licence plate X (src)	\$ 50.00
08	1 set	reverse sensor ✓ shift	\$ 300.00
			\$ 365.00
		LABOUR & MISC. CHARGES	
01		To reinstall of rear bumper parking sensor.	\$ 100.00
02		To check electrical lighting concerned.	\$ 50.00
03		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same. + repair R/H back	\$ 850.00
04		Putty and spray painting of the affected portion. + per per R/H back End part	\$ 600.00
			\$ 1,600.00
		Total	\$ 4,390.95

1350.80 ✓

210.80 ✓

200 ✓

20 ✓

30 ✓

500 ✓

300 ✓

4,610.95

1/5 repair
without prejudice
Resurvey after part
Hock Ann
853/1234
2.30 pm
8/1/20
Hock ANN @ LKK Auto. com

10/1/2020

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



陳林摩呀私人有限公司
TAN LIM MOTOR PTE LTD

NTUC Insured's Veh No : EQ1221Z
Date of Accident : 31 December 2019

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Messrs Poon Yong Hup Industry Co Pte Ltd

Date : 04 February 2020

Supplementary To Repair GX2385S - NISSAN Cabstar
Chassis No : JN1SF4F23Z0851855

S/No	Quantity	Description	Amount
01	1 pc	<u>SPECIAL NETT ITEMS</u> n/s rear door sticker ✓ <i>nee</i>	\$ 220.00 120 ✓
			\$ 220.00
		Total	\$ 220.00