

ASS. REC. BY:

REF: CS/INC 20000505/Hsf322 Special Instruction:

Surveyor: Hock Ann ASSIGNMENT (Office)

From (Person): Theresa Vimala of INC Date/Time: 8 Jan 2020 10:20:17

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMP 36054 Insured: SLZ 48282

at Workshop m/s Tan Lim Motor Tel: 62585151

of 1 Refu Lane

Policy No: Claim No: MT / 1078980-001

Sum Insured: Excess:

Make of Veh: D.O.A. 5.1. 2020
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 8 Jan 2020 11:00:00

Person Contacted: Caymen

H.O.D. Endorsement:

Vehicle IN / OUT

Date/Time	Action/Instruction (V) Estimate
	SMP 36054 - NAI/INC 20000431/114 12.0A - 05/01/2020

Lum Sum: % J Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	* SMP 36054
	UIC / N/S
	Hock Ann Confirmed L/S \$2,800 / @ 4 days by Bala Singh
	with Wei Sheng. C \$3,247.30 Red - 54% 2
	MV - 104000
	PV - 45550
	NV - 38400

Date/Time: File Pass to?

02/04/20

Type: 4

Date/Time: File Return to?

3

☐ : Prel. Report☒ : Final Report

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Insp (\$☐ : Wash and (\$

Survey Fee:

Transportation:

S + RS \$

Paints

Others

Total:

250

250

Report Fee/Total:

Total Fee/Total: \$2800 L/S