



TRANS EUROKARS PTE LTD



FINALISED COST OF REPAIRS

NTUC INCOME INSURANCE 1 MARITIME SQUARE #10-01 HARBOURFRONT CENTRE SINGAPORE 099253 ATTN. : MOTOR CLAIMS FAX :		NAME : Mr Eddie See Wan Ming ADDRESS : Blk 25 Lorong 3 Toa Payoh #10-12 TREVISTA Singapore 319583 TEL : 81686590		WIP : 18198 EXCESS : DATE: 30-Dec-19	
VEH NO :	SLE8868S	DATE IN :		CONTACT PERSON :	Ronald 63957875
CHASSIS NO :	JM6CW1071G0124073	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA5	DATE REG.:	18-Aug-16	POLICY NO. :	
<u>NATURE OF WORKS</u>					
<u>Parts Description</u>					
NO	QTY			REVISED	PRICES
1	FRONT BUMPER	1	MC513-50-031BBB	\$ 1,108.20	\$ 1,108.20
2	BRACKET RHS, FRONT BUMPER	1	MC513-50-151A		\$ 42.30
3	COVER RHS, FOGLAMP	1	MC513-50-C11		\$ 78.20
4	CLIP, FRONT BUMPER	10	MC274-50-133	\$ 37.00	\$ 37.00
5	GROMMET, FRONT BUMPER	1	MC513-50-0T5A	\$ 16.20	\$ 16.20
6	RIVET, FRONT BUMPER	4	MBN8F-50-355	\$ 22.80	\$ 22.80
7	RIVET, FRONT BUMPER	4	MEA01-50-037	\$ 32.00	\$ 32.00
8	FOAM, FRONT REINFORCEMENT	1	MC513-50-111		\$ 79.20
9	FASTENER, FRONT REINFORCEMENT	2	MFD01-68-AC3	\$ 12.40	\$ 12.40
10	FRONT REINFORCEMENT	1	MC513-50-070A		\$ 531.60
11	HEADLAMP RHS	1	MC513-51-0K0F		\$ 1,482.00
12	CLIP, HEADLAMP	3	MDR61-50-133		\$ 19.50
13	RIVET, HEADLAMP	1	MB092-51-833		\$ 3.50
TOTAL PARTS				\$ 1,228.60	\$ 3,464.90
TOTAL PARTS COST				\$ 1,228.60	\$ 3,464.90
<u>Labour Description</u>					
1	MZ-BR-FRONT1	TO REPLACE FRONT BUMPER. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.		\$ 660.00	\$ 1,320.00
2		TO RESPRAY FRONT BUMPER.		\$ 630.00	\$ 1,890.00
3	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.			\$ 250.00
4	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		\$ 150.00	\$ 250.00

5	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 180.00	\$ 350.00	
6	MZ-BR-SUNDRI	SUNDRIES.	\$ 20.00	\$ 100.00	
			TOTAL LABOUR	\$ 1,640.00	\$ 4,160.00
			TOTAL PARTS	\$ 1,228.60	\$ 3,464.90
			TOTAL	\$ 2,868.60	\$ 7,624.90
			LESS EXCESS	\$ -	\$ -
			TOTAL AFTER EXCESS	\$ 2,868.60	
			GST 7%	\$ 200.80	\$ -
			GRAND TOTAL	\$ 3,069.40	\$ -

REMARKS:

3 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)