

T K LEE AUTOMOTIVE PTE.LTD

NO 1 KAKI BUKIT AVE 6 #02-47

AUTOBAY SINGAPORE 417883

Tel : 6509 5521 / 65095524 Fax : 6509 5523

The Motor Claims Dept.

QBE INSURANCE (INTERNATIONAL) LTD

60 ANSON ROAD

#11-01 MAPLETREE ANSON

SINGAPORE 079914

GBD4374A

ESTIMATE

DATE : 08.01.2020

VEHICLE NO : SJL6848A

HONDA

MAKE/MODEL : CROSSROAD

ACC DATE : 07.01.2020

PARTICULAR

UNIT PRICE

AMOUNT

QTY	LIST PRICE	SS	SS
1	1 REAR TAILGATE <i>Bed 5 m</i>	1,191.50	1,191.50
2	2 REAR TAILGATE HINGE RH/LH <i>17</i>	55.10	110.20
3	2 REAR TAILGATE DAMPER RH/LH <i>17</i>	196.50	393.00
4	1 REAR TAILGATE RUBBER <i>twi</i>	160.90	160.90
5	1 REAR TAILGATE LOCK <i>shrub</i>	219.30	219.30
6	1 REAR TAILGATE LOCK CATCH <i>17</i>	32.90	32.90
7	1 REAR TAILGATE INNER TRIM <i>del to in</i>	491.80	491.80
8	1 REAR TAILGATE INNER HANDLE <i>17</i>	86.50	86.50
9	1 REAR TAILGATE WIPER ARM <i>17</i>	74.60	74.60
10	1 REAR TAILGATE WIPER MOTOR <i>del to in</i>	391.50	391.50
11	1 REAR TAILGATE EMBLEM H <i>del</i>	44.90	44.90
12	2 REAR TAILGATE NUMBER PLATE LAMP <i>17</i>	38.50	77.00
13	1 REAR TAILGATE NUMBER PLATE GARNISH <i>del to in</i>	660.20	660.20
14	2 REAR TAILLAMP RH/LH <i>sen/cor</i>	616.10	1,232.20
15	1 REAR BUMPER <i>dis</i>	968.40	968.40
16	1 REAR BUMPER TOW COVER <i>twi</i>	29.50	29.50
17	2 REAR BUMPER REFLECTOR RH/LH <i>del 17</i>	81.60	163.20
18	2 REAR BUMPER SIDE RH/LH <i>del to in</i>	185.50	371.00
19	1 REAR BUMPER BEAM <i>del</i>	115.20	115.20
20	2 REAR BUMPER SIDE HOLDER RH/LH <i>del</i>	39.50	79.00
21	2 REAR BUMPER SIDE RETAINER RH/LH <i>17</i>	48.80	97.60
22	1 REAR EXHAUST BOX HEAT SHIELD <i>17</i>	142.80	142.80
23	1 REAR EXHAUST BOX <i>17</i>	791.50	791.50
24	1 REAR END PANEL <i>del to in</i>	545.90	545.90
25	1 REAR END PANEL GARNISH <i>twi</i>	227.90	227.90
26	1 REAR FLOOR PANEL CARDBOARD <i>del to in</i>	285.90	285.90
27	2 REAR FENDER INNER TRIM RH/LH <i>del to in</i>	395.20	790.40
			9,774.80
Less 20%			1,954.96
			7,819.84

7410.3
5928.24

T K LEE AUTOMOTIVE PTE.LTD

PARTICULAR		UNIT PRICE	AMOUNT
		S\$	S\$
<u>SPECIAL NETT ITEMS</u>			
1	1 REAR WINDSCREEN SPONGE TAPE <i>ner</i>	20.00	20.00 ✓
2	1 (SET) REAR WINDSCREEN SEALANT <i>ner</i>	80.00	80.00 40
3	1 REVERSE CAMERA <i>shund</i>	350.00	350.00 350
4	1 (SET) REAR NUMBER PLATE WITH CASING <i>ner</i>	50.00	50.00 40
5	1 (SET) REVERSE SENSOR <i>shund</i>	280.00	280.00 280
6	1 (SET) REAR BUMPER CLIPS <i>ner</i>	45.00	45.00 ✓
			<u>825.00</u>

LABOUR CHARGES :

1	TO KNOCK OUT DENT, CUT/WELD REAR PANEL AND REPLACE ACCIDENT PARTS	900.00	600
2	TO SPRAY PAINTING ON ACCIDENT PORTION	1,200.00	1000
3	TO CHECK WIRING	30.00	L
4	TO REMOVE, REFIX REAR WINDSCREEN	120.00	✓
5	TO TRANSFER REAR TAILGATE PARTS	100.00	60
6	TO REMOVE, REFIX CUSHION AND INNER TRIM	150.00	80
7	TO REMOVE, REPLACE REVERSE CAMERA AND REVERSE SENSOR	150.00	50
8	TO REMOVE, REPLACE REAR EXHAUST BOX	11 120.00	X
9	TO TUFF KOTE	90.00	60
TOTAL:		2,860.00	

TOTAL AMOUNT :		11,504.84
----------------	--	-----------

signs hence notify
following:
ent prove he
SI
Company
Company
Company

2-5928.24
5.2645
L-1000

8573.24
6854.