

REF: BY: Steve

REF: SMO

ASSIGNMENT

From:

Date:

14/01/2020

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SKZ 2670K

at Workshop m/s

Mova Automotive

of Blk 1008 Bukit merah lane 3 #01-04

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

After 1pm

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 1up

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: SKZ 2670K

Yr Regn: 15/1/16

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Nissan Teana

C.C.

1997

Colour:

White

A/C: Insured / Std / NI / NA

Sp. Reading

67845

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MNTBQAL3320095524

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/55R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

31/12/19

D.O.I.

14/1/20

Survey held at

Mova, Bukit merah

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MK-65K

Finalize @ \$3950/- (Red: 2800.80: 41%)

Date/Time, File Pass to?



Preli. Report



Final Report

Date/Time, File Return to?

2)

Report Format:

TP

Lump Sum / L.P.C. @

3950/-

Days Of Repair: 5

Resurvey No. of Trip: -

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Week end (\$)

Survey Fee:

Transportation:

S + PS. SI

Photos

Others

TOTAL

Estimate

07/01/2020

SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623.

Attention :- **XA018**

Page # :- 1

Veh # :- SKZ2670K

Veh Model :- NISSAN TEANA 2.0XL CVT

Estimate# :- CK420204

Claim # :- TP/CK137269

ACC. Date :- 31/12/19

Terms :- C.O.D Days

Remarks :- MFG 15 JAN 2016 (2015)

Main Office:
 Mova Building
 No. 22, Jalan Kilang,
 Singapore 159419
 Tel: (65) 6476 3333
 Fax: (65) 6271 5891
 www.mova.com.sg

Workshop Dept:
 Block 1008,
 Bukit Merah Lane 3,
 #01-04/06/08/94
 Singapore 159722

Tel: (65) 6272 3892
 Fax: (65) 6270 8314
 Co. Reg. 198904033G
 GST Reg. M2-0088864-2

No.	Description	Qty	U.Price	Amounts S\$
NET ITEMS :				
1.	BOOTLID / <i>00</i>	1 PC	798.00	798.00
2.	BOOTLID LOGO / <i>nk</i>	1 PC	59.00	59.00
3.	BOOTLID EMBLEM - TEANA / <i>nk</i>	1 PC	89.00	89.00
4.	BOOTLID EMBLEM - 2.0 XL / <i>nk</i>	1 PC	86.00	86.00
5.	BOOTLID EMBLEM PLATE - XTRONIC CVT / <i>nk</i>	1 PC	59.00	59.00
6.	BOOTLID LOCK / <i>BT?</i>	1 PC	155.00	155.00
7.	BOOTLID RUBBER	1 PC	142.00	<i>X</i> 142.00 <i>nn</i>
8.	REAR BUMPER / <i>00</i>	1 PC	849.00	849.00
9.	REAR PARKING SENSOR CTR LH / <i>sh</i>	1 PC	220.00	220.00
10.	REAR PARKING SENSOR CTR RH / <i>sh</i>	1 PC	220.00	220.00
11.	REAR BUMPER CLIPS / <i>nk</i>	10 PC	4.00	40.00 <i>30</i>
12.	REAR BUMPER SIDE RETAINER LH / <i>BR</i>	1 PC	53.00	53.00
13.	REAR BUMPER SIDE RETAINER RH / <i>BR</i>	1 PC	53.00	53.00
14.	REAR BUMPER SPONGE	1 PC	245.00	245.00 <i>xnn</i>
15.	REAR BUMPER REINFORCEMENT	1 PC	534.00	534.00
16.	ELECTRICAL ANTENNA	1 PC	264.00	264.00 <i>xnn</i>
17.	END PANEL TOP GARNISH	1 PC	148.00	148.00 <i>mm</i>
18.	END PANEL / <i>dent</i>	1 PC	464.00	464.00
19.	TAILLAMP LH / <i>dent</i>	1 PC	402.00	402.00
20.	TAILLAMP RH / <i>x nn</i>	1 PC	402.00	402.00 <i>X</i>
21.	BOOTLID HINGE LH + RH - REPAIR / <i>x R</i>	2 PC		
22.	SPARE TYRE PANEL - REPAIR / <i>x nn</i>	1 PC		
NET TOTAL S\$				5,282.00
10% DISCOUNT S\$				-528.20
				4,753.80

LABOUR :

TO INSPECT REAR LIGHTING MECHANISM

30 80.00TO CUT OFF END PANEL. TO REPLACE DAMAGED ITEM
REALIGN CONNECTION600.00 */*

TO REMOVE & REFIT REAR COMPARTMENT ATTACHMENT

30 150.00

TO APPLY BODY JOINT SEALANT

30 80.00

TO RUST PROOF ON REPAIRED AREAS

30 80.00

TO SPRAY PAINT ON REPAIRED AREAS

700 800.00

LABOUR TOTAL S\$

1,790.00

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-008864-2

Page # :- 1 137269
Veh # :- SKZ2670K
Veh Model :- NISSAN TEANA 2.0XL CVT
Estimate# :- CK420204
Claim # :-
ACC. Date :- 31/12/19
Terms :- C.O.D Days
Remarks :-

Estimate

7/01/2020

OMPO INSURANCE SINGAPORE PTE LTD
D RAFFLES PLACE
05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623.

Attention :- XA018

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$

6,543.80

GST @ 7 %

458.07

AMOUNT DUE S\$

7,001.87

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

Jacelyn

Steve (LKK) M/L PM

14/1/20, 2.00pm

5 dys

L/S

M AL SY

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: