

FASTECH AUTO PTE LTD  
BLK1 KAKI BUKIT AVE 6  
#01-46,48,50 AUTOBAY  
SINGAPORE 417883

Not Authorized  
HAR  
8/1/20  
SLY. 2/5 4000

VEHICLE NO: SFD 1608Z

QTY	PARTICULAR		
1 PCS	TAILGATE	12	\$1,485.00 X
1 PCS	TAILGATE REAR LOGO	11	\$48.00 X
1 PCS	TAILGATE 'CARENS' EMBLEM 39	11	\$62.00
1 PCS	TAILGATE 'CRDI' EMBLEM 35	11	\$63.00
1 PCS	TAILGATE C&C LOGO	11	\$50.00
1 PCS	TAILGATE WEATHERSTRIP 131.00	11	\$311.00
1 PCS	TAILGATE INNER LOCK	11	\$395.00 X
1 PCS	REAR BUMPER 676.00	11	\$909.00
1 PCS	REAR BUMPER LOWER 201.00	11	\$488.00
1 PCS	REAR BUMPER SIDE SPOILER N/S 205.00	11	\$480.00
1 PCS	REAR BUMPER SIDE RETAINER N/S	11	\$66.00 X
1 SET	REAR BUMPER CLIPS	11	\$50.00
1 PCS	REAR BUMPER REINFORCEMENT 427.00	11	\$611.00
1 PCS	REAR BUMPER BRACKET N/S 157.00	11	\$255.00
1 PCS	REAR BUMPER LAMP N/S 245	11	\$392.00
2 PCS	REAR BUMPER PDC SENSORS @\$265.00 192	11	\$530.00 PC
1 PCS	REAR END PANEL 545	11	\$505.00
1 PCS	REAR END PANEL TOP GARNISH	11	\$266.00
1 PCS	TAILLAMP N/S 488.00	11	\$820.00
1 PCS	REAR END PANEL SEALANT	11	\$50.00
1 PCS	REAR WINDSCREEN SEALANT	11	\$50.00 X
1 PCS	REAR FLOOR PANEL	11	\$1,145.00 X
			\$9,031.00
	LABOUR CHARGES		
	TO CHECK WIRING		\$80.00 20
	TO DISMANTLE & REPLACING PDC SENSOR		\$80.00 50
	TO DISMANTLE & REFIX REAR WINDSCREEN	11	\$150.00 X
	TO DISMANTLE & REFFIX CUSHION UPHOLSTREY		\$120.00 80
	TO SPRAY RUST PROOFING		\$80.00 30
	LABOUR FOR PANEL BEATING & REPLACING PARTS		\$1,280.00 600
	TO PUTTY & SPRAY PAINTING		\$1,500.00 900
		TOTAL	\$12,321.00

(102)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

5019