

INS. CASE OWNER: LEE HING YAO

CC 4/ AIG 2000 0524 / THS3

LKK:

IDAC:

Surveyor:

Taufik

DOI:

13/1/2020

Date / Time:

8/1/2020

Registered in Merimen:

8/1/2020

Pre-assign / CCU / FTE

Insured Vehicle No. : SJA8718LClaim No. : 703062196866Name of Insured : Lim Hai Leong

Policy No. : _____

Insured Tel No. : _____ HP: _____

Make / Model : _____

Excess Sec II : \$\$ D.O.A : 28/12/19

Place of Accident : _____

Is driver the owner? (YES / NO) Nature of Accident : _____

If NO, Driver Name / Age :

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. :

(V/L: YES / NO)

Insured Liability : % Final ? Yes / No

SKL 2791TINSRS:
WSP: Hua Tiong
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/ Time	STAGE	DATE / PIC
	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List: Handler Typist	
	Notification ltr (if non-pickup)	
	After call ltr to OI:	
	Authorisation To Act:	
	Release Voucher:	
	Final Repair Bill:	
	Car Rental Invoice:	
	Towing Invoice	
	LTA / GIA:	
	Medical Bill:	
	PIR:	
	Mandate/Reject Instruction:	
	LOD	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	
12/01/2020	MUS REBUND. OI RATE - ENDED TP.	
13/1 4:45pm	called but no response	
19/1 9:43am	spoke to OI, OI tel TP for below. Internal TP claim & advise N.O. attached. email sent.	
	- PINKSLIP	
	- TP LOD IN BY EMAIL	
03/03/2020	TYPE REPORT FOR WANDRE APPROVAL	
	REPORT DONE	
18/03/2020	SEND WANDRE APPROVAL TO AG	
	AG APPROVED MANDATE	
	SEND 1ST OFFER TO TP.	
19/03/2020	TP ACCEPTED OFFER. ALL DOCS IN ORDER.	
PRELIMINARY ADVICE	Date/Time:	Sent By:
FINALIZATION	Date/Time:	Confirm with:
Repair Cost: <u>119</u>	\$S 8,750.00 (8 days) Reduction: <u>84</u> %	Confirm by: Email ☐ Call ☐
FINAL SETTLEMENT	Date/Time: <u>19/03/2020</u>	Confirm with: <u>BOOK KWAH</u>
Final Liability:	% <u>100</u> (Agreed / Assessed) BOLA S/N No.: <u>27</u>	Email ☒ Call ☐
Repair Cost: <u>(w/ger)</u>	\$S 9,362.50	If NO or B 28, Ass. Lia: <u>COI RATE - ENDED TP</u>
Loss of Rental (LOR) <u>(w/ger)</u>	\$S 1,125.00 (7 days) X \$150	
Loss of Use (LOU):	\$S - (\$ x days)	
Loss of Income (LOI):	\$S - (\$ x days)	
LOR only ☒ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]		
GIA/LTA Search	\$S 2.00	
Medical:	\$S -	
Disbursement:	\$S - (e.g. Tow/ Independent)	
Legal Cost	\$S -	
Total:	\$S 10,488.00	Global Sum \$S: -
FINAL PAYMENT	Date/Time:	Confirm with:
Payee 1:	\$S 10,488.00	Name 1: <u>HUKTONG CONTRACTOR PTE LTD</u>
Payee 2: (Strike if N.A.)	\$S -	Name 2: -
Payee 3: (Strike if N.A.)	\$S -	Name 3: -

Tan Mr
SJE tautik

REF: AIG

ASSIGNMENT

From: Date: 13/01/2020

Estimated Cost:

OT / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKL 2791T

at Workshop m/s Hua Tiong

of 9 Benoi Crescent

Insured:

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh: 2pm-4pm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 432K

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 8 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS up

Date: Person Contacted: Kenny Kenny Vehicle: IN / OUT

Date / Time	Action / Instruction
	84487093
	Rebate: 423,244
-	Vehicle Not economical to repair, total loss. (TP REPAIR CATE)
-	to Call Kenny & co
	LV: 40750.00
	(TP: 44,693.30 / 84%)
	MV: 402,000.00 (net)
	UCA: 423,250.00 (net)
	Nett: 408,750.00 (net)

Veh No: SKL2791T Regn: 20/0 July

Type: M.C. / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 523I CC: 2497

Colour: Black NC: Insured / Std / NI / NA

Sp. Reading: 101673 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 275/35Z R19

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Roadstone

Front

Rear

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A. D.O.I. 13/1/20

Survey held at Hua Tiong

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Path to: ☐ : Prel. Report

☐ : Final Report

Date/Time, File Path to:

3

Report Format:

Lump Sum / U.C. /

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp. (\$

☐ : Interview (\$

☐ : Tech. Insp. (\$

☐ : (Work) (\$

Survey Fee:

Transportation:

3 + RS \$

Phone:

Other:

POST



Huatong Contractor Pte Ltd

50, 5 Road, Singapore 628972
TEL: 6346 8888 FAX: 6346 1291
U.S. Registration No: 1902647323

Repair Estimate

Damage Assessed by:	Kemmy
Classification:	Third Party Claim
Owner:	HUATONG CONTRACTOR PTE LTD
Date:	1/2/2020
Vehicle Type:	Passenger Car
Registration Number:	SKL 2791T
Chassis No:	WBAFP320X0C544845/-
Engine No:	06987469N52B25AF/-
Year of Make:	2010
Date of Registration:	21/7/2010

Parts			
Operation	Description	Qty	Dollar Amount
Replace and install	Rear bumper assy	1	\$3,780.00
Replace and install	Rear bumper reinforcement bar	1	\$1,374.00
Replace and install	Rear bumper reinforcement bracket	1	\$796.00
Replace and install	Rear bumper light reflector LH	1	\$174.37
Replace and install	Rear bumper light reflector RH	1	\$174.37
Replace and install	Tow hook cover	1	\$156.35
Replace and install	Rear parking sensor assy	1	\$853.45
Replace and install	Rear tail lamp assy LH	1	\$1,345.76
Replace and install	Rear tail lamp assy RH	1	\$1,345.76
Replace and install	Rear boot tail assy LH	1	\$792.32
Replace and install	Rear boot tail assy RH	1	\$792.32
Replace and install	Rear boot assy	1	\$7,845.35
Replace and install	Rear boot moulding cover	1	\$1,321.87
Replace and install	Rear BMW emblem	1	\$257.53
Replace and install	Rear BMW Model Designation	1	\$125.39
Replace and install	Rear muffler assy	1	\$2,380.48
Replace and install	Rear muffler exhaust hanger	1	\$392.51
Replace and install	Rear bumper undertray protection	1	\$689.32
Replace and install	Rear undertray chassis repair panel	1	\$11,439.54
Replace and install	Boot plastic moulding	1	\$450.18
Replace and install	Boot rubber seal	1	\$784.23
Replace and install	Boot automatic motor assy	1	\$1,940.65
Replace and install	Boot lock upper	1	\$275.13
Replace and install	Boot lock lower	1	\$229.10
Replace and install	Electronic ABS module	1	\$9,887.32
			\$49,603.30

Labour			
Remove/Replace	All parts stated above - 14 working days	14	\$3,360.00
Spray Paint	2 working days	2	\$480.00

Estimate Totals			
Labour Subtotal			\$3,840.00
Parts			\$49,603.30
Gross Total			\$53,443.30

Tanfah 97445749 / 674418434
- WP
tanfah e 11kauto.com 08 days
13/1/20
To check repair limit
To check if vehicle can repair or
uneconomical to repair

de ✓ 1531
b/ ✓ 640.73
Xnh 300
Run 95
Run 95
mis ✓
Run ✓ 590
Run ✓ 590
Run 420
Run 420
b/ ✓ 1866
Run
Run
Run 550
Run
Run ✓ 175
Run
Run ✓ 275
b/ ✓ 586
b/ ✓
b/ ✓ 2750
129880.88

- 1440
- 1200
\$ 15,630.88
415,12,500

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	714G
Vehicle Details	
Vehicle No.:	SKL2791T
Vehicle to be Exported:	Yes
Intended Deregistration Date:	08 Jan 2020
Vehicle Make:	B.M.W.
Vehicle Model:	523I 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV
Primary Colour:	Grey
Manufacturing Year:	2010
Engine No.:	06987469N52B25AF
Chassis No.:	WBAFP320X0C544845
Maximum Power Output:	150.0 kW (201 bhp)
Open Market Value:	\$42,241.00
Original Registration Date:	21 Jul 2010
First Registration Date:	21 Jul 2010
Transfer Count:	1
Actual ARF Paid:	\$42,241.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Jul 2020
PARF Rebate Amount:	\$21,120.00
Intended COE Rebate Details	
COE Expiry Date:	20 Jul 2020
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$39,911.00
COE Rebate Amount:	\$2,124.00
Total Rebate Amount:	\$23,244.00

The information contained herein is correct as at 08 Jan 2020

OK

MV : \$32,000.00 (est)

LTA : \$13,250.00 (est)

Nett : \$ 8,750.00 (est)

RENTAL CAR DEALS

Exclusive Sunroof Auto Transmission
Cross Country BS250
Find out more

time 523i Price Range Depreciation 2010 Vehicle Type Search Advanced Search

Home » Used Cars » Dickson Automobile » BMW 5 Series 523i

BMW 5 Series 523i

Overview Financial Insurance Accessories Similar Research Photos Map



DICKSON AUTOMOBILE PTE LTD
A member of DICKSON AUTO GROUP
Established since 1988



Price	\$32,800		
Depreciation	N.A.	Reg Date	30-Jun-2010 (4mths 22days COE left)
Mileage	N.A.	Manufactured	2010
Road Tax	\$1,796 /yr	Transmission	Auto
Dereg Value	\$20,183 as of today (change)	OMV	\$37,309
COE	\$39,002	ARF	\$37,309
Engine Cap	2,497 cc	Power	150.0 kW (201 bhp)
Curb Weight	1,650 kg	No. of Owners	3
Type of Vehicle	Luxury Sedan		

Features

Powerful BMW 2.5L 6-cylinder In-line, E-Gear Produced 201 bhp And 250Nm Of Torque, Dual Zone Auto Climate, Keyless Entry/Start, Multi Steering Control View specs of the BMW 5 Series Sedan

Accessories

19"Sports Rim, Leather Seats, I-Drive, Bluetooth, Park Assist, Auto Tailgate, Comfort Access, Cruise Control, Retractable Side Mirrors, Fog Lights.

Description

We Provide Immediate Transfer For A Peace Of Mind, Very Suitable For Short Term Drive With Option To Renew COE, Engine And Gearbox Very Smooth, Super Well Maintained And Kept By Previous Owner, Buy It From Us With A Peace Of Mind From A Company Accredited With Outstanding Awards And Professional After Sales Service Assured. Ready For Viewing In Our Aircon Showroom.

Category


PAIF Car

Status

Available


Resources

Compare



Location Map

Price Chart



Click on the point to view the vehicle

Shortlist Compare Add note
Report Error More Actions

Seller Information

Dickson Automobile

30 vehicles for sale, 27 sold in past 3 mths

31 Kall Bukit Road 3 #01-01
Technic

Vic (LKKAUTO)

From: Douglas Ng <douglas.ng@huatong.com.sg>
Sent: Monday, 17 February, 2020 1:31 PM
To: Vic (LKKAUTO)
Cc: Taufikh (LKKAUTO); Admin A; Au Sook Kwan
Subject: Re: Your Ref: SKL 2791T - ACCIDENT INVOLVING VEHICLES SJA 8781L & SKL 2791T
ON 28/12/2019 - LKK REF CC4/AIG20000524/T1hs3

Dear Vic,

Thank you for the email.

As spoken, we will accept the below value and will proceed to repair the vehicle.

We will send you the LOD in due course.

Best Regards,
Douglas Ng
Business Manager

HUATIONG CONTRACTOR PTE LTD
(A subsidiary of Huatong Global Limited)
No. 9 Benoi Crescent
Singapore 629972
Tel: (65) 6366 5005
Fax: (65) 6368 1391
Email: douglas.ng@huatong.com.sg
Website: www.huatong-global.com

This message and attachments transmitted with, it may contain confidential or may be privileged and are intended solely for the use of the individual or entity to which they are addressed. Any unauthorized dissemination or copying of the email and its attachments, and any use or disclosure of any information contained in them is strictly prohibited. If you received this message in error, please notify the sender immediately by returning a copy of this message to the sender indicating that you have received it in error or delete it from your system. Any views expressed by an individual within the email do not necessarily reflect the views of Huatong Global Limited and its subsidiaries. Please check this message and any attachments transmitted with it for the presence of viruses. Huatong Global Limited accepts no liability for any damage caused by any virus transmitted by this message.

On 11 Feb 2020, at 4:00 pm, Vic (LKKAUTO) <vicalpeh@lkkauto.com> wrote:

Without Prejudice

Dear Kemmy,

We refer to the subject matter and to our telephone conversation earlier.
As spoken, please find below amended total loss computation as per our surveyor's recommendation.

MARKET VALUE (a) : \$32,000.00 (est)
LTA REBATE (b) : \$23,250.00 (est)

NETT VALUE (a-b) : \$ 8,750.00 (est)

Kindly note that the above amount and recommendation is still subject to our principal's approval.
Thank you.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

<image002.jpg> *Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: Vic (LKKAuto)

Sent: Tuesday, 4 February, 2020 11:27 AM

To: kemmy.su@huatong.com.sg; Taufikh (LKKAuto)

Cc: Admin A; Vic (LKKAuto)

Subject: RE: Your Ref: SKL 2791T - ACCIDENT INVOLVING VEHICLES SJA 8781L & SKL 2791T ON 28/12/2019 - LKK REF CC4/AIG20000524/T1hs3

Without Prejudice

Dear Taufikh,

Please assist below email.

Thank you.

<image005.png><image011.png>

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

<image002.jpg> *Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: kemmy.su@huatong.com.sg [<mailto:kemmy.su@huatong.com.sg>]

Sent: Tuesday, 4 February, 2020 11:20 AM

To: Vic (LKKAuto)

Cc: Admin A; Taufikh (LKKAuto); douglas.ng@huatong.com.sg; 'Au Sook Kwan'

Subject: RE: Your Ref: SKL 2791T - ACCIDENT INVOLVING VEHICLES SJA 8781L & SKL 2791T ON 28/12/2019 - LKK REF CC4/AIG20000524/T1hs3

Dear Vic,

I had just browse from SG car , for the market value which you had offer us can it be adjusted to a higher offer?

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	714G

Vehicle Details

Vehicle No.:	SKL2791T
Vehicle to be Exported:	Yes
Intended Deregistration Date:	08 Jan 2020
Vehicle Make:	B.M.W.
Vehicle Model:	523i 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV
Primary Colour:	Grey
Manufacturing Year:	2010
Engine No.:	069B7469N52B25AF
Chassis No.:	WBAFP320X0C544845
Maximum Power Output:	150.0 kW (201 bhp)
Open Market Value:	\$42,241.00
Original Registration Date:	21 Jul 2010
First Registration Date:	21 Jul 2010
Transfer Count:	1
Actual ARF Paid:	\$42,241.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Jul 2020
PARF Rebate Amount:	\$21,120.00

Intended COE Rebate Details

COE Expiry Date:	20 Jul 2020
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$39,911.00
COE Rebate Amount:	\$2,124.00
Total Rebate Amount:	\$23,244.00

The information contained herein is correct as at 08 Jan 2020

OK

MV - \$30,000

Rebate - \$23,244

Repair Net Value : \$6756.

Everyone says that the 3-cylinder engine is no...

Mazda CX-30

Ace Gt - Best Value
Durable Protections - t...

bmw 523Price RangeDepreciation2010Vehicle Type\$2SearchAdvanced Search

Home > Used Cars > Kimhung Hegary Holding(5) > BMW 5 Series 523i

BMW 5 Series 523i

- OverviewFinancialInsuranceAccessoriesSimilarResearchPhotosMap

Price	\$30,888		
Depreciation	N.A.	Reg Date	30-Jun-2010 (5mths 14days COE left)
Mileage	105,500 km (11k /yr)	Manufactured	2010
Road Tax	\$1,795 /yr	Transmission	Auto
Derog Value	\$20,854 as of today (changed)	OMV	\$38,161
COE	\$38,002	ARF	\$38,161
Engine Cap	2,497 cc	Power	150.0 kW (201 bhp)
Curb Weight	1,650 kg	No. of Owners	3
Type of Vehicle	Luxury Sedan		

Features
3.5L Inline 6 Cylinders Engine, 201Bhp, ABS, SRS Airbags, Cruise Control, Multi Function Steering, Keyless Entry, Push Start. View specs of the BMW 5 Series Sedan

Accessories
Factory Audio Player System, Electric Memory Seats, Keyless Entry/Start, Reverse Camera, Electrical Retractable Side Mirrors, Fog Lights.

Description
Cheapest Only \$30.8k! Actual 2 Ownership. Maintain Only By Optima Works In Superb Condition Guaranteed! 3M Matte Wrapping, Front/Rear BMW Eye, 20" Pirelli Zero Tires On US Vossen Forged Wheels. Good For Short Term Or Decide On Your COE Renewal Direction, Jan 2020 New 10 Yrs POP \$39,463.00. One Of The Best Reliable BMW Luxury Model Not To Be Missed! Daily Viewing Via Appointment Only, Thanks.

Category
BMW Car, Premium Aft Car

Status
Available


- Resources
- STW

Vehicle Evaluation
Afraid of lemons? Request to have this car evaluated professionally. Find out more
- Car Valuation - Free
Find out the market value of your existing car for free. Get started

Posted on: 11-Jun-2020 | Last Updated on: 11-Jan-2020

Upfront Payment		+ more Financial info
Transfer Fee	\$25	
Down Payment	\$9,256 (example)	Maximum 20% Loan
1st Instalment	\$4,378	Based on 2.98% interest rate
Insurance	\$666 onwards (Get a quote) Extra 15% Off for MINDEF, MHA & PGGIS policyholders Quote assumes a standard profile. "Get a quote" for exact figure.	
Total Upfront Payment	\$14,335	Check with seller for exact figure

Compare



Seller Information
Kimhung Hegary Holding(5)
8 vehicles for sale, 7 sold in past 3 mths
9 Marshall Road
Tel: 66838002
Search Cars Nearby

PRE-REPAIR INSPECTION REQUEST – SKL2791T vs SJA8718L (OI) on D.O.A.: 28/12/2019

From: Hor, Yinrul
To: 'assignments@kkauto.com', Admin A (admin-a@kkauto.com)
Cc: Fong, Andy-SY, Fan, Winnie-LW, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Parthiban, Theerthan, Subramaniam, Divyashni
Sent: 11/8/2020 10:47:04 AM
Attachments: CAA Report - SKL2791T P12; CAA Report - SKL2791T P12

Hi,

Please refer to the enclosed request from **Hua Tiong Contractor Pte Ltd**.

Claim no : 7030621968SG003
Case Owner : Lee Ming Yao

If you have any queries/concerns, please let us know.
*Kindly assist to assign **Mohamad Taufikh** as Single Joint Expert as requested.*

Thanks & Regards,

Hor Yin Rul (Viviane)
AIG
FNOL Adjuster I
Singapore AUTO Claims

Tel: 8001298558 | Ext: 1092208
Yinrul.Hor@aig.com | www.aig.sg

From: kemmy.su@huatong.com.sg <kemmy.su@huatong.com.sg>
Sent: Wednesday, January 8, 2020 8:57 AM
To: Hor, Yinrul <Yinrul.Hor@aig.com>
Cc: Fong, Andy-SY <Andy-SY.Fong@aig.com>; Fan, Winnie-LW <Winnie-LW.Fan@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Azlan, Syazairdina <Syazairdina.Azlan@aig.com>; Chan, Yoke Shi <yokeshi.chan@aig.com>; Lim, Sheng Yang <ShengYang.Lim@aig.com>; Mithoosingh, Aashweenjeetkaur <Aashweenjeetkaur.Mithoosingh@aig.com>; Parthiban, Theerthan <Theerthan.Parthiban@aig.com>; Subramaniam, Divyashni <Divyashni.Subramaniam@aig.com>; douglas.ng@huatong.com.sg; 'Au Sook Kwan' <sookkwan.au@huatong.com.sg>
Subject: [EXTERNAL] RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJA8718L AND SKL2791T ON 28/12/2019

This message is from an external sender; be cautious with links and attachments.

Dear Yinrul,

Kindly inform Mr Mohamad Taufikh from LKK Auto Consultants Pte Ltd to conduct the Pre-Repair Inspection.

Date : 13th Jan 2020
Time : 1400hrs
Venue : 9 Benoi Crescent

Pls contact myself at HP number : 84487093 to confirm.

Thank you
Regards,
Kemmy

From: Hor, Yinrul <Yinrul.Hor@aig.com>
Sent: Monday, January 06, 2020 10:37 AM
To: kemmy.su@huatong.com.sg
Cc: Fong, Andy-SY <Andy-SY.Fong@aig.com>; Fan, Winnie-LW <Winnie-LW.Fan@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Azlan, Syazairdina <Syazairdina.Azlan@aig.com>; Chan, Yoke Shi <yokeshi.chan@aig.com>; Lim, Sheng Yang <ShengYang.Lim@aig.com>; Mithoosingh, Aashweenjeetkaur <Aashweenjeetkaur.Mithoosingh@aig.com>; Parthiban, Theerthan <Theerthan.Parthiban@aig.com>; Subramaniam, Divyashni <Divyashni.Subramaniam@aig.com>
Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJA8718L AND SKL2791T ON 28/12/2019

This is a secure, encrypted message. To read it, open the attachment.

Este es un mensaje cifrado y seguro. Para leerlo, abra el archivo adjunto.

Esta é uma mensagem criptografada segura. Para lê-lo, abra o anexo.

Ceci est une sécurité, un message crypté. Pour le lire, ouvrez la pièce jointe.

これは暗号化された電子メールです。閲覧には添付ファイルを開いてください。

[Click here](#) by 2020-01-12 21:37 EST to read your message.
After that, open the attachment.

11:41am @ 8/1/2020
P: Kemmy
v: Not In
average on 13/01/2020

[More Info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the individual named. If you have received this email in error or simply do not

Seccured by Proofpoint Encryption, Copyright © 2009-2017 Proofpoint, Inc. All rights reserved.

From: Yinru.Hor@aig.com
To: kemmy.su@huatong.com.sg
Cc: Andy-SY.Fong@aig.com ,Winnie-LW.Fan@aig.com ,NoorMariessa.AbuKassim@aig.com ,Syazaidina.Azlan@aig.com ,yokeshi.chan@aig.com ,ShengYang.Lim@aig.com ,Aashweenjeetkaur.Mithoosinghi@aig.com ,Theerthan.Parthiban@aig.com ,Divyashri.Subramaniam@aig.com
Subject: aigencrypt PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJAB71BL AND SKL2791T ON 28/12/2019
Date: Mon, 6 Jan 2020 02:37:08 +0000
Without Prejudice

Your Reference : SKL2791T
Our Reference : 7030621968SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufik	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Hor Yin Rui (Vivienne)
AIG
FNOL Adjuster I
Singapore AUTO Claims

Tel: 8001206556 | Ext: 1002206
Yinru.Hor@aig.com | www.aig.sg

From: kemmy.su@huatong.com.sg <kemmy.su@huatong.com.sg>
Sent: Monday, January 6, 2020 10:08 AM
To: ClaimsDocManagement <ClaimsDocManagement@aig.com>
Subject: [EXTERNAL] Accident between SJL2791T & SJAB71BL on 28th December 2019 - Arrange for Pre Repair Inspection

This message is from an external sender; be cautious with links and attachments.

Dear Officers,

We would like to arrange for PRI to excess the damages caused by your insured's negligent driving.
Attached with GIA report for your kind attention.

Kindly contact myself at HP: 84487093 on the date & time.

Location of inspection : 9 Benoi Crescent.

Thank you.

Best Regards,
Kemmy Su

Admin Executive (Workshop)

Hua Tong Contractor Pte Ltd
(A subsidiary of Huatong Global Limited)
No.9 Benoi Crescent
Singapore 629872
Tel : (65) 6366 5005
Tel : (65) 6368 1391
Email: Kemmy.gu@huatong.com.sg
Website: www.huatong.com.sg

This message and attachments transmitted with it may contain confidential or may be privileged and are intended solely for the use of the individual or entity to which they are addressed. Any unauthorized dissemination or copying of the email and its attachments, and any use or disclosure of any information contained in them is strictly prohibited. If you received this information contained in them is strictly prohibited. If you received this message to the sender indicating that you have received it in error or delete it from your system. Any views expressed by an individual within the email do not necessarily reflect the views of Huatong Global Limited and its subsidiaries. Please check this message and any attachments transmitted with it for the presence of viruses. Huatong Global Limited accepts no liability for any damage caused by any virus transmitted by this message.

Print Received Message

This mail is associated with :

***SKL2791T (7030621968SG)**
[SJA8718L]
TP
HT EQUIPMENT PTE LTD
Dec 28 2019 9:00PM
[LIM HAI LEONG]
Huafong Contractor Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 18/03/2020 14:44 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$10488.00) - SKL2791T - Claim Handler: Lee, Ming-Yao

Approved:10488.00:Hi, Mandate given. However, please request TP to put company stamp on rental agreement









...CLAIM SUBFOLDER...(Pending for Survey Report)
Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Dec 2019 <a>Edit Reg		08 Jan 2020 00:00 <a>Edit Adj Rpt	S\$8,750.00 <a>Edit Estimates	S\$8,750.00 <a>View Rpt		Pending for Survey Report <a>Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:

LIM HAI LEONG, ID: 57038691G

Main Claimant:

HT EQUIPMENT PTE LTD

Vehicle Reg. No.:

SKL2791T

Date of Loss:

28/12/2019 21:00 - :59
[113 Months and 7 Days From LTA Reg Date (Man Yr)]

Claim Type:

TP / 7030621968SG

Policy/Cover Note No.:

2100488629 (Comprehensive)

Vehicle Reg. No. (Insured):

SJAB718L

Policy No. (Claimant):

Excess:

Repairer:

Huatong Contractor Pte Ltd (HQ) 9 Benoi Crescent, 629972 Pioneer - Tel: 63665005

Handling Insurer:

AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 17/01/2020]

ASSOCIATED MAIL RECEIVED

View All Compose Case Mail

• AIG_SG_EXPRESS (18/03/2020): Alert - Adj Mandate Approved (S\$10488.00) - SKL2791T - Claim Handler: Lee, Ming-...

ALL ASSOCIATED TASKS

View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKL2791T (7030621968SG)
[SJA8718L]
TP
HT EQUIPMENT PTE LTD
Dec 28 2019 9:00PM
[LIM HAI LEONG]
Huatlong Contractor Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

Upload Video

Upload Audio

View

View in Browser

Letters/Correspondences

1 per page

☒

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown	 Edit	

Photos/Images

3 per page

☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/03/20 09:45	Odometer Reading	 Load JPG	☒
2	03/03/20 09:45	General View	 Load JPG	☒
3	03/03/20 09:46	General View	 Load JPG	☒
4	03/03/20 09:46	General View	 Load JPG	☒
5	03/03/20 09:46	General View	 Load JPG	☒
6	03/03/20 09:46	General View	 Load JPG	☒
7	03/03/20 09:46	General View	 Load JPG	☒
8	03/03/20 09:46	General View	 Load JPG	☒
9	03/03/20 09:46	General View	 Load JPG	☒
10	03/03/20 09:46	General View	 Load JPG	☒
11	03/03/20 09:46	General View	 Load JPG	☒
12	03/03/20 09:46	General View	 Load JPG	☒
13	03/03/20 09:46	General View	 Load JPG	☒
14	03/03/20 09:46	General View	 Load JPG	☒
15	03/03/20 09:46	General View	 Load JPG	☒
16	03/03/20 09:46	General View	 Load JPG	☒
17	03/03/20 09:46	General View	 Load JPG	☒
18	03/03/20 09:46	General View	 Load JPG	☒
19	03/03/20 09:46	General View	 Load JPG	☒
20	03/03/20 09:46	General View	 Load JPG	☒
21	03/03/20 09:46	General View	 Load JPG	☒
22	03/03/20 09:46	General View	 Load JPG	☒
23	03/03/20 09:46	General View	 Load JPG	☒

Documentation

1 per page

☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/01/20 15:23	TP GIA REPORT	 Load PDF	
2	08/01/20 15:23	EMAIL FROM AIG DD08012020	 Load PDF	
3	08/01/20 15:23	ACKNOWLEDGEMENT EMAIL TO AIG DD08012020	 Load PDF	
4	16/01/20 11:26	TP ESTIMATE-MARKED	 Load PDF	
5	19/02/20 09:52	LETTER TO OI	 Load PDF	
6	24/02/20 13:55	TP MV AND LTA REBATE	 Load PDF	
7	16/03/20 12:18	RENTAL RECEIPT	 Load PDF	
8	16/03/20 12:18	GIA SEARCH	 Load PDF	
9	16/03/20 12:18	LOD	 Load PDF	
10	19/03/20 09:42	TP RENTAL AGGREMENT	 Load PDF	
11	19/03/20 09:42	EMAIL FROM TP	 Load PDF	
12	20/03/20 09:49	WORKSHOP INVOICE	 Load PDF	
13	20/03/20 09:49	AUTHORISATION TO ACT FORM	 Load PDF	
14	20/03/20 09:49	Release Voucher	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	09/01/20 17:07	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR TEAM _____

THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)

Vehicle No:	SJA8718L (Insd veh)	Model:	BMW 523I 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV (A)
	SKL2791T (TP veh)		
Date of Accident:	28/12/2019		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	57,954.73
Final Repair Cost	:	\$	9,362.50
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	1,123.50 7 days
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	10,488.00
Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability <u>100</u> (%)	
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No BOLA Scenario No:	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Huatong Contractor Pte Ltd	:	\$ 10,488.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

20 Mar
2020

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20000524/T1HS3Q2

Date: 20/03/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100488629
 Claimant: SKL2791T Insured Vehicle No: SJA8718L
 Date of Loss: 28/12/2019 Nature of Claim: TP Claim No: 7030621968SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKL2791T
 Make & Model: BMW 523i, 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV (A) Engine No: 06987469N52B25AF
 Reg. Date: 21/07/2010 (Man. Year: 2010) Chassis No: WBAFP320X0C544845
 Colour: Black Odometer: 101673 km
 Engine Capacity: 2497 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/35Z R19 Rear Tyre Size: 275/35Z R19
 Front Left Side: Roadstone 6 mm Rear Left Side: Roadstone 6 mm
 Front Right Side: Roadstone 6 mm Rear Right Side: Roadstone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	49,603.30	10,130.88	39,472.42	79.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,560.00	2,640.00	1,920.00	42.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	54,163.30	12,770.88	41,392.42	76.42
Approved Total (Overridden) (S\$)		8,750.00		
(S\$)	54,163.30	8,750.00	45,413.30	83.85
+ GST 7.00/7.00% (S\$)	3,791.43	612.50	3,178.93	83.85
Nett Amount (S\$)	57,954.73	9,362.50	48,592.23	83.85
+ Car Rental (7.0 x S\$150.00/day + 7.00% GST) (S\$)		1,123.50		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		10,488.00		

INSPECTION

Date of Assignment: 08/01/2020
 Date Inspected: 13/01/2020 Inspected At: Huatong Contractor Pte Ltd (HQ)
 9 Benoi Crescent
 Singapore 629972
 Estimated Period of Repair: 8.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	Deformed	3,780.00 F	*1,531.00 F
2	1		*REAR BUMPER REINFORCEMENT BAR	Bent	1,374.00 F	*640.93 F
3	1		*REAR BUMPER REINFORCEMENT BRACKET	Not Necessary	796.00 F	*- F
4	1		*REAR BUMPER LIGHT REFLECTOR LH	Not Necessary	174.37 F	*- F
5	1		*REAR BUMPER LIGHT REFLECTOR RH	Not Necessary	174.37 F	*- F
6	1		*TOW HOOK COVER	Missing	156.35 F	*156.35 F
7	1		*REAR PARKING SENSOR ASSY	Not Working	853.45 F	*853.45 F
8	1		*REAR TAIL LAMP ASSY LH	Cut	1,345.76 F	*590.00 F
9	1		*REAR TAIL LAMP ASSY RH	Not Necessary	1,345.76 F	*- F
10	1		*REAR BOOT TAIL ASSY LH	Cut	792.32 F	*420.00 F
11	1		*REAR BOOT TAIL ASSY RH	Not Necessary	792.32 F	*- F
12	1		*REAR BOOT ASSY	Bent	7,845.35 F	*1,866.00 F
13	1		*REAR BOOT MOULDING COVER	Not Necessary	1,321.87 F	*- F
14	1		*REAR BMW EMBLEM	Necessary	257.53 F	*257.53 F
15	1		*REAR BMW MODEL DESIGNATION	Necessary	125.39 F	*125.39 F
16	1		*REAR MUFFLER ASSY	Not Necessary	2,380.48 F	*- F
17	1		*REAR MUFFLER EXHAUST HANGER	Not Necessary	392.51 F	*- F
18	1		*REAR BUMPER UNDERTRAY PROTECTION	Deformed	689.32 F	*175.00 F
19	1		*REAR UNDERTRAY CHASSIS REPAIR PANEL	Repair	11,439.54 F	*- F
20	1		*BOOT PLASTIC MOULDING	Not Necessary	450.18 F	*- F
21	1		*REAR RUBBER SEAL	Twisted	784.23 F	*275.00 F
22	1		*REAR AUTOMATIC MOTOR ASSY	Bent	1,940.65 F	*586.00 F
23	1		*REAR LOCK UPPER	Bent	275.13 F	*275.13 F
24	1		*BOOT LOCK LOWER	Bent	229.10 F	*229.10 F
25	1		*ELECTRONIC ABS MODULE	Activated	9,887.32 F	*2,150.00 F
F=Franchise part.						
				Total Parts (S\$)	49,603.30	10,130.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE/REPLACE	New	3,360.00	1,440.00
2	SPRAY PAINT	New	1,200.00	1,200.00
Gross Labour Cost (\$\$)			4,560.00	2,640.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >