

ASS. REC. BY:

REF: CS/CT1 20000524/AS f3024 Special Instruction:

SUIVOR/DR: Adrian

ASSIGNMENT (Office)

From (Person): Irene Tay of CT1 Date/Time: 8-Jan-2002 2:22p.m

Estimated Cost: Bill to:

OD: TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SJX 845J Insured: GBH 3723L

at Workshop m/s SK Automobile Tel: 81210478

of B Kati Bukit hri 4 #02-46 Premier

Policy No: Claim No: SNM200200091/GBH3723L/JKENE

Sum Insured: Excess:

Make of Veh: D.O.A. 4-Jan-2002
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 8-1-2002 3:24p.m. Person Contacted: Xiong H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SJX 845J - X
	GBH 3723L - NBA/CT1 20000524/4 DCA - 6/4/01/2002

Adrian

ASSIGNMENT

Estimated Cost: _____
 OD / TP / WS / TP RES / OO RES / EVA / RT / MV: _____
 To Inspect Vehicle No: _____
 at Workshop ref: _____
 at: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record): _____
 Make of Veh: _____
 (Policy Condition): _____
 Remark: The veh had commenced its repair at the time of inspection
 Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? Yes or No
 GIA / PR Seen: _____ Consistent? Yes or No
 Est. Repairs: _____ days Res: Yea or No
 Lim Sum: _____ % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle IN / OUT

N/S	O/S

Vch No: STX 845J at Time: 2010 May
 Type: ☒ M Car / ☐ M Cycle / ☐ Bus / ☐ Van / ☐ Heavy / ☐ Taxi / ☐ Prime Mover
 Truck / Trailer: ☐
 Make: Kia Genio Forle Coup 1591
 Colour: Red A/C: ☐ Insured / Std / Nil / NA
 Sp Reading: 137377 Traction: ☐ Insured / Std / Nil / NA
 Eng No: _____
 C/Nr: KNAFW611LA521016
 Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt
 Steering: ☐ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt
 Brake: ☐ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt
 Mod: ☐ Nil / ☒ S/Rim / ☐ STD A/Rim
 Tyre Size: F: 215/45 R17
 R: 215/45 R17
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Kumho
 Front: _____ Rear: _____
 R/Bal: 06 mm R/Bal: 06 mm
 L/Bal: 06 mm L/Bal: 06 mm
 D.O.A: _____ D.O.I: 13/01/20
 Survey held at S.K
 Des. of Damages: ☒ Fnt / ☒ Rear / ☐ O/S / ☐ N/S / ☐ UIC / ☐ Rooftop
 The UIC / Chassis frame / Body Structure affected due to collision

Date / Time: _____ Action / Instruction: TP China
17/02/20 Typ: 4
 Date / Time: _____ Action / Instruction: COE Expiry: 31/01/25
RECEIVED 17 FEB 2020
 mv: 32k Calculation by Adrian
 PV: 16.2K (Estimated, Log Card is renewed)
 Nett: 15.81K
 Adrian Confirmed L/S \$15,000/- @ 15 days with Boss
 \$25,359.46 Red - 63%
 Date/Time, File Path: _____ : ☐ Prel. Report
 : ☒ Final Report
 Days Of Repair: 15
 Resurvey No. of Trip: 1
 Add'l Fees: ☐ Site Insp. ☐
☐ Interview ☐
☐ Test ☐
☐ ☐
 Salary Fee: 270
\$15,000/- 45
270

Summer Lee (LKK Auto)

From: Irene Tay <irene.tay@sg.cntaiping.com>
Sent: Wednesday, 8 January, 2020 3:22 PM
To: SK Admin; SK Admin
Cc: assignments; Admin A
Subject: FW: OUR REF: SNM20D200091/GBH3723L/IRENE - Arrange surveyor for SJX845J & Your Ref:GBH3723L
Attachments: SJX845J ARRANGE.pdf; SJX845J GIA Report.pdf

Dear Sir (LKK) .

We refer to the above matter.

Please get your surveyor to liaise with SK AUTO to conduct survey.

Regards,

Irene Tay
Executive
Claims Department (Motor Division)

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 63896192 | F:(65) 62247478/62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI
Sent: Wednesday, January 8, 2020 11:02 AM
To: Irene Tay <irene.tay@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; admin@skauto.com.sg
Cc: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: OUR REF: SNM20D200091/GBH3723L/IRENE - Arrange surveyor for SJX845J & Your Ref:GBH3723L

Dear Irene,

Please conduct PRs for SJX845J.

Note : officer in charge – Irene Tay 63896192.

***** Kindly quote our reference number when replying.**

Thank you

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Ahson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: SK Admin [<mailto:admin@skauto.com.sg>]

Sent: Tuesday, January 07, 2020 5:38 PM

To: Claims Dept of CTI

Cc: JING XIONG KHOO; md daud nadzim

Subject: Arrange surveyor for SJX845J & Your Ref:GBH3723L

Dear Sir / Mdm,

We the repairers of motor vehicle no. SJX845J
Kindly arrange surveyor to conduct a pre-repair inspection

Location : 8 Kaki Bukit Ave 4#08-46
Premier @ Kaki Bukit
Singapore 415875

Contact No : 8121 0478 Xiong

We appreciate your early reply.
Thanks.

—

Regards,
Huey Lee

SK Automobile Pte Ltd

Tel: 6789 5155 Fax: 6783 5155

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Information	
Owner ID Type:	Singapore NRIC
Owner ID:	350J
Vehicle Details	
Vehicle No.:	SJX845J
Vehicle to be Exported:	Yes
Intended Deregistration Date:	13 Jan 2020
Vehicle Make:	KIA
Vehicle Model:	CERATO FORTE KOUP 1.6 SX MT D/AB 2DR SR
Primary Colour:	Red
Manufacturing Year:	2010
Engine No.:	G4FCAH371061
Chassis No.:	KNAFW611LA5211016
Maximum Power Output:	92.7 kW (124 bhp)
Open Market Value:	\$13,822.00
Original Registration Date:	13 May 2010
First Registration Date:	13 May 2010
Transfer Count:	2
Actual ARF Paid:	\$13,822.00
Intended PARF Eligibility	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 May 2020
PARF Rebate Amount:	\$6,911.00
Intended COE Details	
COE Expiry Date:	31 Jan 2025
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$16,184.00
COE Rebate Amount:	\$860.00
Total Rebate Amount:	\$7,771.00
Remarks	

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 13 Jan 2020

OK



CONNECTING CAR BUYERS & SELLERS.
We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)





Post an Advertisement
Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

 Post an Ad
  Advertiser Login
  Ways of Selling

New 5 Years Renewal COE Toyota Altis 1.6A



2.98% P.A. \$0 down, \$0 admin, mthly from \$488, 2 Yrs warranty engine, gearbox
CVT Gearbox - StarAd



Republic Auto | CERTIFIED PRE-OWNED MERCEDES BENZ



[View our Cars](#)

Browse by Category 
[Save Search](#)
[Print](#)
[Back \(1 2 3 4 \) Next >](#)
 Sort by Date Posted  20 results/page 

61 vehicles

Search

[Advanced Search](#)  [Search](#) [View All](#)

Search Selection	koup	Any	Any	Any	Any	Any	Any	Any	Available
------------------	------	-----	-----	-----	-----	-----	-----	-----	-----------



☐ **Kia Cerato Forte Koup 1.6A SX (New 5-yr COE)**

\$31,800 **\$6,350 /yr** **21-Dec-2009** **1,591 cc** **-** **Sports** **Available**

Most Sporty Koup With Sunroof, Best Unit With Free Extended Warranty. Don't Miss It. Selling Cheap! Hurry! View Now. Up To 100% Flexible Loan Of The Car Price Available. We Provide Lowest Interest Rate. Flexible Loan And High Trade In Are Available. Meet Our Friend...

Classic Credit Pte Ltd

 [Posted: 11-Dec-2019](#) [Tags: 2009 Kia Cerato, 2009 Kia Cerato, Kia Cerato, Kia Cerato, Kia Cerato, Kia Cerato, Kia Cerato, Kia Cerato](#)



☐ **Kia Cerato Forte Koup 1.6A SX Sunroof (New 5-yr COE)**

\$33,800 **\$6,750 /yr** **04-Jan-2010** **1,591 cc** **136,000 km** **Sports** **Available**

Rare 1 Owner Unit With New Paintwork. Bank/In House 100% Immediate Loan Approval! Very Well Maintained Unit With Weekly Cleaning And Upholstery Care! Vehicle Always Park In Shelter Area To Protect Original Paintwork! We Provide Value Integrity Passion Only At V.I.P...

 [Posted: 17-Dec-2019](#) [Tags: 2010 Kia Cerato, 2010 Kia Cerato, Kia Cerato, Kia Cerato, Kia Cerato, Kia Cerato, Kia Cerato, Kia Cerato](#)



☐ **Kia Cerato Forte Koup 1.6M SX (New 5-yr COE)**

\$29,800 **\$5,950 /yr** **05-Jan-2010** **1,591 cc** **86,000 km** **Sports** **Available**

Free CNY Promo With Attractive Freebies Including Grooming, Servicing, Petrol Vouchers And Many More! COE Specialist With More Than 200 Positive Reviews And 100% Immediate Loan Approval! Highest Specs Topped With Full Bodykit! Very Well Maintained By Previous O...

 [Posted: 05-Jan-2020](#) [Tags: 2010 Kia Cerato, 2010 Kia Cerato, Kia Cerato, Kia Cerato, Kia Cerato, Kia Cerato, Kia Cerato, Kia Cerato](#)



☐ **Kia Cerato Forte Koup 1.6M SX (New 5-yr COE)**

\$32,800 **\$6,550 /yr** **05-Jan-2010** **1,591 cc** **-** **Sports** **Available**

1 Year Extended Engine And Gear Box Warranty! 100% Or Bank Loan With Attractive Interest Rate Available! Low Mileage! Come With After Market Exhaust With Cert, Adjustable Sport Suspension And Gauges. Engine And Gearbox (Great), Undercarriage (Good), Exterior...

 [Posted: 24-Dec-2019](#) [Tags: 2010 Kia Cerato, 2010 Kia Cerato, Kia Cerato, Kia Cerato, Kia Cerato, Kia Cerato, Kia Cerato, Kia Cerato](#)



Kia Cerato Koup is now turbocharged

The second generation of Kia's Cerato Koup promises more fun and more power with the help of a 1.5-litre turbocharged engine.

[Read this article](#)



☐ **Kia Cerato Forte Koup 1.6A SX Sunroof (COE till 08/2024)**

\$28,800 **\$6,210 /yr** **06-Jan-2010** **1,591 cc** **139,000 km** **Sports** **Available**

New 6Mth Rd Tax, Very Well Kept Interior, Leather, Dashboard, Paintwork Etc. 2 Months Old New Tyre, Major Service Done With Receipts. Loan/Trade In Available. View By Appointment. Please SMS/Call.

 [Posted: 13-Jan-2020](#) [Tags: 2010 Kia Cerato, 2010 Kia Cerato, Kia Cerato, Kia Cerato, Kia Cerato, Kia Cerato, Kia Cerato, Kia Cerato](#)



☐ **Kia Cerato Forte Koup 1.6M SX (OPC) (New 5-yr COE)**

\$29,800 **\$5,950 /yr** **06-Jan-2010** **1,591 cc** **-** **Sports** **Available**

Low Ownership. Original Paint Work And Accident Free. Weekends Car, Well Taken Care And Under Use By Previous Owner. Well Maintained Interior, Nice Leather Seats. Always Service On Time. Smooth Transmission And Engine In Excellent Condition. Don't Miss O...

 [Posted: 20-Jan-2020](#) [Tags: 2010 Kia Cerato, 2010 Kia Cerato, Kia Cerato, Kia Cerato, Kia Cerato, Kia Cerato, Kia Cerato, Kia Cerato](#)

☐ **Kia Cerato Forte Koup 1.6A SX (New 5-yr COE)**

\$32,800 **\$6,550 /yr** **06-Jan-2010** **1,591 cc** **96,000 km** **Sports** **Available**

Free CNY Offer With Attractive Freebies Including Grooming, Servicing, Petrol Vouchers And Many More! COE Specialist With More Than 200 Positive Reviews Offering 6 Months Warranty And Road Tax Just For You! 100% Immediate Loan Approval! Highest Specs Topped...

 [Posted: 10-Feb-2020](#) [Tags: 2010 Kia Cerato, 2010 Kia Cerato, Kia Cerato, Kia Cerato, Kia Cerato, Kia Cerato, Kia Cerato, Kia Cerato](#)

[Compare](#)

1/6/2020

PARF/COE Rebate Enquiry

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 350J

Vehicle Details

Vehicle No.: SJX845J
Vehicle to be Exported: No
Intended Deregistration Date: 06 Jan 2020
Vehicle Make: KIA
Vehicle Model: CERATO FORTE KOUP 1.6 SX MT D/AB 2DR SR
Primary Colour: Red
Manufacturing Year: 2010
Engine No.: G4FCAH371061
Chassis No.: KNAFW611LA5211016
Maximum Power Output: 92.7 kW (124 bhp)
Open Market Value: \$13,822.00
Original Registration Date: 13 May 2010
First Registration Date: 13 May 2010
Transfer Count: 2
Actual ARF Paid: \$13,822.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 12 May 2020
PARF Rebate Amount: \$6,911.00

Intended COE Rebate Details

COE Expiry Date: 12 May 2020
COE Category: A - Car (1600cc & below)
COE Period(Years): 10
QP Paid: \$26,102.00
COE Rebate Amount: \$912.00
Total Rebate Amount: \$7,823.00

The information contained herein is correct as at 06 Jan 2020.

OK

MTC420002219 / TC AutoClinic Pte Ltd - Loh Yang
ENTRY DATE & TIME: 06/01/2020 18:29
SUBMITTED BY: Chua Leng Leng

CHINA
TAPPING

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 06/01/2020 16:29
Date Of Accident 04/01/2020 16:45
Exact Location Of Accident PIE TOWARDS CHANGI NEAR LP 668A
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJX845J
Insured/Policyholder
Name Of Registered Owner TEO XIN YI
NRIC No SXXXX350J
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-96964231
Alternative Phone No OFFICE-96964231

Vehicle Particulars

Manufacturer KIA
Model FORTE KOUP-1.6 SX (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company AUTO & GENERAL INSURANCE (SINGAPORE) PTE. LIMITED.
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number P10187572R00
Cover Note Number

Driver

Name of Driver TEO XIN YI
NRIC No SXXXX350J
Date Of Birth 12/07/1987
Occupation OUTDOOR
Date Of Driving Pass 26/12/2007
Driving Experience 12 YEARS AND 0 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-96964231
Fax Number
Contact Number OFFICE-96964231
Email Address NOEMAIL

Address 402 FAJAR ROAD #10-221
 Postcode 670402
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 4
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? NO
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBH3723L
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number GBG8023X

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

SLA6846P

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

TEO XIN YI

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SJX845J

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be filled out by the Insured Driver.
3. Information provided in this Form must be true and correct. Any wilful misrepresentation or withholding of material facts may allow the insurer to refuse to pay the claim.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 04/01/2020 AT 1645 HRS I WAS DRIVING ALONG PIE TWDS
 CHANGI AS THE FRONT VEHICLE STOPPED, I FOLLOW SUIT.
 SUDDENLY THERE WAS A GREAT IMPACT FROM THE REAR, IT
 PUSHED MY VEHICLE FWD WITH GREAT FORCE.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:

UATMOC SketchPlanForm_V9

Driver's Signature
 (if driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

SK Automobile Pte Ltd
(Co Reg. No. 201500047H)
23 Kaki Bukit Ave 4, #03-01
Vicom Inspection Centre (S415933)
Tel: 6789 5155 Fax : 6783 5155

TO	: CHINA TAIPING	DATE	: 7-Jan-20
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT :			
<u>OWNER'S PARTICULAR</u>		<u>VEHICLE DETAILS</u>	
NAME	:	VEHICLE NO	: SJX845J
ADDRESS	: Shirley	MODEL	: KIA FORTE K3
TEL. NO.	:	CHASSIS NO	:
OWNER'S INSURANCE	:	KNAFW611LAS211016	
POLICY NO.	:		
<u>ACCIDENT DETAILS</u>	DATE :		
	TIME :		
THIRD PARTY REQUESTOR / CONTACT : DAUD/93911482			

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BONNET repaired Dented	1	\$ 874.00	\$ 874.00
2	BONNET WEATHERSTRIP ?	1	\$ 65.00	\$ 65.00
3	BONNET HINGE	2	\$ 45.00	\$ 90.00
4	BONNET LOCK	1	\$ 153.00	\$ 153.00
5	BONNET LOCK CABLE	1	\$ 155.00	\$ 155.00
6	FRONT BUMPER Dented	1	\$ 758.00	\$ 758.00
7	FRONT BUMPER BRACKET	1	\$ 38.00	\$ 38.00
8	FRONT BUMPER REINFORCEMENT Bent	1	\$ 485.00	\$ 485.00
11	FRONT BUMPER SPONGE	1	\$ 189.00	\$ 189.00
14	FRONT BUMPER LOWER GRILLE	1	\$ 185.00	\$ 185.00
15	FRONT BUMPER LOWER GRILLE GARNISH	1	\$ 226.00	\$ 226.00
15	FRONT BUMPER FOG LAMP	2	\$ 389.00	\$ 778.00

✓
+
+
+
+
✓
+
306
✓
+
✓
340

* 16	FRONT BUMPER FOGLAMP GARNISH <i>new</i>	2	\$ 86.00	\$ 172.00	+
17	FRONT BUMPER SIDE RETIANER <i>new</i>	2	\$ 21.00	\$ 42.00	✓
* 19	FRONT BUMPER LOWER COVER <i>new</i>	1	\$ 321.00	\$ 321.00	+
* 20	HEADLAMP <i>LH RH Cooled</i>	2	\$ 684.00	\$ 1,368.00	✓ 1368
* 21	HEADLAMP LOWER BRACKET <i>Best</i>	1	\$ 146.00	\$ 146.00	✓
22	FRONT SUPPORT PANEL <i>Cooled</i>	1	\$ 845.00	\$ 845.00	✓ 485
24	FRONT SUPPORT PANEL TOP GARNISH <i>new</i>	1	\$ 220.00	\$ 220.00	+
26	AIRCON PRESSURE PIPE <i>new</i>	1	\$ 423.00	\$ 423.00	+
27	AIRCON SUCTION PIPE	1	\$ 421.00	\$ 421.00	+
29	AIR DUCT <i>Cooled</i>	1	\$ 198.00	\$ 198.00	✓
* 31	RADIATOR <i>Dented</i>	1	\$ 1,404.00	\$ 1,404.00	✓ 746
32	RADIATOR TOP BRACKET <i>new</i>	1	\$ 65.00	\$ 65.00	+
* 34	RADIATOR FAN COWLING WITH MOTOR <i>new Cooled</i>	1	\$ 845.00	\$ 845.00	✓ 659
36	AIR CONDENSOR <i>Best</i>	1	\$ 1,224.90	\$ 1,224.90	✓ 852
* 38	AIR ARCH GARNISH <i>new</i>	2	\$ 65.00	\$ 130.00	+
39	HORN <i>new</i>	1	\$ 189.00	\$ 189.00	+
41	FRONT FENDER <i>Repl.</i>	2	\$ 689.00	\$ 1,378.00	+
* 43	FRONT FENDER COWLING <i>new</i>	2	\$ 160.00	\$ 320.00	+
44	DASHBOARD <i>new</i>	1	\$ 1,542.00		+
46	BOOT LID <i>Dented</i>	1	\$ 894.50	\$ 894.50	✓
* 48	BOOT LID LAMP <i>RH Cooled</i>	2	\$ 785.00	\$ 1,570.00	✓ 785 325
49	BOOT LID STOPPER <i>new</i>	2	\$ 19.00	\$ 38.00	+
* 51	BOOT LID HINGE <i>new</i>	2	\$ 148.00	\$ 296.00	+
53	BOOT LID INSULATOR <i>new</i>	1	\$ 231.00	\$ 231.00	+
55	BOOT LID WEATHER STRIP <i>Cut</i>	1	\$ 148.00	\$ 148.00	✓
56	BOOT LID LOCK <i>Repl.</i>	1	\$ 174.00	\$ 174.00	✓
* 58	BOOT LID DETECTOR <i>Missing</i>	1	\$ 312.00	\$ 312.00	✓ 78 970
60	TAIL LAMP <i>Cut</i>	2	\$ 788.00	\$ 1,576.00	✓
* 61	TAIL LAMP PANEL <i>RH Dented</i>	2	\$ 389.00	\$ 778.00	✓ 389 115
63	REAR BUMPER <i>Dented</i>	1	\$ 712.00	\$ 712.00	✓
65	REAR BUMPER LOWER LIP <i>Dented</i>	1	\$ 589.00	\$ 589.00	✓
* 66	REAR BUMPER BRACKET <i>Repl.</i>	5	\$ 22.00	\$ 110.00	✓
68	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 16.00	\$ 32.00	✓
70	REAR BUMPER REINFORCEMENT <i>Cooled</i>	1	\$ 448.00	\$ 448.00	✓ 348
72	REAR BUMPER SPONGE <i>Cooled</i>	1	\$ 188.00	\$ 188.00	✓
* 73	REAR BUMPER REFLECTOR <i>nt</i>	2	\$ 85.00	\$ 170.00	✓
* 75	REAR REVERSE SENSOR <i>2pl. 2plugs</i>	4	\$ 354.00	\$ 1,416.00	✓ 440

* *After Reinforcement Bracket # 75 x 2 = \$ 150.00 ✓*
Best

77	REAR FENDER <i>Del</i>	1	\$ 1,045.00	\$ 4795.00	1045
78	REAR FENDER INNER COWLING <i>new</i>	2	\$ 120.00	\$ 240.00	+
80	REAR FENDER INNER TRIM <i>new</i>	2	\$ 489.00	\$ <u>978.00</u>	490
82	REAR WINDSCREEN MOULDING <i>new</i>	1	\$ 189.00	\$ 189.00	✓
83	REAR END PANEL <i>Del</i>	1	\$ 845.00	\$ <u>845.00</u>	565
85	REAR END PANEL TOP GARNISH <i>Del</i>	1	\$ 143.00	\$ 143.00	✓
87	REAR FLOOR PANEL <i>Regis</i>	1	\$ 1,201.00	\$ 1,201.00	+
* 89	REAR FLOOR PANEL TOP BOARD <i>Del</i>	1	\$ 358.00	\$ <u>358.00</u>	269
* 90	REAR TOOLS SPONGE <i>new</i>	1	\$ 258.00	\$ 258.00	+
92	REAR EXHAUST PIPE <i>new</i>	1	\$ 985.00	\$ 985.00	+
94	REAR EXHAUST INSULATOR <i>new</i>	1	\$ 189.00	\$ 189.00	+
95	REAR EXHAUST MOUNTING <i>new</i>	4	\$ 18.00	\$ 72.00	+

15518.50
13966.65

TOTAL PRICE \$ 30,644.40
LESS 10% \$ 3,064.44
SUB TOTAL PRICE \$ 27,579.96

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT NUMBER PLATE <i>Missing</i>	1	\$ 50.00	\$ 50.00	-
2	FRONT BUMPER CLIP <i>new</i>	10	\$ 6.50	\$ 65.00	30
3	FRONT BUMPER GRILLE <i>new</i>	1	\$ 1,000.00	\$ <u>1,000.00</u>	350
4	CENTER GRILLE CLIP <i>new</i>	3	\$ 6.50	\$ 19.50	-
5	FRONT FENDER INNER COWLING CLIP RH <i>new</i>	12	\$ 6.50	\$ 78.00	+
6	RADIATOR COOLANT <i>new</i>	1	\$ 80.00	\$ <u>80.00</u>	40
7	REAR NUMBER PLATE <i>Best</i>	1	\$ 50.00	\$ 50.00	-
8	REAR BUMPER CLIPS <i>new</i>	10	\$ 6.50	\$ 65.00	30
9	BOOT LID SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00	+
10	BOOT LID INSULATOR CLIP <i>new</i>	10	\$ 6.50	\$ 65.00	+
11	TAIL LAMP CLIP <i>new</i>	4	\$ 8.00	\$ 32.00	-
12	TAIL LAMP PANEL SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00	+
13	EXHAUST CHROME <i>new</i>	1	\$ 150.00	\$ 150.00	+
14	REAR FENDER INNER COWLING CLIP <i>new</i>	18	\$ 6.50	\$ 117.00	+
15	REAR FENDER INNER TRIM CLIP <i>new</i>	18	\$ 6.50	\$ <u>117.00</u>	60
16	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 120.00	\$ 120.00	60
17	REAR END PANEL TOP GARNISH CLIP <i>new</i>	4	\$ 6.50	\$ 26.00	10
18	REAR FLOOR PANEL INSULATION SEAL <i>new</i>	1	\$ 250.00	\$ 250.00	180
19	REAR WINDSCREEN SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00	60

20) Accura ~~450~~ 380
2nd

20	REAR WINDSCREEN INNER SEAL <i>m</i>	1	\$ 80.00	\$ 80.00 <i>40</i>
----	-------------------------------------	---	----------	--------------------

1391.50

TOTAL \$ 2,604.50

CLAIM DETAILS: FRONT LABOUR AND SPRAY PAINTING

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$1,400.00	800	
2	TO SPRAY PAINT AFFECTED AREA	\$1,400.00	600	
3	TUFF COAT	\$250.00	x	
4	WIRING CHECK	\$100.00	30	
5	REMOVE AND REFIX AIRCON CONDENSER AND REFILL AIRCON GAS	\$120.00	60	
6	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$50.00	✓	
7	REFOCUS HEADLAMP BEAM	\$80.00	x	
8	REMOVE AND REFIT DASHBOARD WITH WIREHARNESS	\$600.00	x	

1540

CLAIM DETAILS: REAR LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, WELDING GRAZING, CUT, JOIN, STRAIGHTEN ALL AFFECTED PARTS	\$ 2,200.00	1400	
2	TO PUTTY, POLISH, SPRAY PAINT, WAX ALL AFFECTED PANELS	\$ 1,800.00	1200	
3	TUFF COAT	\$ 250.00	80	
4	WIRING CHECK	\$ 120.00	30	
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 200.00	80	
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50	
7	REAR CHASSIS ALIGNMENT	\$ 350.00	x	

8	TRANSFER BOOTLID MECHANISM	\$ 80.00	✓	
	REMOVE AND REFIX REAR WINDSCREEN GLASS	\$ 120.00	✓	
9	CONDUCT WATER LEAKAGE TEST	\$ 100.00	x	
10	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 180.00	x	
11	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x	

TOTAL \$ 9,660.00 3040

ESTIMATE REPORT

TOTAL PARTS COST : \$ 30,184.46
TOTAL LABOUR COST : \$ 9,660.00
TOTAL REPAIR COST : \$ 39,844.46

APPROVED DETAILS

EXCESS :
NO. OF WORKING DAYS :
RE-SURVEY :
PART BY PART OR LUMP SUM :
DATE & TIME OF SURVEY :
SURVEYED BY :
CONTACT NUMBER :
FAX NUMBER :

40359.46 Adrian L
2/5/13/01/20

15 Pays

total 18838.15

2/5 15K (Nett Value)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

41141 36

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Jan 2020		08 Jan 2020 15:33 Edit Adj Rpt	S\$15,000.00 Edit Estimates	S\$15,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured: -, Co. Reg. No.: -									
Main Claimant: TEO XIN YI									
Vehicle Reg. No.: SJX845J		Date of Loss: 04/01/2020 16:00 - :59 [115 Months and 22 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM20D200091C02		Policy/Cover Note No.: DMCVSN18155319011							
Vehicle Reg. No. (Insured): GBH3723L		Policy No. (Claimant):							
		Excess: S\$0.00							
Repairer: Sk Automobile Pte Ltd () 8 Kaki Bukit Ave 4, #08-46 Premier @ Kaki Bukit, 415875 Kaki Bukit - Tel: 8121 0478									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 17/01/2020]									
Adj Asg. Remarks: PLEASE SURVEY AND REVERT									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJX845J (SNM20D200091C02)**
[GBH3723L]
TP
TEO XIN YI
Jan 4 2020 4:00PM
[-]
Sk Automobile Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/02/20 10:01	General View	 Load JPG	☒
2	17/02/20 10:01	General View	 Load JPG	☒
3	17/02/20 10:01	General View	 Load JPG	☒
4	17/02/20 10:01	General View	 Load JPG	☒
5	17/02/20 10:01	General View	 Load JPG	☒
6	17/02/20 10:01	General View	 Load JPG	☒
7	17/02/20 10:01	General View	 Load JPG	☒
8	17/02/20 10:01	General View	 Load JPG	☒
9	17/02/20 10:01	General View	 Load JPG	☒
10	17/02/20 10:01	General View	 Load JPG	☒
11	17/02/20 10:01	General View	 Load JPG	☒
12	17/02/20 10:01	General View	 Load JPG	☒
13	17/02/20 10:01	General View	 Load JPG	☒
14	17/02/20 10:01	General View	 Load JPG	☒
15	17/02/20 10:01	General View	 Load JPG	☒
16	17/02/20 10:01	General View	 Load JPG	☒
17	17/02/20 10:01	General View	 Load JPG	☒
18	17/02/20 10:01	General View	 Load JPG	☒
19	17/02/20 10:01	General View	 Load JPG	☒
20	17/02/20 10:01	General View	 Load JPG	☒
21	17/02/20 10:01	General View	 Load JPG	☒
22	17/02/20 10:01	General View	 Load JPG	☒
23	17/02/20 10:01	General View	 Load JPG	☒
24	17/02/20 10:01	General View	 Load JPG	☒
25	17/02/20 10:01	General View	 Load JPG	☒
26	17/02/20 10:01	General View	 Load JPG	☒
27	17/02/20 10:01	General View	 Load JPG	☒
28	17/02/20 10:01	General View	 Load JPG	☒
29	17/02/20 10:01	General View	 Load JPG	☒
30	17/02/20 10:01	General View	 Load JPG	☒
31	17/02/20 10:01	General View	 Load JPG	☒
32	17/02/20 10:01	General View	 Load JPG	☒
33	17/02/20 10:01	General View	 Load JPG	☒
34	17/02/20 10:01	General View	 Load JPG	☒
35	17/02/20 10:01	General View	 Load JPG	☒
36	17/02/20 10:01	General View	 Load JPG	☒
37	17/02/20 10:01	General View	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	17/02/20 10:01	General View	 Load JPG	☒
39	17/02/20 10:01	General View	 Load JPG	☒
40	17/02/20 10:01	General View	 Load JPG	☒
41	17/02/20 10:01	General View	 Load JPG	☒
42	17/02/20 10:01	General View	 Load JPG	☒
43	17/02/20 10:01	General View	 Load JPG	☒
44	17/02/20 10:01	General View	 Load JPG	☒
45	17/02/20 10:01	General View	 Load JPG	☒
46	17/02/20 10:01	General View	 Load JPG	☒
47	17/02/20 10:01	General View	 Load JPG	☒
48	17/02/20 10:01	General View	 Load JPG	☒
49	17/02/20 10:01	General View	 Load JPG	☒
50	17/02/20 10:01	General View	 Load JPG	☒
51	17/02/20 10:01	General View	 Load JPG	☒
52	17/02/20 10:01	General View	 Load JPG	☒
53	17/02/20 10:01	General View	 Load JPG	☒
54	17/02/20 10:01	General View	 Load JPG	☒
55	17/02/20 10:01	General View	 Load JPG	☒
56	17/02/20 10:01	General View	 Load JPG	☒
57	17/02/20 10:01	General View	 Load JPG	☒
58	17/02/20 10:01	General View	 Load JPG	☒
59	17/02/20 10:01	General View	 Load JPG	☒
60	17/02/20 10:01	General View	 Load JPG	☒
61	17/02/20 10:01	General View	 Load JPG	☒
62	17/02/20 10:01	General View	 Load JPG	☒
63	17/02/20 10:01	General View	 Load JPG	☒
64	17/02/20 10:01	General View	 Load JPG	☒
65	17/02/20 10:01	General View	 Load JPG	☒
66	17/02/20 10:01	General View	 Load JPG	☒
67	17/02/20 10:01	General View	 Load JPG	☒
68	17/02/20 10:01	General View	 Load JPG	☒
69	17/02/20 10:01	General View	 Load JPG	☒
70	17/02/20 10:01	General View	 Load JPG	☒
71	17/02/20 10:01	General View	 Load JPG	☒
72	17/02/20 10:01	General View	 Load JPG	☒
73	17/02/20 10:01	General View	 Load JPG	☒
74	17/02/20 10:01	General View	 Load JPG	☒
75	17/02/20 10:01	General View	 Load JPG	☒
76	17/02/20 10:01	General View	 Load JPG	☒
77	17/02/20 10:01	General View	 Load JPG	☒
78	17/02/20 10:01	General View	 Load JPG	☒
79	17/02/20 10:01	General View	 Load JPG	☒
80	17/02/20 10:01	General View	 Load JPG	☒
81	17/02/20 10:01	General View	 Load JPG	☒
82	17/02/20 10:01	General View	 Load JPG	☒
83	17/02/20 10:01	General View	 Load JPG	☒
84	17/02/20 10:01	General View	 Load JPG	☒
85	17/02/20 10:01	General View	 Load JPG	☒
86	17/02/20 10:01	General View	 Load JPG	☒
87	17/02/20 10:01	General View	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	17/02/20 10:01	General View	 Load JPG	☒
89	17/02/20 10:01	General View	 Load JPG	☒
90	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
91	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
92	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
93	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
94	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
95	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
96	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
97	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
98	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
99	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
100	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
101	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
102	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
103	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
104	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
105	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
106	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
107	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
108	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
109	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
110	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
111	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
112	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
113	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
114	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
115	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
116	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
117	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
118	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
119	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
120	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
121	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
122	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
123	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
124	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
125	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
126	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
127	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
128	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
129	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
130	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
131	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
132	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
133	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
134	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
135	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
136	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
137	17/02/20 10:02	Reinspection Photo	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
138	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
139	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
140	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
141	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
142	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
143	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
144	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
145	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
146	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
147	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
148	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
149	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
150	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
151	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
152	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
153	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
154	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
155	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
156	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
157	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
158	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
159	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
160	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
161	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
162	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
163	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
164	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
165	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
166	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
167	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
168	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
169	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
170	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
171	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
172	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
173	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
174	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
175	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
176	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
177	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
178	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
179	17/02/20 10:02	Reinspection Photo	 Load JPG	☒
180	17/02/20 10:02	Reinspection Photo	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20000528/ASF3E2

Date: 17/02/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN18155319011
Claimant Vehicle No:	SJX845J	Insured Vehicle No:	GBH3723L
Date of Loss:	04/01/2020	Nature of Claim:	TP
		Claim No:	SNM20D200091C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJX845J	Engine No:	G4FCAH371061
Make & Model:	KIA FORTE KOUP, 1.6 SX (A)	Chassis No:	KNAFW611LA5211016
Reg. Date:	13/05/2010 (Man. Year: 2010)	Odometer:	137377 km
Colour:	Red		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Kumho 6 mm	Rear Left Side:	Kumho 6 mm
Front Right Side:	Kumho 6 mm	Rear Right Side:	Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	31,481.36	15,358.15	16,123.21	51.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,660.00	4,580.00	5,080.00	52.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	41,141.36	19,938.15	21,203.21	51.54
Approved Total (Overridden) (S\$)		15,000.00		
(S\$)	41,141.36	15,000.00	26,141.36	63.54
+ GST 7.00/7.00% (S\$)	2,879.90	1,050.00	1,829.90	63.54
Nett Amount (S\$)	44,021.26	16,050.00	27,971.26	63.54

INSPECTION

Date of Assignment:	08/01/2020	Sk Automobile Pte Ltd 8 Kaki Bukit Ave 4, #08-46 Premier @ Kaki Bukit Singapore 415875
Date Inspected:	13/01/2020 Inspected At:	
Estimated Period of Repair:	15.0 days	

Adjuster: ADRIAN LING**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$32,000.00 (EST)-PAPER VALUE: \$16,200.00=NETT VALUE: \$15,800.00

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 17 Feb 2020)
Parts: 143	KIA FORTE KOUP 1.6 SX (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJX845J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented	874.00 FL	*874.00 FL
2	1		*BONNET WEATHERSTRIP	Not Necessary	65.00 FL	*- FL
3	2		*BONNET HINGE	Not Necessary	90.00 FL	*- FL
4	1		*BONNET LOCK	Not Necessary	153.00 FL	*- FL
5	1		*BONNET LOCK CABLE	Not Necessary	155.00 FL	*- FL
6	1		*FRONT BUMPER	Deformed	758.00 FL	*758.00 FL
7	1		*FRONT BUMPER BRACKET	Not Necessary	38.00 FL	*- FL
8	1		*FRONT BUMPER REINFORCEMENT	Bent	485.00 FL	*306.00 FL
9	1		*FRONT BUMPER SPONGE	Cracked	189.00 FL	*189.00 FL
10	1		*FRONT BUMPER LOWER GRILLE	Cracked	185.00 FL	*185.00 FL
11	1		*FRONT BUMPER LOWER GRILLE GARNISH	Cracked	226.00 FL	*226.00 FL
12	2		*FRONT BUMPER FOGLAMP	Cracked	778.00 FL	*340.00 FL
13	2		*FRONT BUMPER FOGLAMP GARNISH	Not Necessary	172.00 FL	*- FL
14	2		*FRONT BUMPER SIDE RETAINER	Necessary	42.00 FL	*42.00 FL
15	1		*FRONT BUMPER LOWER COVER	Not Necessary	321.00 FL	*- FL
16	2		*HEADLAMP	Cracked	1,368.00 FL	*1,368.00 FL
17	1		*HEADLAMP LOWER BRACKET	Bent	146.00 FL	*146.00 FL
18	1		*FRONT SUPPORT PANEL	Cracked	845.00 FL	*485.00 FL
19	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	220.00 FL	*- FL
20	1		*AIRCON PRESSURE PIPE	Not Necessary	423.00 FL	*- FL
21	1		*AIRCON SUCTION PIPE	Not Necessary	421.00 FL	*- FL
22	1		*AIR DUCT	Cracked	198.00 FL	*198.00 FL
23	1		*RADIATOR	Dented	1,404.00 FL	*746.00 FL
24	1		*RADIATOR TOP BRACKET	Not Necessary	65.00 FL	*- FL
25	1		*RADIATOR FAN COWLING WITH MOTOR	Cracked	845.00 FL	*659.00 FL
26	1		*AIR CONDENSOR	Bent	1,224.90 FL	*852.00 FL
27	2		*AIR ARCH GARNISH	Not Necessary	130.00 FL	*- FL
28	1		*HORN	Not Necessary	189.00 FL	*- FL
29	2		*FRONT FENDER	Repair	1,378.00 FL	*- FL
30	2		*FRONT FENDER COWLING	Not Necessary	320.00 FL	*- FL
31	1		*DASHBOARD	Not Necessary	1,542.00 FL	*- FL
32	1		*BOOT LID	Dented	894.50 FL	*894.50 FL
33	1		*BOOT LID LAMP	O/S Cracked	1,570.00 FL	*325.00 FL
34	2		*BOOT LID STOPPER	Not Necessary	38.00 FL	*- FL
35	2		*BOOT LID HINGE	Not Necessary	296.00 FL	*- FL
36	1		*BOOT LID INSULATOR	Not Necessary	231.00 FL	*- FL
37	1		*BOOT LID WEATHER STRIP	Cut	148.00 FL	*148.00 FL
38	1		*BOOT LID LOCK	Damaged	174.00 FL	*174.00 FL
39	1		*BOOT LID DETECTOR	Missing	312.00 FL	*78.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	2		*TAIL LAMP	Cut	1,576.00 FL	*970.00 FL
41	1		*TAIL LAMP PANEL	O/S Dented	778.00 FL	*115.00 FL
42	1		*REAR BUMPER	Distorted	712.00 FL	*712.00 FL
43	1		*REAR BUMPER LOWER LIP	Deformed	589.00 FL	*589.00 FL
44	5		*REAR BUMPER BRACKET	Damaged	110.00 FL	*110.00 FL
45	2		*REAR BUMPER SIDE RETAINER	Necessary	32.00 FL	*32.00 FL
46	1		*REAR BUMPER REINFORCEMENT	Cracked	448.00 FL	*348.00 FL
47	1		*REAR BUMPER SPONGE	Cracked	188.00 FL	*188.00 FL
48	2		*REAR BUMPER REFLECTOR	Cut	170.00 FL	*170.00 FL
49	1		*REAR REVERSE SENSOR (4PCS)	Damaged (2Pcs only)	1,416.00 FL	*440.00 FL
50	2		*REAR REINFORCEMENT BRACKET	Bent	150.00 FL	*150.00 FL
51	1		*REAR FENDER	Buckled	1,045.00 FL	*1,045.00 FL
52	2		*REAR FENDER INNER COWLING	Not Necessary	240.00 FL	*- FL
53	2		*REAR FENDER INNER TRIM	Torn	978.00 FL	*490.00 FL
54	1		*REAR WINDSCREEN MOULDING	Necessary	189.00 FL	*189.00 FL
55	1		*REAR END PANEL	Distorted	845.00 FL	*565.00 FL
56	1		*REAR END PANEL TOP GARNISH	Deformed	143.00 FL	*143.00 FL
57	1		*REAR FLOOR PANEL	Repair	1,201.00 FL	*- FL
58	1		*REAR FLOOR PANEL TOP BOARD	Deformed	358.00 FL	*269.00 FL
59	1		*REAR TOOLS SPONGE	Not Necessary	258.00 FL	*- FL
60	1		*REAR EXHAUST PIPE	Not Necessary	985.00 FL	*- FL
61	1		*REAR EXHAUST INSULATOR	Not Necessary	189.00 FL	*- FL
62	4		*REAR EXHAUST MOUNTING	Not Necessary	72.00 FL	*- FL
63	1		*FRONT NUMBER PLATE	Missing	50.00 FS	*50.00 FS
64	10		*FRONT BUMPER CLIP	Necessary	65.00 FS	*30.00 FS
65	1		*FRONT BUMPER GRILLE	Cracked	1,000.00 FS	*350.00 FS
66	3		*CENTER GRILLE CLIP	Necessary	19.50 FS	*19.50 FS
67	12		*FRONT FENDER INNER COWLING CLIP RH	Not Necessary	78.00 FS	*- FS
68	1		*RADIATOR COOLANT	Necessary	80.00 FS	*40.00 FS
69	1		*REAR NUMBER PLATE	Bent	50.00 FS	*50.00 FS
70	10		*REAR BUMPER CLIPS	Necessary	65.00 FS	*30.00 FS
71	1		*BOOT LID SEALANT	Not Necessary	80.00 FS	*- FS
72	10		*BOOT LID INSULATOR CLIP	Not Necessary	65.00 FS	*- FS
73	4		*TAIL LAMP CLIP	Necessary	32.00 FS	*32.00 FS
74	1		*TAIL LAMP PANEL SEALANT	Not Necessary	80.00 FS	*- FS
75	1		*EXHAUST CHROME	Not Necessary	150.00 FS	*- FS
76	18		*REAR FENDER INNER COWLING CLIP	Not Necessary	117.00 FS	*- FS
77	1		*REAR FENDER INNER TRIM CLIP (18PCS)	Necessary	117.00 FS	*60.00 FS
78	1		*REAR END PANEL INSULATION SEAL	Necessary	120.00 FS	*60.00 FS
79	4		*REAR END PANEL TOP GARNISH CLIP	Necessary	26.00 FS	*10.00 FS
80	1		*REAR FLOOR PANEL INSULATION SEAL	Necessary	250.00 FS	*180.00 FS
81	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*60.00 FS
82	1		*CAMERA	Damaged	450.00 FS	*380.00 FS
83	1		*REAR WINDSCREEN INNER SEAL	Necessary	80.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) **34,639.90** **16,910.00**
 - List Item Discount on L Items 10.00/10.00% (S\$) **3,158.54** **1,551.85**

Total Parts (S\$) **31,481.36** **15,358.15**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	New	1,400.00	800.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,400.00	600.00
3	TUFF COAT	New	250.00	0.00
4	WIRING CHECK	New	100.00	30.00
5	REMOVE AND REFIX AIRCON CONDENSER AND REFILL AIRCON GAS	New	120.00	60.00
6	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	New	50.00	50.00
7	REFOCUS HEADLAMP BEAM	New	80.00	0.00
8	REMOVE AND REFIT DASHBOARD WITH WIREHARNESS	New	600.00	0.00
9	PANEL BEATING, WELDING GRAZING, CUT, JOIN, STRAIGHTEN ALL AFFECTED PARTS	New	2,200.00	1,400.00
10	TO PUTTY, POLISH, SPRAY PAINT, WAX ALL AFFECTED PANELS	New	1,800.00	1,200.00
11	TUFF COAT	New	250.00	80.00
12	WIRING CHECK	New	120.00	30.00
13	REMOVE AND REFIX CUSHION SEAT / UPHOLSTRY AND ROOF LINING TO FACILITATE REPAIR	New	200.00	80.00
14	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
15	REAR CHASSIS ALIGNMENT	New	350.00	0.00
16	TRANSFER BOOTLID MECHANISM	New	80.00	80.00
17	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
18	CONDUCT WATER LEAKAGE TEST	New	100.00	0.00
19	REMOVE AND REFIX REAR EXHAUST PIPE	New	180.00	0.00
20	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT / CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (S\$)			9,660.00	4,580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >