

22/07/2002

ASS. REC. BY:

Assigner: Steve

REF: CS/INC20000531/Etd3ⁿ²

Special Instruction:

ASSIGNMENT (Office)

From (Person): Theresa Vimalan

of INC

Date/Time: 8/01/2020 @ 10:20am

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLG 5080G

Insured: SKS 247A

at Workshop m/s Progressive Car

Tel: 67415336

of Blk 3022A Ubi Road 1 # 01-45/46

Policy No:

Claim No: MT/1078868-002

Sum Insured:

Excess:

D.O.A. 87/01/2020

Make of Veh:

(Client's Record)

1up

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10:40am @ 8/1/2020

Person Contacted:

pei wen

Vehicle IN/OUT

Date/Time	Action/Instruction	Estimated
	SLG 5080S - X	✓
	SKS 247A - X	

ASS. REC. BY:

Steve

REF:

INC

ASSIGNMENT

From:

Date:

8/1/2020

Estimated Cost:

OD ☒ TP / NS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SLG 5080S

at Workshop m/s

progressive car

of Blk 3022A Ubi Road 1 #01-45/46

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{lup}

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLG 5080S

Yr Regn:

3/10/16

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Wish

C.C.

1798

Colour:

Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

98286

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JT066 20W 50J00-5425

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

4

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

MAXXIS

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

7/1/20

D.O.I.

8/1/20

Survey held at

Progressive

12.11

Des. of Damages ☒ Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

11/3/20

MK- 7SK

Finkl \$ 7,812.02, 8 days (Ray) (Red: 3725.205; 32%)

RECEIVED 13 MAR 2020

Date/Time, File Pass to?



Preli. Report

1) 13/3 Typist



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

8

Resurvey No. of Trip:

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Week end (\$)

Survey Fee:

Transportation:

3 = RS, \$1

Pins:

Others:

TOTAL

250

Report Format:

TP

Lump Sum / L.B.B. (\$)

7812.02

Nivitha (LKK Auto)

From: Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>
Sent: Thursday, 9 January 2020 9:05 AM
To: Nivitha (LKK Auto); 'assignments'
Cc: 'SUR'
Subject: RE: TP CASES FARMED OUT TO LKK ON 8/1/2020

Details of OIC etc...

Theresa Vimala
Senior Administrator
Operations, Motor & Personal Lines (PL)
T +65 6430 7898
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at Income.com.sg/careers

From: Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Wednesday, 8 January 2020 5:09 PM
To: Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>; 'assignments' <assignments@lkkauto.com>
Cc: 'SUR' <sur@lkkauto.com>
Subject: RE: TP CASES FARMED OUT TO LKK ON 8/1/2020

Dear Sir/Mdm,

Kindly assist to provide us the completed details.

“ Wishing you a Happy and Prosperous Lunar New Year ”



Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Theresa Vimala D/O Balagangadharan [mailto:thrsvim.bala@income.com.sg]

Sent: Wednesday, 8 January 2020 10:20 AM

To: 'assignments' <assignments@lkkauto.com>

Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>

Subject: TP CASES FARMED OUT TO LKK ON 8/1/2020

Hi LKK, please assist to survey these vehicles, Thank you.

SN	OIC	Claim No.	Survey Date	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	DOA	OI VEH	Additional Remarks
1	RAJESWARY	MT/1073837-002	8/1/2020	SKA816C	TAN CHONG MOTOR SALES PTE LTD	17 LORONG 8 TOA PAYOH AUTO WORLD BUILDING SINGAPORE 319254	Mr Aishah / 67038012	13:00-15:00	29/11	SKA816C	
2	DAVID PHUA	MT/1079034-001	8/1/2020	GBH708GR	JOO HAK KEE AUTO PTE LTD	BLK 3007 #01-406 UBI ROAD 1	shimin / 67431913		4/1/	GBF6885T	

3	HELENA	MT/1078836-002	8/1/2020	SKG2923G	MY CAR CONSULTANT PTE LTD	SINGAPORE 408701							
						53 UBI AVENUE 1 #01-33 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934	Huiqin / 88668832						
4	SEREME	MT/1078976-001	8/1/2020	SMF9797P	PREMIUM AUTOMOBILES PTE LTD	55 UBI ROAD 1 SINGAPORE 408699	/ 6388 2323	10:00-12:00	7/1/2020	SLS6871X	Owner waiting		
5	CHARLOTTE	MT/1078868-002	8/1/2020	SLG5080G	PROGRESSIVE CAR CARE PTE LTD	BLK 3022A #01-45/46 UBI ROAD 1 SINGAPORE 408716	Pei Wen NG / 6741 5336		7/1/2020	SKS247A			
6	CHRYLLIS	MT/1078034-002	8/1/2020	GX2385S	TAN LIM MOTOR PTE LTD	1 DEFU LANE 6 SINGAPORE 539365	William / 6858 5151	14:00-16:00	31/12/2019	EQ1221Z	owner waiting		
7	DAVID	MT/1078116-002	8/1/2020	SMM6813I	TAN LIM MOTOR PTE LTD	1 DEFU LANE 6 SINGAPORE 539365	William / 6858 5151		31/12/2019	SKD7824S			
8	HELENA	MT/1078980-001	8/1/2020	SMP3605Y	TAN LIM MOTOR PTE LTD	1 DEFU LANE 6 SINGAPORE 539365	Caymen / 6858 5151	11:00-16:00	5/1/2020	SL24828Z			
9	HELENA	MT/1078963-001	8/1/2020	GBA8436U	THINK ONE AUTOCARE PTE LTD	18 DEFU AVENUE 2 DEFU INDUSTRIAL ESTATE	Michael Ng / 91288488		4/1/2020	GBE5086U			
10	SERENE	MT/1077717-002	8/1/2020	SLE8868S	TRANS EUROKARS PTE LTD	5 UBI CLOSE	Ronald Yap / 9127 7928	10:00-12:00	27/12/2019	GBH5990T	6395 8899		

Theresa Vimala
 Senior Administrator
 Operations, Motor & Personal Lines (PL)
T +65 6430 7898
www.income.com.sg

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.



This email has been checked for viruses by AVG antivirus software.

www.avg.com

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

Steve Chen (LKK Auto)

From: Ray <ray@procarcare.com.sg>
Sent: Wednesday, March 11, 2020 9:45 AM
To: Steve Chen (LKK Auto)
Cc: Wayne; Peiwen; Dawn
Subject: RE: SLG5080G - TO FINALIZE

Hi Steve,

Amount confirm, thank you.

Regards,

Ray Lin
Damage Assessment
Progressive Car Care Pte Ltd
Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
T: +65 6741 5336 | F: +65 6741 7208
E: claims@procarcare.com.sg
W: www.procarcare.com.sg



IMPORTANT NOTICE: The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof.

From: Steve Chen (LKK Auto) [<mailto:SteveChen@lkkauto.com>]
Sent: Wednesday, March 11, 2020 9:32 AM
To: Ray
Subject: SLG5080G - TO FINALIZE

Dear Ray,

Kindly confirm the finalize \$7,812.02 (P/P, before GST). 8 repair days.

Thanks.

Best Regards,
Steve Chen | Assistant Automotive Assessor

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 775J

Vehicle Details

Vehicle No.: SLG5080G
Vehicle to be Exported: No
Intended Deregistration Date: 08 Jan 2020
Vehicle Make: TOYOTA
Vehicle Model: WISH 1.8 CVT
Primary Colour: Grey
Manufacturing Year: 2016
Engine No.: 2ZR1840459
Chassis No.: JTDGG20W50J005425
Maximum Power Output: 105.0 kW (140 bhp)
Open Market Value: \$19,955.00
Original Registration Date: 03 Oct 2016
First Registration Date: 03 Oct 2016
Transfer Count: 0
Actual ARF Paid: \$19,955.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 02 Oct 2026
PARF Rebate Amount: \$14,966.00

Intended COE Rebate Details

COE Expiry Date: 02 Oct 2026
COE Category: E - Open Category
COE Period(Years): 10
QP Paid: \$56,889.00
COE Rebate Amount: \$38,304.00
Total Rebate Amount: \$53,270.00

The information contained herein is correct as at 08 Jan 2020

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/01/2020 11:32
Date Of Accident	07/01/2020 06:40
Exact Location Of Accident	TPE SLIP ROAD TOWARDS KPE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLG5080G
Insured/Policyholder	
Name Of Registered Owner	GOH BENG LEONG MELVIN
NRIC No	SXXXX775J
Email Address	MELVINGOHBENGLEONG@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-97520883
Alternative Phone No	OTHERS-97520883

Vehicle Particulars

Manufacturer	TOYOTA
Model	WISH-1.8 CVT (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	B29093821QMX
Cover Note Number	

Driver

Name of Driver	GOH BENG LEONG MELVIN
NRIC No	SXXXX775J
Date Of Birth	31/08/1977
Occupation	INDOOR
Date Of Driving Pass	28/12/2000
Driving Experience	19 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97520883
Fax Number	
Contact Number	OTHERS-97520883
Email Address	MELVINGOHBENGLEONG@HOTMAIL.COM

Address	BLK 132 EDGEDALE PLAINS #06-40 SINGAPORE
Postcode	820132
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE ATTACH STATEMENT RECORDED BY PEI WEN - PROGRESSIVE CAR CARE PTE LTD TEL 6741 5336

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKS247A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SKM6707G
-----------------------------	----------

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

GOH BENG LEONG MELVIN

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SLG5080G

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

10:48am
7/1/2020

Driver's Signature

(if driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

peawan

Sketch Plan #2

SKETCH PLAN

	Vehicle A - SLG500UG B - SKS247A C - SKM6707G Legend  Vehicle  Motorcycle
---	--

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along TPE towards a single lane road up to LPE on 7th January 2020 at 6.40am. The car (C) did a sudden brake and I also managed to brake on time. Within a second Car B rear-ended me from behind and propelled me forward, thus knocking into Car C. There was no property damage around and (no serious injury, except my neck is currently aching from the ~~accident~~ accident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.
 Please be advised that your insurer may have a fourteen (14) days clause whereby the claim against own policy must be made within the stipulated timeframe from the day of occurrence. Kindly check your policy for more details.

Policyholder's Signature

Date & Time:

7/1/2020
 10:48am

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

penen

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
GST: 201006949C RCB NO: 201006949C

Steve (LKK)
83228813

WA 10 JUL
P/P
Ry Before SN
The 8dy

M/S: GOH BENG LEONG MELVIN
BLK 132 EDGEDALE PLAINS #06-
SINGAPORE 820132

Estimate No: EST1505654
Date: 07 Jan 2020
Policy No: B29093821QMX
Veh Reg No: SLG5080G
Make/Model: TOYOTA WISH 1.8 CVT
Chassis No: JTDGG20W50J005425
Engine No: 2ZR1840459
Reg. Date: 03/10/2016

ATTN: NTUC INCOME
Your Ref No: TP 0120-5823
Claim Type: Third Party
Accident Date: 07/01/2020
TP Veh Reg No: SKS 247 A

8/1/20, 12-15pm

Estimate Repair Cost to Vehicle No :SLG5080G

Description	U/Price	Quantity	Price SS	Amount SS
List Price				
1 REAR BOOT / DD	1,280.60	1 PC	1,280.60 /	
2 REAR BOOT RUBBER / TA	310.70	1 PC	310.70 /	
3 REAR BOOT TOP LOCK / DT	300.40	1 PC	300.40 /	
4 REAR BOOT BOTTOM LOCK X NAI	60.60	1 PC	60.60 X	250 /
5 REAR BOOT GLASS MOULDING / NPC	0.00	1 SET	0.00	
6 REAR BOOT TOYOTA LOGO / NPC	80.60	1 PC	80.60 /	
7 REAR BOOT VALVE MATIC WORDING X NAI	128.70	1 PC	128.70 X	
8 REAR BOOT REFLECTOR - LH X NAI	280.40	1 PC	280.40 X	
9 REAR BOOT OUTER CHROME X NAI	290.40	1 PC	290.40 X	
10 REAR BOOT LOCK SWITCH X NAI	250.60	1 PC	250.60 X	
11 REAR BUMPER / DD	380.50	1 PC	380.50 /	
12 REAR BUMPER SIDE HOLDER - LH / GR	129.40	1 PC	129.40 /	
13 REAR BUMPER SIDE HOLDER - RH X NAI	129.40	1 PC	129.40 X	
14 REAR BUMPER CLIPS / NPC	5.50	10 PC	55.00 /	
15 REAR BUMPER BRACKET - LH / GR	79.80	1 PC	79.80 /	
16 REAR BUMPER BRACKET - RH X NAI	79.80	1 PC	79.80 X	
17 REAR BUMPER REFLECTOR - LH X NAI	58.90	1 PC	58.90 X	
18 TAIL LAMP ASSY - LH / GR	310.40	1 PC	310.40 /	
19 TAIL LAMP PANEL - LH X R	249.70	1 PC	249.70 X	
20 FRONT BUMPER / DD	411.70	1 PC	411.70 /	
21 FRONT BUMPER CLIPS / NPC	5.50	10 PC	55.00 /	
22 FRONT BUMPER SIDE HOLDER - LH / GR	101.70	1 PC	101.70 /	
23 FRONT BUMPER SIDE HOLDER - RH / GR	101.70	1 PC	101.70 /	
24 FRONT BUMPER FOAM ? / GR	150.70	1 PC	150.70 /	
25 FRONT BUMPER REINFORCEMENT ? X DD	0.00	1 PC	0.00	278-10 /
26 HEAD LAMP ASSY - RH ? X NAI	1,080.70	1 PC	1,080.70 X	
27 HEAD LAMP ASSY - LH ? X NAI	1,080.70	1 PC	1,080.70 X	
28 GRILLE ASSY / CH	330.60	1 PC	330.60 /	
29 CONDENSER / DD	1,280.40	1 PC	1,280.40 /	
30 RADIATOR X NAI	1,190.50	1 PC	1,190.50 X	
31 BRACE PANEL X / DD	210.40	1 PC	210.40 /	
32 SUPPORT PANEL TOP GARNISH CLIP X NAI	5.50	8 PCS	44.00 X	
33 BONNET GRILLE LOGO / NPC	80.20	1 PC	80.20 /	
34 BONNET / DD	716.40	1 PC	716.40 /	
35 BONNET RUBBER X NAI	101.70	1 PC	101.70 X	
36 BONNET INSULATOR CLIPS / NPC	5.50	8 PC	44.00 /	

686430
- 75%
5148.72

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
GST:201006949C RCB NO:201006949C

M/S : GOH BENG LEONG MELVIN
BLK 132 EDGEDALE PLAINS #06-40
SINGAPORE 820132

ATTN: NTUC INCOME
Your Ref No: TP 0120-5823
Claim Type: Third Party
Accident Date: 07/01/2020
TP Veh Reg No: SKS 247 A

Estimate No: EST1505654
Date: 07 Jan 2020
Policy No: B29093821QMX
Veh Reg No: SLG5080G
Make/Model: TOYOTA WISH 1.8 CVT
Chassis No: JTDGG20W50J005425
Engine No: 2ZR1840459
Reg. Date: 03/10/2016

Estimate Repair Cost to Vehicle No :SLG5080G

Description	U/Price	Quantity	Price	Amount
			SS	SS
			11,436.30	
		Less 25%	2,859.08	8,577.23
Special Net				
37 REAR BUMPER SENSOR	220.00	1 SET	220.00	200 ✓
38 REAR NUMBER PLATE WITH CASING	35.00	1 SET	35.00	X
39 FRONT NUMBER PLATE WITH CASING	35.00	1 SET	35.00	40 ✓
40 SEALANT	20.00	2 PC	40.00	30 ✓
41 SPONGE TAPE	20.00	1 PC	20.00	10 ✓
			350.00	350.00
Labour				
42 TO KNOCK OUT DENTS, SUPPORT PANEL, REAR PANEL, CUT/WELD, REMOVE, REPLACE ACCIDENT PARTS	900.00	1 JOB	900.00	800
43 TO RESPRAY PAINT ON ACCIDENT PORTIONS	950.00	1 JOB	950.00	900
44 TO TUFF-KOTE	100.00	1 JOB	100.00	30
45 TO CHECK WIRING	50.00	1 JOB	50.00	30
46 TO REMOVE, REFIX REAR GARNISH, CARPET AND RELATED PARTS	150.00	1 JOB	150.00	30 50
47 TO TRANSFER REAR BUMPER SENSOR	100.00	1 JOB	100.00	30
48 TO REMOVE, REFIX REAR GARNISH	80.00	1 JOB	80.00	30 X
49 TO REMOVE, REFIX REAR BOOT GLASS	120.00	1 JOB	120.00	/
50 TO TRANSFER REAR BOOT	60.00	1 JOB	60.00	50
51 TO REMOVE, REPLACE CONDENSER AND REFILL GAS	100.00	1 JOB	100.00	X
			2,610.00	2,610.00
			Total	SS 11,537.23
			Add GST @ 7%	807.61
			Total Amount Payable	SS 12,344.84

LKK Auto Consultants hence notify the Repairer of TOTAL SINGAPORE DOLLAR TWELVE THOUSAND THREE HUNDRED FORTY FOUR AND CENTS EIGHTY FOUR ONLY

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

For Progressive Car Care Pte Ltd

AUTHORISED SIGNATURE

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
 TEL: 6741 5336 FAX: 6741 7208 Email: claims@proccare.com.sg
 GST: 201006949C RCB NO: 201006949C

Stew (LKK)
 83228813
 M/S: GOH BENG LEONG MELVIN
 BLK 132 EDGEDALE PLAINS #06-40
 SINGAPORE 820132

Estimate No: EST1505654
 Date: 07 Jan 2020
 Policy No: B29093821QMX
 Veh Reg No: SLG5080G
 Make/Model: TOYOTA WISH 1.8 CVT
 Chassis No: JTDGG20W50J005425
 Engine No: 2ZR1840459
 Reg. Date: 03/10/2016

ATTN: NTUC INCOME
 Your Ref No: TP 0120-5823
 Claim Type: Third Party
 Accident Date: 07/01/2020
 TP Veh Reg No: SKS 247 A

Estimate Repair Cost to Vehicle No :SLG5080G

Description	U/Price	Quantity	Price	Amount
			SS	SS
List Price				
1 REAR BOOT / <i>OD</i>	1,280.60	1 PC	1,280.60 ✓	
2 REAR BOOT RUBBER / <i>TN</i>	310.70	1 PC	310.70 ✓	
3 REAR BOOT TOP LOCK / <i>OT</i>	300.40	1 PC	300.40 ✓	
4 REAR BOOT BOTTOM LOCK X	60.60	1 PC	60.60	
5 REAR BOOT GLASS MOULDING / <i>n/c</i>	0.00	1 SET	0.00 ✓	340.20
6 REAR BOOT TOYOTA LOGO / <i>n/c</i>	80.60	1 PC	80.60 ✓	
7 REAR BOOT VALVE MATIC WORDING X	128.70	1 PC	128.70	
8 REAR BOOT REFLECTOR - LH X	280.40	1 PC	280.40	
9 REAR BOOT OUTER CHROME X	290.40	1 PC	290.40	
10 REAR BOOT LOCK SWITCH X	250.60	1 PC	250.60	
11 REAR BUMPER / <i>OD</i>	380.50	1 PC	380.50 ✓	
12 REAR BUMPER SIDE HOLDER - LH / <i>OR</i>	129.40	1 PC	129.40 ✓	
13 REAR BUMPER SIDE HOLDER - RH / <i>OR</i>	129.40	1 PC	129.40	
14 REAR BUMPER CLIPS / <i>n/c</i>	5.50	10 PC	55.00	
15 REAR BUMPER BRACKET - LH / <i>OR</i>	79.80	1 PC	79.80 ✓	
16 REAR BUMPER BRACKET - RH X	79.80	1 PC	79.80	
17 REAR BUMPER REFLECTOR - LH X	58.90	1 PC	58.90	
18 TAIL LAMP ASSY - LH / <i>OR</i>	310.40	1 PC	310.40 ✓	
19 TAIL LAMP PANEL - LH X R	249.70	1 PC	249.70	
20 FRONT BUMPER / <i>OD</i>	411.70	1 PC	411.70 ✓	
21 FRONT BUMPER CLIPS / <i>n/c</i>	5.50	10 PC	55.00	
22 FRONT BUMPER SIDE HOLDER - LH / <i>OR</i>	101.70	1 PC	101.70 ✓	
23 FRONT BUMPER SIDE HOLDER - RH / <i>OR</i>	101.70	1 PC	101.70 ✓	
✓24 FRONT BUMPER FOAM / <i>OR</i>	150.70	1 PC	150.70 ✓	
✓25 FRONT BUMPER REINFORCEMENT / <i>OR</i>	0.00	1 PC	0.00	278.10
26 HEAD LAMP ASSY - RH X	1,080.70	1 PC	1,080.70	
27 HEAD LAMP ASSY - LH X	1,080.70	1 PC	1,080.70	
28 GRILLE ASSY / <i>n/c</i>	330.60	1 PC	330.60 ✓	
✓29 CONDENSER / <i>OR</i>	1,280.40	1 PC	1,280.40 ✓	
30 RADIATOR X	1,190.50	1 PC	1,190.50	
31 BRACE PANEL X	210.40	1 PC	210.40 ✓	
32 SUPPORT PANEL TOP GARNISH CLIP X	5.50	8 PCS	44.00	
33 BONNET GRILLE LOGO / <i>n/c</i>	80.20	1 PC	80.20 ✓	
34 BONNET / <i>OD</i>	716.40	1 PC	716.40 ✓	
35 BONNET RUBBER X	101.70	1 PC	101.70	
36 BONNET INSULATOR CLIPS / <i>n/c</i>	5.50	8 PC	44.00	

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
 TEL: 6741 5336 FAX: 6741 7208 Email: claims@proccarcare.com.sg
 GST:201006949C RCB NO:201006949C

M/S : GOH BENG LEONG MELVIN
 BLK 132 EDGEDALE PLAINS #06-40
 SINGAPORE 820132

ATTN: NTUC INCOME

Your Ref No: TP 0120-5823
 Claim Type: Third Party
 Accident Date: 07/01/2020
 TP Veh Reg No: SKS 247 A

Estimate No: EST1505654
 Date: 07 Jan 2020
 Policy No: B29093821QMX
 Veh Reg No: SLG5080G
 Make/Model: TOYOTA WISH 1.8 CVT
 Chassis No: JTDGG20W50J005425
 Engine No: 2ZR1840459
 Reg. Date: 03/10/2016

Estimate Repair Cost to Vehicle No :SLG5080G

Description	U/Price	Quantity	Price	Amount
			SS	SS
			11,436.30	6954.50
	Less 25%		2,859.08	8,577.23
Special Net				5215.87
37 REAR BUMPER SENSOR / OR	220.00	1 SET	220.00	✓
38 REAR NUMBER PLATE WITH CASING X	35.00	1 SET	35.00	
39 FRONT NUMBER PLATE WITH CASING / CW	35.00	1 SET	35.00	
40 SEALANT / MK	20.00	2 PC	40.00	30 ✓ 40
41 SPONGE TAPE / MK	20.00	1 PC	20.00	10 ✓ 20
			350.00	350.00
Labour				315
42 TO KNOCK OUT DENTS, SUPPORT PANEL, REAR PANEL, CUT/WELD, REMOVE, REPLACE ACCIDENT PARTS	900.00	1 JOB	900.00	800 ✓
43 TO RESPRAY PAINT ON ACCIDENT PORTIONS	950.00	1 JOB	950.00	900 ✓
44 TO TUFF-KOTE	100.00	1 JOB	100.00	30 ✓
45 TO CHECK WIRING	50.00	1 JOB	50.00	30 ✓
46 TO REMOVE, REFIX REAR GARNISH, CARPET AND RELATED PARTS	150.00	1 JOB	150.00	30 50 ✓
47 TO TRANSFER REAR BUMPER SENSOR	100.00	1 JOB	100.00	30 ✓
48 TO REMOVE, REFIX REAR GARNISH	80.00	1 JOB	80.00 30 X	
49 TO REMOVE, REFIX REAR BOOT GLASS	120.00	1 JOB	120.00	✓
50 TO TRANSFER REAR BOOT	60.00	1 JOB	60.00	50 ✓
51 TO REMOVE, REPLACE CONDENSER AND REFILL GAS	100.00	1 JOB	100.00 X	200 ✓
			2,610.00	2,610.00
Total			SS	11,537.23
Add GST @ 7%				807.61
Total Amount Payable			SS	12,344.84

TOTAL: SINGAPORE DOLLAR TWELVE THOUSAND THREE HUNDRED FORTY FOUR AND CENTS EIGHTY FOUR ONLY

For Progressive Car Care Pte Ltd

AUTHORISED SIGNATURE

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
GST:201006949C RCB NO:201006949C

M/S: GOH BENG LEONG MELVIN
BLK 132 EDGEDALE PLAINS #06-40
SINGAPORE 820132

Estimate No: EST1505654
Date: 10 Jan 2020
Policy No: B29093821QMX
Veh Reg No: SLG5080G
Make/Model: TOYOTA WISH 1.8 CVT
Chassis No: JTDGG20W50J005425
Engine No: 2ZR1840459
Reg. Date: 03/10/2016

ATTN: NTUC INCOME
Your Ref No: TP 0120-5823
Claim Type: Third Party
Accident Date: 07/01/2020
TP Veh Reg No: SKS 247 A

Estimate Repair Cost to Vehicle No :SLG5080G

Description	U/Price	Quantity	Price	Amount
			SS	SS
Supplementary Parts to Repair				
List Price				
1 REAR PANEL	498.40	1 PCS	498.40	
			498.40	
		Less 25%	124.60	373.80
Total				SS 373.80
GST Amount				SS 26.17
Total Amount Payable				SS 399.97

Gmo Auth.
10/1/20.

For Progressive Car Care Pte Ltd

AUTHORISED SIGNATURE

SUPP 373.80

PARTS 5215.87

SN 315.00

LAB. 2060.00

7914.67



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC20000531/Etd3n2
73 BRAS BASAH ROAD Date: 18-03-2020
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556



ATTN: CHARLOTTE

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKS 247A	Veh. Inspected	SLG 5080G
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1078868-002	Excess (\$)	0.00
Assign From	THERESA VIMALA	Assign Date	08/01/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA WISH	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JTDGG20W50J005425	Colour	GREY
Odometer	98286 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	MAXXIS	5 mm
L/H Front Tyre	195/65 R15	MAXXIS	5 mm
R/H Rear Tyre	195/65 R15	MAXXIS	5 mm
L/H Rear Tyre	195/65 R15	MAXXIS	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	07/01/2020	Inspect Date / Time	08/01/2020 (12:11 PM)
Survey held at	PROGRESSIVE CAR CARE PTE LTD BLK 3022A UBI ROAD 1 #01-45/46, SINGAPORE 048716		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	8 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 5080G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BOOT	DENTED	1,280.60	1,280.60
1	REAR BOOT RUBBER	TORN	310.70	310.70
1	REAR BOOT TOP LOCK	BENT	300.40	300.40
1	REAR BOOT BOTTOM LOCK	NOT NECESSARY	60.60	-
1	SET REAR BOOT GLASS MOULDING	NECESSARY	250.00	250.00
1	REAR BOOT TOYOTA LOGO	NECESSARY	80.60	80.60
1	REAR BOOT VALVE MATIC WORDING	NOT NECESSARY	128.70	-
1	REAR BOOT REFLECTOR-LH	NOT NECESSARY	280.40	-
1	REAR BOOT OUTER CHROME	NOT NECESSARY	290.40	-
1	REAR BOOT LOCK SWITCH	NOT NECESSARY	250.60	-
1	REAR BUMPER	DENTED	380.50	380.50
1	REAR BUMPER SIDE HOLDER-LH	BROKEN	129.40	129.40
1	REAR BUMPER SIDE HOLDER-RH	NOT NECESSARY	129.40	-
10	REAR BUMPER CLIPS @\$5.50	NECESSARY	55.00	30.00
1	REAR BUMPER BRACKET-LH	BROKEN	79.80	79.80
1	REAR BUMPER BRACKET-RH	NOT NECESSARY	79.80	-
1	REAR BUMPER REFLECTOR-LH	NOT NECESSARY	58.90	-
1	TAIL LAMP ASSY-LH	BROKEN	310.40	310.40
1	TAIL LAMP PANEL-LH	TO REPAIR SEE LABOUR	249.70	-
1	FRONT BUMPER	DENTED	411.70	411.70
10	FRONT BUMPER CLIPS @\$5.50	NECESSARY	55.00	30.00
1	FRONT BUMPER SIDE HOLDER-LH	BROKEN	101.70	101.70
1	FRONT BUMPER SIDE HOLDER-RH	BROKEN	101.70	101.70
1	FRONT BUMPER FOAM	BROKEN	150.70	150.70
1	FRONT BUMPER REINFORCEMENT	DENTED	278.10	278.10
1	HEAD LAMP ASSY-RH	NOT NECESSARY	1,080.70	-
1	HEAD LAMP ASSY-LH	NOT NECESSARY	1,080.70	-
1	GRILLE ASSY	CUT	330.60	330.60
1	CONDENSER	DENTED	1,280.40	1,280.40
1	RADIATOR	NOT NECESSARY	1,190.50	-

Report Ref No. CS/INC20000531/Etd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BRACE PANEL	DENTED	210.40	210.40
8	SUPPORT PANEL TOP GARNISH CLIP @\$5.50	NOT NECESSARY	44.00	-
1	BONNET GRILLE LOGO	NECESSARY	80.20	80.20
1	BONNET	DENTED	716.40	716.40
1	BONNET RUBBER	NOT NECESSARY	101.70	-
8	BONNET INSULATOR CLIPS @\$5.50	NECESSARY	44.00	20.00
1	REAR PANEL (ADDITIONAL)	BUCKLED	498.40	498.40
	LESS 25% DISCOUNT		-3,115.70	-1,840.68
			9,347.10	5,522.02
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER SENSOR (SN)	BROKEN	220.00	200.00
1	SET REAR NUMBER PLATE WITH CASING (SN)	NOT NECESSARY	35.00	-
1	SET FRONT NUMBER PLATE WITH CASING (SN)	CUT	40.00	40.00
2	SEALANT @\$20.00 (SN)	NECESSARY	40.00	30.00
1	SPONGE TAPE (SN)	NECESSARY	20.00	10.00
			355.00	280.00
	LABOUR			
	TO KNOCK OUT DENTS,SUPPORT PANEL,REAR PANEL,CUT/WELD,REMOVE,REPLACE ACCIDENT PARTS.INCLUSIVE OF THE REPAIR OF TAIL LAMP PANEL -LH.		900.00	800.00
	TO RESPRAY PAINT ON ACCIDENT PORTIONS.		950.00	900.00
	TO TUFF-KOTE.		100.00	30.00
	TO CHECK WIRING.		50.00	30.00
	TO REMOVE,REFIX REAR GARNISH,CARPET AND RELATED PARTS.		150.00	50.00
	TO TRANSFER REAR BUMPER SENSOR.		100.00	30.00
	TO REMOVE,REFIX REAR GARNISH.	NOT NECESSARY	80.00	-
	TO REMOVE,REFIX REAR BOOT GLASS.		120.00	120.00
	TO TRANSFER REAR BOOT.		60.00	50.00
	TO REMOVE,REPLACE CONDENSER AND REFILL GAS.	NOT NECESSARY	100.00	-
			2,610.00	2,010.00
	GRAND TOTAL		12,312.10	7,812.02

Report Ref No. CS/INC20000531/Etd3n2



RECOMMENDED COST OF REPAIRS (CONFIRMED)			7,812.02
---	--	--	----------

Report Ref No. CS/INC20000531/Etd3n2

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.