



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SMQ3902J
Date of Accident : 31 December 2019

Messrs Shaddai-Plan

Date : 02 January 2020

Estimate To Repair GBE8049H - NISSAN NV200 1.6 A
Chassis No : VM20087686

L44-Rasul
07/01/2020 @ 1350h

S/No	Quantity	Description	Amount
NETT ITEMS			
01	1 pc	tailgate lid 4 ✓	\$ 1,724.60
02	1 pc	tailgate lid inner lock X NN	\$ 261.00
03	2 ps	tailgate lid hinges @ \$99.10 X NN	\$ 198.20
04	1 pc	tailgate lid NV200 emblem badge re ✓	\$ 87.00
05	1 pc	tailgate lid Nissan emblem badge re ✓	\$ 59.70
06	1 pc	tailgate lid Vanette emblem badge re ✓	\$ 59.70
07	1 pc	rear bumper cut ✓	\$ 581.10
08	1 pc	rear end panel bt ✓	\$ 358.80
09	1 pc	tailgate lid weatherstrip re ✓	\$ 63.70
10	1 pc	rear bumper reinforcement X NN	\$ 154.00
11	1 pc	rear bumper absorber foam cr ✓	\$ 84.00
12	1 pc	rear end panel inner trim de ✓	\$ 133.80
13	4 ps	rear end panel inner trim clips @ \$5.00 re ✓	\$ 20.00
Rear lamp o/s \$358.70 scr ✓			\$ 3,785.60
Less 10 %			\$ 378.56
			\$ 3,407.04
SPECIAL NETT ITEMS			
14	1 pc	tailgate lid 70 Km/h sticker re ✓	\$ 20.00 10
15	1 pc	tailgate lid 6 pax sticker re ✓	\$ 20.00 10
16	1 set	rear bumper reverse sensor re ✓	\$ 320.00 200
17	1 pc	rear windscreen glass sealant re ✓	\$ 65.00 50
			\$ 425.00
LABOUR & MISC. CHARGES			
01		To reinstall of rear bumper parking sensor.	\$ 80.00 60
02		To remove and refit rear windscreen glass.	\$ 140.00 120
03		To check electrical lighting concerned.	\$ 60.00 30
04		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 1,000.00 650
05		Putty and spray painting of the affected portion.	\$ 1,200.00 500
			\$ 2,480.00
Total			\$ 6,312.04

Rasul
Hp 90010068

5 days

4/8

07/01/2020

@ 1400

Resey after repair

Acknowledged by Repairer
Signature:
Date: