

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 25415

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0024/2020/NS
Date : 7-Jan-20

Vehicle NOT IN workshop. Please arrange for survey.

Your insured veh no : **SJA 8366 T**

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Sze Eng Teck
Address : 85 Compassvale Bow
#09-15
Singapore 544685
Telephone : (HP) +65 97600164
Type of Claim : Third Party Claims
Policy No. : 10736787
Vehicle No : **SKE 735 G**
Model Code : A4 Sedan 1.4 TFSI S
Model / Year : 18/5/2016
Engine No : CVN 009573
Chassis No : WAUZZZF44GA074244
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 6-Jan-20
Place of Accident : PIE Towards Tuas Near Around KPE

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SKE 735 G

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓	
2	To dismantle and renew front bumper and bonnet. Re-organise crash management components. Reinstall all parts removed.	\$ 2,100.00 1000	
3	To respray front bumper and bonnet.	\$ 2,000.00 1100	
4	To carry out first measurement test on car o-liner	S/N \$ 800.00 ✗	
5	To remove and renew rear parking aid and rear lid kick sensor.	S/N \$ 360.00 ✓	
SUB TOTAL LABOUR CHARGES		: \$ 5,620.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SKE 735 G

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
6	To remove and reinstall rear wire harness, audio equipment, control units, relay, fuse and relay trays, end panelling and spare wheel housing.	S/N \$ 1,800.00 ✓	
7	To remove and reinstall rear seats, back rest, carpets, ABCD pillar trims, disengage airbag system.	S/N \$ 1,800.00 ✓	
8	To remove exhaust system and fuel tank assy. Renew centre and rear exhaust silencer if necessary.	S/N \$ 780.00 ✓	
9	To remove and install rear suspension assy to facilitate car-o-liner repairs. Inspect for damages and renew accordingly.	S/N \$ 2,800.00 ✓	
10	To place vehicle on car o-liner.	S/N \$ 1,800.00 ✓	
SUB TOTAL LABOUR CHARGES		: \$ 8,980.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SKE 735 G

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
11	To dismantle and renew rear bumper. Cut out and reweld rear end panelling, spare wheel housing and cross members. Repair and align whole rear substructure to position. Reorganise crash management components. Reinstall all parts removed.	\$ 5,600.00	3500.
12	To carry out stone chip primer work on rear panelling and spare wheel housing.	S/N \$ 780.00 ✓	
13	To spray paint on rear bumper, spare wheel housing and ^{end panel} boot floor. To carry out joint sealer works and cavity preservation.	\$ 3,000.00	1650.
14	To carry out wheel alignment.	S/N \$ 240.00 ✓	
15	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 24,412.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

tel 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKE 735 G

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>Rehamed</i>	\$ 1,946.00	✓
2	FRONT BUMPER FIXING PARTS	\$ 258.00	+
3	FRONT BUMPER SECURING STRIP <i>from</i>	2 \$ 64.00	+
4	FRONT BBUMPER GRILLE - CENTRE	\$ 178.00	+
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>plan</i>	\$ 191.00	+
6	RADIATOR GRILLE <i>crushed</i>	\$ 1,666.00	✓
7	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>plan</i>	2 \$ 666.00	+
8	FRONT BUMPER FOAM FILLER PIECE <i>Not nec</i>	\$ 113.00	X.
9	FRONT BUMPER CARRIER <i>Not nec</i>	\$ 733.00	X.
10	FRONT BUMPER COVER <i>plan</i>	\$ 116.00	+
11	CAUTION SIGN STICKER <i>2 Not nec</i>	NEC \$ 13.00	+
12	AIRCON STICKER	NEC \$ 7.00	+
13	LOCK CARRIER BRACKET	\$ 125.00	+
14	FRONT BUMPER SUPPORT - LH / RH <i>Not nec</i>	2 \$ 52.00	+
15	HORN - LH HIGH TONE	\$ 37.00	+
16	HORN - RH HIGH TONE	\$ 262.00	+
17	SPRING SHACKLE - LH / RH	2 \$ 52.00	+
18	BONNET <i>Dented</i>	\$ 2,554.00	✓
19	BONNET ATTACHMENT PARTS <i>Not nec</i>	\$ 111.00	+
20	BONNET IMPACT PROTECTION - CENTRE / LH / RH <i>plan</i>	3 \$ 75.00	✓
SUB TOTAL SPARE PARTS		: \$ 9,219.00	

premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKE 735 G

		Damaged Parts & Prices	
		S/Nett	Remarks
S/N	Parts Description		
21	BONNET BOWDEN CABLE	\$ 53.00	x
22	BONNET BOWDEN CABLE - CENTRE	\$ 53.00	x
23	BONNET RELEASE LEVER	\$ 12.00	x
24	RADIATOR AIR GUIDE - LH / RH	2 \$ 50.00	x
25	RADIATOR AIR GUIDE - LH / RH	2 \$ 22.00	x
26	RADIATOR AIR GUIDE - UPPER	\$ 15.00	x
27	RADIATOR AIR GUIDE - LOWER	\$ 19.00	x
28	REAR BUMPER <i>Del'd</i>	\$ 2,015.00	✓
29	REAR BUMPER FIXING PARTS <i>Not nec</i>	\$ 66.00	x
30	REAR BUMPER SECURING STRIP <i>Def</i>	\$ 203.00	✓
31	REAR BUMPER SPOILER - LH <i>Del'd</i>	\$ 227.00	✓
✓ 32	REAR LIGHT REFLECTOR - LH / RH <i>Not nec</i>	2 \$ 76.00	x
<i>photo</i> 33	REAR BUMPER CARRIER <i>Best</i>	\$ 819.00	✓
34	REAR BUMPER SEAL <i>Not nec</i>	2 \$ 25.00	x
35	REAR BUMPER GUIDE SECTION - LH	\$ 40.00	x
36	REAR BUMPER GUIDE SECTION - RH	\$ 41.00	x
37	REAR BUMPER GUIDE SECTION - LH / RH	2 \$ 40.00	x
38	AERIAL RETAINER <i>Not nec</i>	\$ 23.00	x
39	TELEPHONE AERIAL <i>Not Nec</i>	\$ 164.00	x
40	REAR PARKING AID SENSOR - INNER / OUTER <i>Not Nec</i>	\$ 924.00	x
SUB TOTAL SPARE PARTS		: \$ 4,887.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKE 735 G

S/N	Parts Description		S/Nett	Damaged Parts & Prices	
				S/Nett	Remarks
41	REAR PARKING AID SEAL RING	Not Nec	4 \$	12.00	X
42	REAR BUMPER WIRING SET	Not Nec	\$	618.00	X
43	BOOT LID CONTROL UNIT	Damaged	\$	350.00	✓
44	TAILGATE OPENING SENSOR LINE	Not Nec	\$	190.00	X
45	REAR CROSS PANEL	Distorted	\$	238.00	✓
46	CROSS PANEL REINFORCEMENT		\$	461.00	✓
47	SPARE WHEEL WELL	Distorted	\$	2,020.00	✓
48	REAR SILENCER HEAT SHIELD - LH	crushed	\$	139.00	✓
49	HEAT SHIELD - CENTRE	Not Nec	\$	62.00	X
50	LUGGAGE COMPARTMENT FLOOR	Not Nec	\$	648.00	X
51	REAR CROSS PANEL TRIM	Not Nec	\$	154.00	X
52	INSERT PART	Not Nec	\$	247.00	X
53	STOWAGE COMPARTMENT	Not Nec	\$	83.00	X
54	REAR SILENCER HEAT SHIELD - LH	Not Nec	\$	999.00	X
55	REAR SILENCER DUAL CLIP	Not Nec	\$	45.00	X
56	EXHAUST SILENCER BRACKET	Not Nec	\$	38.00	X
57	CENTRE SILENCER	Not Nec	\$	902.00	X
58	CENTRE SILENCER DUAL CLIP	Not Nec	\$	45.00	X
59	DUAL CLIP	Not Nec	\$	45.00	X
60	FRONT NO PLATE	Dented	S/N \$	40.00	✓
61	ACRYLIC SEALANT		S/N \$	180.00	✓
62	CAVITY WAX		S/N \$	140.00	✓
63	STONE CHIP		S/N \$	180.00	✓
64	SUNDRIES		\$	600.00	120.96.

TOTAL SPARE PARTS : \$ 22,542.00

TOTAL LABOUR CHARGES : \$ 24,412.00

GRAND TOTAL : \$ 46,954.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King
Surveyed Date : 08/01/20
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 16 Days.
15

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice"
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company.

Acknowledged by Repairer
Signature:
Date:

Please Note

: This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Khurchna

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

PA/TP/0024/2020/NS

Date

26-Feb-20

Service Advisor

Glory Tan

Pages

1 of 1

Regn No

SKE 735 G

Model No

A4 Sedan 1.4 TFSI S

Quantity	Description	Unit Price	Amount
Parts			
1	Mounting for spare wheel <i>bf ✓</i>	\$	127.00

TOTAL

\$ 127.00

For Premium Automobiles Pte Ltd

Rahul
27/02/2020

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 25415

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0024/2020/NS
Date : 7-Jan-20

Vehicle NOT IN workshop. Please arrange for survey.

Your insured veh no : **SJA 8366 T**

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

*15 days exclude 3 Sundays - ok
jb 26 Mar 20*

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Sze Eng Teck
Address : 85 Compassvale Bow
#09-15
Singapore 544685
Telephone : (HP) +65 97600164
Type of Claim : Third Party Claims
Policy No. : 10736787
Vehicle No : **SKE 735 G**
Model Code : A4 Sedan 1.4 TFSI S
Model / Year : 18/5/2016
Engine No : CVN 009573
Chassis No : WAUZZZF44GA074244
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 6-Jan-20
Place of Accident : PIE Towards Tuas Near Around KPE

Premium Automobiles

65 Ubi Road 1, Singapore 408600

Tel: 6360 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle, SKE 735 G

S/n	Nature of Jobs		Estimated Charges	Surveyor's recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$	360.00	\$ 360.00
2	To dismantle and renew front bumper and bonnet. Re-organise crash management components. Reinstall all parts removed.	\$	2,100.00	\$ 1,000.00
3	To respray front bumper and bonnet.	\$	2,000.00	\$ 1,100.00
4	To carry out first measurement test on car o-liner	S/N \$	800.00	
5	To remove and renew rear parking aid and rear lid kick sensor.	S/N \$	360.00	\$ 360.00
SUB TOTAL LABOUR CHARGES		:	<u>\$ 5,620.00</u>	<u>\$ 2,820.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SKE 735 G

S/n	Nature of Jobs		Estimated Charges	Surveyor's recommendations
		<i>c/f</i>		\$ 2,820.00
6	To remove and reinstall rear wire harness, audio equipment, control units, relay, fuse and relay trays, end panelling and spare wheel housing.	S/N	\$ 1,800.00	\$ 1,800.00
7	To remove and reinstall rear seats, back rest, carpets, ABCD pillar trims, disengage airbag system.	S/N	\$ 1,800.00	\$ 1,800.00
8	To remove exhaust system and fuel tank assy. Renew centre and rear exhaust silencer if necessary.	S/N	\$ 780.00	\$ 780.00
9	To remove and install rear suspension assy to facilitate car-o-liner repairs. Inspect for damages and renew accordingly.	S/N	\$ 2,800.00	\$ 2,800.00
10	To place vehicle on car o-liner. (C/bench)	S/N	\$ 1,800.00	\$ 1,200.00
SUB TOTAL LABOUR CHARGES			: \$ 8,980.00	\$ 11,200.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SKE 735 G

S/n	Nature of Jobs	Estimated Charges	Surveyor's recommendations
			\$ 11,200.00
11	To dismantle and renew rear bumper. Cut out and reweld rear end panelling, spare wheel housing and cross members. Repair and align whole rear substructure to position. Reorganise crash management components. Reinstall all parts removed.	\$ 5,600.00	\$ 3,500.00
12	To carry out stone chip primer work on rear panelling and spare wheel housing.	S/N \$ 780.00	\$ 780.00
13	To spray paint on rear bumper, spare wheel housing and boot floor. To carry out joint sealer works and cavity preservation.	\$ 3,000.00	\$ 1,650.00
14	To carry out wheel alignment.	S/N \$ 240.00	\$ 240.00
15	To carry out diagnostic check.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 24,412.00	\$ 17,562.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKE 735 G

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER	\$ 1,946.00	\$ 1,556.80
2	FRONT BUMPER FIXING PARTS	\$ 258.00	
3	FRONT BUMPER SECURING STRIP	2 \$ 64.00	
4	FRONT BBUMPER GRILLE - CENTRE	\$ 178.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$ 191.00	
6	RADIATOR GRILLE	\$ 1,666.00	\$ 1,332.80
7	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2 \$ 666.00	
8	FRONT BUMPER FOAM FILLER PIECE	\$ 113.00	
9	FRONT BUMPER CARRIER	\$ 733.00	
10	FRONT BUMPER COVER	\$ 116.00	
11	CAUTION SIGN STICKER	NEC \$ 13.00	
12	AIRCON STICKER	NEC \$ 7.00	
13	LOCK CARRIER BRACKET	\$ 125.00	
14	FRONT BUMPER SUPPORT - LH / RH	2 \$ 52.00	
15	HORN - LH HIGH TONE	\$ 37.00	
16	HORN - RH HIGH TONE	\$ 262.00	
17	SPRING SHACKLE - LH / RH	2 \$ 52.00	
18	BONNET	\$ 2,554.00	\$ 2,043.20
19	BONNET ATTACHMENT PARTS	\$ 111.00	
20	BONNET IMPACT PROTECTION - CENTRE / LH / RH	3 \$ 75.00	\$ 59.44
SUB TOTAL SPARE PARTS		: \$ 9,219.00	\$ 4,992.24

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKE 735 G

S/N	Parts Description	c/f	Damaged Parts & Prices	
			S/Nett	Remarks
			\$	4,992.24
21	BONNET BOWDEN CABLE		\$ 53.00	
22	BONNET BOWDEN CABLE - CENTRE		\$ 53.00	
23	BONNET RELEASE LEVER		\$ 12.00	
24	RADIATOR AIR GUIDE - LH / RH	2	\$ 50.00	
25	RADIATOR AIR GUIDE - LH / RH	2	\$ 22.00	
26	RADIATOR AIR GUIDE - UPPER		\$ 15.00	
27	RADIATOR AIR GUIDE - LOWER		\$ 19.00	
28	REAR BUMPER		\$ 2,015.00	\$ 1,612.00
29	REAR BUMPER FIXING PARTS		\$ 66.00	
30	REAR BUMPER SECURING STRIP		\$ 203.00	\$ 162.40
31	REAR BUMPER SPOILER - LH		\$ 227.00	\$ 181.20
32	REAR LIGHT REFLECTOR - LH / RH	2	\$ 76.00	
33	REAR BUMPER CARRIER		\$ 819.00	\$ 655.20
34	REAR BUMPER SEAL	2	\$ 25.00	
35	REAR BUMPER GUIDE SECTION - LH		\$ 40.00	
36	REAR BUMPER GUIDE SECTION - RH		\$ 41.00	
37	REAR BUMPER GUIDE SECTION - LH / RH	2	\$ 40.00	
38	AERIAL RETAINER		\$ 23.00	
39	TELEPHONE AERIAL		\$ 164.00	
40	REAR PARKING AID SENSOR - INNER / OUTER	4	\$ 924.00	
SUB TOTAL SPARE PARTS			\$ 4,887.00	\$ 7,603.04

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKE 735 G

S/N	Parts Description	c/f	Damaged Parts & Prices		Remarks
			S/Nett	\$	
41	REAR PARKING AID SEAL RING	4	\$	12.00	
42	REAR BUMPER WIRING SET		\$	618.00	
43	BOOT LID CONTROL UNIT		\$	350.00	\$ 280.00
44	TAILGATE OPENING SENSOR LINE		\$	190.00	
45	REAR CROSS PANEL		\$	238.00	\$ 190.00
46	CROSS PANEL REINFORCEMENT		\$	461.00	\$ 368.80
47	SPARE WHEEL WELL		\$	2,020.00	\$ 1,616.00
48	REAR SILENCER HEAT SHIELD - LH		\$	139.00	\$ 110.80
49	HEAT SHIELD - CENTRE		\$	62.00	
50	LUGGAGE COMPARTMENT FLOOR		\$	648.00	
51	REAR CROSS PANEL TRIM		\$	154.00	
52	INSERT PART		\$	247.00	
53	STOWAGE COMPARTMENT		\$	83.00	\$ 66.00
54	REAR SILENCER HEAT SHIELD - LH		\$	999.00	
55	REAR SILENCER DUAL CLIP		\$	45.00	
56	EXHAUST SILENCER BRACKET		\$	38.00	
57	CENTRE SILENCER		\$	902.00	
58	CENTRE SILENCER DUAL CLIP		\$	45.00	
59	DUAL CLIP		\$	45.00	
60	FRONT NO PLATE	S/N	\$	40.00	\$ 40.00
61	ACRYLIC SEALANT	S/N	\$	180.00	\$ 180.00
62	CAVITY WAX	S/N	\$	140.00	\$ 140.00
63	STONE CHIP	S/N	\$	180.00	\$ 180.00
64	Added parts - see attached		\$	127.00	\$ 101.20
65	SUNDRIES		\$	600.00	\$ 120.96
TOTAL SPARE PARTS			:	\$ 22,669.00	\$ 10,996.80
TOTAL LABOUR CHARGES			:	\$ 24,412.00	\$ 17,562.00
GRAND TOTAL			:	\$ 47,081.00	\$ 28,558.80

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.