

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

**WIP : 25415**

## Telefax

**Estimate** : Accident Repairs  
**Workshop** : Ubi Road 1  
**Contact No** : 6366 2323  
**Fax No** : 6841 1183  
**Reference** : PA/TP/0024/2020/NS  
**Date** : 7-Jan-20

**Vehicle NOT IN workshop. Please arrange for survey.**

**Your insured veh no : SJA 8366 T**

## AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

**Attn: Mr. Adrian Ling - Motor Claims Dept**

**Tel: 6841 0055 - Fax: 6256 4315**

**Owner's Name** : Mr Sze Eng Teck  
**Address** : 85 Compassvale Bow  
#09-15  
Singapore 544685  
**Telephone** : (HP) +65 97600164  
**Type of Claim** : Third Party Claims  
**Policy No.** : 10736787  
**Vehicle No** : **SKE 735 G**  
**Model Code** : A4 Sedan 1.4 TFSI S  
**Model / Year** : 18/5/2016  
**Engine No** : CVN 009573  
**Chassis No** : WAUZZZF44GA074244  
**Mileage** : -  
**Date In** : -  
**Estimated By** : Johnny Boo / Allan Wu  
**Accident Date** : 6-Jan-20  
**Place of Accident** : PIE Towards Tuas Near Around KPE

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle. SKE 735 G

| S/n                             | Nature of Jobs                                                                                                                 | Estimated Charges            | Surveyor's Recommendations |
|---------------------------------|--------------------------------------------------------------------------------------------------------------------------------|------------------------------|----------------------------|
| 1                               | To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy. | S/N \$ 360.00 ✓              |                            |
| 2                               | To dismantle and renew front bumper and bonnet. Re-organise crash management components. Reinstall all parts removed.          | \$ <del>2,100.00</del> 1000  |                            |
| 3                               | To respray front bumper and bonnet.                                                                                            | \$ <del>2,000.00</del> 1100. |                            |
| photo. 4                        | To carry out first measurement test on car o-liner                                                                             | S/N \$ 800.00 ✓              |                            |
| 5                               | To remove and renew rear parking aid and rear lid kick sensor.                                                                 | S/N \$ 360.00 ✓              |                            |
| <b>SUB TOTAL LABOUR CHARGES</b> |                                                                                                                                | <b>: <u>\$ 5,620.00</u></b>  |                            |

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle. SKE 735 G

| S/n                             | Nature of Jobs                                                                                                                                 | Estimated Charges    | Surveyor's Recommendations |
|---------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------|----------------------|----------------------------|
| 6                               | To remove and reinstall rear wire harness, audio equipment, control units, relay, fuse and relay trays, end panelling and spare wheel housing. | S/N \$ 1,800.00 ✓    |                            |
| 7                               | To remove and reainstall rear seats, back rest, carpets, ABCD pillar trims, disengage airbag system.                                           | S/N \$ 1,800.00 ✓    |                            |
| 8                               | To remove exhaust system and fuel tank assy. Renew centre and rear exhaust silencer if necessary.                                              | S/N \$ 780.00 ?      |                            |
| 9                               | To remove and install rear suspension assy to facilitate car-o-liner repairs. Inspect for damages and renew accordingly.                       | S/N \$ 2,800.00 ✓    |                            |
| 10                              | To place vehicle on car o-liner.                                                                                                               | S/N \$ 1,800.00 ✓    |                            |
| <b>SUB TOTAL LABOUR CHARGES</b> |                                                                                                                                                | <b>: \$ 8,980.00</b> |                            |

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle. SKE 735 G

| S/n                         | Nature of Jobs                                                                                                                                                                                                                               | Estimated Charges     | Surveyor's Recommendations |
|-----------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------|----------------------------|
| 11                          | To dismantle and renew rear bumper. Cut out and reweld rear end panelling, spare wheel housing and cross members. Repair and align whole rear substructure to position. Reorganise crash management components. Reinstall all parts removed. | \$ 5,600.00           | 3500.                      |
| 12                          | To carry out stone chip primer work on rear panelling and spare wheel housing.                                                                                                                                                               | S/N \$ 780.00         | ✓                          |
| 13                          | To spray paint on rear bumper, spare wheel housing and <sup>end panel</sup> boot floor. To carry out joint sealer works and cavity preservation.                                                                                             | \$ 3,000.00           | 1650.                      |
| 14                          | To carry out wheel alignment.                                                                                                                                                                                                                | S/N \$ 240.00         | ✓                          |
| 15                          | To carry out diagnostic check.                                                                                                                                                                                                               | S/N \$ 192.00         | ✓                          |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                                                                                                                              | <b>: \$ 24,412.00</b> |                            |

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SKE 735 G

| S/N | Parts Description                                        | Damaged Parts & Prices |          | Remarks |
|-----|----------------------------------------------------------|------------------------|----------|---------|
|     |                                                          | S/Nett                 |          |         |
| 1   | FRONT BUMPER <i>Deformed</i>                             | \$                     | 1,946.00 | ✓       |
| 2   | FRONT BUMPER FIXING PARTS                                | \$                     | 258.00   | +       |
| 3   | FRONT BUMPER SECURING STRIP <i>2 pieces</i>              | 2 \$                   | 64.00    | +       |
| 4   | FRONT BBUMPER GRILLE - CENTRE                            | \$                     | 178.00   | +       |
| 5   | FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>1 pc</i>  | \$                     | 191.00   | +       |
| 6   | RADIATOR GRILLE <i>crushed</i>                           | \$                     | 1,666.00 | ✓       |
| 7   | FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>1 pc</i>      | 2 \$                   | 666.00   | +       |
| 8   | FRONT BUMPER FOAM FILLER PIECE <i>?</i>                  | \$                     | 113.00   | ?       |
| 9   | FRONT BUMPER CARRIER <i>?</i>                            | \$                     | 733.00   | ?       |
| 10  | FRONT BUMPER COVER <i>1 pc</i>                           | \$                     | 116.00   | +       |
| 11  | CAUTION SIGN STICKER <i>2 pcs</i>                        | NEC \$                 | 13.00    | +       |
| 12  | AIRCON STICKER                                           | NEC \$                 | 7.00     | +       |
| 13  | LOCK CARRIER BRACKET                                     | \$                     | 125.00   | +       |
| 14  | FRONT BUMPER SUPPORT - LH / RH <i>2 pcs</i>              | 2 \$                   | 52.00    | +       |
| 15  | HORN - LH HIGH TONE                                      | \$                     | 37.00    | +       |
| 16  | HORN - RH HIGH TONE                                      | \$                     | 262.00   | +       |
| 17  | SPRING SHACKLE - LH / RH                                 | 2 \$                   | 52.00    | +       |
| 18  | BONNET <i>Dented</i>                                     | \$                     | 2,554.00 | ✓       |
| 19  | BONNET ATTACHMENT PARTS <i>1 pc</i>                      | \$                     | 111.00   | +       |
| 20  | BONNET IMPACT PROTECTION - CENTRE / LH / RH <i>3 pcs</i> | 3 \$                   | 75.00    | ✓       |

**SUB TOTAL SPARE PARTS**

**: \$ 9,219.00**

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SKE 735 C

| S/N                          | Parts Description                       | Damaged Parts & Prices |                    | Remarks |
|------------------------------|-----------------------------------------|------------------------|--------------------|---------|
|                              |                                         | S/Nett                 |                    |         |
| 21                           | BONNET BOWDEN CABLE                     | \$                     | 53.00              | x       |
| 22                           | BONNET BOWDEN CABLE - CENTRE            | \$                     | 53.00              | x       |
| 23                           | BONNET RELEASE LEVER                    | \$                     | 12.00              | x       |
| 24                           | RADIATOR AIR GUIDE - LH / RH            | 2 \$                   | 50.00              | x       |
| 25                           | RADIATOR AIR GUIDE - LH / RH            | 2 \$                   | 22.00              | x       |
| 26                           | RADIATOR AIR GUIDE - UPPER              | \$                     | 15.00              | x       |
| 27                           | RADIATOR AIR GUIDE - LOWER              | \$                     | 19.00              | x       |
| 28                           | REAR BUMPER <i>Del</i>                  | \$                     | 2,015.00           | ✓       |
| 29                           | REAR BUMPER FIXING PARTS                | \$                     | 66.00              | ?       |
| 30                           | REAR BUMPER SECURING STRIP              | \$                     | 203.00             | ✓       |
| 31                           | REAR BUMPER SPOILER - LH <i>Del</i>     | \$                     | 227.00             | ✓       |
| 32                           | REAR LIGHT REFLECTOR - LH / RH          | 2 \$                   | 76.00              | x       |
| <i>photo</i> 33              | REAR BUMPER CARRIER <i>Bert</i>         | \$                     | 819.00             | ✓       |
| 34                           | REAR BUMPER SEAL                        | 2 \$                   | 25.00              | ?       |
| 35                           | REAR BUMPER GUIDE SECTION - LH          | \$                     | 40.00              | x       |
| 36                           | REAR BUMPER GUIDE SECTION - RH          | \$                     | 41.00              | x       |
| 37                           | REAR BUMPER GUIDE SECTION - LH / RH     | 2 \$                   | 40.00              | x       |
| 38                           | AERIAL RETAINER                         | \$                     | 23.00              | ?       |
| 39                           | TELEPHONE AERIAL                        | \$                     | 164.00             | ?       |
| 40                           | REAR PARKING AID SENSOR - INNER / OUTER | 4 \$                   | 924.00             | ?       |
| <b>SUB TOTAL SPARE PARTS</b> |                                         | <b>:</b>               | <b>\$ 4,887.00</b> |         |

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SKE 735 G

| S/N | Parts Description                  | Damaged Parts & Prices |             | Remarks |
|-----|------------------------------------|------------------------|-------------|---------|
|     |                                    | S/Nett                 |             |         |
| 41  | REAR PARKING AID SEAL RING ?       | 4                      | \$ 12.00    | ?       |
| 42  | REAR BUMPER WIRING SET ?           |                        | \$ 618.00   | ?       |
| 43  | BOOT LID CONTROL UNIT              |                        | \$ 350.00   | +       |
| 44  | TAILGATE OPENING SENSOR LINE { for |                        | \$ 190.00   | x       |
| 45  | REAR CROSS PANEL ? Distorted       |                        | \$ 238.00   | ✓       |
| 46  | CROSS PANEL REINFORCEMENT          |                        | \$ 461.00   | ✓       |
| 47  | SPARE WHEEL WELL Distorted         |                        | \$ 2,020.00 | ✓       |
| 48  | REAR SILENCER HEAT SHIELD - LH ?   |                        | \$ 139.00   | ?       |
| 49  | HEAT SHIELD - CENTRE ?             |                        | \$ 62.00    | ?       |
| 50  | LUGGAGE COMPARTMENT FLOOR xel on   |                        | \$ 648.00   | +       |
| 51  | REAR CROSS PANEL TRIM ?            |                        | \$ 154.00   | ?       |
| 52  | INSERT PART ?                      |                        | \$ 247.00   | ?       |
| 53  | STOWAGE COMPARTMENT xel on         |                        | \$ 83.00    | x       |
| 54  | REAR SILENCER HEAT SHIELD - LH ?   |                        | \$ 999.00   | ?       |
| 55  | REAR SILENCER DUAL CLIP ?          |                        | \$ 45.00    | ?       |
| 56  | EXHAUST SILENCER BRACKET ?         |                        | \$ 38.00    | ?       |
| 57  | CENTRE SILENCER ?                  |                        | \$ 902.00   | ?       |
| 58  | CENTRE SILENCER DUAL CLIP ?        |                        | \$ 45.00    | ?       |
| 59  | DUAL CLIP ?                        |                        | \$ 45.00    | ?       |
| 60  | FRONT NO PLATE Dented              | S/N                    | \$ 40.00    | ✓       |
| 61  | ACRYLIC SEALANT {                  | S/N                    | \$ 180.00   | ✓       |
| 62  | CAVITY WAX { for                   | S/N                    | \$ 140.00   | ✓       |
| 63  | STONE CHIP                         | S/N                    | \$ 180.00   | ✓       |
| 64  | SUNDRIES ?                         |                        | \$ 600.00   | ?       |

|                             |                       |
|-----------------------------|-----------------------|
| <b>TOTAL SPARE PARTS</b>    | <b>: \$ 22,542.00</b> |
| <b>TOTAL LABOUR CHARGES</b> | <b>: \$ 24,412.00</b> |
| <b>GRAND TOTAL</b>          | <b>: \$ 46,954.00</b> |

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

**Name** : Adrian King  
**Surveyed Date** : 08/01/20  
**Authorised Date** :  
**Excess Cost** :  
**Liability** :  
**Remarks** : Not Authorised, 16 Days.

**Please Note** : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant