

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 9834K****AAD2001-027***Not Authored  
11/1/2020*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

07 JAN 2020

**SHD 9834K**

VF1ABL15AUC277415

RENAULT

LATITUDE

4.1.2020

**III**

25/4/2014

**PART**

- 1 BUMPER COVER FRT
- 1 BUMPER SPOILER FRT
- 1 BUMPER ABSORBER FRT
- 1 BUMPER RETAINER FRT LH
- 1 BUMPER SUPPORT FRT
- 1 BUMPER UNDERTRAY FRT
- 1 BUMPER GRILLE LOWER FRT
- 1 BUMPER FOG LAMP GRILLE LH
- 1 BUMPER BEAM FRT
- 1 HEADLAMP LH
- 1 HEADLAMP PANEL FRT LH
- 1 FENDER PANEL FRT LH
- 1 WHEELARCH FRT LH
- 1 FENDER BRACKET FRT LH
- 1 FENDER BRACKET LOWER LH
- 1 FENDER INSULATOR LH
- 1 FRONT BRACE PANEL
- 1 BONNET
- 1 BONNET INSULATOR
- 1 BONNET STRUT LH
- 1 BONNET HINGE LH
- 1 BONNET LOCK
- 1 BONNET CABLE
- 1 BONNET CABLE COVER
- 1 BONNET SEAL OUTER
- 1 BONNET SEAL INNER
- 1 RADIATOR GRILLE

**LIST**

|    |      |          |     |
|----|------|----------|-----|
| \$ | mgcm | 747.20   | ✓   |
| \$ | sn   | 344.70   | X   |
| \$ | sn   | 394.68   | X   |
| \$ | dir  | 101.40   | ✓   |
| \$ | ra   | 10.70    | X   |
| \$ | sn   | 292.50   | X   |
| \$ | sn   | 147.00   | X   |
| \$ | sn   | 207.21   | X   |
| \$ | R    | 663.70   | X   |
| \$ | mgcm | 743.60   | ✓   |
| \$ | R    | 127.70   | X   |
| \$ | R    | 414.40   | ✓   |
| \$ | sn   | 112.30   | } X |
| \$ | sn   | 38.90    |     |
| \$ | sn   | 11.80    |     |
| \$ | sn   | 65.50    |     |
| \$ | R    | 177.22   |     |
| \$ | R    | 1,312.70 |     |
| \$ | sn   | 294.30   |     |
| \$ | sn   | 53.30    |     |
| \$ | R    | 236.50   |     |
| \$ | R    | 152.80   |     |
| \$ | sn   | 55.20    |     |
| \$ | sn   | 80.60    |     |
| \$ | sn   | 83.20    |     |
| \$ | sn   | 70.10    |     |
| \$ | sn   | 969.90   |     |

**Trans-cab Auto Services Pte Ltd****AAD2001-027**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 9834K**

|   |                                 |    |          |                |
|---|---------------------------------|----|----------|----------------|
| 1 | RADIATOR GRILLE BADGE 'RENAULT' | \$ | 225.36   | } <i>Prz X</i> |
| 1 | RADIATOR GRILLE FRAME           | \$ | 686.00   |                |
| 1 | FRAME FULL SUPPORT PANEL        | \$ | 592.70   |                |
| 1 | FRAME FULL SUPPORT BRACKET      | \$ | 41.60    |                |
| 1 | AIR CLEANER BOX                 | \$ | 464.20   |                |
| 1 | AIR CLEANER HOSE                | \$ | 175.85   |                |
| 1 | AIR CLEANER LOWER               | \$ | 271.26   |                |
| 1 | LOWER ARM LH L70Y               | \$ | 192.70   |                |
| 1 | KNUCKLE ARM LH L70Y             | \$ | 481.50   |                |
| 1 | ABSORBER FRT LH L70Y            | \$ | 274.10   |                |
| 1 | DRIVESHAFT LH                   | \$ | 1,355.70 |                |
| 1 | STABILIZER BAR FRT              | \$ | 427.90   |                |

|              |           |                  |
|--------------|-----------|------------------|
| <b>TOTAL</b> | <b>\$</b> | <b>13,097.98</b> |
| <b>10%</b>   | <b>\$</b> | <b>1,309.80</b>  |
|              | <b>\$</b> | <b>11,788.18</b> |

**Special Nett**

|      |                                 |    |                  |            |
|------|---------------------------------|----|------------------|------------|
| 1    | BUMPER CLIP FRT                 | \$ | <i>na</i> 66.00  | } <i>X</i> |
| 1    | BUMPER BRACKET CLIP FRT LH      | \$ | <i>na</i> 12.00  |            |
| 1    | BUMPER SUPPORT CLIP FRT LH      | \$ | <i>na</i> 10.50  |            |
| 1    | BUMPER GRILLE LOWER CLIP        | \$ | <i>na</i> 69.00  |            |
| 1    | WHEELARCH CLIP FRT LH           | \$ | <i>na</i> 30.50  |            |
| 1    | FRAME FULL SUPPORT PANEL CLIP   | \$ | <i>na</i> 70.00  |            |
| 1SET | FRAME FULL SUPPORT PANEL NUT    | \$ | <i>na</i> 20.00  |            |
| 2    | FRAME FULL SUPPORT PANEL STUD   | \$ | <i>na</i> 30.00  |            |
| 1SET | RADIATOR GRILLE SCREW           | \$ | <i>na</i> 16.00  |            |
| 1SET | RADIATOR GRILLE FRAME CLIP      | \$ | <i>na</i> 52.00  |            |
| 1    | FRONT LEFT TYRE                 | \$ | <i>sa</i> 300.00 |            |
| 1    | FRONT LEFT TYRE RIM             | \$ | <i>sa</i> 380.00 |            |
| 1    | FRONT LEFT TYRE RIM COVER       | \$ | <i>sa</i> 60.00  |            |
| 1SET | Front licence plate with holder | \$ | <i>sa</i> 80.00  |            |
| 6    | BONNET INSULATOR CLIP L70Y      | \$ | <i>na</i> 7.30   |            |
| 2    | BONNET CABLE CLIP L70Y          | \$ | <i>na</i> 6.31   |            |
| 2    | BONNET CABLE COVER SCREW L70Y   | \$ | <i>na</i> 10.85  |            |

**Trans-cab Auto Services Pte Ltd****AAD2001-027**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 9834K****TOTAL \$ 1,220.47****TOTAL PARTS \$ 13,008.65****LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 6,000.00 *4001*

To transfer of front bumper fittings, attachment and perform water seepage test.

\$ *nn* 170.00 *X*

To transfer of front fender fittings, attachment and perform water seepage test.

\$ 170.00 *X*

To transfer of tire, rim and on wheel balancing.

\$ 170.00 *X*

To check steering geometry and computer wheel alignment

\$ 220.00 *X*

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ 380.00 *X*

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ 380.00 *X*

To transfer of bonnet fittings, attachment and perform water seepage test.

\$ 170.00 *X*

Putty and spray painting of the affected portion.

\$ 6,000.00 *4401*

To dismantle and refit front end suspension, undercarriage parts, final checking and testing.

\$ 380.00 *X*

To Check Electrical Lighting Concerned.

\$ 170.00 *201*

**Trans-cab Auto Services Pte Ltd****AAD2001-027**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 9834K**

To check ABS and brake efficiency, final checking and testing.

\$ *na* 380.00 *x*

To rust-proofing of the affected areas.

\$ 170.00 *301***TOTAL \$ 14,760.00****Over All Total \$ 27,768.65****LUMP SUM (REPAIR DAY)***20 days**2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: