

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG20000540/UQD3S2**Date:** 14/01/2020**REFERENCE**

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1001208043

Claimant Vehicle No : SJW2886H**Insured Vehicle No :** YP4729A

Date of Loss: 07/01/2020

Nature of Claim: TP

Claim No: 236953

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJW2886H**

Make & Model: BMW 520I, 2.0 LED NAV MSPT (A)

Engine No: B489I470N46B20BE

Reg. Date: 08/02/2010 (Man. Year: 2009)

Chassis No: WBANT12060CX30166

Colour: Black

Odometer: 181780 km

Engine Capacity: 1995 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Fair Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R17

Rear Tyre Size: 225/50 R17

Front Left Side: Bridgestone 5 mm

Rear Left Side: Bridgestone 5 mm

Front Right Side: Bridgestone 5 mm

Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 08/01/2020

Date Inspected: 08/01/2020 Inspected At:

Imperium Automotive - Kaki Bukit (HQ)

25 Kaki Bukit Road 4, #01-49 Synergy@KB

Singapore 417800

Estimated Period of Repair: 0.0 days

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

1/14/2020

Adjuster Report

PLEASE BE INFORMED OWNER THAT THE VEHICLE NOT ECONOMICAL FOR REPAIR.

MARKET VALUE: \$22,500.00 (est)

LTA REBATE: \$21,105.00

NETT VALUE: \$1,395.00

IN VIEW OF THE ABOVE, THE VEHICLE IS UNECONOMICAL TO BE REPAIRED.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 14 Jan 2020)

Parts: 143 BMW 520I 2.0 LED NAV MSPT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJW2886H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >