



FALCON - AIR AUTO SERVICES PTE LTD

Co. Reg. No.: 199501140D
GST Reg. No.: 199501140D

FALCON - AIR

LO SHEK SUM ERIC
C/O 176 SIN MING DRIVE #01-06/07
SIN MING AUTOCARE 575721Attention: Motor Claim Department
Contact: 96820151

Not Authorized
11 Sep 87
Return After Paint
6 *4-5 days*
summary on 8/1/20

Estimate: ES011977

Date: 08/01/2020
Vehicle Num.: SDN 388K
Make/Model: BMW 320i-2010/2011
Chassis/Eng#: VVBAPG56030NM26487
Accident Date: 06/01/2020
Claim No.: CMTD2000122/AGC
Reference: TP - MSIG AGT SOMPO (SM)
Policy No.: B 27073961 SMP

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS:				
1.	1 PC	BOOT COVER	1232.00	1,491.50 ✓
2.	1 PC	BOOT COVER LOGO	62.00	62.00 ✓
3.	1 PC	BOOT COVER EMBLEM (320i)	58.00	58.00 ✓
4.	2 PCS	BOOT COVER REFLECTOR	513.00	1,026.00 ✓
5.	1 PC	BOOT COVER SWITCH		102.65 7✓
6.	1 PC	BOOT COVER LOCK		244.50 7✓
7.	2 PCS	BOOT COVER HINGE	142.85	285.70 7X
8.	1 PC	BOOT COVER WEATHERSTRIP	79.53	79.53 7✓
9.	1 PC	BOOT COVER INNER TRIM	224.25	224.25 X
10.	1 PC	REAR BUMPER	1182.00	1,182.00 ✓
11.	10 PCS	REAR BUMPER CLIP	5.00	50.00 ✓
12.	2 PCS	REAR BUMPER SIDE RETAINER	102.20	204.40 7✓
13.	1 PC	REAR BUMPER CENTER RETAINER		115.20 7✓
14.	1 PC	REAR BUMPER REINFORCEMENT		600.85 7✓
15.	2 PCS	REAR BUMPER SENSOR	298.05	596.10 7✓
16.	1 SET	REAR BUMPER SENSOR WIRE		364.00 7
17.	1 PC	REAR BUMPER TOW COVER		82.15 ✓
18.	1 PC	REAR END PANEL		788.30 7✓
19.	1 PC	REAR END PANEL GARNISH		185.95 7
20.	1 PC	SPARE TYRE BOARD		475.85 X
21.	2 PCS	TAILLAMP	563.00	1,126.00 7✓
22.	2 PCS	TAILLAMP RETAINER	68.00	136.00 X
List Total S\$:			5701.62	10,579.85
5.00% Discount S\$:			285.08	528.99
			5416.53	10,050.86

9574 - 9754

CONTINUE / ...

Parts - 5416.53
S/N - 122.52
Labour - 1610.00
Total - 7149.05
LS 20% - 5719.24
LS - \$5700.00

FALCON - AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S[575721] Tel: 6452-0880 / 6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S[528840] Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop (Blk 1/Blk K) S[128226] Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg



FALCON - AIR

LO SHEK SUM ERIC
C/O 176 SIN MING DRIVE #01-06/07
SIN MING AUTOCARE 575721

Attention : Motor Claim Department

Contact : 96820151

Estimate : ES011977

Date : 08/01/2020
Vehicle Num. : SDN 388K
Make/Model : BMW 320i-2010/2011
Chassis/Eng# : WBAPG56030NM26487
Accident Date : 06/01/2020
Claim No. : CMTD2000122/AGC
Reference : TP - MSIG AGT SOMPO (SM)
Policy No. : B 27073961 SMP

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1 PC	SPECIAL NETT ITEMS : REAR NUMBER PLATE		Net 45.00 ✓
		Special Nett Total S\$:		45.00
		LABOUR :		
		TO CHECK REAR WIRING	50.00	201
		TO TRANSFER TAILGATE MECHANISM	120.00	601
		TO REMOVE/REFIX TRIMS, ETC TO FACILITATE REPAIRS	280.00	601
		TO FIT REVERSE SENSOR INTO NEW BUMPER	50.00	✓
		TO CONDUCT WATER TEST TO CHECK FOR LEAKAGE	50.00	201
		TO APPLY BODY SEALANT TO CAR JOINTS	160.00	740
		TO RUSTPROOF ACCIDENT DAMAGE AREA	160.00	740
		TO STRAIGHTEN LH/RH REAR CHASIS, SPARE TYRE PANEL, LH/RH REAR FENDER, CUT OUT/RE-WELD REAR END PANEL AND REPLACEMENT OF PARTS	1,200.00	600.00 ✓
		TO SPRAY PAINT ON BOOT COVER, REAR BUMPER, REAR END PANEL, REAR COMPARTMENT PANEL, LH/RH REAR FENDER	1,280.00	8001
		Labour Total S\$:		3,350.00

SingDollars : Thirteen Thousand Four Hundred Forty-Five & Cents Eighty-Six Only

E. & O.E.

Total S\$: 13,445.86

for FALCON AIR AUTO SERVICES PTE LTD

The quotation was prepared from visual inspection. Further materials and labour charges may be required when repair commences. We will advise you accordingly.