

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: AIG	DATE	: 6-Jan-20
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: TP CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SMG2953X		
MODEL	: HONDA FREED 1.5G A		6B71082096
CHASSIS NO			Ashes.
<u>ACCIDENT DETAILS</u>		DATE	: 5-Jan-20
		TIME	: 12:45HRS
THIRD PARTY REQUESTOR / CONTACT	:	JACK LI	

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAIL GATE <i>Distorted</i>	1	\$ 1,460.30	\$ 1,460.30 ✓ 1115
2	TAIL GATE LOGO	1	\$ 72.30	\$ 72.30 ✓
3	TAIL GATE EMBLEM 'FREED'	1	\$ 76.40	\$ 76.40 ✓
4	TAIL GATE EMBLEM 'HYBRID'	1	\$ 76.40	\$ 76.40 ✓
5	TAIL GATE INNER HOLDER <i>new</i>	1	\$ 80.00	\$ 80.00 +
6	TAIL GATE INNER TRIM <i>curved</i>	1	\$ 460.00	\$ 460.00 = 288
7	TAIL GATE TOP LOCK <i>Dented</i>	1	\$ 255.90	\$ 255.90 ✓
8	TAIL GATE WEATHERSTRIP <i>cut</i>	1	\$ 241.70	\$ 241.70 ✓
9	TAIL GATE WINDSCREEN MOULDING <i>new</i>	1	\$ 194.20	\$ 194.20 -
10	NUMBER PLATE LAMP CHROME <i>new</i>	1	\$ 320.00	\$ 320.00 +
11	NUMBER PLATE LAMP(SET) <i>new</i>	1	\$ 168.50	\$ 168.50 +
12	REAR BUMPER <i>Dented</i>	1	\$ 1,155.60	\$ 1,155.60 ✓ 783
13	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 69.70	\$ 139.40 -
14	REAR BUMPER TOW HOOK COVER <i>new</i>	1	\$ 55.90	\$ 55.90 +
15	REAR BUMPER INNER HOLDER <i>new</i>	2	\$ 80.50	\$ 161.00 +
16	REAR FENDER INNER TRIM <i>new</i>	2	\$ 655.50	\$ 1,311.00 +
17	REAR END PANEL (OUTER) <i>Dented</i>	1	\$ 655.50	\$ 655.50 ✓
18	REAR END PANEL (INNER) <i>Repair</i>	1	\$ 530.80	\$ 530.80 +

19	REAR END PANEL TOP GARNISH <i>Cracked</i>	1	\$ 190.00	\$ 190.00	✓
20	REAR FLOOR PANEL <i>Reps</i>	1	\$ 1,350.60	\$ 1,350.60	+
21	REAR FLOOR PANEL TOP BOARD <i>Neu</i>	1	\$ 1,180.60	\$ 1,180.60	+

408780

327024

TOTAL PRICE	\$ 10,136.10
LESS 20%	\$ 2,027.22
SUB TOTAL PRICE	\$ 8,108.88

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>slot neu</i>	1	\$ 50.00	\$ 50.00	+
2	TAIL GATE INNER TRIM CLIP(SET) <i>neu</i>	1	\$ 20.00	\$ 20.00	-
3	TAIL GATE WINDSCREEN SEALANT <i>neu</i>	1	\$ 80.00	\$ 80.00	60
4	REAR BUMPER CLIP(SET) <i>neu</i>	1	\$ 20.00	\$ 20.00	-
5	REAR END PANEL INSULATOR SEAL(OUTER) <i>neu</i>	1	\$ 120.00	\$ 120.00	60
6	REAR END PANEL INSULATOR SEAL(INNER) <i>neu</i>	1	\$ 120.00	\$ 120.00	+
7	REAR END PANEL TOP GARNISH CLIPS(SET) <i>neu</i>	1	\$ 20.00	\$ 20.00	-
8	REAR FLOOR PANEL INSULATOR SEAL <i>neu</i>	1	\$ 120.00	\$ 120.00	+
9	REAR REVERSE SENSOR <i>Reps</i>	1	\$ 220.00	\$ 220.00	200
10	REAR REVERSE CAMERA <i>neu</i>	1	\$ 550.00	\$ 550.00	+

380

TOTAL \$ 1,320.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

1	PANEL BEATING, WELDING, CUTTING, GRAZING ADJUST, KNOCK STRAIGHTEN	\$ 1,800.00	850	
2	TO PUTTY, SPRAY PAINT, POLISH, WAX	\$ 1,800.00	850	
3	TO APPLY RUST PROOFING/ UNDER COAT	\$ 250.00	80	
4	WIRNING, BULB CHECKING	\$ 80.00	30	
5	REMOVE AND REFIX UPHOLSTERY, CUSHION, SEAT TO FACILITATE REPAIR	\$ 250.00	80	
6	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	✓	
7	TO TRANSFER TAIL GATE MECHANISM	\$ 80.00	✓	
8	CONDUCT WATER LEAKAGE TEST	\$ 100.00	+	
9	REMOVE AND REFIX REAR REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	80	
10	REMOVE AND REFIX REAR REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	60	

2210

TOTAL

\$4,640.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 9,428.88
TOTAL LABOUR COST : \$ 4,640.00
TOTAL REPAIR COST : \$ 14,068.88

APPROVED DETAILS

SURVEYOR :
CONTACT NO :

FAX :

PART BY PART / LUMP SUM :
NO OF DAYS :

Adrian Lij
H/s 07/01/20.

06 Days.

Total: 5860.24

H/s: A-7K.

A-7K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: