

LH Express Motor Trading

Blk 5038#01-405, Ang Mo Kio Ind. Park 2 Singapore 569541.

Email : dyeo.lhmotortrading@gmail.com

Fax: 64816131 Tel : 64817221

Not Ashark

Li Rep 8?

Resurvey After Paint

4-5 days

Ng Boon Li Jeffrey

Blk 540 Hougang Ave 8 #08-1235

Singapore 530540.

Vehicle No : SKT 3818 C

Chassis No : KJ10-006682

Make : NISSAN DUALIS 2.0G A

Year : 2017

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

QTY	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

2	Rear Side Retainer LH/RH	\$26.50	<i>Rn</i> \$53.00 <i>X</i>
1	Rear Wheel Arch Garnish LH		<i>Rn</i> \$237.30 <i>X</i>
2	Tail Lamp LH/RH	<i>MS?</i> \$365.00	<i>MS Rn</i> \$730.00 <i>X</i>
1	Boot Lid		<i>Rn</i> \$1,530.60 <i>✓</i>
2	Boot Lid Reflector LH/RH	\$265.00 <i>MS?</i>	\$530.00
			<u>\$3,080.90</u>
			Less 30% \$924.27
			<u>\$2,156.63</u>

Nett Items

1	Boot Lid Lock	R	\$320.00	X
1	Boot Lid Emblem'DUALIS'	MS	\$60.00	✓
1	Boot Lid Emblem 'NISSAN' Logo	MS	\$58.00	✓
1	Rear Bumper	Rn	\$1,230.60	✓
1	Rear Sponge		\$220.00	?
1	Rear Number Plate Garnish	Rn	\$265.30	X
1	Tow Cover	Rn	\$21.30	X
1 set	Bumper Clip(Set)	MS	\$40.00	✓
1	End Panel		\$680.00	?
1	End Panel Top Garnish		\$126.00	?
1	Rear Bumper Stay LH/RH	R	\$90.00	X
			<u>\$3,111.20</u>	
			Less 10%	\$311.12

\$2,800.08

Special Nett Items

1	Reverse Censor
1	Rear Camera
1	Rear Windscreen Sealant

Short \$300.00 *2000m*
in \$450.00 *X*
me \$50.00 *400m*

Labour Charges

To remove and replaced damaged parts including straightening
repositioning replacement parts.

\$1,000.00 *7*

Supply Paint Material and necessary items. To respray replaced
and other affected panels

\$850.00 *6000*

To remove/refit wire harness, all related connectors. Check for proper
functions.

\$150.00 *200*

To remove/refit rear windscreen and check water leakage.

\$150.00 *1200*

To carry out antirust treatment on affected panels.

\$100.00 *?*

To perform diagnostic check on control units. Reset to factory specification.

\$350.00 *7*

Grand Total :

\$8,356.71