



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
#08-1339 Singapore 470130
Tel: 9450 7920
* zoomautowerks@gmail.com

8 January 2020

Not Authorized

2/5 @ 6650
9 dy.

REG NO.: SKA 9269 Y
MAKE/MODEL: TOYOTA COROLLA ALTIS

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
	<u>LIST ITEMS</u>	
1	Rear windscreen glass	\$ 11 1,304.57 X
1	Rear windscreen moulding	\$ 22 89.50
1	Rear boot lid	\$ 7.5 778.20
2	Rear boot hinges	\$ 2 173.80 X
1	Rear boot inner trim	\$ 2 189.60 X
1	Rear boot lamp o/s	\$ 320 181.50
1	Rear boot inner lock	\$ 221 166.75
1	Rear boot logo	\$ 22 58.50
1	Rear boot outer chrome moulding	\$ 22 281.65
1	Rear boot weatherstrip	\$ 70.2 165.60
1	Rear boot "COROLLA" emblem	\$ 22 45.30
1	Rear boot "ALTIS" emblem	\$ 22 42.50
1	Rear boot "1.6" emblem	\$ 22 38.40
2	Rear boot number plate lamps 41.50	\$ 22 85.20 1PC
2	Rear taillamps	\$ 22 781.90
2	Rear taillamp panels 450.50	\$ 22 930.00 1PC
1	Rear bumper spray	\$ 70.2 171.00
1	Rear end panel 615.20	\$ 22 762.60
1	Rear end panel inner garnish	\$ 22 192.50
1	Rear bumper 520.30	\$ 22 560.60
2	Rear bumper side brackets 42.90	\$ 22 97.00 1PC
2	Rear bumper reflectors 66.50	\$ 22 151.00 1PC
2	Rear bumper side retainers 60.80	\$ 22 131.00 1PC
1	Rear floor panel	\$ 22 857.60 X
1	Rear floor board	\$ 70.2 363.40
1	Rear exhaust silencer	\$ 22 881.70 X
2	Rear exhaust mountings	\$ 22 97.20 X
2	Rear fenders 1081.60	\$ 22 2,163.20 1PC
1	Rear fender inner air vent o/s	\$ 22 111.20
2	Rear fender inner trims 311.45	\$ 22 622.90 1PC
		\$ 12,475.87
	Less 25%	\$ 3,118.97
		\$ 9,356.90

N/S

N/S R o/s

6658.65
25%
4993.91

Signature:

Date:

SPECIAL NETT ITEMS

- | | |
|---|-------------------------------|
| 1 | Rear windscreen sealant |
| 1 | Rear bumper clip (1 set) |
| 1 | Rear number plate with holder |
| 1 | Rear reverse sensor (1 set) |

\$	net	80.00	40
\$	net	50.00	✓
\$	net	50.00	X
\$	shells	350.00	200
\$		530.00	

S/NLABOUR CHARGES

- | | |
|----|--|
| 1 | To remove, replaced damaged lamps and check up rear wiring. |
| 2 | To remove and refit inner garnishes. |
| 3 | To remove and refit rear reverse sensor. |
| 4 | To transfer boot lid mechanism and wiring assembly. |
| 5 | To remove and refit fuel tank assembly with all attachments. |
| 6 | To remove and refit rear windscreen glass. |
| 7 | To remove, refit and replace exhaust silencer and mountings. |
| 8 | To apply undercoating. |
| 9 | Panel beating. |
| 10 | To re-spray painting on the affected areas. |

\$		80.00	30
\$		150.00	80
\$		150.00	50
\$		120.00	60
\$	11	150.00	X
\$		180.00	120
\$	11	120.00	X
\$		200.00	100
\$		1,600.00	1400
\$		1,500.00	1200
\$		4,250.00	

GRAND TOTAL :**\$ 14,136.90**

LRK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To insure damaged part(s) during resurvey
- Particulars are subject to confirmation
- Temporary survey is on a "Without Prejudice" basis
- No legal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

P-4993.91
S.V-290.00
L-3040.00

8323.91
202
6659.12