BY EMAIL: venessa.chan@fwd.com

Kaki Bukit Autohub, 2 Kaki Bukit Ave 2, #01-18 Singapore 417921

Tel No.: +65 6842 0051 / 6744 0510 Fax No.: +65 6741 0510

Company Reg. No.: 200616038C GST Registration No.: 200616038C

Our Ref:

SLQ 9478 P

Your ref:

SJJ 8089 X

7 January 2020

FWD SINGAPORE PTE LTD

6 TEMASEK BOULEVARD #18-01 SUNTEC TOWER FOUR SINGAPORE 038986

Attn: Motor Claims Department

Dear Sir/Madam.

NAME OF CLAIMANT: PHILHEIDMER VEHICLE NUMBER: SLQ 9478 P

YOUR INSURED VEHICLE NUMBER: SJJ 8089 X

ACCIDENT ON 07 Jan 2020 ALONG TPE TWDS CHANGI BEFORE SELETAR LINK EXIT

AT ABOUT 08:20 HOURS

We refer to your email/fax dated 07 Jan 2020 informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment LKK AUTO CONSULTANTS PTE LTD as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit Autohub 2 Kaki Bukit Avenue 2 #01-18 Singapore 417921

Contact Person:

6842 0051 / 6744 0510 (ZiTing)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully

FOR SURVEYOR:

Please initial here after completion of pre-repair inspection. Thank you! Appointed surveyor:

(Name & Signature):

Date & Time of Inspection:

N-51 AUTOMOTIVE PTE LTD