

TP A19

Page No. 1

Vic.

Vehicle No. SLK7410D HONDA VEZEL

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE (\$)	SURVEYOR ADJUSTMENT
PARTS (LIST ITEMS)				
1	TAILGATE <i>Distorted.</i>		1950.00	1100
1	TAILGATE HANDLE COVER <i>Del'd.</i>		55.00	✓
1	TAILGATE UPPER GARNISH <i>2mld</i>		550.00	2 325
2	TAILGATE RUBBER STOPPER @\$6.00 <i>new</i>		12.00	x
1	TAILGATE "VEZEL" EMBLEM <i>new</i>		85.20	
1	TAILGATE EDGE WEATHERSHIP <i>wt.</i>		310.00	135
1	TAILGATE INNER TRIM GARNISH <i>Del'd</i>		660.50	285
1	TAILGATE HONDA LOGO <i>TR</i>		81.20	35
1	TAILGATE LOCK <i>Dmgd</i>		495.20	183
2	TAILGATE DAMPER LH & RH @\$300.00 <i>new</i>		600.00	x
1	REAR WIPER MOTOR <i>new</i>		355.00	x
2	REAR TAILGATE LAMP LH & RH @ 630.20	LH cut, RH <i>cmld</i>	1260.40	826
2	REAR TAILLAMP LH & RH @\$751.30	LH? , RH <i>cmld</i>	1502.60	949
2	REAR TAILLAMP PANEL LH & RH @\$299.50	<i>Repr</i>	599.00	x
1	REAR BUMPER <i>Distorted</i>		830.00	✓
2	REAR BUMPER SIDE RETAINER LH & RH @\$110.00 <i>new</i>		220.00	17
2	REAR BUMPER SIDE BRACKET LH & RH @\$91.00 <i>new</i>		182.00	x
2	REAR BUMPER REFLECTOR LH & RH @\$160.00 <i>new</i>		320.00	x
2	REAR BUMPER CORNER PANEL LH & RH @\$220.00	RH <i>Del'd</i>	440.00	220
2	REAR FENDER WHEEL ARCH LH & RH @\$283.00	<i>new</i> RH <i>2mld</i>	566.00	392
2	REAR FENDER INNER SHIELD LH & RH @\$226.10 <i>new</i>		452.20	x
1	REAR END PANEL <i>Distorted</i>		952.20	585
1	REAR END PANEL OUTER BEAM <i>new</i>		175.00	x
1	REAR END PANEL TOP GARNISH <i>Del'd</i>		280.00	98
1	REAR SPARE TYRE PANEL <i>Repr</i>		1258.00	x
1	REAR SPARE TYRE BOX LOWER COVER <i>Del'd</i>		242.10	✓
1	REAR SPARE TYRE BOX TOP GARNISH <i>Del'd</i>		650.00	307
1	REAR EXHAUST MOUNTINGS <i>new</i>		98.00	x
1	REAR EXHAUST SILENCE ASSY <i>Best</i>		980.00	598
1	REAR REMOTE CONTROL SENSOR <i>2mld</i>		258.00	85
			16419.60	
less 20%			3283.92	20%
			13135.68	
SPECIAL NETT ITEMS				
1 SET	REVERSE SENSOR <i>Dmgd</i>		280.00	200
1	REAR END PANEL SEALANT <i>new</i>		100.00	60
1	REAR END PANEL TOP GARNISH CLIPS <i>new</i>		80.00	10
1 SET	TAILGATE INNER TRIM CLIPS <i>new</i>		60.00	30
1	REAR WINDSCREEN SEALANTS <i>new</i>		100.00	60
1 SET	REAR BUMPER CLIPS <i>new</i>		80.00	30
Total Parts			13835.68	



ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-28

Singapore 417807

Tel:6702 4282 Fax:6702 4202

Page No. 2

Vehicle No. SLK7410D HONDA VEZEL

S/N	DESCRIPTION	REPAIRER'S ESTIMATE	OUR ASSESSMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs and replace damaged parts	1800.00	1100
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1200.00	1000
3	To remove and refix wiring at damaged areas	200.00	70
4	To perform anti rust treatment on affected areas	240.00	80
5	To remove & refix / replace rear trims, garnish and fitting so as to facilitate repairs as rear compartment	250.00	80
6	To remove and replace reverse sensors and check for proper functions	120.00	100
7	To remove and refix rear tailgate windscreen	150.00	120
Labour Total :		3960.00	
TOTAL (PARTS & LABOUR):		17795.68	

2510

Supplementary

2 Rees Fender Inner Trim Board @ 285 ^{Rebond} 570 ✓
 1 Rees Buzzer Sensor cauled. 635 508 65 ✓

total: 9245.68

y/s. 7.4K.

Supplementary: 508

07 Days

7.4K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: