

INS. CASE OWNER:

Gerald Poh.

CC4/LPC20000554/Fda3

LKK:

IDAC:

## ASSIGNMENT

Surveyor:

RAM

DOI: 07/01/2020

Date / Time : 07/01/2020

Registered in Merimen: \_\_\_\_\_

Pre-assign / CCU / FTE



Insured Vehicle No. : SJQ 6849X

Claim No. : 19/20/20/VP05/022873

Name of Insured : \_\_\_\_\_

Policy No. : \_\_\_\_\_

Insured Tel No. : \_\_\_\_\_

HP: \_\_\_\_\_

Make / Model : \_\_\_\_\_

Excess Sec II : S\$

D.O.A : 06/01/2020

Place of Accident : PIE TO ECP

Is driver the owner? ( YES / NO )

Nature of Accident : \_\_\_\_\_

If NO, Driver Name / Age : \_\_\_\_\_

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. : \_\_\_\_\_

(V/L: YES / NO )

Insured Liability : % Final ? Yes / No

SHA 3647P



INSRS:

WSP:

Tel :

Liability :

RMKS:

CDGE

LOYANG



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:

| Date / Time |                                                  | STAGE                             | DATE / PIC               |
|-------------|--------------------------------------------------|-----------------------------------|--------------------------|
|             | SJQ 6849X - CS/AIG16019137/Ggbn2; DOA: 07/10/16  | Non-Reporting ltr (1st):          |                          |
|             | SHA 3647P - CC3/FCI16014876/Kgbc2; DOA: 08/08/16 | Non-Reporting ltr (2nd):          |                          |
|             |                                                  | Non-Reporting ltr (Final):        |                          |
|             |                                                  | Notification ltr (if non-pickup): |                          |
|             |                                                  | Call OI:                          |                          |
|             |                                                  | After call ltr to OI:             |                          |
|             |                                                  | Documentation Check List:         | Handler Typist           |
|             |                                                  | Notification ltr (if non-pickup)  | <input type="checkbox"/> |
|             |                                                  | After call ltr to OI:             | <input type="checkbox"/> |
|             |                                                  | Authorisation To Act:             | <input type="checkbox"/> |
|             |                                                  | Release Voucher:                  | <input type="checkbox"/> |
|             |                                                  | Final Repair Bill:                | <input type="checkbox"/> |
|             |                                                  | Car Rental Invoice:               | <input type="checkbox"/> |
|             |                                                  | Towing Invoice:                   | <input type="checkbox"/> |
|             |                                                  | LTA / GIA :                       | <input type="checkbox"/> |
|             |                                                  | Medical Bill:                     | <input type="checkbox"/> |
|             |                                                  | PIR:                              | <input type="checkbox"/> |
|             |                                                  | Mandate/Reject Instruction:       | <input type="checkbox"/> |
|             |                                                  | LOD                               | <input type="checkbox"/> |
|             |                                                  | Payment Breakdown Form:           | <input type="checkbox"/> |
|             |                                                  | Post-Repair Photos:               | <input type="checkbox"/> |
|             |                                                  | Others:                           | <input type="checkbox"/> |

12/3/2020 - FILED PAS) TO HML TO LOSE

\* OI and TP settled privately and send the form to LPL. We only survey the vehicle.

|                                   |                                   |                                    |                                    |                                                              |
|-----------------------------------|-----------------------------------|------------------------------------|------------------------------------|--------------------------------------------------------------|
| <b>PRELIMINARY ADVICE</b>         |                                   | Date/Time:                         | Sent By:                           | Confirm by:                                                  |
| <b>FINALIZATION</b>               |                                   | Date/Time:                         | Confirm with:                      | Confirm by:                                                  |
| Repair Cost:                      | S\$                               | ( days)                            | Reduction:                         | %                                                            |
| <b>FINAL SETTLEMENT</b>           |                                   | Date/Time:                         | Confirm with:                      | Email <input type="checkbox"/> Call <input type="checkbox"/> |
| Final Liability:                  | %                                 | (Agreed / Assessed) BOLA S/N No. : |                                    | If NO or B 28, Ass. Lia :                                    |
| Repair Cost:                      | S\$                               |                                    |                                    |                                                              |
| Loss of Rental (LOR):             | S\$                               | ( days)                            |                                    |                                                              |
| Loss of Use (LOU):                | S\$                               | ( \$ x days)                       |                                    |                                                              |
| Loss of Income (LOI):             | S\$                               | ( \$ x days)                       |                                    |                                                              |
| LOR only <input type="checkbox"/> | LOU only <input type="checkbox"/> | LOR + LOU <input type="checkbox"/> | LOR + LOI <input type="checkbox"/> | [Tick only one]                                              |
| GIA/LTA Search                    | S\$                               |                                    |                                    |                                                              |
| Medical:                          | S\$                               |                                    |                                    |                                                              |
| Disbursement:                     | S\$                               | (e.g. Tow/ Independent )           |                                    |                                                              |
| Legal Cost                        | S\$                               |                                    |                                    |                                                              |
| Total:                            | S\$                               | Global Sum S\$:                    |                                    |                                                              |
| <b>FINAL PAYMENT</b>              |                                   | Date/Time:                         | Confirm with:                      | Email <input type="checkbox"/> Call <input type="checkbox"/> |
| Payee 1:                          | S\$                               | Name 1:                            |                                    |                                                              |
| Payee 2: (Strike if N.A.)         | S\$                               | Name 2:                            |                                    |                                                              |
| Payee 3: (Strike if N.A.)         | S\$                               | Name 3:                            |                                    |                                                              |

COPY SENT  
12/3/2020

1) Claim status: Normal/Reject/Private Settle

2) Report Format: WP

3) Survey fee: \$250

A.S.S. REC. BY: RamREF: lpc

## ASSIGNMENT

From:

Date:

7/01/2020

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SHA 3647P

at Workshop m/s

Comfort delgro

of

5a loyang drive

Insured:

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS lup

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SHA 3647PYr Regn: 26/06/2019Type: M.Car / M.Cycle / Bus / Van / Lorry / (Taxi) Prime Mover /

Truck / Trailer or

Make:

Hyundai iong (G2) c.c. 1580

Colour:

blue

A/C: Insured / Std / NI / NA

Sp. Reading

92265

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KMHCB81CVKU164331Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

DAVANTI

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

06/01/2020

D.O.I.

07/01/2020

Survey held at

comfort delgro (loyang)Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orrear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

PIR - \$ 6801.30 (Red \$ 1471.60 / 181)PIR

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Week end (\$

Survey Fee:

Transportation:

S = RS \$

Photos:

Others:

TOTAL

Report Format:

Lump Sum / L&amp;L: (\$

Our Job Ref No 305372205  
Date : 16.01.20

Toichan Jia

# COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

## FINALIZATION FORM

To : LKK

Fax :

Attn : Mr RAM

Vehicle Reg No. SHA3647P CTPL

06.01.20

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: LONPAC --- SJQ6849X
2. The finalized amount shall be:
  - (a) Spare Parts after List discount \$5,021.30
  - (b) Labour Charges \$1,780.00
  - Total for Part-By-Part Repair Cost \$6,801.30**
  - (c.) Lumpsum Repair (if applicable)  
Total for Lumpsum repair cost after Less: 20%  
**Final Lumpsum Repair cost**

3. Estimated normal period for repairs: 4 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.


We confirm the estimates and finalized amount

Signature : 

Name : LIM KWOK ENG

Tel : 62148316

Fax : 65468156

Signature : 

Name : Ram

Date : 17/1/2020

### For Official Use Only

| Item                                                 | Amount | Document Attached Yes or No | Confirm By (Signature) | Remarks |
|------------------------------------------------------|--------|-----------------------------|------------------------|---------|
| 1. Rental Rate P/Day                                 |        | YES                         |                        |         |
| 2. Loss of Income Paid                               |        | NO                          |                        |         |
| 3. Survey Fees                                       |        |                             |                        |         |
| 4. LTA Search Fee                                    | \$7.49 |                             |                        |         |
| 5. Medical Fees (on behalf of driver, if applicable) |        |                             |                        |         |
| 6. Overrun                                           |        |                             |                        |         |

Remarks:

# ComfortDelGro Engineering Pte Ltd

## REPAIR ESTIMATE

DATE: 06.01.2020

MODEL: HYUNDAI IONIQ (REAR)

VEHICLE NO.: SHA 3647P

INSURANCE: LON.PAC  
MVA: LKE

P1

| PART NO. | Description                                         | Qty | List Price | Amount      |         |
|----------|-----------------------------------------------------|-----|------------|-------------|---------|
|          | Boot Lid Trimboard Xnn                              |     |            | \$ 60.40    | X       |
|          | Licence Lamp Cover <del>GRN</del> Xnn               |     |            | \$ 35.10    | X       |
|          | Rear Bumper Bv                                      |     |            | \$ 459.40   | ✓       |
|          | Rear Bumper Reinforcement Bracket (LH & RH) 3Xnn    |     | \$138.10   | \$ 276.20   | X       |
|          | Rear Bumper Lower Centre Moulding Assy Xnn          |     |            | \$ 47.50    | ✓       |
|          | Rear Bumper Stay (LH & RH) Xnn                      |     | \$138.10   | \$ 276.20   | ✓       |
|          | Rear Bumper Side Bracket (LH) DIS                   |     |            | \$ 33.10    | ✓       |
|          | Rear Bumper Cover Clips nec                         |     |            | \$ 22.00    | ✓       |
|          | Rear Bumper Under Centre <del>GRN</del> ? Xnn       |     |            | \$ 53.85    | X       |
|          | Rear Bumper Side Under(LH) <del>GRN</del> ? Xnn     |     |            | \$ 27.50    | X       |
|          | Rear Bumper Rear Hook <del>GRN</del> Xnn            |     |            | \$ 15.40    | X       |
|          | Rear Bumper Reflector Lamp(LH) <del>GRN</del> Xnn   |     |            | \$ 31.90    | X       |
|          | Rear Bumper Fog Lamp Bv                             |     |            | \$ 201.50   | ✓       |
|          | Rear Bumper Towing Cover mus                        |     |            | \$ 98.80    | ✓       |
|          | Rear Bumper Reserve Light (Parking Brake Light) Xnn |     |            | \$ 257.10   | X       |
|          | Rear Bumper Reverse Sensor <del>GRN</del> SC        |     |            | \$ 135.70   | Nett ✓  |
|          | Bootlid Lamp(LH & RH) Xnn                           |     | \$794.40   | \$ 1,588.80 | X       |
|          | Rear Bumper Reflector Lamp(LH & RH) Xnn             |     | \$31.90    | \$ 63.80    | X       |
|          | Rear Panel DP take pic                              |     |            | \$ 532.00   | ✓       |
|          | Rear Panel Lower Panel Xnn                          |     | \$39.40    | \$ 78.80    | X       |
|          | Bootlid Assy <del>GRN</del> DP                      |     |            | \$ 2,840.40 | 2480.40 |
|          | Rear Bumper Reinforcement Bt takepic                |     |            | \$ 294.80   | ✓       |
|          | Rear Bumper Centre Moulding Assy GRN                |     |            | \$ 451.25   | ✓       |
|          | Boot Lid Glass, Upper Xnn nec                       |     |            | \$ 543.30   | ✓       |
|          | Boot Lid Glass, Lower Xnn nec                       |     |            | \$ 384.90   | ✓       |
|          | Boot Lid Lamp(LH/RH) Xnn                            |     | \$794.40   | \$ 1,588.80 | X       |
|          | Boot Lid 'H' Emblem <del>GRN</del> Xnn              |     |            | \$ 28.00    | ✓       |
| S        | Rear Number Plate                                   |     |            | \$ 25.00    | Nett ✓  |
| S        | Rear Number Plate Trim Cover Bv                     |     |            | \$ 30.00    | Nett ✓  |
| S        | Bootlid Emblem - IONIQ - nec                        |     |            | \$ 31.30    | ✓       |
| S        | Bootlid Emblem - Hybrid - nec                       |     |            | \$ 24.30    | ✓       |
|          | SUB TOTAL                                           |     |            | \$ 6,990.75 |         |
|          | LESS 20%                                            |     |            | \$ 1,398.15 |         |
|          | DISCOUNTED TOTAL                                    |     |            | \$ 5,592.60 |         |

LKK LONTAL

P2

| PART NO. | Description                                 | Qty | List Price | Amount      |
|----------|---------------------------------------------|-----|------------|-------------|
| PART NO. | Description                                 | Qty | List Price | Amount      |
|          |                                             |     |            |             |
|          |                                             |     |            |             |
| 5        | Boot lid Windscreen Sealant ra              | 2   |            | 46.00       |
|          | Boot Lid Comfort Logo & Tel No. Sticker rec |     |            | \$ 30.00    |
|          | Rear Bumper Rubber Mat rec                  |     |            | \$ 50.00    |
|          | TOTAL                                       |     |            | \$ 80.00    |
|          | Labour Charge                               |     |            |             |
|          | Panel Beating                               |     |            | \$ 1,200.00 |
|          | Spray Painting Charge                       |     |            | \$ 600.00   |
|          | Tuff Kote                                   |     |            | \$ 80.00    |
|          | Remove/Refix Reverse Sensor                 |     |            | \$ 120.00   |
|          | Remove/Refix Rear Windscreen Glass          |     |            | \$ 120.00   |
|          | TOTAL LABOUR                                |     |            | \$ 2,120.00 |
|          | ESTIMATE TOTAL                              |     |            | \$ 7,792.60 |

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

10684.80

10937.64

Raw (LKK)

07/01/2020 1310hrs

Rawesurim@lkkauto.com

88622778 hp

(4) repair days

Ref paint photo

(P/R)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# COMFORTDELGRO ENGINEERING

VEHICLE NO. : SHA3647P

MODEL IONIQ (G2)

JOB NO 305372205

TYPE OF CASE : TP-SJQ 6849X

SURVEY BY : LKK/RAH

DATE 1 07/01/20

### SUPPLEMENTARY OF PARTS AND LABOUR COSTS

[illegible]

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE

Date: 16.01.2020

Time: 17:34:02

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
 CUSTOMER: 7010045  
 ADDRESS : COMFORT TRANSPORTATION PTE LTD  
 383 SIN MING DRIVE  
 SINGAPORE SINGAPORE 575717  
 65508755

JOB NO : 305372205  
 REGN NO : SHA3647P  
 MILEAGE : 0000000000  
 MAKE : HYUNDAI  
 MODEL : IONIQ(G2)  
 DATE OF REGN : 26.06.2019  
 DATE/TIME IN : 06.01.2020 09:50  
 ACCIDENT DATE : 06.01.2020

## JOB / PARTS DESCRIPTION

## QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

|      |                   |                           |      |        |       |        |     |
|------|-------------------|---------------------------|------|--------|-------|--------|-----|
| 0001 | 04-01-0104-2282-G | IONIQVC COVER-RR BUMPER#  | 1 L  | 459.40 | 20.00 | 367.52 | Br  |
| 0002 | 04-01-0104-2531-G | IONIQVC BRACKET ASSY-RR B | 1 L  | 33.10  | 20.00 | 26.48  | Dis |
| 0003 | 04-01-0101-0111-G | HYUNDAI BUMPER COVER CLIP | 10 L | 22.00  | 20.00 | 17.60  | rec |
| 0004 | 04-01-0104-2544-G | IONIQVC CAP-RR HOOK       | 1 L  | 98.80  | 20.00 | 79.04  | ms  |
| 0005 | 04-01-0104-2370-G | IONIQ LAMP ASSY-REAR FOG  | 1 L  | 201.50 | 20.00 | 161.20 | Br  |
| 0006 | 09-01-9999-0068-A | HYUNDAI REVERSE SENSOR AS | 1 N  | 135.70 | 2.00- | 135.70 | SC  |
| 0007 | 04-01-0104-2288-G | IONIQ BEAM-RR BUMPER      | 1 L  | 294.80 | 20.00 | 235.84 | Bt  |
| 0008 | 04-01-0104-2533-G | IONIQV2 MOULDING ASSY-RR  | 1 L  | 451.25 | 20.00 | 361.00 | cr  |
| 0009 | 28-01-0103-0005-A | (I40/SONATA)REAR BOOT LOG | 1 N  | 20.00  | 2.00- | 20.00  | rec |
| 0010 | 28-01-0103-0006-A | (I40/SONATA)REAR BOOT TEL | 1 N  | 10.00  | 0.20  | 10.00  | rec |
| 0011 | FNPS              | NO PLATE(S) WITH TRIM COV | 1 N  | 55.00  | 0.02- | 55.00  | Br  |
| 0012 | 04-01-0104-2271-G | IONIQ EMBLEM-IONIQ        | 1 L  | 31.30  | 20.00 | 25.04  | rec |
| 0013 | 04-01-0104-2270-G | IONIQ EMBLEM-HYBRID       | 1 L  | 24.30  | 20.00 | 19.44  | rec |

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE

Date: 16.01.2020

Time: 17:34:02

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
 CUSTOMER: 7010045  
 ADDRESS : COMFORT TRANSPORTATION PTE LTD  
 383 SIN MING DRIVE  
 SINGAPORE SINGAPORE 575717  
 65508755

JOB NO : 305372205  
 REGN NO : SHA3647P  
 MILEAGE : 0000000000  
 MAKE : HYUNDAI  
 MODEL : IONIQ(G2)  
 DATE OF REGN : 26.06.2019  
 DATE/TIME IN : 06.01.2020 09:5  
 ACCIDENT DATE : 06.01.2020

## JOB / PARTS DESCRIPTION

## QTY IND UNIT-PRICE DISC% AMOUNT

|                        |                           |     |          |       |          |     |
|------------------------|---------------------------|-----|----------|-------|----------|-----|
| 0014 04-01-0104-1150-A | IONIQVC PROTECTOR MAT     | 1 N | 50.00    | 2.00- | 50.00    | nee |
| 0015 04-01-0104-2346-G | IONIQ PANEL ASSY-BACK     | 1 L | 532.00   | 20.00 | 425.60   | pp  |
| 0016 04-01-0104-2256-G | IONIQVC PANEL ASSY-TAIL G | 1 L | 2,480.40 | 20.00 | 1,984.32 | pp  |
| 0017 04-01-0104-2257-G | IONIQ GLASS ASSY-TAIL GAT | 1 L | 384.90   | 20.00 | 307.92   | nee |
| 0018 04-01-0104-2258-G | IONIQ GLASS ASSY-TAIL GAT | 1 L | 543.30   | 20.00 | 434.64   | nee |
| 0019 05-01-0199-0032-A | (ALL)WINDSCREEN AHESIVE-3 | 2 N | 46.00    | 2.00- | 46.00    | nee |
| 0020 04-01-0104-3819-G | IONIQ STAY-RR BUMPER LH   | 1 L | 138.10   | 20.00 | 110.48   | B+  |
| 0021 04-01-0104-3919-G | IONIQ STAY-RR BUMPER RH   | 1 L | 138.10   | 20.00 | 110.48   | B+  |
| 0022 04-01-0104-2545-G | IONIQVC MOULDING-REAR BUM | 1 L | 47.50    | 20.00 | 38.00    | crn |

SUB-TOTAL : 5,021.30

JOB NATURE

4704.6

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE

Date: 16.01.2020

Time: 17:34:02

Page: 3

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305372205  
REGN NO : SHA3647P  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : IONIQ(G2)  
DATE OF REGN : 26.06.2019  
DATE/TIME IN : 06.01.2020 09:  
ACCIDENT DATE : 06.01.2020

| JOB / PARTS DESCRIPTION |                                      | QTY    | IND | UNIT-PRICE | DISC% | AMOUNT   |
|-------------------------|--------------------------------------|--------|-----|------------|-------|----------|
| 0000 L                  | PANEL BEATING                        | 960.00 |     |            |       |          |
| 0001 23-502             | SPRAYPAINT ON AFFECTED AREA          | 600.00 |     |            |       |          |
| 0002 20-00              | TUFF COAT ON AFFECTED PARTS.         | 50.00  |     |            |       |          |
| 0003 20-22              | REMOVE/REFIX REVERSE SENSOR          | 50.00  |     |            |       |          |
| 0004 20-20              | REMOVE/REFIX RR W/SCREEN TO ASST R/P | 120.00 |     |            |       |          |
| SUB-TOTAL :             |                                      |        |     |            |       | 1,780.00 |
| TOTAL :                 |                                      |        |     |            |       | 6,801.30 |

MVA NAME & SIGNATURE  
DATE :

AUTHORISED : YES / NO  
SURVEYOR NAME & SIGNATURE  
DATE :

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order:

JC NO.: 305372205

OMER

S. COMFORT TRANSPORTATION PTE LTD  
7010045

OMER NO. 383 SIN MING DRIVE  
ESS Singapore SINGAPORE 575717  
65508755 (R) (Q)

(R)

(P)

JUNT CARD NO.

REGN NO.: SHA3647P

MILEAGE

MAKE : HYUNDAI

FUEL

E.....1/2.....F

MODEL IONIQ(G2)

DATE/TIME IN 06.01.2020 09:50

YR OF MANU 26.06.2019

TARGET DATE

CHASSIS CODE KMH851CVKU164331


COMPLETION DATE/TIME:

## JOB DESCRIPTION

Accident Date: 06.01.2020

NATURE: 3P 06.01.2020

S/NO LABOR CODE DESCRIPTION



KED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

Io.: SHA3647P

LKE

Vehicle No.: SHA3647P

Service Advisor

Signature/Date

Name of Service Advisor

Date

turned to Service Reception upon collection

To be kept by Security Guard



LKE LONPAC

P2

| PART NO. | Description                                        | Qty | List Price | Amount      |
|----------|----------------------------------------------------|-----|------------|-------------|
| PART NO. | Description                                        | Qty | List Price | Amount      |
|          |                                                    |     |            |             |
|          |                                                    |     |            |             |
|          |                                                    |     |            |             |
|          | Boot Lid Comfort Logo & Tel No. Sticker <i>rec</i> |     |            | \$ 30.00    |
|          | Rear Bumper Rubber Mat <i>rec</i>                  |     |            | \$ 50.00    |
|          | TOTAL                                              |     |            | \$ 80.00    |
|          | <b>Labour Charge</b>                               |     |            |             |
|          | Panel Beating                                      |     |            | \$ 1,200.00 |
|          | Spray Painting Charge                              |     |            | \$ 600.00   |
|          | Tuff Kote                                          |     |            | \$ 80.00    |
|          | Remove/Refix Reverse Sensor                        |     |            | \$ 120.00   |
|          | Remove/Refix Rear Windscreen Glass                 |     |            | \$ 120.00   |
|          | TOTAL LABOUR                                       |     |            | \$ 2,120.00 |
|          | ESTIMATE TOTAL                                     |     |            | \$ 7,792.60 |

Nett  
Nett  
\$960  
\$50  
\$50  
xun

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Ram (LKK)  
07/01/2020 13:10 hrs  
Rameshram@lkkauto.com  
88622778 hp  
(4) repair days  
Ref paint photo  
(P/R)

**Nivitha (LKK Auto)**

**From:** GERALD POH WEE BIN <geraldpoh@lonpac.com>  
**Sent:** Tuesday, 7 January 2020 8:44 AM  
**To:** 'assignments@lkkauto.com'  
**Cc:** MT\_Claim\_SG  
**Subject:** FW: SHA3647P with your insured SJQ6849X [External Confidential]  
**Attachments:** 2762\_001.pdf

**Lonpac External - Confidential**

Our Ref : 19/20/20/VP05/022873

Dear Nivitha,

Kindly proceed accordingly.


Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



*Lonpac External - Confidential data is for use by authorised external parties only.*

**From:** Lim Kwok Eng [mailto:limke@cdge.com.sg]

**Sent:** Monday, 6 January 2020 5:05 pm

**To:** MT\_Claim\_SG

**Cc:** Ng Nyuk Phin; Roger How Keen Meng

**Subject:** SHA3647P with your insured SJQ6849X

To Officer In Charge

pls arrange surveyor, refer attachments

Best Regards

Lim Kwok Eng

Taxi Crash Repairs / ComfortDelgro Engineering Pte Ltd

Tel. 6214-8355 / 6214-8156



Think Before Printing

8.59am 7/1/2020

P: Mr Lim

v: IN

s: Ram

---

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

ComfortDelGro Engineering Pte Ltd [Registration No: 199506048W]

---

Recovery Claims Unit  
59, Loyang Drive  
Singapore 508969

## COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd  
205 Braddell Road Singapore 579701

Mainline +65 6383 6280  
Facsimile +65 6280 9755

www.cdge.com.sg

Company Registration No: 199508048W

### Workshops

**Braddell**  
205 Braddell Road  
Singapore 579701

**Loyang**  
59 Loyang Drive  
Singapore 508969

**Sin Ming**  
383 Sin Ming Drive  
Singapore 575717

**Pandan**  
45 Pandan Road  
Singapore 609286

**Ubi**  
320 Ubi Road 3  
Singapore 408649

**Sungei Kadut**  
7 Sungei Kadut Way  
Singapore 728791

20-02-2020

NurSaledahwati Binte Saleh  
Blk 613,  
Bedok Reservoir Road  
#07-1182  
Singapore 470613

Dear Madam

**Re:- ACCIDENT INVOLVING SHA 3647P & SJO 6849X ON 06/01/2020  
ALONG P.I.E. (TOWARDS E.C.P.)**

We attach the original official receipts #180541 in settlement of our claims for the above two cases paid by yourself for the sum of S\$8,310.83 respectively.

We shall proceed to close our file accordingly as the matter towards the property damage claims only has been resolved. Thank you.

Regards

Yours sincerely,

  
Kazali Hj Selahudin (Email:- kazali@cdge.com.sg)  
CDGE Claims Department (Loyang)  
DID : 6214 8736 Fax : 6214 1843

A member of

COMFORTDELGRO

## MUTUAL SETTLEMENT

We, the undersigned, hereby agree to mutually settle the accident involving Motor vehicles No SHA 3647P and SJQ 6849X, which happened along P.I.E. (TOWARDS E.C.P.) on 06/01/2020 at 0755 hrs.

We further agree that the sum of S\$8,310.83 for loss and damage caused to SHA 3647P will be paid to ComfortDelGro Engineering Pte Ltd by Nursaledahwati Binte Saleh (on behalf of the owner/driver of SJQ 6849X) as full and final settlement to the above-mentioned accident and shall discharge the owner/driver of SJQ 6849X from any liability arising from the said accident.

The contents of this document apply to vehicle damages only. All personal injuries and damages arising there from are excluded from the ambit and application of this document.

ACCIDENT INVOLVING SHA 3647P AND SJQ 6849X ON 06.01.2020  
REPAIR JOB NO: 305372205 INVOICE NO: 91490053.

Dated this 21 day of 01 (Month) 2020 (Year)

Vehicle No: SJQ 6849X

NurS  
(Signature)

Name : NurSaledahwati Binte Saleh  
NRIC No: SXXXX576C  
Address: Blk 613 Bedok Reservoir Rd  
#07-1182 Singapore 470613  
Contact No : 9626 4184

Vehicle No: SHA 3647P

SALES DEPARTMENT  
COMFORTDELGRO ENGINEERING PTE LTD  
59 LOYANG DRIVE  
SINGAPORE 508969  
(Signature)

Name : KAZALI  
for ComfortDelGro Engineering Pte Ltd  
on behalf of the taxi owner and hirer/  
driver both by Letter of Authorisation  
Address: 59 Loyang Drive S(508969)

"The contents of this document apply to vehicle damages only  
All personal injuries and damages arising therefrom are excluded  
from the ambit and application of this document"



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                          |                              |                                                                                     |  |
|----------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------|------------------------------|-------------------------------------------------------------------------------------|--|
| LONPAC INSURANCE BHD                                                                                                                   |                                                                          | Ref : CC4/LPC20000554/Fda3s2 |                                                                                     |  |
| 300 BEACH ROAD<br>#17-04/07 THE CONCOURSESINGAPORE 199555                                                                              |                                                                          | Date : 06-04-2020            |  |  |
|                                                                                                                                        |                                                                          | Code : LPC2                  |                                                                                     |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                          |                              |                                                                                     |  |
| Insured Veh.                                                                                                                           | SJQ 6849X                                                                | Veh. Inspected               | SHA 3647P                                                                           |  |
| Policy No.                                                                                                                             |                                                                          | Coverage (\$)                | 0.00                                                                                |  |
| Claim No.                                                                                                                              | 19/20/20/VP05/022873                                                     | Excess (\$)                  | 0.00                                                                                |  |
| Assign From                                                                                                                            | GERALD POH                                                               | Assign Date                  | 07/01/2020                                                                          |  |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                          |                              |                                                                                     |  |
| Make & Model                                                                                                                           | HYUNDAI IONIQ                                                            | c.c                          | 1580                                                                                |  |
| Engine No.                                                                                                                             | HIDDEN                                                                   | Year of Reg.                 | 2019                                                                                |  |
| Chassis No.                                                                                                                            | KMHC851CVKU164331                                                        | Colour                       | BLUE                                                                                |  |
| Odometer                                                                                                                               | 92265                                                                    | Steering                     | IN ORDER                                                                            |  |
| Brakes                                                                                                                                 | IN ORDER                                                                 | Modification                 | SPORTS RIM                                                                          |  |
| General                                                                                                                                | GOOD                                                                     |                              |                                                                                     |  |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                          |                              |                                                                                     |  |
|                                                                                                                                        | Size                                                                     | Make                         | Balance                                                                             |  |
| R/H Front Tyre                                                                                                                         | 195/65 R15                                                               | DAVANTI                      | 9 mm                                                                                |  |
| L/H Front Tyre                                                                                                                         | 195/65 R15                                                               | DAVANTI                      | 9 mm                                                                                |  |
| R/H Rear Tyre                                                                                                                          | 195/65 R15                                                               | DAVANTI                      | 9 mm                                                                                |  |
| L/H Rear Tyre                                                                                                                          | 195/65 R15                                                               | DAVANTI                      | 9 mm                                                                                |  |
| <b>4. Description of Damages</b>                                                                                                       |                                                                          |                              |                                                                                     |  |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.<br>DAMAGES SEE DETAILS.                                                             |                                                                          |                              |                                                                                     |  |
| <b>5. General Information</b>                                                                                                          |                                                                          |                              |                                                                                     |  |
| Accident Date                                                                                                                          | 06/01/2020                                                               | Inspection Date              | 07/01/2020                                                                          |  |
| Survey held at                                                                                                                         | COMFORTDELGRO ENGINEERING PTE LTD<br>59 LOYANG DRIVE<br>SINGAPORE 508969 |                              |                                                                                     |  |
| <b>5a. Remarks</b>                                                                                                                     |                                                                          |                              |                                                                                     |  |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                          |                              |                                                                                     |  |
| <b>5b. Estimate Days of Repair</b>                                                                                                     |                                                                          |                              |                                                                                     |  |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                    |                                                                          | 4 Working Days               |                                                                                     |  |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 3647P

| Qty                         | Description of Parts                                   | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------|--------------------------------------------------------|---------------|---------------------------|-------------------|
| <b>REPLACEMENT OF PARTS</b> |                                                        |               |                           |                   |
| 1                           | BOOT LID TRIMBOARD                                     | NOT NECESSARY | 60.40                     | -                 |
| 1                           | LICENCE LAMP COVER                                     | NOT NECESSARY | 35.10                     | -                 |
| 1                           | REAR BUMPER                                            | BROKEN        | 459.40                    | 459.40            |
| 2                           | REAR BUMPER REINFORCEMENT BRACKET (LH & RH) @ \$138.10 | NOT NECESSARY | 276.20                    | -                 |
| 1                           | REAR BUMPER LOWER CENTRE MOULDING ASSY                 | NOT NECESSARY | 47.50                     | -                 |
| 2                           | REAR BUMPER STAY (LH & RH) @ \$138.10                  | NOT NECESSARY | 276.20                    | -                 |
| 1                           | REAR BUMPER SIDE BRACKET (LH)                          | DISTORTED     | 33.10                     | 33.10             |
| 1                           | REAR BUMPER COVER CLIPS                                | NECESSARY     | 22.00                     | 22.00             |
| 1                           | REAR BUMPER UNDER CENTRE                               | NOT NECESSARY | 53.85                     | -                 |
| 1                           | REAR BUMPER SIDE UNDER (LH)                            | NOT NECESSARY | 27.50                     | -                 |
| 1                           | REAR BUMPER REAR HOOK                                  | NOT NECESSARY | 5.40                      | -                 |
| 1                           | REAR BUMPER REFLECTOR LAMP (LH)                        | NOT NECESSARY | 31.90                     | -                 |
| 1                           | REAR BUMPER FOG LAMP                                   | BROKEN        | 201.50                    | 201.50            |
| 1                           | REAR BUMPER TOWING COVER                               | MISSING       | 98.80                     | 98.80             |
| 1                           | REAR BUMPER RESERVE LIGHT (PARKING BRAKE LIGHT)        | NOT NECESSARY | 257.10                    | -                 |
| 2                           | BOOTLID LAMP (LH & RH) @ \$794.40                      | NOT NECESSARY | 1,588.80                  | -                 |
| 2                           | REAR BUMPER REFLECTOR LAMP (LH & RH) @ \$31.90         | NOT NECESSARY | 63.80                     | -                 |
| 1                           | REAR PANEL                                             | DENTED        | 532.00                    | 532.00            |
| 2                           | REAR PANEL LOWER PANEL @ \$39.40                       | NOT NECESSARY | 78.80                     | -                 |
| 1                           | BOOTLID ASSY                                           | DENTED        | 2,840.40                  | 2,480.40          |
| 1                           | REAR BUMPER REINFORCEMENT                              | BENT          | 294.80                    | 294.80            |
| 1                           | REAR BUMPER CENTRE MOULDING ASSY                       | CRACKED       | 451.25                    | 451.25            |
| 1                           | BOOT LID GLASS, UPPER                                  | NECESSARY     | 543.30                    | 543.30            |
| 1                           | BOOT LID GLASS, LOWER                                  | NECESSARY     | 384.90                    | 384.90            |
| 2                           | BOOT LID LAMP (LH/RH) @ \$794.40                       | NOT NECESSARY | 1,588.80                  | -                 |
| 1                           | BOOT LID 'H' EMBLEM                                    | NOT NECESSARY | 28.00                     | -                 |
| 1                           | BOOTLID EMBLEM - IONIQ (ADDITIONAL)                    | NECESSARY     | 31.30                     | 31.30             |
| 1                           | BOOTLID EMBLEM - HYBRID(ADDITIONAL)                    | NECESSARY     | 24.30                     | 24.30             |
| 1                           | IONIQ STAY RR BUMPER LH                                | BENT          | 138.10                    | 138.10            |

Report Ref No. CC4/LPC20000554/Fda3s2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

| Qty                                | Description of Parts                           | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|------------------------------------------------|---------------|---------------------------|-------------------|
| 1                                  | IONIQ STAY RR BUMPER RH                        | BENT          | 138.10                    | 138.10            |
| 1                                  | IONIQVC MOULDING - REAR BUM                    | CRACKED       | 47.50                     | 47.50             |
|                                    | LESS 20% DISCOUNT                              |               | -2,132.02                 | -1,176.15         |
|                                    |                                                |               | 8,528.08                  | 4,704.60          |
| 1                                  | REAR BUMPER REVERSE SENSOR (SN)                | SHORT CIRCUIT | 135.70                    | 135.70            |
|                                    | LESS 20% DISCOUNT                              |               | -27.14                    | -                 |
|                                    |                                                |               | 108.56                    | 135.70            |
| <b>SPECIAL NETT ITEMS</b>          |                                                |               |                           |                   |
| 1                                  | REAR NUMBER PLATE (SN) (ADDITIONAL)            | CRACKED       | 25.00                     | 25.00             |
| 1                                  | REAR NUMBER PLATE TRIM COVER (SN) (ADDITIONAL) | BROKEN        | 30.00                     | 30.00             |
| 2                                  | BOOTLID WINDSCREEN SEALANT (SN) (ADDITIONAL)   | NECESSARY     | 46.00                     | 46.00             |
| 1                                  | BOOT LID COMFORT LOGO & TEL NO. STICKER (SN)   | NECESSARY     | 30.00                     | 30.00             |
| 1                                  | REAR BUMPER RUBBER MAT (SN)                    | NECESSARY     | 50.00                     | 50.00             |
|                                    |                                                |               | 181.00                    | 181.00            |
| <b>LABOUR</b>                      |                                                |               |                           |                   |
|                                    | PANEL BEATING.                                 |               | 1,200.00                  | 960.00            |
|                                    | SPRAY PAINTING CHARGE.                         |               | 600.00                    | 600.00            |
|                                    | TUFF KOTE.                                     |               | 80.00                     | 50.00             |
|                                    | REMOVE / REFIX REVERSE SENSOR.                 |               | 120.00                    | 50.00             |
|                                    | REMOVE / REFIX REAR WINDSCREEN GLASS.          |               | 120.00                    | 120.00            |
|                                    |                                                |               | 2,120.00                  | 1,780.00          |
| <b>GRAND TOTAL</b>                 |                                                |               | <b>10,937.64</b>          | <b>6,801.30</b>   |
| <b>RECOMMENDED COST OF REPAIRS</b> |                                                |               |                           | <b>6,801.30</b>   |

Report Ref No. CC4/LPC20000554/Fda3s2

PARASURAM S/O SHANMUGAM

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.