

REPAIR ESTIMATE

P1

PART NO.	Description	Qty	List Price	Amount
	Boot Lid Trimboard Xnn		\$	60.40
	Licence Lamp Cover BR ?		\$	35.10
	Rear Bumper Br SC		\$	459.40
	Rear Bumper Reinforcement Bracket (LH & RH) ?		\$138.10	\$ 276.20
	Rear Bumper Lower Centre Moulding Assy Xnn		\$	47.50
	Rear Bumper Stay (LH & RH) Xnn		\$138.10	\$ 276.20
	Rear Bumper Side Bracket (LH) DIS		\$	33.10
	Rear Bumper Cover Clips nec		\$	22.00
	Rear Bumper Under Centre SCA ?		\$	53.85
	Rear Bumper Side Under(LH) SCA ?		\$	27.50
	Rear Bumper Rear Hook BR Xnn		\$	5.40
	Rear Bumper Reflector Lamp(LH) B Xnn		\$	31.90
	Rear Bumper Fog Lamp Br		\$	201.50
	Rear Bumper Towing Cover ms		\$	98.80
	Rear Bumper Reserve Light (Parking Brake Light) Xnn		\$	257.10
	Rear Bumper Reverse Sensor SC SC		\$	1.00
	Bootlid Lamp(LH & RH) Xnn		\$794.40	\$ 1,588.80
	Rear Bumper Reflector Lamp(LH & RH) Xnn		\$31.90	\$ 63.80
	Rear Panel DP take pic		\$	532.00
	Rear Panel Lower Panel Xnn		\$39.40	\$ 78.80
	Bootlid Assy xlr		\$	2,840.40
	Rear Bumper Reinforcement BT takepic		\$	294.80
	Rear Bumper Centre Moulding Assy GR		\$	451.25
	Boot Lid Glass, Upper Xnn		\$	543.30
	Boot Lid Glass, Lower Xnn		\$	384.90
	Boot Lid Lamp(LH/RH) Xnn		\$794.40	\$ 1,588.80
	Boot Lid 'H' Emblem nec		\$	28.00
	SUB TOTAL		\$	6,990.75
	LESS 20%		\$	1,398.15
	DISCOUNTED TOTAL		\$	5,592.60

LKE LONFAC

P2

PART NO.	Description	Qty	List Price	Amount
PART NO.	Description	Qty	List Price	Amount
	Boot Lid Comfort Logo & Tel No. Sticker			\$ 30.00
	Rear Bumper Rubber Mat			\$ 50.00
	TOTAL			\$ 80.00
	Labour Charge			
	Panel Beating			\$ 1,200.00
	Spray Painting Charge			\$ 600.00
	Tuff Kote			\$ 80.00
	Remove/Refix Reverse Sensor			\$ 120.00
	Remove/Refix Rear Windscreen Glass			\$ 120.00
	TOTAL LABOUR			\$ 2,120.00
	ESTIMATE TOTAL			\$ 7,792.60

Nett

Nett

\$960

\$50

\$50

xm

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Raw (LKK)
07/01/2020 1310hrs
Ramesh@lkkauto.com
88622778 hf
(4 repair days)
Ref paint photo
P/R