

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG: 200707743D GST REG: 200707743D

To: Sanghian  
VIC

6-Jan-20

## ESTIMATE REPAIR BILL FOR MIT OUTLANDER REGN NO: SMQ 7182 T

1 pc	Rear bumper <del>CR</del>	
1 pc	Rear bumper moulding <del>DEF</del>	
1 pc	Rear bumper lower cover (silver) <del>SCR</del>	
2 pcs	Rear bumper side bracket o/s & n/s <del>xxx</del>	
1 pc	Rear bumper inner sponge <del>xnn</del>	
1 pc	Rear bumper reinforcement <del>xnn</del>	
1 pc	Tail gate <del>BUC</del>	\$963
1 pc	Rear windscreen moulding <del>rec</del>	\$98
1 pc	Mitsubishi Emblem <del>rec</del>	\$65
1 pc	Outlander Badge <del>rec</del>	\$65
1 pc	Tail gate lock <del>xxx</del>	
1 pc	Tail gate striker <del>xxx</del>	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Total: \$2440/=

10% LOSS: \$2196/=

Less 10%

### S/NETT

1 set	Reverse sensor <del>xnn</del>		
1 set	Rear bumper clips <del>rec</del>		
	windscreen sealant		
	Sundry		
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		
	To dismantle / replace reverse sensor to new bumper and reset to the same		
	To dismantle / refit the rear windscreen into new tail gate		
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel etc		
	To putty and spray painting on rear bumper, end panel, tail gate		
	To apply rustproofing on the repaired and replaced panels.		

Ran (LKR)  
07/01/2020  
Rameshram@lkkauto.com  
88622778

3 repair days

P/P

Ref print

photo

P/P: \$3404/-  
3 repair days

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )