



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2005996
INV Date 02/09/2020
Reference CC4/LPC20000559/Ada3n2
Code LPC2



PROFESSIONAL SERVICE FEE

Vehicle No. GBE 9228B
Insured Veh. GBE 2796Z
Claim No. 19/20/20/VC05/022876
Policy No. Z19VC05003660
Accident Date 06/01/2020
Inspection Date 08/01/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC20000559/Ada3n2

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 02-09-2020



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBE 2796Z	Veh. Inspected	GBE 9228B
Policy No.	Z19VC05003660	Coverage (\$)	0.00
Claim No.	19/20/20/VC05/022876	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	07/01/2020

2. Vehicle Particulars & Condition

Make & Model	FIAT DOBLO	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	ZFA26300006C28466	Colour	BRONZE
Odometer	115807	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/60 R16	YOKOHAMA	6 mm
L/H Front Tyre	195/60 R16	YOKOHAMA	6 mm
R/H Rear Tyre	195/60 R16	YOKOHAMA	6 mm
L/H Rear Tyre	195/60 R16	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	06/01/2020	Inspection Date	08/01/2020
Survey held at	ZERO GRAVITY 2 KAKI BUKIT AVE 2 #01-25 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 9228B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	DOOR (L/H/F)	DENTED	1,270.00	1,270.00
1	DOOR HANDLE (OUTER) (L/H/F)	CUT	250.00	250.00
1	DOOR INNER TRIM BOARD (L/H/F)	CRACKED	360.00	360.00
1	SET DOOR INNER TRIM BOARD CLIP	NECESSARY	60.00	30.00
1	DOOR ANTI SPLASH FOAM	NOT NECESSARY	105.00	-
1	GARNISH (DOOR FRAME)	NOT NECESSARY	120.00	-
1	SIDE MIRROR (L/H)	DAMAGED	538.00	538.00
1	DOOR GLASS (L/H/F)	CUT	249.00	249.00
1	DOOR INNER LOCK (L/H/F)	DAMAGED	310.00	310.00
1	WINDOW REGULATOR (L/H/F)	DAMAGED	360.00	360.00
1	DOOR CHANNEL (L/H/F)	NOT NECESSARY	320.00	-
1	BRACKET DOOR CHANNEL (L/H/F)	NOT NECESSARY	145.00	-
1	DOOR CATCH (L/H/F)	NOT NECESSARY	95.00	-
1	DOOR STOPPER RUBBER	NOT NECESSARY	65.00	-
1	DOOR WEATHERSTRIP (L/H/F)	NOT NECESSARY	145.00	-
1	DOOR (L/H/R) (SLIDING)	TO REPAIR SEE LABOUR	1,850.00	-
1	DOOR STICKER (L/H/R) (FRAME)	NOT NECESSARY	170.00	-
1	DOOR HANDLE (OUTER) (L/H/R)	CUT	240.00	240.00
1	SWITCH (DOOR)	NOT NECESSARY	215.00	-
1	CENTER PILLAR (L/H)	NOT NECESSARY	690.00	-
	LESS 10% DISCOUNT		-755.70	-360.70
			6,801.30	3,246.30
2	DOOR STICKER (L/H/F) (FRAME) @\$190.00 (SN)	NECESSARY	380.00	120.00
	LESS 10% DISCOUNT		-38.00	-
			342.00	120.00
<u>SPECIAL NETT ITEMS</u>				
1	SEALANT (WINDSCREEN) (SN)	NOT NECESSARY	35.00	-
1	DOOR STICKER (SN)	NECESSARY	20.00	20.00

Report Ref No. CC4/LPC20000559/Ada3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR VISOR (SN)	CRACKED	120.00	60.00
			175.00	80.00
	LABOUR			
	TO REMOVE AND REFIT SIDE WINDSCREEN GLASS (SLIDING DOOR).	NOT NECESSARY	150.00	-
	TO REMOVE ,TRANSFER & INSTALL RELATED COMPONENT.		120.00	80.00
	TO CHECK WIRING SYSTEM & ENSURE FUNCTION OF COMPONENT.		80.00	30.00
	TO PROVIDE UNDER TURFCOAT.		120.00	40.00
	TO PUTTY AND RE-SPRAY AFFECTED PORTION .		800.00	450.00
	PANEL BEATING & REPLACING OF THE ABOVE.INCLUSIVE OF THE REPAIR OF DOOR (L/H/R) (SLIDING) .		1,000.00	350.00
			2,270.00	950.00
GRAND TOTAL			9,588.30	4,396.30
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,500.00

Report Ref No. CC4/LPC20000559/Ada3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBE 9228B

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBE 9228B

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBE 9228B

RE-INSPECTION

