

Lion City Rentals Pte Ltd  
CARROS CENTER  
60 JALAN LAM HUAT #04-01 S(737869)  
Main +65 62524991

Ms AIG Asia Pacific Insurance Pte Ltd  
Date: 08/01/2020  
Attn: MOTOR CLAIMS DEPT

### ESTIMATE

VEHICLE NO. SLG5594R  
CHASSIS NO: RU11203870  
MAKE / MODEL: Honda Vezel 1.5 X CVT  
DATE OF ACCIDENT: 30/12/2019  
YOUR INSURED VEHICLE NUMBER: SCL8199J  
MILEAGE: 192694 km

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

#### PARTS DESCRIPTION

|                                           | QTY | UNIT PRICE | LIST PRICE       |
|-------------------------------------------|-----|------------|------------------|
| 1 Rear tailgate ✓ DD                      | 1PC | \$1,450.00 | \$1,450.00 972   |
| 2 Rear tailgate Vezel emblem ✓ Nec        | 1PC | \$86.80    | \$86.80 56       |
| 3 Rear tailgate Honda emblem X SVC        | 1PC | \$81.30    | \$81.30 X        |
| 4 Rear tailgate windscreen moulding ✓ Nec | 1PC | \$195.00   | \$195.00 ✓       |
| 5 Rear tailgate weatherstrip X SVC        | 1PC | \$155.00   | \$155.00 X       |
| 6 Rear end panel 2 X SVC                  | 1PC | \$830.00   | \$830.00 X       |
| 7 Rear end panel top garnish 2 X SVC      | 1PC | \$155.00   | \$155.00 X       |
| 8 Rear bumper ✓ DD                        | 1PC | \$955.00   | \$955.00 762     |
| LIST TOTAL S\$:                           |     |            | \$3,908.10 1,985 |
| 20.00% DISCOUNT S\$:                      |     |            | \$781.62 -20%    |
|                                           |     |            | \$3,126.48 1,588 |

#### SPECIAL NETT

|                                    |       |               |
|------------------------------------|-------|---------------|
| 1 Rear bumper clips ✓ Nec          | 1 SET | \$80.00 30    |
| 2 End panel top garnish clips X MV | 1 SET | \$80.00 X     |
| 3 Reverse sensor X MV              | 1PC   | \$490.00 X    |
| 4 Windscreen sealant ✓ Nec         | 1PC   | \$2,100.00 40 |
| Special Nett Total S\$:            |       | \$2,750.00 70 |

#### LABOUR CHARGES

|                   |                                                                                                                                     |            |     |       |
|-------------------|-------------------------------------------------------------------------------------------------------------------------------------|------------|-----|-------|
| 1                 | To labour charge for removing rear tailgate, rear end panel, rear bumper out to facilitate repairs and replacement of damaged parts | \$900.00   | 400 | 500   |
| 2                 | To respray rear tailgate, end panel and spare tyre panel                                                                            | \$1,000.00 | 300 | 400   |
| 3                 | To remove and install rear tailgate glass                                                                                           | \$160.00   | 120 |       |
| 4                 | To apply rustproofing on all damaged parts                                                                                          | \$180.00   | X   |       |
| 5                 | To check wiring system                                                                                                              | \$100.00   | 30  |       |
| LABOUR TOTAL S\$: |                                                                                                                                     | \$2,340.00 |     | 1,050 |
| TOTAL S\$:        |                                                                                                                                     | \$8,216.48 |     |       |
| 7% GST            |                                                                                                                                     | \$575.15   |     |       |
| GRAND TOTAL S\$:  |                                                                                                                                     | \$8,791.63 |     |       |

Repair day - 3 days.

Lump Sum

After spray photo

08/01/2020.

Sum Pin (LKK)

TP without prejudice

$$P = 1,588$$

$$N = 70$$

$$L = 1,050$$

$$2,708$$

$$- 20\%$$

$$2,166.4$$

$$L/S = \$ 2,100$$

3 days