



凱摩哆服務

KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com
BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打嗎呷，噴漆。

Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

Date : 06/01/2020

Attn: The Motor Claims Department
Your Insured veh no :SHC 1901 H
India International Insurance Pte Ltd
64 Cecil Street
#04--02 IOB Building
Singapore 049711

WITHOUT PREJUDICE

(By Email Only)

Xiao Tony

MNTBL AL3320003718

Dear Sir / Madam

Estimate Cost Repair Bill To Nissan Teana SLC 4478 X & SHC 1901 H on 02/01/2020

To Supply :-

1pc	Front Fender RH	Repair		\$	652.70	*
1pc	Front Fender Inner cowl			\$	119.70	+
10pcs	Front Fender Cowling Clips	3 new	\$ 4.20	\$	42.00	+
1pc	Front Head Lamp	cracked		\$	1,610.00	1470
1pc	Front Bumper	Disorted		\$	944.90	811.70
1pc	Front Bumper side retainer	new		\$	24.50	✓
10pcs	Front Bumper clips	new	\$ 5.00	\$	50.00	30
1pc	Front Bumper Nozzle	new		\$	147.80	✓
1pc	Front Bumper Nozzle Cover	missing	3104.30	\$	72.50	✓
1pc	Front Bumper Towing Cover	missing		\$	24.00	✓
1pc	Front Bumper Ford Lamp RH	new	2993.87	\$	340.00	✓
1pc	Front Grille	cracked		\$	395.40	✓
1pc	Front No. Plate Garnish	new		\$	141.00	+
1pc	Front Bumper Lamp RH	new		\$	162.50	✓
1pc	Front Ford Lamp Cover RH	new		\$	113.70	✓
				\$	4,840.70	
			less	\$	968.14	
				\$	3,872.56	
1pc	Front Bumper Sensor Seal	new		\$	320.00	930
	To dismantle & replace damage parts, panel beat where necessary			\$	850.00	500
	To putty, apply primer & spray paint on the affected portion.			\$	900.00	400
	To apply rust-proofing on repair, replace panel.			\$	80.00	+
	To check wiring functions.			\$	80.00	30
				\$	6,102.56	

Adrian Lij
1/2 06/01/20
04 Pmp

Total 3723.87
1/2 2950