

Lion City Rentals Pte Ltd
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Ms: AIG Asia Pacific Insurance Pte Ltd

Date: 08/01/2020

Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO. : SLQ3194Y

CHASSIS NO : RU31214754

MAKE / MODEL : Honda Vezel Hybrid 1.5X Auto

DATE OF ACCIDENT : 04/01/2020

YOUR INSURED VEHICLE NUMBER : SJC2123G

MILEAGE : 168500 Km

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PARTS DESCRIPTION

	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1 Front bumper ✓ CR4	1PC	\$955.00	\$955.00
2 F/L headlamp (LED) ?	1PC	\$2,100.00	\$2,100.00
3 F/L fender ✓ CR4	1 PC	\$600.00	\$600.00
4 F/L fender wheel arch moulding ✓ SCH.	1PC	\$300.00	\$300.00
		LIST TOTAL S\$:	\$3,955.00
		20.00% DISCOUNT S\$:	\$791.00
			\$3,164.00

SPECIAL NETT

1 Bumper and end panel clips	1 SET	\$200.00	30
	Special Nett Total S\$:	\$200.00	

LABOUR CHARGES

1 To labour charge for removing front bumper and F/L fender out to facilitate repairs and replacement of damaged parts.	\$750.00	500
2 To respray front bumper, F/R fender and F/L fender wheel arch moulding	\$700.00	600
	LABOUR TOTAL S\$:	\$1,450.00
	TOTAL S\$:	\$4,814.00
	7% GST	\$336.98
	GRAND TOTAL S\$:	\$5,150.98

Repair day - 3 days.

P/P Repair.

before spray photo.

Sun Pin (Lkk)

08/01/2020

TP without prejudice.