



STUTTGART AUTO PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
ESTIMATE COST OF REPAIRS



PORSCHE

MS FIRST CAPITAL INSURANCE LTD		NAME :	Mdm Chua Kheng Yeng	WIP :	54422
6 Raffles Quay #21-00		ADDRESS :	27 Greenleaf Drive	EXCESS :	
Singapore 048580			Singapore 279574	DATE:	6-Jan-20
ATTN. :	MOTOR CLAIMS	TEL :			
FAX :					

VEH NO :	SJG3131E	DATE IN :		CONTACT PERSON :	EVA	63310683
CHASSIS NO :	WP1ZZZ95ZFLB67021	MILEAGE :		TYPE OF CLAIM :	TP	
MODEL :	Macan S	DATE REG.:	16.03.2015	POLICY NO. :		

NATURE OF WORKS

S/NO	<u>Parts Description</u>			REVISED	PRICES
	QTY				
1	PROTECTIVE FILM REAR FEENDER	1	P95B-853-225- -		\$ 64.50
2	DOOR SHELL REAR (LH)	1	P95B-833-021-B -GRV		\$ 1,989.40
3	DOOR INSULATION	1	P970-556-543-00-		\$ 8.90
4	DOOR SEAL OUTER	1	P95B-839-911- -		\$ 224.50
5	CLIP	6	P8K0-837-199- -		\$ 5.40
6	DOOR SEAL	1	P95B-839-761-B -		\$ 172.20
7	DOOR SEAL	1	P95B-839-119-B -		\$ 130.80
8	REPAIR KIT	1	P95B-898-633- -		\$ 102.10
9	DOOR TRIM REAR BLACK LH	1	P95B-898-565- -OK1		\$ 529.70
10	MOULDING	1	P95B-839-475-D -041		\$ 210.40
11	SIDE SKIRT	1	P95B-853-563- -1E0		\$ 242.30
12	SIDE SKIRT SPONGE	2	P95B-857-993-A -		\$ 69.40
	TOTAL PARTS				\$ 3,749.60
	LESS 10%				\$ 374.96
	TOTAL PARTS COST				\$ 3,374.64

	<u>Labour Description</u>		
1	TO REPLACE REAR DOOR LH, SIDE SKIRT LH & TO REPAIR REAR FENDER LH		\$ 5,460.00
	AREAS AFFECTED BY THE ACCIDENT.		
2	TO RESPRAY REAR DOOR LH & REAR FENDER LH.		\$ 2,400.00
3	TO REPLACE 1 PC TYRE. 255/55 R18		\$ 980.00
4	TO MOUNT 1 PC SPORT RIM AND CONDUCT WHEEL BALANCING.	NETT	\$ 120.00
5	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.	NETT	\$ 680.00
6	TO TRANSFER THE DOOR MECHANISM.	NETT	\$ 780.00
7	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	NETT	\$ 250.00

8	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	NETT	\$ 600.00
9	SUNDRIES.	NETT	\$ 50.00
		TOTAL LABOUR	\$ - \$ 11,320.00
		TOTAL PARTS	\$ - \$ 3,374.64
		TOTAL	\$ - \$ 14,694.64
		LESS EXCESS	\$ - \$ -
		TOTAL AFTER EXCESS	\$ -
		GST 7%	\$ - \$ -
		GRAND TOTAL	\$ - \$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.