

HUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE

VEHICLE NO : SHA 3083 R

MAKE :
MODEL : TOYOTA PRIUS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

DATE: 31/12/2019

TEL : 6483 6016

FAX : 6483 6015

Parts Description/Labour	Qty	Unit Price	Amount	
BONNET <i>Dented</i>			\$ 950.50	L
INSULATOR HOOD <i>HN</i>			\$ 398.10	X
INSULATOR CLIPS <i>HN</i>			\$ 3.60	X
BONNET RUBBER <i>HN</i>			\$ 35.50	X
BONNET CABLE <i>HN</i>			\$ 53.20	X
BONNET HINGE (RH) <i>HN</i>			\$ 57.70	L
BONNET HINGE (LH) <i>HN</i>			\$ 57.70	L
BONNET LOCK <i>HN</i>			\$ 132.60	L
RADIATOR GRILLE <i>crack/broken</i>			\$ 438.00	L
RADIATOR GRILLE EMBLEM <i>HN</i>			\$ 88.00	L
FRONT RADIATOR LOWER SUPPORT PANEL <i>HN</i>			\$ 357.70	L
RADIATOR ASSY <i>HN</i>			\$ 1,841.80	L
RADIATOR BOTTOM MOUNTING <i>HN</i>			\$ 27.50	X
STAY,RADIATOR SUPPORT,RH <i>HN</i>			\$ 65.70	X
STAY,RADIATOR SUPPORT,LH <i>HN</i>			\$ 65.70	X
RADIATOR FAN BLADE (RH) <i>HN</i>			\$ 233.10	X
RADIATOR FAN BLADE (LH) <i>HN</i>			\$ 233.10	X
RADIATOR FAN MOTOR (RH) <i>HN</i>			\$ 543.70	X
RADIATOR FAN MOTOR (LH) <i>HN</i>			\$ 543.70	X
DEFLECTOR,RADIATOR SIDE,RH <i>HN</i>			\$ 83.50	X
DEFLECTOR,RADIATOR SIDE,LH <i>HN</i>			\$ 77.00	X
LAMP ASSY,FOG,RH <i>broken</i>			\$ 920.00	L
LAMP ASSY,FOG,LH <i>HN</i>			\$ 920.00	X
UNIT ASSY,HEADLAMP,RH (LED) <i>broken</i>			\$ 3,455.00	L
UNIT ASSY,HEADLAMP,LH (LED) <i>money crack</i>			\$ 3,455.00	L
FRONT HEADLAMP CONTROL UNIT <i>HN o/s crack/broken</i>			\$ 1,280.00	L
FRONT HEADLAMP PANEL (RH) <i>HN</i>			\$ 240.10	L
FRONT HEADLAMP PANEL (LH) <i>HN</i>			\$ 240.10	L
FRONT BUMPER COVER <i>HN</i>			\$ 499.90	L
FRONT BUMPER REINFORCEMENT <i>Dented</i>			\$ 696.40	L
FRONT BUMPER REINFORCEMENT ABSORBER <i>HN</i>			\$ 165.00	L
FRONT BUMPER SPONGE <i>HN</i>			\$ 78.80	L
FRONT BUMPER CENTRE GRILLE <i>money crack/dented</i>			\$ 301.90	L
FRONT BUMPER CLIPS <i>HN</i>			\$ 22.00	L
FRONT BUMPER SIDE RETAINER (RH/LH) <i>HN</i>			\$ 154.00	L
FRONT BUMPER TOP GARNISH <i>crack</i>			\$ 225.40	L
COVER,FRONT BUMPER,HOLE,RH <i>cut</i>			\$ 28.38	L
COVER,FRONT BUMPER,HOLE,LH <i>distorted</i>			\$ 28.38	L
BRACKET,FRONT BUMPER SIDE,RH <i>HN</i>			\$ 82.30	X
BRACKET,FRONT BUMPER SIDE,LH <i>HN</i>			\$ 82.30	X
ENGINE UNDER COVER (RR) <i>HN</i>			\$ 457.40	X

Acknowledged by Repairer
Signature:
Date:

\$ 77.00

Parts Description/Labour	Qty	Unit Price	Amount	
TOP PANEL CENTRE <i>Dental</i>			\$ 364.90	✓
TOP PANEL SIDE, LH <i>vt</i>			\$ 145.90	✓
TOP PANEL SIDE, RH <i>vt</i>			\$ 145.90	✓
BRACE PANEL <i>vt</i>			\$ 75.20	X
HORN <i>vt</i>		\$ 112.71	\$ 225.42	X
AIRDUCT <i>broken</i>			\$ 129.40	✓
INLET ASSY, AIR CLEANER <i>vt</i>			\$ 132.00	X
AIRDUCT CENTRE <i>detuned</i>			\$ 94.03	X
COMPRESSOR ASSY, W/MOTOR <i>vt</i>			\$ 2,924.20	X
CONDENSER ASSY, W/RECEIVER <i>vt</i>			\$ 1,336.60	✓
AIRCON DISCHARGE HOSE <i>vt</i>			\$ 386.90	✓
AIRCON LIQUID HOSE & PIPE <i>vt</i>			\$ 580.45	✓
FENDER SUB-ASSY, FRONT LH <i>Dental</i>			\$ 945.30	✓
FENDER SUB-ASSY, FRONT RH <i>Dental</i>			\$ 945.30	✓
FRONT HOUSING ASSY, RH <i>vt</i>			\$ 958.30	X
FRONT FENDER SHIELD, RH <i>vt</i>			\$ 196.60	✓
FRONT FENDER SHIELD CLIP <i>vt</i>		\$ 38.00	\$ 76.00	✓
FRONT FENDER HYBRID EMBLEM, LH <i>vt</i>			\$ 53.50	✓
FRONT FENDER HYBRID EMBLEM, RH <i>vt</i>			\$ 53.50	✓
FRONT FENDER HOUSING BRACKET, RH <i>vt</i>			\$ 44.50	X
FRONT WINDSCREEN GLASS <i>Crack</i>			\$ 1,627.30	✓
FRONT WINDSCREEN GLASS MOULDING <i>vt</i>			\$ 208.60	✓
WIPER TOP GARNISH <i>Crack</i>			\$ 668.32	✓
WIPER SPARE TANK <i>broken</i>			\$ 183.75	✓
WIPER SPARE TANK MOTOR <i>Done</i>			\$ 242.70	✓
ENGINE CROSS MEMBER <i>vt</i>			\$ 2,531.70	✓
ENGINE CHASSIS MEMBER (RH) <i>vt</i>			\$ 2,035.10	X
ENGINE MOUNTING (FRONT) <i>vt</i>			\$ 174.63	X
ENGINE MOUNTING (REAR) <i>vt</i>			\$ 172.90	X
WIRING FRONT <i>socket broken / wiring torn</i>			\$ 6,685.90	✓
FRONT WIPER GARNISH RH/LH <i>dislodged / broken</i>		\$ 26.50	\$ 53.00	✓
FRONT RADIATOR SPARE TANK <i>broken</i>			\$ 395.30	✓
FRONT DOOR RH/LH <i>vt</i>		\$ 1,264.00	\$ 2,528.00	✓
FRONT DOOR MIRROR OUTER RH <i>vt</i>			\$ 212.80	X
MIRROR ASSY OUTER REAR VIEW RH <i>broken</i>			\$ 1,390.10	X
FRONT WINDSCREEN PILLAR RH <i>vt</i>			\$ 343.10	X
FRONT WINDSCREEN PILLAR COVER RH <i>dislodged</i>			\$ 196.00	✓
ROCKER PANEL OUTER GARNISH RH <i>vt</i>			\$ 576.00	✓
WATER PUMP ASSY <i>vt</i>			\$ 925.30	X
FAN BELT <i>vt</i>			\$ 155.00	X
FRONT BUMPER UNDER COVER <i>broken</i>			\$ 180.80	✓
FRT ABS WIRE <i>torn</i>			\$ 455.10	X
FRONT WHEEL RIM <i>vt</i>			\$ 1,555.10	✓
FRONT WHEEL CAP <i>vt</i>			\$ 177.70	X
FRONT WHEEL BEARING RH <i>Done</i>			\$ 560.10	✓
FRONT SHOCK ABSORBER <i>broken</i>			\$ 401.80	✓
FRONT SHOCK ABSORBER MOUNTING <i>vt</i>			\$ 196.20	X

Parts Description/Labour	Qty	Unit Price	Amount	
SUSPENSION LOWER ARM <i>2 lt</i>			\$ 637.50	<i>2 ✓</i>
DRIVE SHAFT <i>2 lt</i>			\$ 1,310.10	<i>2 ✓</i>
RACK & PINION ASSY <i>2 D-m</i>			\$ 1,634.90	<i>2 ✓</i>
END SUB ASSY TIE ROD RH <i>2 distal</i>			\$ 158.10	<i>2 ✓</i>
ENGINE CROSS MEMBER <i>replaced</i>			\$ 2,531.70	<i>X</i>
KNUCKLE STEERING RH <i>2 broken</i>			\$ 562.30	<i>2 ✓</i>
BAR STABILIZER <i>2 distal</i>			\$ 360.00	<i>2 ✓</i>
BAR STABILIZER LINK <i>2 distal</i>			\$ 199.00	<i>2 ✓</i>
BRAKE HOSE <i>2 torn</i>			\$ 238.00	<i>* ✓</i>
FRONT CUSHION SEAT (RH) <i>lt</i>			\$ 1,180.00	<i>✓ 590.00</i>
			<i>50% depreciation - SN</i>	
			\$ 63,077.56	
			\$ 12,615.51	
			\$ 50,462.05	
FRONT NO. PLATE <i>distorted / broken</i>			\$ 25.00	NETT ✓
FRONT NO. PLATE TRIM COVER <i>distorted / broken</i>			\$ 30.00	NETT ✓
FRONT NO. PLATE GARNISH <i>nl</i>			\$ 99.00	NETT X
FRT TYRE <i>punctured 50% depreciation</i>			\$ 108.00 - 216.00	NETT ✓
FRONT WINDSCREEN SEALANT <i>hec</i>			\$ 46.00	NETT ✓
FRONT FENDER ADVERTISEMENT LOGO (LH/RH) <i>hec</i>		\$ 100.00	\$ 200.00	NETT ✓
			\$ 616.00	
LABOUR CHARGE			\$ 2,600.00	<i>1200/-</i>
PANEL BEATING			\$ 1,600.00	<i>1000/-</i>
SPRAYPAINTING CHARGE			\$ 80.00	<i>30/-</i>
WIRING CHARGE			\$ 100.00	<i>40/-</i>
TUFF KOTE			\$ 150.00	<i>nl</i>
TOWING CHARGE			\$ 150.00	<i>80/-</i>
REMOVE/REFIX AIRCON & REFILL GAS			\$ 480.00	<i>7-150/-</i>
REMOVE/REFIX DASHBOARD			\$ 120.00	<i>50/-</i>
REMOVE/REFIX FUSE BOX			\$ 120.00	<i>80/-</i>
REMOVE/REFIX FRONT WINDSCREEN GLASS			\$ 250.00	<i>80/-</i>
REMOVE/REFIX CUSHION & UPHOLSTERY FRONT			\$ 400.00	<i>150/-</i>
REMOVE/REFIX ENGINE			\$ 250.00	<i>180/-</i>
REMOVE/REFIX FRONT UNDERCARRIAGE			\$ 120.00	<i>60/-</i>
WHEEL ALIGNMENT			\$ 200.00	<i>nl</i>
RESET POWER WINDOW			\$ 480.00	<i>180/-</i>
DIAGNOSIS & RESETTING TO ERASE FAULT CODE				
			\$ 7,100.00	
			\$ 58,178.05	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

2KK And