



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

MR.OZGUR KILIC
279 BEDOK SOUTH AVE 3 #08-33
SINGAPORE 465458

Contact : 84444872 , 96430835

ESTIMATE

Repair Code : CLM15923

Date in : 06/01/2020

Vehicle Num. : S5030TE

Model : MITSUBISHI GRANDIS 2.4A

Chassis/Eng# : JMYLRNA4W4Z000677/4G69KK2855

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Rehd.</i>	1	744.00	✓ 744.00
REAR BUMPER CENTER BRACKET L/R <i>RH could</i>	2	87.00	<i>87</i> 174.00
REAR BUMPER SIDE RETAINER L/R <i>RH could</i>	2	28.00	<i>28</i> 56.00
REAR END PANEL <i>Dented</i>	1	684.00	✓ 684.00
REAR EXHAUST GASKET <i>new</i>	1	12.00	✓ 12.00
REAR EXHAUST RUBBER MOUNTING <i>new</i>	1	20.00	✓ 20.00
REAR EXHAUST SILENCER BOX <i>Regis</i>	1	498.00	✗ 498.00
REAR RH FENDER INNER AIR VENT <i>could</i>	1	35.00	✓ 35.00
REAR RH FENDER INNER SHIELD <i>torn</i>	1	45.00	✓ 45.00
REAR RH TAILLAMP <i>could</i>	1	585.00	✓ 585.00
REAR RH TAILLAMP INNER BLACK RUBBER GASKET <i>new</i>	1	20.00	✓ 20.00
REAR RH TAILLAMP INNER PANEL <i>Regis Dented</i>	1	275.00	✗ 275.00
Subtotal before discount			3,148.00
Percentage discount 10%			314.80
Sub-total 1			2,833.20
REAR BUMPER CLIPS - SET <i>new</i>	1	80.00	<i>30</i> 80.00
REAR BUMPER REVERSE SENSOR - SET <i>new</i>	1	350.00	✗ 350.00
REAR RH FENDER INNER SHIELD CLIPS - SET <i>new</i>	1	30.00	✓ 30.00

*** This is a computer-generated document which requires no signature.***



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

MR.OZGUR KILIC
 279 BEDOK SOUTH AVE 3 #08-33
 SINGAPORE 465458

Contact : 84444872 , 96430835

ESTIMATE

Repair Code : CLM15923
 Date in : 06/01/2020
 Vehicle Num. : S5030TE
 Model : MITSUBISHI GRANDIS 2.4A
 Chassis/Eng# : JMYLRNA4W4Z000677/4G69KK2855

REAR RH TAILLAMP CLIPS - SET	1	30.00	10	30.00
	70			
	Subtotal before discount			490.00
Percentage discount	0%			0.00
	Sub-total 2			490.00
	Parts-total			3,323.20

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.	100.00	30
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	140.00	60
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	800.00	600
To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.	100.00	80
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	1,000.00	600
To apply anti-rust chemical on repaired and replaced panel.	120.00	60
Labour Total	2,260.00	
Parts & Labour Total	5,583.20	

*** This is a computer-generated document which requires no signature.***

page 2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Adrian Lim
 H/S 08/01/20
 05 Days

total: 3852.70
 H/S: 3K ✓