

ASSIGNMENT

Surveyor:

LEE HOCK ANN

DOI: 10/01/2020

Date / Time: 08/01/2020

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. : SHA 8158B

Name of Insured : CITYCAB PTE LTD

Insured Tel No. : HP:

Excess Sec II : S\$

D.O.A: 04/01/2020 18:55

Is driver the owner?

(YES / ☒ NO)

Nature of Accident:

If NO, Driver Name / Age:

LEE PUAY MENG

Driver Tel No.:

+65-97328287

(V/L: YES / NO)

Claim No.:

D20000183MFSH

Policy No.:

D-18088937MFSH

Make / Model:

HYUNDAI I40-1.7 D CRDI (A)

Place of Accident:

ALONG FARRER ROAD TOWARDS QUEENS WAY

OI GIA REPORT: ☒ YES / NOTP GIA REPORT: ☒ YES / NO

Insured Liability:

%

Final ? Yes / No

SJP 2770U



INSRS:

WSP: REVO

Tel: PERFORMANCE

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time		STAGE	DATE / PIC
	SJP 2770U - X	Non-Reporting ltr (1st):	
	SHA 8158B - CC3/LCR17013894/K1zb3q2; DOA: 14.07.17	Non-Reporting ltr (2nd):	
	- CC3/AIG16021515/H1wb3q2; DOA: 10.11.16	Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
		Call OE:	
		After call ltr to OE:	
		Documentation Check List:	Handler Typist
		Notification ltr (if non-pickup)	☐
		After call ltr to OE:	☐
		Authorisation To Act:	☒
		Release Voucher:	☒
		Final Repair Bill:	☒
		Car Rental Invoice:	☐
		Towing Invoice:	☐
		LTA / GIA:	☐
		Medical Bill:	☐
		PIR:	☐
		Mandate/Reject Instruction:	☒
		LOD:	☒
		Payment Breakdown Form:	☐
		Post-Repair Photos:	☐
		Others:	☐
PRELIMINARY ADVICE Date/Time: Sent By:			
FINALIZATION Date/Time: Confirm with: Confirm by:			
Repair Cost: S\$ (days) Reduction: % Email ☐ Call ☐			
FINAL SETTLEMENT Date/Time: 5/3/2020 Confirm with: Gao Ping Email ☒ Call ☐			
Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 27 If NO or B 28, Ass. Lia:			
Repair Cost: 6491 S\$ 3531.00			
Loss of Rental (LOR): S\$ - (days)			
Loss of Use (LOU): S\$ 300.00 (\$ 60 x 5 days)			
Loss of Income (LOI): S\$ - (\$ x days)			
LOR only ☐ LOU only ☒ LOR + LOU ☐ LOR + LOI ☐ (Tick only one)			
GIA/LTA Search S\$ -			
Medical: S\$ -			
Disbursement: S\$ - (e.g. Tow/ Independent)			
Legal Cost S\$ -			
Total: S\$ 3831.00 Global Sum S\$: 3800.00			
FINAL PAYMENT Date/Time: Confirm with: Email ☐ Call ☐			
Payee 1: S\$ 3800.00 Name 1: Revo Performance Pte Ltd			
Payee 2: (Strike if N.A.) S\$ Name 2:			
Payee 3: (Strike if N.A.) S\$ Name 3:			

COPY SENT
16/3/2020



REVO PERFORMANCE PTE LTD

BLK 1 KAKI BUKIT AVE 6 #02-51
SINGAPORE 417883 (AUTOBAY@KAKI BUKIT)
TEL : +65 6745 6706 FAX : +65 6484 3653
EMAIL : contact@revoperformance.com.sg
WEBSITE : www.revoperformance.com.sg
GST REG NO : 201200256H

M/S : First Capital Insurance Limited
36 Robinson Road
#16-01 City House
Singapore 068877
TEL : 65073848
ATTN : Motor Claim Department
Your Ref No : SJP2770U
Claim Type : Third Party
Accident Date : 04/01/2020
TP Veh Reg No : SHA8158B

Date : 07 January 2020
Policy No : 5111511673
Veh Reg No : SJP2770U
Make / Model : DAIHATSU
: TERIOS 1.5L 4WD AUTO ABS AIRBAG
Chassis No : JDAJ210G001060744
Engine No : 1995088
Reg Date : 17-03-2009

ESTIMATE REPAIR COST TO VEHICLE NO : SJP2770U

NO	DESCRIPTION	U/PRICE	QUANTITY	LIST PRICE	AMOUNT
1	Rear gate ✓ <i>bt</i>	\$ 948.00	1	\$ 948.00	870.180 ✓
2	Rear gate hinges top and lower <i>x (suc)</i>	\$ 56.00	2	\$ 112.00	
3	Rear gate rubber ✓ <i>CR4</i>	\$ 189.00	1	\$ 189.00	✓
4	Rear gate inner cover board ✓ <i>CR4</i>	\$ 480.00	1	\$ 480.00	420.20 ✓
5	Rear spare tyre bracket ✓ <i>bt</i>	\$ 110.00	1	\$ 110.00	✓
6	Rear end panel <i>x (R)</i>	\$ 320.00	1	\$ 320.00	
7	Rear end panel top garnish <i>x (R)</i>	\$ 120.00	1	\$ 120.00	
8	Rear bumper ✓ <i>cut</i>	\$ 890.00	1	\$ 890.00	725.130 ✓
9	Rear bumper side bracket <i>x (R)</i>	\$ 87.00	1	\$ 87.00	
1	Rear gate emblem (TERIOS) <i>28</i> ✓ <i>acc</i> ✓				
1	Rear gate logo (1) <i>120</i> ✓ <i>acc</i> ✓			\$ 3,256.00	
	Less 15%			\$ 488.40	\$ 2,767.60
	Special Net				
10	Rear spare tyre <i>x (suc)</i>	\$ 320.00	1	\$ 320.00	
11	Rear spare rim ✓ <i>scr</i>	\$ 750.00	1	\$ 750.00	400 ✓
12	Rear number plate ✓ <i>bt</i>	\$ 50.00	1	\$ 50.00	30 ✓
13	Rear bumper sensor ✓ <i>short</i>	\$ 300.00	1	\$ 300.00	200 ✓
14	Rear windscreen <i>gam</i> ✓ <i>acc</i>	\$ 80.00	1	\$ 80.00	40 ✓
				\$ 1,500.00	\$ 1,500.00



REVO PERFORMANCE PTE LTD

BLK 1 KAKI BUKIT AVE 6 #02-51

SINGAPORE 417883 (AUTOBAY@KAKI BUKIT)

TEL : +65 6745 6706 FAX : +65 64843653

EMAIL : contact@revoperformance.com.sg

WEBSITE : www.revoperformance.com.sg

GST REG NO : 201200256H

M/S : First Capital Insurance Limited

36 Robinson Road

#16-01 City House

Singapore 068877

TEL : 65073848

ATTN : Motor Claim Department

Your Ref No : SJP2770U

Claim Type : Third Party

Accident Date : 04/01/2020

TP Veh Reg No : SHA8158B

Date : 07 January 2020

Policy No : 5111511673

Veh Reg No : SJP2770U

Make / Model : DAIHATSU

TERIOS 1.5L 4WD AUTO ABS AIRBAG

Chassis No : JDAJ210G001060744

Engine No : 1995088

Reg Date : 17-03-2009

parts 2363.30

parts 15%

2008.80

labour 670

labour 1480

4158.80

20%

3327.04

↓ \$3300 H

ESTIMATE REPAIR COST TO VEHICLE NO : SJP2770U

NO	DESCRIPTION	U/PRICE	QUANTITY	LIST PRICE	AMOUNT
	Labour				
15	Panel beating ✓	\$ 900.00	1	\$ 900.00	700 ✓
16	Check wiring ✓	\$ 60.00	1	\$ 60.00	30 ✓
17	Rust proofing ✓	\$ 60.00	1	\$ 60.00	30 ✓
18	To remove and refit rear windscreen ✓	\$ 160.00	1	\$ 160.00	100 ✓
19	To remove and replace bumper sensor ✓	\$ 80.00	1	\$ 80.00	20 ✓
20	To Spray painting ✓	\$ 820.00	1	\$ 820.00	600 ✓
				\$ 2,080.00	\$ 2,080.00
	TOTAL				\$ 6,347.60

TOTAL : SINGAPORE DOLLAR SIX THOUSAND THREE HUNDRED FORTY SEVEN AND CENTS SIXTY ONLY

L/S repair
without progress
Hock ANIV
PS311883
5 day
10/1/20
1:05 pm
Resurvey after part
Hock ANIV@kaki-bukit.com

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after repair
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- This is a survey on a "Without Prejudice" basis
- No repair work is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	662A
Vehicle Details	
Vehicle No.:	SJP2770U
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Jan 2020
Vehicle Make:	DAIHATSU
Vehicle Model:	TERIOS 1.5L 4WD AUTO ABS AIRBAG
Primary Colour:	Blue
Manufacturing Year:	2007
Engine No.:	1995088
Chassis No.:	JDAJ210G001060744
Maximum Power Output:	77.0 kW (103 bhp)
Open Market Value:	\$16,359.00
Original Registration Date:	17 Mar 2009
First Registration Date:	17 Mar 2009
Transfer Count:	2
Actual ARF Paid:	\$7,188.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	16 Mar 2024
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$12,763.00
COE Rebate Amount:	\$10,656.00
Total Rebate Amount:	\$10,656.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 13 Jan 2020

OK

A AUTODESK
AUTOCAD LTNEW YEAR SALE!
SAVE UP TO 25%*

f Connect with Facebook

HOME

NEW CARS

USED CARS

COMMERCIAL VEH

RENTAL CARS

SELL CARS

MOTOR DIRECTORY

Home > Used Cars > Daihatsu Terios 7 (COE till 11/2024)

DAIHATSU TERIOS 7 (COE TILL 11/2024)

OVERVIEW

GALLERY

Share



Price	\$33,888
Registration Date	24-Nov-2009
COE Remaining	4yrs 10mths 10days
Manufactured	2008
Mileage	120,363 km
No. of Owners	3
Transmission	Auto
Engine Capacity	1,495 cc
COE	\$16,208
OMV	\$20,372
Paper Value	\$7,886
Depreciation	\$6,960 / year
Type	SUV

We Are The COE Specialist. No Gimmicks, Honest Dealing, 3 Owners With Low Mileage Clock, Car In Superb Condition, Full Loan Available, 100% Approval. Trade In Welcome, Bank Loan Available. Call Us For An Appointment At Our Showroom Today.

Features: Powerful And Fuel Efficient 1.5L DOHC DVVT Engine, 5 Speed Auto Transmission, ABS, SRS Airbags, Knockdown Rear Seats, 7 Seaters SUV.

Accessories: Leather Seats, Sport Rims, Audio Systems, Reverse Sensor, Fog Lights.

More info on Daihatsu Terios(2007-2017) |

12 user reviews

For full set of photos and payment break-down, <http://www.sgcarmart...=871838&DL=3454>

Status: Available | Category: COE Car

Date Posted: 03-Dec-2019 | Date Updated: 19-Dec-2019

SELLER INFORMATION

ABS Auto Capital Pte Ltd

6001 Beach Road #22-04A (map)

64753423

KENNY	98259995
ROY	83158315
ALEX	82298229
KEN	91196006

" SAY YOU SAW THIS AD ON
STCARS.SG! "

Rule 4yr 3mths
Mn 6000 + n = 570
24000 + 1500 + 3594
= 29080

VEHICLE TOOLS

Get expert assessment on the condition of this car with STA Evaluation

COE Results
Post an Ad
Road Tax
Carpark Rates
Car Insur

IS YOUR CAR DUE FOR
SCRAP
or
EXPORT?

We help you get the
BEST PRICE for your vehicle!

LIFESTYLE

Food & Beverage
Home Needs
Health
IT Product

RELATED DISCUSSION

+ View All "Terios" Discussion

Topic Title	Replies	Last Action
2018 Daihatsu Terios / Toyota Rush	21	21-Oct-2018
Daihatsu Terios 4X4	28	13-Sep-2017
Feedback on Terios 7	33	13-Jun-2013
Daihatsu Terios 1.5A	3	06-Jun-2011

<https://www.stcars.sg/singapore-car/used-cars/daihatsu-terios-7-coe-till-112024-a871838/overview>



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D20000183MFSH
Our ref: CC4/FCI20000572/Hda3

Date: 24/01/2020

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SJP 2770U

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 10/01/2010 at the premises of M/s Revo Performance Pte Ltd - Kaki Bukit and have the following to report:-

Workshop Estimate Amount	: S\$	6,388.40
Revised Estimate Amount	: S\$	4,765.25
"Check" Items Amount	: S\$	-
Total (Including Check Items)	: S\$	4,765.25

Market Value	: S\$	-	(est.)
LTA Reimbursement Value	: S\$	-	(est.)
Nett Value	: S\$	-	(est.)

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 5.0 day

Yours faithfully,

STEVE CHEN
Licensed Appraiser

Hock Ann (LKK Auto)

From: Hock Ann (LKK Auto)
Sent: Wednesday, 5 February, 2020 5:49 PM
To: contact@revoperformance.com.sg
Cc: Jia Le (LKK Auto)
Subject: RE: SJP 2770U FINALIZED

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear joey ,

Good day, o.k will be process base on finalized total amount COR \$ 3300 L/SUMP REPAIR and DOR 5 days close.

Noted : All finalized document > LOA ,LOD,DV,LTA need send direct LKK claim dept incharge person (jia le)
jjale@lkkauto.com

Thanks.

Best Regards,

Hock Ann | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6741 3061 | Email: HockAnn@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: contact@revoperformance.com.sg [mailto:contact@revoperformance.com.sg]
Sent: Tuesday, 4 February, 2020 11:25 AM
To: Hock Ann (LKK Auto)
Subject: RE: SJP 2770U FINALIZED

Dear Hock Ann,

Thank you for your email.

We accept the final COR @ Lump sum \$3,300.00 (bf GST) and DOR @ 5 days.

Kindly refer attached as LOD of SJP2770U.

For more information, please do not hesitate to contact us.

Thank you.

Best Regards,

Joey Chong

Revo Performance Pte Ltd

Tel : +65 6745 6706

Fax : +65 6484 3653

From: Hock Ann (LKK Auto) [mailto:HockAnn@lkkauto.com]
Sent: Monday, February 03, 2020 5:43 PM
To: CONTACT@REVOPERFORMANCE.COM.SG
Cc: Jia Le (LKK Auto)
Subject: RE: SJP 2770U FINALIZED

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear joey ,

Good day , Kindly attached refer SJP 2770U DAIHATSU TERIOS finalized updated calculate adjustment on 3.2.2020

COR - \$ 3300

DOR – 5 DAYS

Please refer adjustment updated total LUMP/SUMP amount \$ 3300 if agree total LUMP/SUMP amount and repair days, will be to close case.

Please to updated email back asap.

Thanks.

Best Regards,

Hock Ann | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6741 3061 | Email: HockAnn@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

MOTOR SURVEY ASSIGNMENT

Date	07-01-2020	Our Ref No. D20000183MFSH
Accident Date	04-01-2020	Claim Type. Third Party
Insured Vehicle	SHA8158B	Third Party Vehicle. SJP2770U
Survey Location	1 KAKI BUKIT AVE 6#02-51 AUTOBAY@KAKI BUKIT	
Contact Person.	JOEY CHONG	
Contact No.	67456706/ 0	Fax No. 64843653
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	REVO PERFORMANCE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MERINA CHIA SAN SAN	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

P: Joey
T: 2.24pm 8.1.2020
V: all
E: ✓

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CC4/FCI20000572/Hda3q2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 17-03-2020	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 8158B	Veh. Inspected	SJP 2770U	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D20000183MFSH/1	Excess (\$)	0.00	
Assign From	MERINA CHIA	Assign Date	08/01/2020	
2. Vehicle Particulars & Condition				
Make & Model	DAIHATSU TERIOS	c.c	1495	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	JDAJ210G001060744	Colour	BLUE	
Odometer	103925	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/70 R16	MAXXIS	5 mm	
L/H Front Tyre	235/70 R16	MAXXIS	5 mm	
R/H Rear Tyre	235/70 R16	MAXXIS	5 mm	
L/H Rear Tyre	235/70 R16	MAXXIS	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/01/2020	Inspection Date	10/01/2020	
Survey held at	REVO PERFORMANCE PTE LTD NO 1 KAKI BUKIT AVENUE 6 #02-51 AUTOBAY @KAKI BUKIT SINGAPORE 417883.			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJP 2770U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR GATE	BENT	948.00	870.80
2	REAR GATE HINGES TOP AND LOWER @\$56.00	SERVICEABLE	112.00	-
1	REAR GATE RUBBER	CRUSHED	189.00	189.00
1	REAR GATE INNER COVER BOARD	CRACKED	480.00	420.20
1	REAR SPARE TYRE BRACKET	BENT	110.00	110.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	320.00	-
1	REAR END PANEL TOP GARNISH	TO REPAIR SEE LABOUR	120.00	-
1	REAR BUMPER	CUT	890.00	725.30
1	REAR BUMPER SIDE BRACKET	TO REPAIR SEE LABOUR	87.00	-
1	REAR GATE EMBLEM (TERIOS)	NECESSARY	28.00	28.00
1	REAR GATE LOGO	NECESSARY	20.00	20.00
	LESS 15% DISCOUNT		-495.60	-354.50
			2,808.40	2,008.80
<u>SPECIAL NETT ITEMS</u>				
1	REAR SPARE TYRE (SN)	SERVICEABLE	320.00	-
1	REAR SPARE RIM (SN)	SCRATCHED	750.00	400.00
1	REAR NUMBER PLATE (SN)	BENT	50.00	30.00
1	REAR BUMPER SENSOR (SN)	SHORTED	300.00	200.00
1	REAR WINDSCREEN GUM (SN)	NECESSARY	80.00	40.00
			1,500.00	670.00
<u>LABOUR</u>				
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR END PANEL ,REAR END PANEL TOP GARNISH AND REAR BUMPER SIDE BRACKET .		900.00	700.00
	CHECK WIRING.		60.00	30.00
	RUST PROOFING .		60.00	30.00
	TO REMOVE & REFIT REAR WINDSCREEN.		160.00	100.00
	TO REMOVE AND REPLACE BUMPER SENSOR .		80.00	20.00

Report Ref No. CC4/FCI20000572/Hda3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SPRAY PAINTING.		820.00	600.00
			2,080.00	1,480.00
GRAND TOTAL			6,388.40	4,158.80

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,300.00
---	--	--	--	----------

Report Ref No. CC4/FCI20000572/Hda3q2

LEE HOCK ANN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.