

ASS. REC. BY:

REF: (S1(71)2000576/A1sf3<sup>87</sup>

Special instruction:

Surveyor: ZASU

### ASSIGNMENT (Office)

From (Person): Tan Kah Leong of C71

Date/Time: 8. Jan. 2020 17:02 p.m

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: XD 6545A

Insured:

at Workshop m/s VFIX Auto

Tel: 64552957

of 26 Chia Ping Road

Policy No: DMCV SN 1900161900

Claim No: SNM 20D 200100001

Sum Insured:

Excess: \$1500.00

Make of Veh:

D.O.A. 7.1.2020

(Client's Record)

CA / REV REP. / REV 24 HRS

H.O.D. Endorsement

Date/Time: 9 Jan. 20 10:00am

Person Contacted: Vincent

Vehicle IN/OUT

[illegible]

Paul


CTI

117G

# ASSIGNMENT

Vehicle No. XD 6545A  
Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
☒ Truck / Trailer or  
Make: VOLVO FM X42084RTSC C.C. 12777  
Colour: WHITE A/C: Insured / Std / NI / NA  
Sp. Reading: 622968 T/Radio: Insured / Std / NI / NA  
Eng/No.:  
C/No.: 4V2JG10G6DA 738197  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: In order / Jammed / Leaked / Burnt or  
Brake: In order / Jammed / Leaked / Burnt or  
Modi: Nil / S/Rim / STD A/Rim or  
Tyre Size: F: 315/80R 22.5  
R:  
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or TRIANGLE  
Front  
R/Bal. 8 mm  
L/Bal. 8 mm  
D.O.A. 07/01/2020  
Survey held at V FIX AUTO  
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
The U/C / Chassis frame / Body Structure affected due to collision.

Date: 9. Jan. 2020  
To Inspect Vehicle No. XD 6545A  
at Workshop m/s V Fix Auto  
at 26 Chia Ping Road  
Insured:  
Policy No.:  
Claims No.:  
Sum Insured: \$1500.00  
Excess:  
(Client's Record)  
Make of Velt:  
(Policy Condition)  
Remark: The veh had commenced its repair at the time of inspection.  
Bal. or Market Value: 79K  
IDAC Accident Report: Consistent? : Yes or No  
GIA / PR Seen: Consistent? : Yes or No  
Est. Repairs: days Res.: Yes or No  
Lum Sum: % 3 Val.: Yes or No  
CA / REV / REP. / 24 HRS  
Vehicle: IN / OUT  
Dater: Person Contacted:



Date / Time	Action / Instruction
	Repair limit is 60K. refer to email copy
	Vehicle is uneconomical to repair
	MV - \$79K
	LTA - \$18,264.00
	Net - \$60,736.00

RECEIVED 17 JAN 2020

14/1/2020

Cost/Time Fee Post, m/ 17/01/20  
Type  
Date/Time Fee Return m/

☐ : Prel. Report  
☒ : Final Report

Days Of Repair: 30  
Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)  
☐ Interview (\$)  
☐ Tech. Insp. (\$)  
☐ Misc. (\$)

Survey Fee:  
Transportation  
S. + R. \$  
Phone  
Other

Reported: Total Loss  
Total Sum Insured:

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Jan 2020		08 Jan 2020 17:02 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

#### CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured: <b>KOK TONG TRANSPORT &amp; ENGINEERING WORKS PTE LTD</b> , Co. Reg. No.: 199904117E	Date of Loss: 07/01/2020 13:00 - :59
Vehicle Reg. No.: <b>XD6545A</b>	Policy/Cover Note No.: DMCVSN1900161900 (Comprehensive)
Claim Type: <b>OD / SNM20D200100C01</b>	Excess: S\$1,500.00
Repairer: <b>Vfix Auto Service Pte Ltd (HQ)</b> 26 Chia Ping Road, 619977 Boon Lay - Tel: 64552957	
Handling Insurer: <b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Tan Kah Leong</b> - 63896193]	
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... <b>[Final Rpt due 17/01/2020]</b>	
Driver/Custodian: <b>MANICKA PADAYACHI</b> (49 / Male) , NRIC: F8477954R, Tel: +6584302653 Email: NOEMAIL	

#### ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

#### ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Shirley Hiew (LKK Auto)

---

**From:** Rasul (LKKAuto)  
**Sent:** Friday, 10 January 2020 3:16 pm  
**To:** wskoh@vfixauto.com.sg  
**Cc:** ybsim@vfixauto.com.sg; jeffbz@vfixauto.com.sg; jessicassy@vfixauto.com.sg; 'kentsh'; alanclk@vfixauto.com.sg; Shirley Hiew (LKK Auto)  
**Subject:** RE: XD 6545A DOA : 07/01/2020

Hi Weng Sheng,

As spoken, there is mistake on the market value  
I've checked and confirmed again that the repair limit should be 60K not 75K.  
Kindly take note

Best Regards,

**Rasul** | Assessor

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Rasul@lkkauto.com](mailto:Rasul@lkkauto.com) | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

---

**From:** wskoh@vfixauto.com.sg [mailto:wskoh@vfixauto.com.sg]  
**Sent:** Friday, 10 January, 2020 9:32 AM  
**To:** Rasul (LKKAuto)  
**Cc:** ybsim@vfixauto.com.sg; jeffbz@vfixauto.com.sg; jessicassy@vfixauto.com.sg; 'kentsh'; alanclk@vfixauto.com.sg  
**Subject:** RE: XD 6545A DOA : 07/01/2020



Dear Rasul,

Noted with thanks !

Remark: W.e.f 22<sup>nd</sup> April 2019, our office has been relocated to 26, Chia Ping Road, Singapore 619977. Please update your record with the following: Company contact number - 6455 2957 ; Company general email - [contact@vfixauto.com.sg](mailto:contact@vfixauto.com.sg)

Thanks & Regards,

**Weng Sheng**

Motor Claim Operation Admin

Vfix Auto Pte Ltd | Vfix Auto Service Pte Ltd | Vfix Leasing Pte Ltd

26 Chia Ping Road Singapore 619977

Contact: 6455 2957 | E: [wskoh@vfixauto.com.sg](mailto:wskoh@vfixauto.com.sg)

---

**From:** Rasul (LKKAuto) <[Rasul@lkkauto.com](mailto:Rasul@lkkauto.com)>  
**Sent:** Friday, 10 January 2020 9:22 AM

## Rasul (LKKAUTO)

---

**From:** Rasul (LKKAUTO)  
**Sent:** Friday, 10 January, 2020 9:22 AM  
**To:** 'wskoh@vfixauto.com.sg'  
**Subject:** XD 6545A DOA : 07/01/2020

Hi Weng Sheng,

With regards on this case, I've spoken to Ken and Alan that this vehicle recommended to be uneconomical to repair due to high cost of repair.

The repair limit for your info, is 75K.

Best Regards,

**Rasul** | Assessor

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Rasul@lkkauto.com](mailto:Rasul@lkkauto.com) | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

## View Received Message

This mail is associated with :

**\*XD6545A (SNM20D200100C01)**

OD

Jan 7 2020 1:00PM

[KOK TONG TRANSPORT & ENGINEERING WORKS PTE LTD]

Vfix Auto Service Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA\_TAIPING), sent on 14/01/2020 15:48 PM.

**To** LKK\_HQ

**Subject** Alert - Adj Mandate Revoked - XD6545A - Claim Handler: Tan Kah Leong

Revoked.

### DOCUMENTS SUMMARY

There are no documents.

Note: This document has not been finalised.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Tan Kah Leong

Date: 10 Jan 2020

**Preliminary Advice**

Vehicle No	: XD6545A	Accident Date	: 07/01/2020
Make	: VOLVO FMX420	Policy No.	: DMCVSN1900161900
Assignment Date	: 08/01/2020	Excess	: S\$1,500.00
Date of Inspection	: 09/01/2020	Est. Duration of Repair	: 30 days
Inspection At	: Vfix Auto Service Pte Ltd (HQ) 26 Chia Ping Road Singapore 619977		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	152,413.30
Revised Amount	:S\$	56,619.00
Check Items (Estimated)	:S\$	84,125.70
Total	:S\$	140,744.70

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	79,000.00
COE / PARF Rebate	:S\$	18,264.00
Salvage Value	:S\$	
Margin for Repair	:S\$	60,736.00

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( X ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	08/01/2020 13:53
Date Of Accident	07/01/2020 13:00
Exact Location Of Accident	ALONG TUAS AVE 5 (LAMP POST 3) CONSTRUCTION SITE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	XD6545A
<b>Insured/Policyholder</b>	
Name Of Registered Owner	KOK TONG TRANSPORT & ENGINEERING WORKS PTE LTD
Co Reg No	1XXXXX117E
Email Address	KINHOE.NG@KTCGROUP.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-96155910

### Vehicle Particulars

Manufacturer	VOLVO
Model	FMX420-12.8 D (M)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	COMMERCIAL VEHICLE
------------------	--------------------

### Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCVSN1900161900
Cover Note Number	

### Driver

Name of Driver	MANICKA PADAYACHI
NRIC No	FXXXX954R
Date Of Birth	12/09/1970
Occupation	OUTDOOR
Date Of Driving Pass	27/01/2014
Driving Experience	5 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-84302653
Fax Number	
Contact Number	
Email Address	NOEMAIL



Address	N/A
Postcode	
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	1
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:  
NRIC/FIN No.:

# Sketch Plan Pg. 2

## SKETCH PLAN



Vehicle A - XD6545A

X - dropping soil material Area

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 7/1/2020 around 1300 hrs, vehicle A along Tuas Ave 5 (lamp post 3) construction site reverse and dropping the soil material suddenly vehicle A turn over to right portion. No one injury.

<input type="checkbox"/> Claim own policy	
<input type="checkbox"/> Claim third party	
<input checked="" type="checkbox"/> Claim OD (TP) at other workshop	V-17XX
<input type="checkbox"/> For record purpose only	
Policy No	
Insurer	China
Vehicle No	XD6545A

## DECLARATION:

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	117E
Vehicle Details	
Vehicle No.:	XD6545A
Vehicle to be Exported:	No
Intended Deregistration Date:	09 Jan 2020
Vehicle Make:	VOLVO
Vehicle Model:	FMX420 84RT SC
Primary Colour:	White
Manufacturing Year:	2012
Engine No.:	D13372388
Chassis No.:	YV2JG10G6DA738197
Maximum Power Output:	-
Open Market Value:	\$133,054.00
Original Registration Date:	22 Jan 2013
First Registration Date:	22 Jan 2013
Transfer Count:	0
Actual ARF Paid:	\$6,653.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	21 Jan 2023
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$60,235.00
COE Rebate Amount:	\$18,264.00
Total Rebate Amount:	\$18,264.00

The information contained herein is correct as at 09 Jan 2020

OK

79,000  
18,264  
-----  
60,736  
  
(60K)

95,000  
18,264  
-----  
76,736  
  
(75K)

3455

## Need Items for Your Car?

We have thousands of car parts & accessories to explore.

The best online platform to sell and buy car parts & accessories - Marketplace

**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad

Advertiser Login

Ways of Selling

New Year Promo , Low Interest Rate .



New Year Promo , Low Interest  
Rate  
HTS Motor Star Ad



Browse by Category

Sort by Date Posted

20 results

1 vehicles

Volvo FMX370

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Stz
<b>Search Selection</b>	Volvo FMX370	Any	Any	Any	Any	Any	Any	
	<b>Volvo FMX370 Tipper</b> Fuel Type: Diesel	<b>\$39,600</b>	<b>\$15,020 /yr</b>	<b>30-Aug-2012</b>	<b>10,837 cc</b>	<b>-</b>	<b>Truck</b>	<b>A</b>
Posted: 06-Dec-2019 Tags: 2012 Volvo FMX370, 2012 volvo fmx370, Volvo FMX370, volvo fmx370, Volvo, FMX370, fmx370, Used Volvo								

Save this search criteria, to get email alerts whenever a match is found.

For old advertisements, view Expired ads

20 results

Home | New Cars | Used Cars | Sell My Car | Directory | Products | Insurance | Article | Forum | Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, car insurance. Find buy used Volvo FMX370, Volvo FMX370 Singapore, used Volvo FMX370 Singapore, used Volvo FMX370, used vehicles Singapore or even buy used Volvo FMX370 Si have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE n

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

About Us | Careers | Contact Us | Sitemap | Terms of Service | Privacy Policy | Personal Data Protection Statement

©2004-2020 sgCarMart. All rights reserved.



86840506

Vfix Auto Pte Ltd

26 Chia Ping Road

Singapore 619977

Email : contact@vfixauto.com.sg

Tel : 6448 9268 Fax: 6445 2368

UEN / GST Reg No.: 201830761R

# ESTIMATE

DATE :

ACC DATE :

REF NO :

POLICY NO :

**Attention: Motor Claim Department**
**RE : VEHICLE NO :XD6545A VOLVO FMX420(COST PRICE)**

DESCRIPTION	AMOUNT S\$
1 1 FRONT WINDSCREEN <i>cm</i>	2,700.00
2 1 FRONT WINDSCREEN RUBBER <i>re</i>	367.00
3 1 FRONT PANEL <i>X</i>	1,650.60
4 1 FRONT WIPER SIDE GARNISH RH <i>sc</i>	74.00
5 1 FRONT CORNER PANEL RH <i>bt</i>	300.00
6 1 FRONT BUMPER ?	3,177.00
7 1 FRONT BUMPER REINFORCEMENT ?	890.00
8 1 FRONT SIDE BUMPER RH <i>cm</i>	576.00
9 1 FRONT SIDE BUMPER SIGNAL LAMP RH <i>cm</i>	310.00
10 1 FRONT SIDE BUMPER SIGNAL LAMP COVER RH <i>cm</i>	217.00
11 1 FRONT BUMPER SIDE PAD RH <i>sc</i>	457.60
12 1 FRONT BUMPER SIDE PAD FOG LAMP RH ?	576.00
13 1 FRONT BUMPER SIDE PAD FOG LAMP COVER RH ?	245.00
14 1 FRONT HEAD LAMP RH ?	375.00
15 1 FRONT HEAD LAMP RIM RH ?	195.70
16 1 FRONT PARKING LAMP RH ?	274.00
17 1 FRONT SIGNAL LAMP RH ?	252.00
18 1 FRONT LAMP INNER HOLDER RH ?	257.00
19 1 CABIN ROLLER BAR ?	3,831.40
20 2 CABIN ROLLER HINGE ?	750.00
21 2 CABIN ROLLER HINGE BUSHING ?	680.00
22 2 CABIN FRONT ABSORBER ?	420.00
23 1 FRONT DOOR PILLAR (OUTER) RH <i>repair</i>	890.00
24 1 FRONT DOOR PILLAR (INNER) RH <i>repair</i>	792.50
25 1 FRONT SIDE MIRROR RH <i>bo</i>	650.00
26 1 FRONT SIDE BOTTOM MIRROR RH <i>bo</i>	450.00
27 1 FRONT SIDE MIRROR BRACKET RH <i>bt</i>	570.00
28 1 FRONT SIDE MIRROR BRACKET BOTTOM SUPPORTER RH <i>bt</i>	270.00
29 1 FRONT SIDE MIRROR BRACKET TOP ADJUSTOR RH <i>bt</i>	579.00
30 1 FRONT DOOR RH <i>bt</i>	2,400.00
31 1 FRONT DOOR GLASS RH <i>bo</i>	890.00
32 1 FRONT DOOR OUTER MOULDING RH <i>re</i>	289.00
33 1 FRONT DOOR OUTER HANDLE RH <i>sc</i>	472.00
34 2 FRONT DOOR HINGE RH <i>X</i>	285.00
35 1 FRONT DOOR CHECKER RH <i>X</i>	279.00
36 1 FRONT DOOR INNER LOCK RH <i>X</i>	469.00
37 1 FRONT DOOR LOCK CATCH RH <i>X</i>	97.50

38	1	FRONT DOOR WEATHERSTRIP RH <i>new</i> ✓		285.00
39	1	FRONT DOOR CHANNEL RH ?		120.00
40	1	FRONT DOOR CHANNEL SEAL RH ?		287.30
41	1	FRONT DOOR REGULATOR MOTOR RH ?		579.00
42	1	FRONT DOOR REGULATOR GEAR RH ?		320.00
43	1	FRONT DOOR INNER TRIM RH ?		679.00
44	1	FRONT DOOR BOTTOM ARCH GARNISH RH <i>scr</i> ✓		579.00
45	1	FRONT DOOR FRAME WEATHERSTRIP RH <i>new</i> ✓		320.00
46	1	FRONT DOOR TOP STEP GARNISH RH <i>scr</i> ✓		632.00
47	1	FRONT DOOR BOTTOM STEP GARNISH RH <i>scr</i> ✓		322.00
48	2	FRONT DOOR BOTTOM STEP PLATE RH <i>scr</i> ✓	194.00	388.00
49	1	FRONT MUDGUARD RH <i>scr</i> ✓		702.00
50	1	REAR FENDER RH <i>bt</i> ✓		1,100.00
51	1	REAR FENDER INNER TRIM RH ?		477.30
52	1	REAR FENDER EMBLEM (420) <i>new</i> ✓		200.00
53	1	REAR FENDER EMBLEM (EURO 5) <i>new</i> ✓		197.50
54	1	REAR FENDER BOTTOM ARCH GARNISH RH <i>scr</i> ✓		569.50
55	1	REAR FENDER BOTTOM MUDFLAP RH <i>scr</i> ✓		377.90
56	1	CABIN BACK PANEL <i>repair</i>		1,570.00
57	1	DASH BOARD ?		4,700.00
58	1	DASH BOARD INNER FRAME ?		3,790.00
59	1	SIDE GUARD PANEL ASSY RH <i>bt</i> ✓		900.00
60	1	DIESEL FUEL TANK ASSY RH <i>bt</i> ✓		897.00
61	1	REAR MUDGUARD RH <i>bt</i> ✓		877.50
62	4	REAR MUDGUARD BRACKET RH <i>bt</i> ✓	150.00	600.00
63	3	REAR ABSORBER RH ?	300.00	900.00
64	6	REAR AIR BALLON RH <i>punctured</i> ✓	400.00	2,400.00
65	3	REAR TOD ROD WITH BUSH RH ?	500.00	1,500.00
66	1	ENGINE ASSY ?		41,000.00
67	1	REAR EXTENTION AXLE <i>dis</i> ✓		12,000.00
68	1	REAR EXTENTION AXLE TROJAN CARRIER ?		3,500.00

---

\$ 112,863.30

	DESCRIPTIONS	UNIT PRICE	AMOUNT S\$
	<u>SPECAIL NETT</u>		
1	1 <u>REAR CARRIER</u> 64✓		\$ 13,000.00
2	1 <u>REAR CARRIER HYDRAULIC JACK</u> 7.		\$ 9,000.00
3	1 <u>REAR PTO</u> 7,		\$ 3,500.00
			\$ 25,500.00

	LABOUR & MISCELLANEOUS :	AMOUNT S\$
1	To remove damaged body panel with all necessary components/attachments apply hot-works where necessary straighten front door pillar, repair/reshape body dented panels in accordance with factory specifications replace new parts refit and align into position refit all necessary components / attachments	5,000.00 4000
2	To spray paint replaced/repaired body panels inclusive of preparatory works and painting materials	2500 4,000.00
3	To remove, refit front door	100 200.00
4	To remove, refit dash board and interior	300 650.00
5	To remove, refit rear carrier	1000 2,000.00
6	To check and reconnect wiring	3.200 1,000.00
7	To reset and diagnos failt code	600 1,200.00
		\$ 14,050.00

GRAND TOTAL : \$ 152,413.30

Vfix Auto Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Repair  
Hp 90010068  
30 days  
43  
09/01/2020 @ 1400  
EXCESS: 1500  
Revert  
Repair after repair



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Status
Main	08 Jan 2020		08 Jan 2020 17:02 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>	<b>Pending for Survey Report</b>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	KOK TONG TRANSPORT & ENGINEERING WORKS PTE LTD, Co. Reg. No.: 199904117E		
Vehicle Reg. No.:	XD6545A	Date of Loss:	07/01/2020 13:00 - :59 [83 Months and 16 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / SNM20D200100C01	Policy/Cover Note No.:	DMCVSN1900161900 (Comprehensive)
		Excess:	S\$1,500.00
Repairer:	Vfix Auto Service Pte Ltd (HQ) 26 Chia Ping Road, 619977 Boon Lay - Tel: 64552957		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 17/01/2020]		
Driver/Custodian:	MANICKA PADAYACHI (49 / Male) , NRIC: F8477954R, Tel: +6584302653 Email: NOEMAIL		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- CHINA\_TAIPING (14/01/2020): Alert - Adj Mandate Revoked - XD6545A - Claim Handler: Tan Kah Leong

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date   Priority   Type   Task Group   Subject   Handler   Assigned By   Completed On   Created On   Done?

No results.



## Claim Documents

\*XD6545A (SNM20D200100C01)

OD

Jan 7 2020 1:00PM

[KOK TONG TRANSPORT & ENGINEERING WORKS PTE LTD]

Vfix Auto Service Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

### Assessment Reports














1 per page ▼ ☒

No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)		Thumbnail	Print
1	08/01/20 14:04	<b>Accident Statement</b>	1	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	10/01/20 15:34	<b>Adjuster Immediate Advice</b>	1	Load HTM	

### Photos/Images

3 per page ▼ ☒

No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)		Thumbnail	Print
1	08/01/20 14:03	<b>Accident Photo</b> [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
2	08/01/20 14:03	<b>Accident Photo</b> [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
3	08/01/20 14:03	<b>Accident Photo</b> [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
4	08/01/20 14:03	<b>Accident Photo</b> [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
5	08/01/20 14:03	<b>Accident Photo</b> [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
6	08/01/20 14:03	<b>Accident Photo</b> [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
7	08/01/20 14:03	<b>Accident Photo</b> [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
8	08/01/20 14:03	<b>Accident Photo</b> [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
9	08/01/20 14:03	<b>Accident Photo</b> [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
10	08/01/20 14:03	<b>Accident Photo</b> [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	10/01/20 11:45	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
2	10/01/20 11:45	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
3	10/01/20 11:45	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
4	10/01/20 11:45	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
5	10/01/20 11:45	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
6	10/01/20 11:45	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
7	10/01/20 11:45	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
8	10/01/20 11:45	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
9	10/01/20 11:45	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
10	10/01/20 11:45	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
11	10/01/20 11:45	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
12	10/01/20 11:45	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
13	10/01/20 11:45	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
14	10/01/20 11:45	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
15	10/01/20 11:45	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
16	10/01/20 11:45	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
17	10/01/20 11:45	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
18	10/01/20 11:45	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page ▾	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
67	10/01/20 11:45	General View	 Load JPG	<input checked="" type="checkbox"/>
68	10/01/20 11:45	General View	 Load JPG	<input checked="" type="checkbox"/>
69	10/01/20 11:45	General View	 Load JPG	<input checked="" type="checkbox"/>
70	10/01/20 11:45	General View	 Load JPG	<input checked="" type="checkbox"/>
71	10/01/20 11:45	General View	 Load JPG	<input checked="" type="checkbox"/>
72	10/01/20 11:45	General View	 Load JPG	<input checked="" type="checkbox"/>
73	10/01/20 11:45	General View	 Load JPG	<input checked="" type="checkbox"/>
74	10/01/20 11:45	General View	 Load JPG	<input checked="" type="checkbox"/>
75	10/01/20 11:45	General View	 Load JPG	<input checked="" type="checkbox"/>
76	10/01/20 11:45	General View	 Load JPG	<input checked="" type="checkbox"/>
77	10/01/20 11:45	General View	 Load JPG	<input checked="" type="checkbox"/>
78	10/01/20 11:45	General View	 Load JPG	<input checked="" type="checkbox"/>
79	10/01/20 11:45	General View	 Load JPG	<input checked="" type="checkbox"/>
80	10/01/20 11:45	General View	 Load JPG	<input checked="" type="checkbox"/>
81	10/01/20 11:45	General View	 Load JPG	<input checked="" type="checkbox"/>
82	10/01/20 11:45	General View	 Load JPG	<input checked="" type="checkbox"/>
83	10/01/20 11:45	General View	 Load JPG	<input checked="" type="checkbox"/>
84	10/01/20 11:45	General View	 Load JPG	<input checked="" type="checkbox"/>
85	10/01/20 11:45	General View	 Load JPG	<input checked="" type="checkbox"/>
86	10/01/20 11:45	General View	 Load JPG	<input checked="" type="checkbox"/>
87	10/01/20 11:45	General View	 Load JPG	<input checked="" type="checkbox"/>
88	10/01/20 11:45	General View	 Load JPG	<input checked="" type="checkbox"/>
89	10/01/20 11:45	General View	 Load JPG	<input checked="" type="checkbox"/>
90	10/01/20 11:45	General View	 Load JPG	<input checked="" type="checkbox"/>
91	10/01/20 11:45	General View	 Load JPG	<input checked="" type="checkbox"/>
92	10/01/20 11:45	General View	 Load JPG	<input checked="" type="checkbox"/>
93	10/01/20 11:45	General View	 Load JPG	<input checked="" type="checkbox"/>
94	10/01/20 11:45	General View	 Load JPG	<input checked="" type="checkbox"/>
95	10/01/20 11:45	General View	 Load JPG	<input checked="" type="checkbox"/>
96	10/01/20 11:45	General View	 Load JPG	<input checked="" type="checkbox"/>
97	10/01/20 11:45	General View	 Load JPG	<input checked="" type="checkbox"/>
98	10/01/20 11:45	General View	 Load JPG	<input checked="" type="checkbox"/>
99	10/01/20 11:45	General View	 Load JPG	<input checked="" type="checkbox"/>
100	10/01/20 11:45	General View	 Load JPG	<input checked="" type="checkbox"/>
101	10/01/20 11:45	General View	 Load JPG	<input checked="" type="checkbox"/>
102	10/01/20 11:45	General View	 Load JPG	<input checked="" type="checkbox"/>
103	10/01/20 11:45	General View	 Load JPG	<input checked="" type="checkbox"/>
104	10/01/20 11:45	General View	 Load JPG	<input checked="" type="checkbox"/>
105	10/01/20 11:45	General View	 Load JPG	<input checked="" type="checkbox"/>
106	10/01/20 11:45	General View	 Load JPG	<input checked="" type="checkbox"/>
107	10/01/20 11:45	General View	 Load JPG	<input checked="" type="checkbox"/>
108	10/01/20 11:45	General View	 Load JPG	<input checked="" type="checkbox"/>
109	10/01/20 11:45	General View	 Load JPG	<input checked="" type="checkbox"/>
110	10/01/20 11:45	General View	 Load JPG	<input checked="" type="checkbox"/>
111	10/01/20 11:45	General View	 Load JPG	<input checked="" type="checkbox"/>
112	10/01/20 11:45	General View	 Load JPG	<input checked="" type="checkbox"/>
113	10/01/20 11:45	General View	 Load JPG	<input checked="" type="checkbox"/>
114	10/01/20 11:45	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
115	10/01/20 11:45	General View	Load JPG	<input checked="" type="checkbox"/>
116	10/01/20 11:45	General View	Load JPG	<input checked="" type="checkbox"/>
117	10/01/20 11:45	General View	Load JPG	<input checked="" type="checkbox"/>
118	10/01/20 11:45	General View	Load JPG	<input checked="" type="checkbox"/>
119	10/01/20 11:45	General View	Load JPG	<input checked="" type="checkbox"/>
120	10/01/20 11:45	General View	Load JPG	<input checked="" type="checkbox"/>
121	10/01/20 11:45	General View	Load JPG	<input checked="" type="checkbox"/>
122	10/01/20 11:45	General View	Load JPG	<input checked="" type="checkbox"/>
123	10/01/20 11:45	General View	Load JPG	<input checked="" type="checkbox"/>
124	10/01/20 11:45	General View	Load JPG	<input checked="" type="checkbox"/>
125	10/01/20 11:45	General View	Load JPG	<input checked="" type="checkbox"/>
126	10/01/20 11:45	General View	Load JPG	<input checked="" type="checkbox"/>
127	10/01/20 11:45	General View	Load JPG	<input checked="" type="checkbox"/>
128	10/01/20 11:45	General View	Load JPG	<input checked="" type="checkbox"/>
129	10/01/20 11:45	General View	Load JPG	<input checked="" type="checkbox"/>
130	10/01/20 11:45	General View	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	08/01/20 14:03	<b>Sketch Plan</b> [Linked Accident Report Documents]	Load TIF	
2	08/01/20 14:04	<b>Identification Card</b> [Linked Accident Report Documents]	Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/01/20 11:40	<b>XD 6545A GIA.pdf</b>	Load PDF	
2	10/01/20 11:40	<b>ESTIMATE.pdf</b>	Load PDF	
3	17/01/20 17:30	<b>LTA REBATE</b>	Load PDF	

## Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	08/01/20 14:04	<b>Accident Statement</b>	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	08/01/20 14:03	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
2	08/01/20 14:03	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
3	08/01/20 14:03	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
4	08/01/20 14:03	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
5	08/01/20 14:03	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
6	08/01/20 14:03	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
7	08/01/20 14:03	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
8	08/01/20 14:03	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
9	08/01/20 14:03	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
10	08/01/20 14:03	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	08/01/20 14:03	<b>Sketch Plan</b>	Load TIF	
2	08/01/20 14:04	<b>Identification Card</b>	Load TIF	

# Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer  
Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

Our File No: CS/CTI20000576/R1SF3S2

Date: 17/01/2020

## REFERENCE

Insured/Claimant: KOK TONG TRANSPORT &amp; ENGINEERING WORKS PTE LTD

Policy No: DMCVSN1900161900

Date of Loss: 07/01/2020

Nature of Claim: OD Claim No: SNM20D200100C01

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: XD6545A  
Make & Model: VOLVO FMX420, 12.8 D (M)  
Reg. Date: 22/01/2013 (Man. Year: 2012)  
Colour: White  
Engine Capacity: 12777 cc  
Market Value/New Car Price: S\$79,000.00  
Sum Insured (S\$): Market Value/New Car Price

Engine No: D13372388  
Chassis No: YV2JG10G6DA738197  
Odometer: 622965 km

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

## CONDITION OF TYRES

Front Tyre Size: 315/80 R22.5 Rear Tyre Size: 315/80 R22.5 (D)  
Front Left Side: Triangle 8 mm Rear Left Side: Triangle 8/8 mm  
Front Right Side: Triangle 8 mm Rear Right Side: Triangle 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	
<b>- Excess (S\$)</b>	<b>1,500.00</b>	<b>1,500.00</b>	<b>0.00</b>	<b>0.00</b>
<b>Nett Amount (S\$)</b>	<b>-1,500.00</b>	<b>-1,500.00</b>	<b>0.00</b>	<b>0.00</b>

## INSPECTION

Date of Assignment: 08/01/2020

Date Inspected: 09/01/2020

Inspected At:

Vfix Auto Service Pte Ltd (HQ)  
26 Chia Ping Road  
Singapore 619977

Estimated Period of Repair: 0.0 days

Adjuster: MOHD RASUL

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

**TOTAL LOSS ASPECT**

Market Value :	\$ 79,000.00
OMV :	\$ 133,054.00
PARF Rebate (1) :	\$ 0.00
Quota Premium Paid :	\$ 60,235.00
COE Rebate (2) :	\$ 18,264.00
Total Rebate (1) + (2) = :	\$ 18,264.00

The total amount incurred will be Market Value \$ 79,000.00 minus Total Rebate \$ 18,264.00 = \$ 60,736.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.



## REPAIR DETAILS

### Reference

**Part Source:** (Last Synchronised: 17 Jan 2020)

**Parts:** N/A VOLVO FMX420 12.8 D (M) (Model not available in database)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for XD6545A)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >