ASS, REC. BY	ol	REF: CS3 INC	19 020092/6	d34 Special in	uitroetine	
Sanger: _ From Person		le Insurance	NMENT (Office) Date	Time:	08/01/2020
To Inspect V	STTP RESTOD	FX -Tool & OFO	X869	TIDATE OF		165019 2737469
of Policy No:	BIK	1006 # 010	8 Bulif Mer	uh lane 3 Mt/	1072	062-002
Sum houred;			Excess:			
Make of Veh (Client's Recor				D.0	Α	16/11/2019
	/ REP. / REV 2 1-13cm@26/11		opted Mr Hea			OUT
Date/Time	Action/Instructi	on Enhanget X	_	-		
		K-NA/III 130/			D	04: 141 06 3013
•		: अप्रिचित्र			19	
ودود اله	Submit LS 3 days	\$ 3750	(Red 1350, 3	0690), /	1	monto
	3 44ys					9/1/2020

RECEIVED 1 0 JAN 2020

Time: File Page 147	: Proll. Report	Day	ys Of Repair:	
	: Final Report	Res	survey No. of Trip:	Survey Fee:
Time: File Roturn to?		-	_	Transportston
		Add Fee:	: Site Insp (\$	J3 + R5SF
			: Interview (\$	i Hoke
ort Fornast:	PRS.	Γ	: Tech. Inve (\$	ji - Henri
·	A 15 15 - 71 L 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -	Part Part Part Part Part Part Part Part	Aller Francis II	

Nivitha (LKK Auto)

From:

do_not_reply@income.com.sg

Sent:

Wednesday, 8 January 2020 5:06 PM

To:

assignments@lkkauto.com

Subject:

MT/1072062-002 - Claim Involving SJY6501G / FX7628X on 16 Nov 2019

Attachments:

LOD2 2020-1-8.pdf.PDF; TP SR.PDF; EBGI-300002866-0000177294-1578463869520

_EBAOGICLM_DLET_MT.pdf

Dear Sir / Madam,

We refer to the above claim.

Enclosed is the letter / document for your necessary attention.

Yours sincerely

Motor Insurance

Income

Note: This is a system generated email. Please do not reply to this email.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any withir misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The insure and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5 Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you haveby consent to the archiving of this report at the centre and to copies of the report being made available

aforesaid.	
	ACCIDENT STATEMENT
Date Of Report	22/11/2019 16:41
Date Of Accident	16/11/2019 23:50
Exact Location Of Accident	BANGKIT ROAD
Country/State of Loss	SINGAPORE
D	ETAILS OF OWN VEHICLE
Vehicle Registration Number	FX7628X
Insured/Policyholder	
Name Of Registered Owner	AHMAD MUSTAFA BIN ABDUL HAMEED
NRIC No	S8719653D
Email Address	AHMAD, MUSTAFA1987@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96979035
Alternative Phone No	OFFICE-96979035
Vehicle Particulars	
Manufacturer	HONDA
Model	CB400SF4J-399CC
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO.
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE
Insurance Company	
Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE, LTD.
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	D19MTMC01001356
Cover Note Number	
Deluge	

Contact Number

Driver	
Name of Driver	AHMAD MUSTAFA BIN ABOUL HAMEED
NRIC No	S6719653D
Date Of Birth	19/06/1987
Occupation	INDOOR
Date Of Driving Pass	08/03/2007
Driving Experience	12 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96979035
Fax Number	

OFFICE-96979035

Address

BLK 257 BANGKIT ROAD

#08-67

Plostcode'

670257

Was driver an employee of the Insured's Company NO

If No. Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle

OWNER

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - MAJOR/MINOR RD

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle) involved in the accident

2

Was any body injured in the Accident?

YES

Was any injured conveyed to hospital by

YES

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Police Station Name

UBI AVE 3

Police Station Address Police Station Contact

ROAD: 10 UBI AVE 3 . POSTCODE: 408865 . COUNTRY: SINGAPORE

TEL NO: - FAX NO:

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO POLICE REPORT FOR INCIDENT DETAIL.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SJY6501G

Vehicle Make/Model/Colour

TOYOTA VIOS

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NASIR BIN ABDULLAH

NRIC/Passport Number

S1818945C

Contact Number

82994393

Address

Postcode

Insurance Company Name

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

AHMAD MUSTAFA BIN ABDUL HAMEED

Approximate Age

32

Injunes Sustain

Injured person in which vehicle?

FX7628X

Were seat belts wom?

Was this injured conveyed to hospital by ambulance?

Address

BLK 257 BANGKIT ROAD #08-67

Postcode

670257

Sketch Plan Pg. 1

	Cabone	
SKETCH PLAN	1	Α
		· 102 → 1020 ·
		A - 574 GELL
		, and
-		£3
		Popularian
		国 ~ 6 (3)
		·
		1 '
		G !
DESCRIBE CIRCUMSTANCES	OF THE ACCIDENT	(E) charpoint
Refer to price	Report No. 7/20191119/7603	1
100000	17 3 DO 17 5	
DECLARATION	office and the a local and a second	
/We declare the foregoing partic	war a are true in every rappect	
A		
Policyholder's Signature	Ordered Street	
Date & Time: 32 N 21.5	Driver's Signature Iti driver is not the policyholder! Date & Yimer	Reporting Centre Personnel's Signature Name:



Occupation: Telecommunications engineer



Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

1 of 3 Report No. T/20191119/7007

REPORT (OF A TRAFFI	CACCIDENT					
Date/Time Report Made: 19/11/2019 13:19			Vide Report No.: Station Diary No				
Informa	nt's Partic	ulars					
		BIN ABDUL	Address: APT BLK 257 BANGKIT ROA	D #08-67 SINGAPORE 670257			
ID Type / ID No.; NRIC NO / \$8719653D		53D	Contact No.: Home/Office:	Mobile: 96979035			
National SINGAP	ity: ORE CITIZ	EN	Email: ahmad.mustafa1987@gmail.d	com			
Sex: Male	Age:	Date of Birth: 19/06/1987	Type of Informant Rider				
Race: Indian			Language: English	Institution / School Name:			
Occupation: Telecommunications engineer		s engineer	Driving Licence Information: Class: 2.3 Date of Expiry:				

General Infon	mation of the Accident					
Type of Accident:	Injury Conveyed By Ambul	Injury Conveyed By Ambulance		Date/Time of Accident: 16/11/2019 23:5	Type of Location Straight Road	
Location: BANGKIT RO	DAD					
Weather: Clear		Road	Surface:		Road Speed Limit: 50 Km/h	
			Traffic Control: Not Controlled		Traffic Volume: Light	
Type of Collis Between Mov	ion; ving Vehicles - Head To Si	de		tarative and	Anyone conveyed by ambulance: Yes	

Details of A	ehicle involve	O .				
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FX7628X	Motorcycle	T				0
SJY6501G	Car	OTHERS	Toyota VIOS	Grey	Slightly Damaged	2

Details of Person Involved		
Any Pedestrian Involved: No		
No. of Pedestrians Injured: NIL.	Use of Pedestrian Crossing: NA	

POLICE REPORT Pg. 2





Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

2 of 3 Report No. T/20191118/7007

CONTINUATION OF REPORT

Rider					
Name	AHMAD MUSTAFA BIN ABDUL	HAMEED	ID No.	S8719653D	
Related Vehicle	FX7628X (Matorcycle)	Contact No	96979035		
Hospital/Clinic	NG TENG FONG GENERAL HO	OSPITAL	Class of Driving Licence & Expiry Date	Class: 2,3 Date of Expiry: NIL	
Date Treatment	B CONTROL OF THE PROPERTY OF THE PARTY OF TH	Date Disc		1/2019	
No. of Days gran	ted Medical Leave NIL	Degree of	Injury Sligh	nt .	
Driver	CHIEF TO A CONTROL OF THE CONTROL OF				
Name	NASIR BIN ABDULLAH		ID No.	S1818945C	
Related Vehicle	SJY6501G (Car)		Contact No.	NIL	
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL	
Date Treatment	NIL	Date Disc	harge NIL		
No. of Days gran	led Medical Leave NIL	Degree of			

I stay at Block 257, my carpark is BJ14.

I turned right to Bangkit Road from Buldt Panjang Ring Road. There was a car stopped just before carpark (BJ12) so i overtook it on the right to go towards my carpark (BJ14). Suddenly, a car dashed out from BJ12 and hit me on my left (Head to my left side). He jammed brake after hitting me. I fall to my right. My left ankle had a deep cut and was bleeding.

I was taken to hosp by ambulance. My bro-in-law helped to bring my motorcycle back to my carpark after the accident. He mentioned that the motorcycle could not start up. The clutch handle lever and foot brake lever was broken.

lever was broken.

I was admitted to hosp for 3 days, deep cut but no fracture. The wound was dirty so had to go through surgery to clean the wound before stitching up.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		
Owner ID Type:	Singapore NRIC	
Owner ID: Vehicle Details	653D	
Vehicle No.:	FX7628X	
Vehicle to be Exported:	No:	
Intended Deregistration Date:	26 Nov 2019	
Vehicle Make:	HONDA	
Vehicle Model:	CB400 SF4J M	
Primary Colour:	Silver	
Manufacturing Year:	2004	
Engine No.:	NC23E2060869	
Chassis No.:	NC391050861	
Maximum Power Output:	•	
Open Market Value:	\$8,678.00	
Original Registration Date:	24 Feb 2004	
First Registration Date:	24 Feb 2004	
Transfer Count:	3	
Actual ARF Paid: Intended PARF Rebate Details	\$1,302.00	
PARF Eligibility:	No	
PARF Eligibility Expiry Date:		
PARF Rebate Amount: Intended COE Rebate Details	\$0.00	
COE Expiry Date:	23 Feb 2024	
COE Category:	D - Motorcycle	
COE Period(Years):	10	
PQP Paid:	\$1,952.00	
COE Rebate Amount:	\$828.00	
Total Rebate Amount:	\$828.00	

The information contained herein is correct as at 26 Nov 2019

OK



VEHICLE DAMAGE INSPECTION REPORT

Our Ref:

654/TP/2019

Date: 12/12/2019

REFERENCE

Date of loss:

16/11/2019

Claimant:

Ahmad Mustafa Bin Abdul Hameed

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

FX7628X

Reg date:

24/2/2004

Colour:

Red

Type:

Type of Claims:

Motorbike

Third Party

Make &

Honda

Model

CB400 SF4J M

Engine No: Chassis No: NC23E2060869 NC391050861

Odometer No: N.A.

Engine Cap:

399cc

CONDITION OF VEHICLE AT THE TIME OF SURVEY

(STATIC ONLY)

General Condition: Good

Steering:

N.A.

Engine Modification: Nil

Paint work:

Good

Front brake: Good

Pre-accident

Footbrake: Good

Damage:

Nil

CONDITION OF TYRES

Front Wheel Size: Pirelli 120/60R17 70% Rear Wheel Size: Pirelli 160/60R17 70%

The above percentages represent the remaining life of the tyre threads

COST OF REPAIRS

Repairer S\$ Adjuster S\$

Parts Labour 6,471.90 \$ 5,359.50 1,450.00 S 970.00 7,921.90 \$ 6,329.50

Calculated Cost (S\$):

\$ 5,100.00 Recommended Lump Sum Repair Cost (S\$):

Date of Assignment:

27/11/2019

Date Inspected:

27/11/2019

Est. repair Period:

05 days

Inspected At: Leong Seng Motor Pte Ltd


Blk 1006 Bukit Merah Lane 2

#01-08

Singapore 159762

POINT OF IMPACT

Damaged at the right hand front, right hand rear, left hand front and left hand rear portion.



BRIEF CIRCUMSTANCES OF ACCIDENT

The Insured's vehicle collided onto the Third Party's vehicle along Bangkit Road.

GENERAL DESCRIPTION OF DAMAGES

Our visual inspection of the vehicle revealed that the damages noted are the right hand front, right hand rear, left hand front and left hand rear portion.

SPECIAL REMARKS

We have inspected the actual damages found on the vehicle and recommend the replacement of parts and repairs accordingly. The estimated repair cost is \$7,921.90. The repairer has agreed to undertake the repairs at our adjusted lump sum amount of \$5,100.00.

We have not authorised the repair. Under normal circumstances, estimated 05 working days are required to repair the vehicle.

We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our Inspection Report and photographs.



Automotive Appraiser: Dave Chang

Please note that this report is solely based on our findings at the time and place of inspection. This inspection has been carried out to our best

REPAIR DETAILS

Recommended Parts

No	Qty	Description	Condition		Repairer's Amount		djuster's Amount
2	1	Handle bar	bent	S	225.00	aminani	SELECTION OF SELEC
	1	Handle balancer	necessary	\$	45.00	10000	
3	1	Brake lever	bent	\$	75.00		
4	1	Mirror	bent	\$	85.00		
5	1	Meter assy	cracked	\$	835.00	\$/	55
6	1	Headlamp assy	grazed/bent	S	380.00	5/	
7	1	Headlamp stay	bent	S	210.00	5 ×	
8	1	Front signal lamp	bent	\$	50.00	\$	
9	1	Front fender	repair	\$	195.00	\$	20.00
10	1	Front wheel axle	bent	\$	95.00	s /	95.00 43
11	1	Front fork assy	malfunction	S	880.00	s/	880.00
12	1	Fork under bracket	bent	\$	285.00	\$ /	
13	1	Steering cone & bearing	necessary	\$	150.00	\$/	150.00 9
14	1	Brake pedal	bent	\$	125.00	\$ X	AND THE RESERVE OF THE PARTY OF
15	1	Front right foot rest	intact	\$	68.00	\$	170.00
16	1	Rear right foot rest	intact	S	45.00	\$	- 2NC
17	1	Exhaust muffler	grazed/bent	S	660.00	\$/	- SV
18	1	Exhaust pipe	grazed/bent	S	785.00	\$/	785.00
19	1	Rear signal lamp	bent	\$	50.00	s×	
20		Gear pedal	bent	\$	85.00	\$ /	20.000
21		Front left foot rest	intact	\$	68.00	\$	85.00 40
22		Rear left foot rest	intact	\$	45.00	\$	-40
23		Rear foot rest bracket	bent	S	285.00	s X	285.00
24		Rear left shock absorder	bent	\$	650.00	SX	650.00
25		Rear swing arm	repair	\$	680.00	\$	050.00 370
26	1	Swing arm brush	repair	\$	135.00	\$	- 18
					7,191.00		- <u>ℝ</u> 5,955.00
		Less 10%	1 . 25	\$	719.10	\$	
			4435	\$ \$ \$		-	595.50 5,359.50
			- 10%				1307130
		Total parts	3 991.50				

ANNEX B

REPAIR DETAILS

Recommended Labour

No	Description		Repairer's Amount		Adjuster's Amount	
1	Engine guard.	\$	250.00	\$	200.00 / [
2	Rear box.	\$	180.00	5	150.00 / (W	
3	Rear carrier.	\$	200.00	\$	120.00 X JV	
4	To conduct wheel alignment.	\$	250.00	S	120.00 49/	
5	Towing 2 way.	\$	120.00	e e		
,	Labour to repair and replace damaged parts.	D	LOS DESCRIPTION OF THE	2	80.00 50	
		5	450.00	S	300.00 950	
	Total labour :	S	1,450.00	S	970.00	

690

ANNEX C

REPAIR DETAILS

Adjusted Repair Cost

	100	depairer's Amount		Adjuster's Amount	
Total parts:	S	6,471.90	s	5,359.50	
Total labour :	S	1,450.00	\$	970.00	
Total repair cost:	S	7,921.90	S	6,329.50	

All and the second		
Adjusted Repair Cost (Lump Sum Repair)	S	5,100.00

P-3991.50 L-690 4681-50 L/S-3745-20 = 3750

3 repar dys



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation	Internationale De	es Experts	En Automobile
--------------------------	-------------------	------------	---------------

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS3/INC19020892/Evd3s2-1

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 14-01-2020

ALEXANDRA VILLAGE SINGAPORE 159762.

ESTIMATED NORMAL PERIOD FOR REPAIR:

189556

5a.

5b.



1895				
ATTN	1: JULIANA LEE		Code: INC	
1.		Policy Particulars	:- THIRD PARTY CLA	AIM
	Insured Veh.	SJY 6501G	Veh. Inspected	FX 7628X
	Policy No.		Coverage (\$)	0.00
	Claim No.	MT/1072062-002	Excess (\$)	0.00
	Assign From	MOTOR INCOME INSURANCE	Assign Date	08/01/2020
2.	Con de pesa	Vehicle Partic	culars & Condition	
	Make & Model	HONDA CB400	c.c	399
	Engine No.	HIDDEN	Year of Reg.	2004
	Chassis No.	NC391050861	Colour	RED
	Odometer		Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3.		Condition	ons of Tyres	
		Size	Make	Balance
	R/H Front Tyre	120/60 R17	PIRELLI	5 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	160/60 R17	PIRELLI	5 mm
	L/H Rear Tyre			mm
		Descriptio	n of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE FRO	NT PORTION, O/S AND	N/S BODY.
	DAMAGES SEE D	ETAILS.		
1	Consideration !!	General	Information	
	Accident Date	16/11/2019	Inspection Date	26/11/2019
1	Survey held at	rvey held at LEONG SENG MOTOR PTE LTD		
		BLK 1006, BUKIT MERAH LANE #01-08	2	

Remarks

Estimate Days of Repair

3 Working Days

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FX 7628X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	HANDLE BAR	BENT	225.00	180.00
1	HANDLE BALANCER	NECESSARY	45.00	45.00
1	BRAKE LEVER	BENT	75.00	75.00
1	MIRROR	BENT	85.00	85.00
1	METER ASSY	CRACKED	835.00	835.00
1	HEADLAMP ASSY	GRAZED / BENT	380.00	380.00
1	HEADLAMP STAY	SERVICEABLE	210.00	
1	FRONT SIGNAL LAMP	BENT	50.00	50.00
1	FRONT FENDER	TO REPAIR SEE LABOUR	195.00	7-
1	FRONT WHEEL AXLE	BENT	95.00	45.00
1	FRONT FORK ASSY	MALFUNCTION	880.00	880.00
1	FORK UNDER BRACKET	BENT	285.00	285.00
1	STEERING CONE & BEARING	NECESSARY	150.00	90.00
1	BRAKE PEDAL	SERVICEABLE	125.00	1
1	FRONT RIGHT FOOT REST	SERVICEABLE	68.00	
1	REAR RIGHT FOOT REST	SERVICEABLE	45.00	5-
1	EXHAUST MUFFLER	GRAZED / BENT	660.00	660.00
1	EXHAUST PIPE	GRAZED / BENT	785.00	785.00
1	REAR SIGNAL LAMP	SERVICEABLE	50.00	
1	GEAR PEDAL	BENT	85.00	40.00
1	FRONT LEFT FOOT REST	SERVICEABLE	68.00	
1	REAR LEFT FOOT REST	SERVICEABLE	45.00	107
1	REAR FOOT REST BRACKET	SERVICEABLE	285.00	14
1	REAR LEFT SHOCK ABSORBER	SERVICEABLE	650.00	2
1	REAR SWING ARM	TO REPAIR SEE LABOUR	680.00	-
1	SWING ARM BRUSH	TO REPAIR SEE LABOUR	135.00	18
	LESS 10% DISCOUNT		-719.10	-443.50
			6,471.90	3,991.50
	SPECIAL NETT ITEMS			
1	ENGINE GUARD (SN)	BENT	250.00	200.00
1	REAR BOX (SN)	сит	180.00	150.00

Report Ref No. CS3/INC19020892/Evd3s2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR CARRIER (SN)	SERVICEABLE	200.00	1.7
	LABOUR		630.00	350.00
	TO CONDUCT WHEEL ALIGNMENT. TOWING 2 WAY.		250.00	40.00
INCLUSIVE	LABOUR TO REPAIR AND REPLACE DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF FRONT FENDER, REAR SWING ARM BRUSH.		120.00 450.00	50.00 250.00
			820.00	340.00
	GRAND TOTAL		7,921.90	4,681.50

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)	3,750.00

Report Ref No. CS3/INC19020892/Evd3s2-1

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.