

22/02/2020

A.S.S. REG. BY:

REF: C8/SMO20000583/hyd3

Special Instruction:

Surveyor: Adnan

ASSIGNMENT (Office)

From (Person): Cince Teo of SMO Date/Time: 9/11/2020 @ 10:42am

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBJ 7047T Insured: YP 731T

at Workshop n/s Vision Autowork Tel: 9856 4815

of 8 kaki Bukit Ave #08-09 premier

Policy No: Claim No: CMTD2000147/APL

Sum Insured: Excess:

Make of Veh: D.O.A. 07/10/2020  
(Client's Record)

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement:

Date/Time: 11:12am @ 9/1/2020 Person Contacted: Michelle Vehicle: IN/OUT

Date/Time	Action/Instruction	Johny? ✓
	GBJ 7047T - X	
	YP 731T - X	
15/1/20	Pending Estimate from workshop	
16/1/20	Sent Preli by email	
17/1 3.25pm	Spoken to Michelle, agreed to repair the vehicle at lump sum not more than \$27,500.	

ASSIGNMENT

Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 (GD / TP / WS / TP RES / CO RES / EVA / INV / MV)  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop no: \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_  
 (Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.  
 Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res: Yes or No  
 Turn Sum: \_\_\_\_\_ % 3 Val: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT

N/S	O/S

Vch No: GIBJ7047T. Date: 2019 July.  
 Type:  Car /  M/Cycle /  Bus /  Van /  Boat /  Taxi /  Private Motor /  
 Truck / Trailer of \_\_\_\_\_  
 Make: Toyota Dyna. No: 2982  
 Colour: White Age: Insured / Std / NI / NA  
 Sp Reading: 30453. Tread: Insured / Std / NI / NA  
 Eng No: \_\_\_\_\_  
 C/No: JTFAT35Y10K213613.  
 Gen. Cond:  Good /  Fair /  Poor /  Burnt  
 Steering:  In order /  Jammed /  Leaked /  Burnt or  
 Brake:  In order /  Jammed /  Leaked /  Burnt or  
 Modi:  Nil /  S/Rim /  STD A/Rim or  
 Tyre Size: F: 195/75R15  
 R: ~~195/75R15~~ 155R12  
 BS /  DUN /  EXNOVA /  GY /  FS /  LIZA /  MIC /  OHTSU /  PIR /  SUMI /  
 TOYO / YOKO or \_\_\_\_\_  
 Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
 R/Bal: 06 mm F. Bal: 06 mm  
 L/Bal: 06 mm L. Bal: 06 mm  
 D.O.A. \_\_\_\_\_ D.O.I. 09/01/20  
 Survey held at: Vision  
 Des. of Damages:  Fr /  Rear /  O/S /  N/S /  U/C /  Rooftop or  
 The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
	<u>TP Sample</u>

MV: 58k  
 PV: 25.6k  
 Nett: 32.4k

RECEIVED 25 MAR 2020

09/07/2020 ADRIAN SAID NEED TO TAKE OUT 1 ITEM AND L/S AMOUNT \$26000.00 REPAIR 28 DAYS *Celine 14/07/2020*

Date/Time: File Pass to?  : Prel. Report  
 : Final Report  
 Days Of Repair: 28  
 Resurvey No. of Trip: 4  
 Date/Time: File Pass to? 25/3/20 Typist  
 Add Pas:  Site Insp: 15  
 Interview: 15  
 Policy: 15  
 Total: 45  
 Survey Fee: \_\_\_\_\_  
 Transport: \_\_\_\_\_  
 Other: \_\_\_\_\_  
 Total: \_\_\_\_\_  
 (Stamp) \$26500/=