



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL Ref : CS/SMO20000583/Ayd3e2

50 RAFFLES PLACE
#05-01/06
SINGAPORE LAND TOWERSINGAPORE 048623

Date : 07-04-2020



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YP 731T	Veh. Inspected	GBJ 7047T
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2000147/GPL	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	09/01/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA DYNA	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	JTFAT35Y10K213613	Colour	WHITE
Odometer	30453	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/75 R15	BRIDGESTONE	6 mm
L/H Front Tyre	195/75 R15	BRIDGESTONE	6 mm
R/H Rear Tyre	155 R12	BRIDGESTONE	6 mm
L/H Rear Tyre	155 R12	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	07/01/2020	Inspection Date	09/01/2020
Survey held at	VISION AUTOWORK PTE LTD 8 KAKI BUKIT AVE 4, #08-09 PREMIER @ KAKI BUKIT SINGAPORE 415875		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **28 Working Days**