



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CC4/FCI20000588/Gka3q2

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 04-05-2020



Code : FCI2

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SHC 629B	<b>Veh. Inspected</b>	SKS 7515E
<b>Policy No.</b>	D-19092579MFSH	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	D20000135MFSH	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	RACHEL WU	<b>Assign Date</b>	08/01/2020

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	PORSCHE MACAN 2.0	<b>c.c</b>	1984
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2015
<b>Chassis No.</b>	WP1ZZZ95ZFLB22525	<b>Colour</b>	WHITE
<b>Odometer</b>	87055	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>	265/40 R21	PIRELLI	6 mm
<b>L/H Front Tyre</b>	265/40 R21	PIRELLI	6 mm
<b>R/H Rear Tyre</b>	265/40 R21	PIRELLI	6 mm
<b>L/H Rear Tyre</b>	265/40 R21	PIRELLI	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.
---

### 5. General Information

<b>Accident Date</b>	19/12/2019	<b>Inspection Date</b>	14/01/2020
<b>Survey held at</b>	51 UBI AVE 1 #05-02		
<b>Repairer</b>	1ST AUTO PRO PTE LTD		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>2 Working Days</b>
-------------------------------------	-----------------------