

(08/11/13) Wef

ASS. REC. BY: *Marcus*

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

COR 31-8-2022

Vehicle: IN / OUT

Date:

Person Contacted:

2 yrs back.

Veh No:

FRG 54064

Yr Regn:

182

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Vespa SPRI

c.c

150

Colour:

Green

A/C: Insured / Std / NI / NA

Sp. Reading

20896

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

423690

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

110-70-12

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

maxxis

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

4/1/20

D.O.I.

9/1/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt, O/S Rnd

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Self skid MIA 491

29/5/20 2/5 1850 confirmed with MR Teo. (Red \$3267.70, 64%)

Date/Time, File Pass to?

☐

: Preli. Report

1/29/05 Typist

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) S + RS SI

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format :

MER-TP

Lump Sum + L.B. (\$

1850

)

TOTAL

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

CHINA

Owner : Muhammad Raihan Bin Mansor

Accident Date : 4-Jan-20

Vehicle No : FBG 5406 U

Vehicle Model : Vespa

Estimated Repair Costs

Qty	Description	Amount S(\$)
	<u>List Items</u>	
1	Front fender	\$ 85.00 ✓
1	Front fork assy	\$ 580.00 X
1	Front shock absorber	\$ 250.00 ✓
1	Front panel	\$ 320.00 X
1	Front panel moulding	\$ 110.00 ✓
1	Front signal	\$ 65.00 ✓
1	Side mirror	\$ 60.00 ✓
1	Handle-bar	\$ 185.00 X
1	Handle-bar end	\$ 35.00 ✓
1	Brake lever "Brembo" → 495	\$ 495.00 ✓
1	Step board panel	\$ 180.00 X
1	Engine cover	\$ 155.00 ✓
1	Engine cover moulding	\$ 50.00 X
1	Kick starter	\$ 90.00 ✓
1	Gear selector	\$ 98.00 X
1	Rear signal	\$ 55.00 ✓
		\$ 1150
	Less 10%	\$

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

c/f: \$ 2,171.70

Special Nett Items

1	Number plate (1 set)	\$	22	28.00	20
1	Steering cone (1 set)	\$	17	85.00	X
1	Rear box	\$	647	280.00	250
1	Rear box bracket	\$	82	100.00	X
1	E.R.P IU	\$	647	175.00	—
1	" VESPA " Emblem	\$	22	38.00	—
		\$		706.00	

S/No. **Labour**

1	To provide towing service.	\$	17	50.00	X
2	To provide labour.	\$	300	380.00	.
3	To respray painting .	\$	450	1,000.00	
4	To repair body frame.	\$	17X	450.00	
		\$		1,880.00	

Grand Total

\$


EROFIA MOTOR TRADING PTE LTD