

SK Automobile Pte Ltd
 (Co Reg. No. 201500047H)
 23 Kaki Bukit Ave 4, #03-01
 Vicom Inspection Centre (S415933)
 Tel: 6789 5155 Fax : 6783 5155

TO	: LONPAC	DATE	: 9-Jan-20
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>OWNER'S PARTICULAR</u>		<u>VEHICLE DETAILS</u>	
NAME	:	VEHICLE NO	: SJK6685H
ADDRESS	: <i>Khoochua</i>	MODEL	: HONDA CIVIC
TEL. NO.	:	CHASSIS NO	: <i>FD11202360</i>
OWNER'S INSURANCE	:		
POLICY NO.	:		
<u>ACCIDENT DETAILS</u>	DATE :		
	TIME :		
THIRD PARTY REQUESTOR / CONTACT	: XIONG 8121 0478		

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BOOTLID <i>Painted</i>	1	\$ 798.00	\$ 798.00
2	BOOTLID REFLECTOR <i>Curved</i>	2	\$ 222.20	\$ 444.40
3	BOOTLID INNER STOPPER <i>New</i>	2	\$ 32.20	\$ 64.40
4	BOOTLID HINGE <i>Best</i>	2	\$ 98.60	\$ 197.20
5	BOOTLID HINGE COVER <i>New</i>	2	\$ 56.00	\$ 112.00
6	BOOTLID TOP LOCK <i>Strong</i>	1	\$ 194.50	\$ 194.50
7	BOOTLID LOWER LOCK <i>New</i>	1	\$ 35.00	\$ 35.00
8	BOOTLID LOGO <i>New</i>	1	\$ 45.70	\$ 45.70
9	BOOTLID WEATHER STRIP <i>lit</i>	1	\$ 139.70	\$ 139.70
10	REAR NUMBER PLATE LAMP <i>New</i>	2	\$ 44.00	\$ 88.00
11	REAR NUMBER PLATE LAMP GARNISH <i>Painted</i>	1	\$ 110.00	\$ 110.00
12	REAR FENDER <i>LH Painted</i>	2	\$ 741.50	\$ 1,483.00
13	REAR FENDER COWLING <i>New LH missing</i>	2	\$ 79.80	\$ 159.60
14	REAR FENDER MUDFLAP <i>New</i>	2	\$ 79.90	\$ 159.80
15	REAR FENDER AIR VENT <i>New</i>	1	\$ 69.80	\$ 69.80

-
 -
 +
 ✓
 +
 -
 +
 -
 -
 +
 ✓
 741.50
 79.80
 +
 +

16	REAR FENDER INNER TRIM	Rehd	2	\$ 198.90	\$ 397.80	✓
17	REAR WINDSCREEN MOULDING	Neu	1	\$ 136.00	\$ 136.00	✓
18	REAR WINDSCREEN	neu	1	\$ 1,145.00	\$ 1,145.00	+
19	REAR DOOR INNER LOCK	neu	2	\$ 211.60	\$ 423.20	+
20	REAR BUMPER	Dishted	1	\$ 678.60	\$ 678.60	✓
21	REAR BUMPER SIDE RETAINER	neu	2	\$ 42.10	\$ 84.20	✓
22	REAR BUMPER EXHAUST GARNISH	Rehd	1	\$ 67.90	\$ 67.90	✓
23	REAR BUMPER BRACKET	neu	2	\$ 32.80	\$ 65.60	+
24	TAILLAMP	comhd	2	\$ 369.70	\$ 739.40	✓
25	TAILLAMP PANEL	L.H. Derted	2	\$ 256.10	\$ 512.20	256.10
26	TAILLAMP LOWER BRACKET	Best	2	\$ 39.10	\$ 78.20	✓
27	REAR END PANEL	Dishted	1	\$ 397.40	\$ 397.40	✓
28	REAR END PANEL TOP GARNISH	Rehd	1	\$ 142.40	\$ 142.40	✓
29	REAR FLOOR PANEL	Bneled	1	\$ 992.20	\$ 992.20	✓
30	REAR FLOOR PANEL TOP BOARD	Rehd	1	\$ 316.00	\$ 316.00	✓
31	REAR FLOOR PANEL UNDER COVER	Rehd	1	\$ 284.00	\$ 284.00	✓
31	REAR CHASSIS FRAME EXTENSION	Rys	1	\$ 583.50	\$ 583.50	+
32	REAR SPARE TYRE BOLT	neu	1	\$ 29.20	\$ 29.20	+
33	REAR EXHAUST PIPE	neu	1	\$ 635.40	\$ 635.40	+
34	REAR EXHAUST PIPE INSULATOR	neu	1	\$ 221.00	\$ 221.00	+
35	REAR EXHAUST MOUNTING	neu	2	\$ 16.00	\$ 32.00	+

7321

5856.80

TOTAL PRICE	\$ 12,062.30
LESS 20%	\$ 2,412.46
SUB TOTAL PRICE	\$ 9,649.84

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE	neu	1 \$ 50.00	\$ 50.00	+
2	REAR LED LIGHT	Dygd	1 \$ 100.00	\$ 100.00	50
3	REAR BUMPER CLIP	neu	10 \$ 6.50	\$ 65.00	30
4	TAIL LAMP CLIP	neu	4 \$ 8.00	\$ 32.00	20
5	TAILLAMP PANEL SEALANT	neu	2 \$ 40.00	\$ 80.00	+
6	BOOTLID SEALANT	neu	1 \$ 60.00	\$ 60.00	+
7	REAR FENDER COWLING CLIP	neu	12 \$ 6.50	\$ 78.00	20
8	REAR FENDER INNER TRIM CLIPS	neu	18 \$ 6.50	\$ 117.00	60
9	REAR WINDSCREEN SEALANT	Zys	1 \$ 80.00	\$ 80.00	40
10	REAR WINDSCREEN INNER SEAL		1 \$ 60.00	\$ 60.00	40
11	REAR END PANEL TOP GARNISH CLIPS	neu	4 \$ 10.00	\$ 40.00	10
12	REAR END PANEL INSULATION SEAL	neu	1 \$ 120.00	\$ 120.00	60

13	REAR FLOOR PANEL INSULATION SEAL <i>RM</i>	1	\$ 150.00	\$ 150.00	<input checked="" type="checkbox"/>
14	REVERSE SENSOR <i>Dagd</i>	1	\$ 220.00	\$ 220.00	<input checked="" type="checkbox"/>
15	REVERSE CAMERA <i>Dagd</i>	1	\$ 400.00	\$ 400.00	<input checked="" type="checkbox"/>
			TOTAL	\$ 1,652.00	

1030

✓
20
350

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$2,200.00	1600	
2	TO SPRAY PAINT AFFECTED AREA	\$1,800.00	1400	
3	TUFF COAT	\$250.00	120	
4	WIRING CHECK	\$60.00	30	
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$180.00	150	
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$80.00	50	
7	REAR CHASSIS ALIGNMENT	\$250.00	x	
8	TRANSFER BOOTLID MECHANISM	\$80.00	60	
9	REMOVE AND REFIX REAR WINDSCREEN	\$120.00	✓	
10	REMOVE AND REFIX AUDIO SPEAKER	\$80.00	x	
11	CONDUCT WATER LEAKAGE TEST	\$80.00	x	
12	REMOVE AND REFIX REAR EXHAUST PIPE	\$180.00	x	

TOTAL \$5,360.00

3530

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian Ling
1/2 09/01/20
12 Days
total: 10416.80
L/S: 8.3K ✓

ESTIMATE REPORT

TOTAL PARTS COST : \$ 11,301.84
TOTAL LABOUR COST : \$ 5,360.00
TOTAL REPAIR COST : \$ 16,661.84

APPROVED DETAILS

EXCESS :
NO. OF WORKING DAY :
RE-SURVEY :
PART BY PART OR LUMP SUM :
DATE & TIME OF SURVEY :
SURVEYED BY :
CONTACT NUMBER :
FAX NUMBER :