

SK AUTOMOBILE PTE LTD

Roc.No. 201500047H

23 Kaki Bukit Ave 4 #03-01 Vicom Inspection Centre

(South Wing) Singapore 415933

Tel: 67895155 Fax : 67835155

Date: 08/01/2020

To: Longac Insurance Bhd

By Fax & Email

Attn: Motor Claims Department.

Re: Accident involving motor vehicle nos. SJK 6685H and GBE 4947S
Along AYE on 06/01/2020

We refer to the above matter.

Under the new practice directions, we the repairers of motor vehicle no SJK 6685H
Hereby give you the insurer of motor vehicle no GBE 4947S **2 working days.**

Whether you are appointing your own surveyors to conduct a pre-repair inspection on our customers vehicle.

If we do not hear from you after 2 working days, we shall carry out to appoint our own surveyors on behalf of our said customer to conduct the said pre-repair inspection and proceed to repair the said vehicle thereafter.

Thank You.

Regards



Huey Lee

E-mail: admin@skauto.com.sg

FOR SURVEYOR

Please initial here after completion of pre-repair inspection. Thank you.

Appointed Surveyor: _____
(Name & Signature)

Date & Time of Inspection: _____

****8 Kaki Bukit Ave 4 #08-46**

Premier@Kaki Bukit

Singapore 415875

**** Pls contact: Xiong - 8121 0478**

Operations address: 23 Kaki Bukit Ave 4, #03-01 (South Wing) Singapore 415933

Tel: +65 6789-5155 Fax: +65 6783-5155