



凱摩哆服務

KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com
BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打嗎呷，噴漆。

Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

Date : 08/01/2020

Attn: The Motor Claims Department

Your Insured veh no : SLW 174 T

AIG ASIA PACIFIC INSURANCE PTE LTD.

78 Shenton Way

07-16 Chartis Building

Singapore 079120

TP AB.

Vic

Dear Sir / Madam

Estimate Cost repair Bill To Toyota Dyna GBA 3529 T & SLW 174 T on 06/01/2020

To Supply :-

1pc	Rear Tail Gate	Dented.		1,121.10	✓
1pc	Rear Door Toyota Sticker	new		215.00	✓
1pc	Rear Door 70 Sticker	2		48.50	✓ 10(SW)
1pc	Rear Door 13 Sticker	1		48.50	✓ 10(SW)
1pc	Rear Door Member	Repair		1,321.10	+
1pc	Spare Tyre Bracket	Not new		298.70	✗
1pc	Rear Spare Tyre Support Bracket	Not new		298.70	✗
2pcs	Rear Lamp	LH Cambol	LH & RH 285.10 x 2pcs	570.20	285.10
2pcs	Rear Number Plate Lamp	new	LH & RH 52.10 x 2pcs	104.20	+
2pcs	Rear Side Bracket Rubber	Paint.	65 x 2pcs	130.00	✓
1pc	Rear Number Plate	Best		55.00	✓
1pc	Rear Stap Bracekt	Best		350.00	250(SW)
1pc	Rear Floor Panel	Repair		1,390.00	+
1pc	Lh Door Side Bracket	Best		209.00	✓
				6,160.00	

To dismanlte & replace damage parts,panel beat where necessaey.

To putty,apply primer & spray paint on the affecte portion.

To check wiring functions.

850.00 800

1480 750.00 650.

80.00 30
7,840.00

total: 3563.68

1/8: 2850

Adrian Lin
HS 08/01/20.
06 Days.