



TAN LIM MOTOR PTE LTD

AlGAsia Insured's Veh No : GZ6226G
Date of Accident : 30 December 2019

1, Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Messrs BIS Motoring Pte Ltd

Date : 21 February 2020

Estimate To Repair SML7790P - Opel INSIGNIA GRANDSPORT B16DTH
Chassis No : W0VZM6EF3K1035033

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	rear bumper ✓ cut	\$ 1,429.20 ✓
02	1 pc	rear bumper reinforcement ✓ BT	\$ 646.00 ✓
03	2 ps	rear bumper reflector @ \$123.00 X (500)	\$ 246.00 ✓
04	2 ps	rear bumper sensor @ \$298.00 (set) ✓ slant	\$ 596.00 500 ✓
05	2 ps	rear bumper sensor holder @ \$14.00 ✓ m	\$ 28.00 ✓
		Less 10 %	\$ 2,945.20 \$ 294.52 \$ 2,650.68
		<u>SPECIAL NETT ITEMS</u>	
06	1 pc	rear bumper number plate ✓ CNA	\$ 50.00 35 ✓
			\$ 50.00
		<u>LABOUR & MISC. CHARGES</u>	
01		To rust-proofing of the affected areas.	\$ 150.00 30 ✓
02		To check electrical lighting concerned.	\$ 50.00 30 ✓
03		To reinstall of rear bumper parking sensor.	\$ 80.00 20 ✓
04		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same. - P.F.A. PH	\$ 800.00 600 ✓
05		Putty and spray painting of the affected portion. - P.F.A. PH	\$ 750.00 600 ✓
			\$ 1,830.00
		<u>Total</u>	\$ 4,530.68

parts 2603.20

parts less 10%

2342.88

spe nett 35

labour 1280

3657.88

1/5 sup less 20%

2926.30

total

2/5 But

\$ 2900.4