



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV No. AC2005018
INV Date 17/07/2020
Reference CC6/CTI20000605/Aba3n2
Code CTI



PROFESSIONAL SERVICE FEE

Vehicle No. SMC 7832A
Insured Veh. YP 193X
Claim No. SNM20D200132C02/3
Policy No. DMCVSN3081111900
Accident Date 07/01/2020
Inspection Date 08/01/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI20000605/Aba3n2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERSINGAPORE 079909

Date : 17-07-2020



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YP 193X	Veh. Inspected	SMC 7832A
Policy No.	DMCVSN3081111900	Coverage (\$)	0.00
Claim No.	SNM20D200132C02/3	Excess (\$)	0.00
Assign From		Assign Date	08/01/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA SIENTA	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	NHP1707109583	Colour	BROWN
Odometer	131710	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R15	MICHELIN	6 mm
L/H Front Tyre	185/60 R15	MICHELIN	6 mm
R/H Rear Tyre	185/60 R15	MICHELIN	6 mm
L/H Rear Tyre	185/60 R15	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	07/01/2020	Inspection Date	08/01/2020
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMC 7832A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BONNET	DENTED	1,520.00	706.00
1	FRONT BUMPER	DEFORMED	1,420.00	1,266.00
2	FRONT BUMPER SIDE RETAINER @\$62.40	NOT NECESSARY	124.80	-
1	FRONT BUMPER SPONGE	NOT NECESSARY	123.60	-
1	CENTRE GRILLE ASSY	CUT	720.00	640.00
	LESS 25% DISCOUNT		-977.10	-653.00
			2,931.30	1,959.00
<u>SPECIAL NETT ITEMS</u>				
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	20.00	20.00
			20.00	20.00
<u>LABOUR</u>				
	PANEL BEATING,REMOVAL AND REPLACING PARTS.		1,000.00	400.00
	TO SPRAY PAINT AFFECTED AREA.		1,000.00	400.00
	TUFF COAT.	NOT NECESSARY	150.00	-
	WIRING CHECK.		80.00	30.00
			2,230.00	830.00
GRAND TOTAL			5,181.30	2,809.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,200.00

Report Ref No. CC6/CTI20000605/Aba3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMC 7832A

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

